

KaVo M8900L Repair Diagram

Part #	Description

	2 330. 15
10116C-C	Chuck/Spindle Combo
60102M	Bearings (Note: You can also use 60102M-C)
10106PR	O-rings (Highly Recommended)
10216	Spring Washers (Must both be Large)
10116C-BR	Brake Ring (Don't need to remove from head typically)