





TDC NEW PRODUCT RELEASE

- ▶ Replacement turbine for
- ▶ MIDWEST TRADITION +PLUS

TDC PART NO.	EQUIVALENT OEM PART NO.	REPLACEMENT TURBINE FOR HANDPIECE MODELS	BEARING TYPE
40497PL-T	790218	MIDWEST TRADITION +PLUS	ANGULAR / CERAMIC / INTEGRAL SHIELD




**Turbine part No.
40497PL-T**



Part listing:

- | | |
|--------------|--------------|
| 1. 70109 | 2. 40518PL-1 |
| 3. 10106S | 4. 60102M-C |
| 5. 40477PL-A | 6. 40518PL-2 |



**Sub Assembly part No.
40497PL-A**



**Bearing part No.
60102M-C**



**Cap Wrench Part No.
40408XGT**