



| | | | | | |
|-----------------------------------|--------------------|---------------------------|--------------|---------------------------------------|--------------------|
| REPORT RECEIVED BY Kirk Morrow | DATE 08-21-2017 | TIME 08:58 AM | REPORTED VIA | NOTIFICATION NUMBER 082117-KM-0858 | NDEQ ID # 44141 |
| ANONYMOUS REPORT | | CONFIDENTIAL REPORT No | | KEEP REPORTING PARTY INFORMED Yes | |

PROBLEM LOCATION

| | PROBLEM LOCATION | RESPONSIBLE PARTY | REPORTING PARTY |
|--------------------|---------------------------|---------------------------|-------------------|
| NAME | | | Brian Kaman |
| POSITION TITLE | | | Resident |
| BUSINESS NAME | Western Sugar Cooperative | Western Sugar Cooperative | |
| STREET OR PO BOX | 2100 E Overland | | |
| ADDRESS LINE 2 | | | |
| CITY - STATE - ZIP | Scottsbluff NE 69361-7734 | Scottsbluff NE | |
| E-MAIL ADDRESS | | | zeke_61@yahoo.com |
| WORK PHONE | | | |
| CELL PHONE | | | |
| HOME PHONE | | | |

| | |
|------------------------|--|
| COUNTY Scotts Bluff | DIRECTIONS S Side E Overland, SW Cnr w/Hwy26, SE Cnr w/21 Ave |
|------------------------|--|

| | | | | | | | | |
|----------------|---------------|------------------|---------------|--------|------|-----------|----------------------|-------------------------|
| QUARTER NW¼ | SECTION 30 | TOWNSHIP N 22 | RANGE W 54 | MARKER | MILE | ROAD NAME | LATITUDE 41.85942 | LONGITUDE -103.63306 |
|----------------|---------------|------------------|---------------|--------|------|-----------|----------------------|-------------------------|

| | | |
|-----------|----------------------|----------------------|
| LAKE ID | LAKE | RIVER BASIN (LAKE) |
| STREAM ID | STREAM | RIVER BASIN (STREAM) |
| HUC | HYDROLOGIC UNIT NAME | SUBDIVISION |



OBSERVATIONS

WHAT IS THE PROBLEM?
 from complainant - I am writing to report the awful stench caused by the Western Sugar Company factory in Scottsbluff. It is horrible in Scottsbluff any time there is an east wind. I don't think it is their settling ponds. I think it is caused by some process they are doing. It is absolutely horrible, unbearable to be outside! Something needs to be done! I don't understand how they are allowed to continue to spew this stench into..

WHERE AT THE SITE IS THE PROBLEM?

DESCRIBE ANY APPARENT PATTERNS OVER TIME

| FIRST OBSERVED | LAST OBSERVED | ONGOING SITUATION | HOW LONG | OCCURRING NOW | RESPONSE TIMEFRAME |
|---------------------|---------------|-------------------|----------|---------------|--------------------|
| 08-20-2017 12:00 AM | | Yes | 1 Years | Yes | |

| AIR IMPACTED | LAND IMPACTED | WATER IMPACTED | SPILL OR RELEASE | FISH KILL | EVIDENCE OF ENVIRONMENTAL DAMAGE |
|--------------|---------------|----------------|------------------|-----------|----------------------------------|
| Yes | | | | | |

EVIDENCE OF ENVIRONMENTAL DAMAGE - EXPLANATION
 the air!

OTHER PERTINENT DETAILS
 Why isn't anything being done?

WHO ELSE DID THE REPORTING PARTY CONTACT ABOUT THIS PROBLEM?
 NDEQ has received similar previously reported issues.

NDEQ PROGRAM REFERRALS

| LEAD | PROGRAM ISSUE | PROG | PROGRAM ID | DATE CLOSED | REASON CLOSED | FIELD OFFICE |
|------|-------------------|------|------------|-------------|---------------|--------------|
| Yes | Wastewater Lagoon | PCS | | | | |
| | | | | | | |

OTHER AGENCIES NOTIFIED

| DATE | AGENCY | DIVISION | PROGRAM | REFERENCE # |
|------|--------|----------|---------|-------------|
| | | | | |
| | | | | |