

# Colony

OEM and Custom Hardware

April, May, and June  
2020 New Items



Part No. 3261-3 OIL TANK LINE CONNECTOR Reproduction of 63533-52 fitting, 63527-52 nut and 63529-52 brass sleeve used on 1952-early 1961 K, KH, XL, XLH. Retail: \$23.00



Part No. 3379-1 SPEEDO CABLE CLIP Parkerized reproduction of 11194-29 clip used on 1929 JD and 1930-1936 all models except 1936 61". Retail: \$19.99



Part No. 3503-2 MANIFOLD INTAKE NIPPLES Nickel plated reproduction of 1112-23 nipples used on 1923-1924 DCA, DCB, 1925-1929 74" motor and 1928-1929 61" L motor. Retail: \$45.00



Part No. 3504-2 MANIFOLD INTAKE NUTS Nickel plated reproduction of 1115-23 nuts used on 1923-1924 DCA, DCB, 1925-1929 74" motor and 1928-1929 61" L motor. Set of 2. Retail: \$28.00



Part No. 3506-1 COMPENSATING SPROCKET SHAFT NUT TOOL Installation and removal tool for the compensating sprocket shaft nuts (40385-55, 40385-65, 40386-57) used on 1955-1970 FL, FLH, 1957-1976 Sportster. Retail: \$50.00



Part No. 3509-2 MANIFOLD INTAKE NIPPLES Nickel plated reproduction of 1112-17 nipples used on 1917-1923 61" motor. Set of 2. Retail: \$43.00


**WHERE EXCELLENCE IS A STANDARD**



Part No. 3510-2 MANIFOLD INTAKE NUTS Nickel plated reproduction of 1115-15 nuts used on 1915-1927 61" and 1921-1924 FD, JD.  
Retail: \$27.00



Part No. 3513-1 STEERING DAMPER KNOB Aluminum reproduction of 46746-59 knob used on 1959-up XLCH.  
Retail: \$25.00



Part No. 3519-9 CRANKCASE RELIEF PIPE MOUNTING SCREW AND GASKET KIT reproduction of screws 036,1202, washer 0254,7021, gasket 544-37,24921-37 used on 1937-1973 45's, 1937-1948 Sidevalve.  
Retail: \$3.95



Part No. 3520-9 CRANKCASE RELIEF PIPE MOUNTING SCREW AND GASKET KIT reproduction of screws 036,1202, washer 0254,7021, gasket 544-37, 24921-37 used on 1937-1973 45's, 1937-1948 Sidevalve.  
Retail: \$3.95



Part No. 3526-2 MANIFOLD INTAKE NIPPLE BRASS SEALS Reproduction of 1125-15 brass seals used on 1917-1923 61".  
Retail: \$6.00



Part No. 3527-8 FRAME LOWER CLAMP BOLT KIT Parkerized reproduction of 14-30, 16804-30 bolts and 0265, 7055 lock washers used on 1936-1972 Sidecars.  
Retail: \$21.99



Part No. 3528-2 MANIFOLD INTAKE NIPPLE BRASS SEALS Reproduction of 1125-23 brass seals used on 1923-1924 DCA, DCB, 1925-1929 74" motor and 1928-1929 61" L motor.  
Retail: \$6.50

Disclaimer: The listed retail price is our suggested retail price. Not responsible for typos.