

Parameter	CCR Concentration	Mohave Concentration	Maximum Contaminate Level
E. coli	Absent	Absent	0
Copper	0.18	<0.01	1.3
Barium	0.059	0.052	2
Nitrate	3.5	5.0	10
Sodium	170	160	
TDS		1000	500