

1. AIRCRAFT SERIAL NUMBER 7923328				2. MODEL UH-60A			3. DATE			4. PAGE 1		
PART I - FAULT INFORMATION						PART II - CORRECTING INFORMATION						
STATUS /	SYS A	DATE 16 Apr 19	NO 1	TIME 06:53	PID MARTINEZ, ARN	DATE	TIME	ACFT HRS				
FAULTS/REMARKS INSTALL ANGLE BRACKETS FOR MR DE-ICE HARNESS PER H-60-19-AMAM-03, MR DE-ICE/CHIP DETECTOR HARNESS CHAFING AND RE-ROUTING AT NEXT MAIN TRANSMISSION REMOVAL						ACTION						
						PID	CAT	HRS	PID	CAT	HRS	
ACFT HRS 6075.6						WHEN DISC O	HOW REC G	MAL EFF 1				
DELAY awaiting next main transmission overhaul						WUC 00			TI MANHOURS			
STATUS —	SYS A	DATE 13 Dec 19	NO 4	TIME 09:00	PID MEDINA, MARIC	DATE	TIME	ACFT HRS				
FAULTS/REMARKS Engine SN: GEE307656C, Cold Section Module SN: GEC002026 requires replacement per H-60-20-ASAM-02 by 31 DEC 23.						ACTION						
						PID	CAT	HRS	PID	CAT	HRS	
ACFT HRS 6171.1						WHEN DISC O	HOW REC O	MAL EFF 1				
DELAY						WUC 04A01			TI MANHOURS			
STATUS /	SYS A	DATE 10 Mar 20	NO 1	TIME 07:13	PID SCHMIDT, NATH-	DATE	TIME	ACFT HRS				
FAULTS/REMARKS L/H cargo door is difficult to open, requires upward pressure.						ACTION						
						PID	CAT	HRS	PID	CAT	HRS	
ACFT HRS 6192.8						WHEN DISC X	HOW REC G	MAL EFF 4				
DELAY part ordered 10 March, 2020 NSN: 1560						WUC 02			TI MANHOURS			

DA FORM 2408-13-1-SG, OCT 1997

DA FORM 2408-13-1, OCT 91, MAY BE USED

AIRCRAFT INSPECTION AND MAINTENANCE RECORD

For use of this form, see DA PAM 738-751; the proponent agency is DCSLOG

APD PE v3.00

1. AIRCRAFT SERIAL NUMBER 7923328				2. MODEL UH-60A			3. DATE			4. PAGE 2		
PART I - FAULT INFORMATION						PART II - CORRECTING INFORMATION						
STATUS —	SYS A	DATE 10 Mar 20	NO 1	TIME 13:03	PID Generated, Cor	DATE	TIME	ACFT HRS				
FAULTS/REMARKS SAFETY MESSAGE NUMBER: H-60-20-AMAM-03 DESCRIPTION: ENGINE 1 HMU CONTROL LINK AND THE VARIABLE GUIDE VANE ACTUATING SHAFT QDP REQUIRES REPLACEMENT PER H-60-20-AMAM-03 BY 31 DEC 21. FOR T700-GE-701D ENGINE ASSY CAGE: 99207 PN: 5130T00G01 NSN: 2840015031701 SN: GEE307656C IS DUE: 31 MAR 2021 CALENDAR						ROUNDS	ACTION CODE	WUC				
ACFT HRS 5254						WHEN DISC O	HOW REC O	MAL EFF 1				
DELAY						WUC 04A			TIPIID ,			TI MANHOURS
STATUS —	SYS A	DATE 10 Mar 20	NO 2	TIME 13:03	PID Generated, Com	DATE	TIME	ACFT HRS				
FAULTS/REMARKS SAFETY MESSAGE NUMBER: H-60-20-AMAM-03 DESCRIPTION: ENGINE 1 HMU CONTROL LINK AND THE VARIABLE GUIDE VANE ACTUATING SHAFT QDP REQUIRES REPLACEMENT PER H-60-20-AMAM-03 BY 31 DEC 21. FOR T700-GE-701D ENGINE ASSY CAGE: 99207 PN: 5130T00G01 NSN: 2840015031701 SN: GEE374385C IS DUE: 31 MAR 2021 CALENDAR						ROUNDS	ACTION CODE	WUC				
ACFT HRS 6327.2						WHEN DISC O	HOW REC O	MAL EFF 1				
DELAY						WUC 04A			TIPIID ,			TI MANHOURS
STATUS —	SYS A	DATE 10 Mar 20	NO 2	TIME 13:05	PID Generated, Com	DATE	TIME	ACFT HRS				
FAULTS/REMARKS SAFETY MESSAGE NUMBER: H-60-20-AMAM-03 DESCRIPTION: ENGINE 1 AI/SBV LINK ASSEMBLY AND THE AI/SBV SHAFT QDP REQUIRES REPLACEMENT PER H-60-20-AMAM-03 BY 31 DEC 21. FOR T700-GE-701D ENGINE ASSY CAGE: 99207 PN: 5130T00G01 NSN: 2840015031701 SN: GEE307656C IS DUE: 31 MAR 2021 CALENDAR						ROUNDS	ACTION CODE	WUC				
ACFT HRS 5254						WHEN DISC O	HOW REC O	MAL EFF 1				
DELAY						WUC 04A			TIPIID ,			TI MANHOURS

DA FORM 2408-13-1-SG, OCT 1997

DA FORM 2408-13-1, OCT 91, MAY BE USED

AIRCRAFT INSPECTION AND MAINTENANCE RECORD

For use of this form, see DA PAM 738-751; the proponent agency is DCSLOG

APD PE v3.00

1. AIRCRAFT SERIAL NUMBER 7923328				2. MODEL UH-60A			3. DATE			4. PAGE 3		
PART I - FAULT INFORMATION						PART II - CORRECTING INFORMATION						
STATUS —	SYS A	DATE 10 Mar 20	NO 3	TIME 13:05	PID Generated, Cor	DATE	TIME	ACFT HRS				
FAULTS/REMARKS SAFETY MESSAGE NUMBER: H-60-20-AMAM-03 DESCRIPTION: ENGINE 1 AI/SBV LINK ASSEMBLY AND THE AI/SBV SHAFT QDP REQUIRES REPLACEMENT PER H-60-20-AMAM-03 BY 31 DEC 21. FOR T700-GE-701D ENGINE ASSY CAGE: 99207 PN: 5130T00G01 NSN: 2840015031701 SN: GEE374385C IS DUE: 31 MAR 2021 CALENDAR						ROUNDS	ACTION CODE	WUC				
						ACTION						
ACFT HRS 6327.2			WHEN DISC O	HOW REC O	MAL EFF 1	PID	CAT	HRS	PID	CAT	HRS	
DELAY				WUC 04A		TIPIID ,			TI MANHOURS			
STATUS —	SYS A	DATE 10 Mar 20	NO 3	TIME 13:06	PID Generated, Com	DATE	TIME	ACFT HRS				
FAULTS/REMARKS SAFETY MESSAGE NUMBER: H-60-20-AMAM-03 DESCRIPTION: ENGINE 2 HMU CONTROL LINK AND THE VARIABLE GUIDE VANE ACTUATING SHAFT QDP REQUIRES REPLACEMENT PER H-60-20-AMAM-03 BY 31 DEC 21. FOR T700-GE-701D ENGINE ASSY CAGE: 99207 PN: 5130T00G01 NSN: 2840015031701 SN: GEE307656C IS DUE: 31 MAR 2021 CALENDAR						ROUNDS	ACTION CODE	WUC				
						ACTION						
ACFT HRS 5254			WHEN DISC O	HOW REC O	MAL EFF 1	PID	CAT	HRS	PID	CAT	HRS	
DELAY				WUC 04A		TIPIID ,			TI MANHOURS			
STATUS —	SYS A	DATE 10 Mar 20	NO 4	TIME 13:07	PID Generated, Com	DATE	TIME	ACFT HRS				
FAULTS/REMARKS SAFETY MESSAGE NUMBER: H-60-20-AMAM-03 DESCRIPTION: ENGINE 2 HMU CONTROL LINK AND THE VARIABLE GUIDE VANE ACTUATING SHAFT QDP REQUIRES REPLACEMENT PER H-60-20-AMAM-03 BY 31 DEC 21. FOR T700-GE-701D ENGINE ASSY CAGE: 99207 PN: 5130T00G01 NSN: 2840015031701 SN: GEE374385C IS DUE: 31 MAR 2021 CALENDAR						ROUNDS	ACTION CODE	WUC				
						ACTION						
ACFT HRS 6327.2			WHEN DISC O	HOW REC O	MAL EFF 1	PID	CAT	HRS	PID	CAT	HRS	
DELAY				WUC 04A		TIPIID ,			TI MANHOURS			

DA FORM 2408-13-1-SG, OCT 1997

DA FORM 2408-13-1, OCT 91, MAY BE USED

AIRCRAFT INSPECTION AND MAINTENANCE RECORD

For use of this form, see DA PAM 738-751; the proponent agency is DCSLOG

APD PE v3.00

1. AIRCRAFT SERIAL NUMBER 7923328				2. MODEL UH-60A			3. DATE			4. PAGE 4				
PART I - FAULT INFORMATION						PART II - CORRECTING INFORMATION								
STATUS —	SYS A	DATE 01 Apr 20	NO 1	TIME 07:33	PID Generated, Cor	DATE	TIME	ACFT HRS						
FAULTS/REMARKS SAFETY MESSAGE NUMBER: H-60-20-AMAM-03 DESCRIPTION: ENGINE 2 AI/SBV LINK ASSEMBLY AND THE AI/SBV SHAFT QDP REQUIRES REPLACEMENT PER H-60-20-AMAM-03 BY 31 DEC 21 FOR T700-GE-701D ENGINE ASSY CAGE: 99207 PN: 5130T00G01 NSN: 2840015031701 SN: GEE307656C IS DUE: 31 DEC 2021 CALENDAR						ROUNDS	ACTION CODE	WUC						
						ACTION								
						PID	CAT	HRS	PID	CAT	HRS	PID	CAT	HRS
ACFT HRS 5267		WHEN DISC O	HOW REC O	MAL EFF 1										
DELAY			WUC 04A			TIPIID ,			TI MANHOURS					
STATUS —	SYS A	DATE 01 Apr 20	NO 2	TIME 07:33	PID Generated, Com	DATE	TIME	ACFT HRS						
FAULTS/REMARKS SAFETY MESSAGE NUMBER: H-60-20-AMAM-03 DESCRIPTION: ENGINE 2 AI/SBV LINK ASSEMBLY AND THE AI/SBV SHAFT QDP REQUIRES REPLACEMENT PER H-60-20-AMAM-03 BY 31 DEC 21 FOR T700-GE-701D ENGINE ASSY CAGE: 99207 PN: 5130T00G01 NSN: 2840015031701 SN: GEE374385C IS DUE: 31 DEC 2021 CALENDAR						ROUNDS	ACTION CODE	WUC						
						ACTION								
						PID	CAT	HRS	PID	CAT	HRS	PID	CAT	HRS
ACFT HRS 6327.2		WHEN DISC O	HOW REC O	MAL EFF 1										
DELAY			WUC 04A			TIPIID ,			TI MANHOURS					
STATUS /	SYS A	DATE 10 Apr 20	NO 2	TIME 21:46	PID FITZGERALD, CH	DATE	TIME	ACFT HRS						
FAULTS/REMARKS HF CONTROL HEAD UNREADABLE						ROUNDS	ACTION CODE	WUC						
						ACTION								
						PID	CAT	HRS	PID	CAT	HRS	PID	CAT	HRS
ACFT HRS 6207.2		WHEN DISC G	HOW REC G	MAL EFF 3										
DELAY w.o to AVI 15 April 2020			WUC 19			TIPIID ,			TI MANHOURS					

DA FORM 2408-13-1-SG, OCT 1997

DA FORM 2408-13-1, OCT 91, MAY BE USED

AIRCRAFT INSPECTION AND MAINTENANCE RECORD

For use of this form, see DA PAM 738-751; the proponent agency is DCSLOG

APD PE v3.00

1. AIRCRAFT SERIAL NUMBER 7923328			2. MODEL UH-60A			3. DATE			4. PAGE 5		
PART I - FAULT INFORMATION						PART II - CORRECTING INFORMATION					
STATUS ⊗	SYS A	DATE 16 Apr 20	NO 2	TIME 11:06	PID TRUJILLO, GABF	DATE	TIME	ACFT HRS			
FAULTS/REMARKS OPERATE WITHIN LIMITATIONS AND RESTRICTIONS IAW: AWR 2122 R5 (10 SEP 21) TECHNISONIC, AWR 2059 R3 (15 Aug 21) SHOUT, AWR 2000 R10(31 Aug 21) BFT-2, AWR 1965 R9 (17 Mar 21) PEDs, AWR 1930 R12 (31 JAN 21) PMI, AWR 1913 R4 (18 DEC 20) ELECTRONIC LOGBOOK, AWR 1877 R4 (24 JAN 22) DCIU, AWR 1872 R3 (31 Jan 21) AWIS, AWR 1859 R10 (15 Jan 21) WULFSBERG FLEXCOM, AWR 1858 R7 (13 JUL 20) EAWIS, AWR 1833 R8 (31 Jul 20) AN/APX-123, AWR 1823 R9 (30 NOV 21) IVHMS, AWR 1801 R20 (31 Aug 20) BFT Dual- EDM, AWR 1788 R7 (8 Jan 21) AN/ARN-147, AWR 1787 R4 (1 Sep 21) AN/ARN-123, AWR 1753 R8 (30 SEP 21) AN/ASN-128B/D, AWR						ACTION					
						PID	CAT	HRS	PID	CAT	HRS
ACFT HRS 6207.2		WHEN DISC O	HOW REC O	MAL EFF 1							
DELAY			WUC 00			TIPIID ,			TI MANHOURS		
STATUS /	SYS A	DATE 14 May 20	NO 2	TIME 10:21	PID KINGSLEY, LEE	DATE	TIME	ACFT HRS			
FAULTS/REMARKS T/R cowlng ejector spring 2nd from bottom corner broken. All parts recovered from assy.						ACTION					
						PID	CAT	HRS	PID	CAT	HRS
ACFT HRS 6229.7		WHEN DISC X	HOW REC G	MAL EFF 2							
DELAY part ordered 6AUGUST20			WUC 00			TIPIID ,			TI MANHOURS		
STATUS —	SYS A	DATE 05 Jun 20	NO 1	TIME 10:04	PID Generated, Com	DATE	TIME	ACFT HRS			
FAULTS/REMARKS INSP A800 24 MONTH RECURRING INSPECTION, REQUIRING TAP TEST INSPECTION OF THE RED MAIN ROTOR BLADE, PN 70150-09100-ALL, SPAR AND HONEYCOMB CORE REGION UPPER AIRFOIL. IAW H-60-20-ASAM-04. NOT TO EXCEED NEXT PMI HRS OR 20 APR 2022. FOR HELICOPTER, UTILITY CAGE: 78286 PN: UH-60A NSN: 1520010350266 SN: 7923328 IS DUE. STATUS WILL UPGRADE TO X ON: 6395.7 AIRCRAFT HOURS OR 21 APR 2022 REFERENCE: H-60-20-ASAM-04						ACTION					
						PID	CAT	HRS	PID	CAT	HRS
ACFT HRS 6244.3		WHEN DISC O	HOW REC O	MAL EFF 1							
DELAY			WUC 00			TIPIID ,			TI MANHOURS		

DA FORM 2408-13-1-SG, OCT 1997

DA FORM 2408-13-1, OCT 91, MAY BE USED

AIRCRAFT INSPECTION AND MAINTENANCE RECORD

For use of this form, see DA PAM 738-751; the proponent agency is DCSLOG

APD PE v3.00

1. AIRCRAFT SERIAL NUMBER 7923328				2. MODEL UH-60A			3. DATE			4. PAGE 6		
PART I - FAULT INFORMATION						PART II - CORRECTING INFORMATION						
STATUS ⊗	SYS A	DATE 12 Jun 20	NO 2	TIME 13:37	PID LAUMBACH, AD	DATE	TIME	ACFT HRS				
FAULTS/REMARKS RESTRICTED TO MANUAL HIT CHECKS DUE TO IVHMS SCREEN NOT POWERING ON						ACTION						
						ROUNDS	ACTION CODE		WUC			
						PID	CAT	HRS	PID	CAT	HRS	PID
ACFT HRS 6248.1		WHEN DISC G	HOW REC G	MAL EFF 3								
DELAY part ordered on 28 July, 2020			WUC 08F01			TIPIID ,			TI MANHOURS			
STATUS /	SYS A	DATE 24 Jun 20	NO 3	TIME 08:49	PID MARQUEZ, GAB	DATE	TIME	ACFT HRS				
FAULTS/REMARKS TROOP COMMANDER STATIC UNLESS AUX AND NAV PINS ARE HELD WITH PRESSURE						ACTION						
						ROUNDS	ACTION CODE		WUC			
						PID	CAT	HRS	PID	CAT	HRS	PID
ACFT HRS 6256.1		WHEN DISC K	HOW REC G	MAL EFF 2								
DELAY W.O. TO AVIONICS 9 JUL 2020			WUC 19			TIPIID ,			TI MANHOURS			
STATUS —	SYS A	DATE 24 Aug 20	NO 2	TIME 07:08	PID KIST, CHRISTOPH	DATE	TIME	ACFT HRS				
FAULTS/REMARKS Perform daily inspection on R/H door track to ensure crack has not propagated. Inspection will remain in effect until door track is repaired or replaced.						ACTION						
						ROUNDS	ACTION CODE		WUC			
						PID	CAT	HRS	PID	CAT	HRS	PID
ACFT HRS 6310.4		WHEN DISC G	HOW REC G	MAL EFF 1								
DELAY			WUC 02			TIPIID ,			TI MANHOURS			

DA FORM 2408-13-1-SG, OCT 1997

DA FORM 2408-13-1, OCT 91, MAY BE USED

AIRCRAFT INSPECTION AND MAINTENANCE RECORD

For use of this form, see DA PAM 738-751; the proponent agency is DCSLOG

APD PE v3.00

1. AIRCRAFT SERIAL NUMBER 7923328				2. MODEL UH-60A			3. DATE			4. PAGE 7		
PART I - FAULT INFORMATION						PART II - CORRECTING INFORMATION						
STATUS —	SYS A	DATE 26 Aug 20	NO 1	TIME 15:47	PID SCHMIDT, NATI	DATE	TIME	ACFT HRS				
FAULTS/REMARKS Creaking feedback heard/felt with boost off and co-pilot left pedal input requires inspection of the co-pilot bellcranks and bellcrank supports inside of MO "Broom Closet" Every 40 Hrs or until next phase inspection when removal of said items can be accomplished. Next inspection is due at: 6353.1 flight hours. Upon completion re-enter this inspection with updated 40 hr time frame inspection.						ACTION						
						PID	CAT	HRS	PID	CAT	HRS	
ACFT HRS 6313.1						WHEN DISC O	HOW REC O	MAL EFF 1				
DELAY				WUC 11		TIPIID ,			TI MANHOURS			
STATUS /	SYS A	DATE 13 Sep 20	NO 2	TIME 12:27	PID CALZADA, MICH	DATE	TIME	ACFT HRS				
FAULTS/REMARKS FM AUDIO VERY WEAK WHEN TRANSMITTING AND RECIEVING						ACTION						
						PID	CAT	HRS	PID	CAT	HRS	
ACFT HRS 6321.3						WHEN DISC G	HOW REC B	MAL EFF 1				
DELAY w/o to avionics 13 SEP				WUC 00		TIPIID ,			TI MANHOURS			
STATUS /	SYS A	DATE 13 Sep 20	NO 3	TIME 12:30	PID CALZADA, MICH	DATE	TIME	ACFT HRS				
FAULTS/REMARKS TECHNASONIC DISPLAYS CLEAR TX ONLY WHEN ATTEMPTING TRANSMISSION						ACTION						
						PID	CAT	HRS	PID	CAT	HRS	
ACFT HRS 6321.3						WHEN DISC G	HOW REC B	MAL EFF 1				
DELAY w/o to avionics 13 Sept				WUC 00		TIPIID ,			TI MANHOURS			

DA FORM 2408-13-1-SG, OCT 1997

DA FORM 2408-13-1, OCT 91, MAY BE USED

AIRCRAFT INSPECTION AND MAINTENANCE RECORD

For use of this form, see DA PAM 738-751; the proponent agency is DCSLOG

APD PE v3.00

1. AIRCRAFT SERIAL NUMBER 7923328				2. MODEL UH-60A			3. DATE			4. PAGE 8		
PART I - FAULT INFORMATION						PART II - CORRECTING INFORMATION						
STATUS X	SYS A	DATE 16 Sep 20	NO 1	TIME 07:22	PID SCHMIDT, NATH	DATE	TIME	ACFT HRS				
FAULTS/REMARKS T/R servo pushrod tri pivot free spinning bolt and bushing and possibly push rod are elongated. radial play beyond limits						ROUNDS	ACTION CODE	WUC				
ACTION												
ACFT HRS 6327.2						WHEN DISC X	HOW REC G	MAL EFF 5				
DELAY Parts request submitted 16 Sept						WUC 11			TIPIID ,			TI MANHOURS
STATUS X	SYS A	DATE 17 Sep 20	NO 1	TIME 07:31	PID SCHMIDT, NATH	DATE 03 Oct 20	TIME 09:31	ACFT HRS 6327.2				
FAULTS/REMARKS Pilot Side door handle spun freely while door was locked. When PI tried to open door, handle came off. Door had to be jettisoned to release pilot.						ROUNDS	ACTION CODE 2	WUC 02				
ACTION						Replaced door. control exchange completed, paperwork submitted to PC. All 13-2 entries are with the control exchange entry. This entry transferred to acft 79-23328						
ACFT HRS 6327.2						WHEN DISC X	HOW REC G	MAL EFF 5				
DELAY						WUC 02			TIPIID ,			TI MANHOURS
STATUS X	SYS A	DATE 17 Sep 20	NO 2	TIME 11:50	PID GOMEZ, CHRIST	DATE	TIME	ACFT HRS				
FAULTS/REMARKS ace inspection inprogress						ROUNDS	ACTION CODE	WUC				
ACTION												
ACFT HRS 6327.2						WHEN DISC O	HOW REC O	MAL EFF 1				
DELAY						WUC 02			TIPIID ,			TI MANHOURS

DA FORM 2408-13-1-SG, OCT 1997

DA FORM 2408-13-1, OCT 91, MAY BE USED

AIRCRAFT INSPECTION AND MAINTENANCE RECORD

For use of this form, see DA PAM 738-751; the proponent agency is DCSLOG

APD PE v3.00

1. AIRCRAFT SERIAL NUMBER 7923328				2. MODEL UH-60A			3. DATE			4. PAGE 9		
PART I - FAULT INFORMATION						PART II - CORRECTING INFORMATION						
STATUS X	SYS A	DATE 23 Sep 20	NO 1	TIME 00:00	PID Generated, Cor	DATE	TIME	ACFT HRS				
FAULTS/REMARKS INSP A820 7 DAY PMD DUE FOR HCPTX UTILITY UH-60A CAGE: 78286 PN: UH-60A NSN: 1520010350266 SN: 7923328 WAS DUE. STATUS UPGRADED TO X ON: 22 SEP 2020 REFERENCE: TM 1-1520-237-PMD						ROUNDS	ACTION CODE	WUC				
						PID	CAT	HRS	PID	CAT	HRS	PID
ACFT HRS 6327.2		WHEN DISC O	HOW REC O	MAL EFF 1								
DELAY			WUC 00			TIPIID ,			TI MANHOURS			
STATUS X	SYS A	DATE 29 Sep 20	NO 1	TIME 00:01	PID Generated, Com	DATE	TIME	ACFT HRS				
FAULTS/REMARKS INSP A022 14 DAY FLYABLE STORAGE ENGINE RUN UP FOR HCPTX UTILITY UH-60A CAGE: 78286 PN: UH-60A NSN: 1520010350266 SN: 7923328 WAS DUE. STATUS UPGRADED TO X ON: 28 SEP 2020 REFERENCE: TM 1-1520-237-23&P						ROUNDS	ACTION CODE	WUC				
						PID	CAT	HRS	PID	CAT	HRS	PID
ACFT HRS 6327.2		WHEN DISC O	HOW REC O	MAL EFF 1								
DELAY			WUC 00			TIPIID ,			TI MANHOURS			
STATUS X	SYS A	DATE 03 Oct 20	NO 1	TIME 00:01	PID Generated, Com	DATE	TIME	ACFT HRS				
FAULTS/REMARKS INSP A103 AIRCRAFT WASH DUE FOR HCPTX UTILITY UH-60A CAGE: 78286 PN: UH-60A NSN: 1520010350266 SN: 7923328 WAS DUE. STATUS UPGRADED TO X ON: 02 OCT 2020 REFERENCE: TM 1-1500-344-23						ROUNDS	ACTION CODE	WUC				
						PID	CAT	HRS	PID	CAT	HRS	PID
ACFT HRS 6327.2		WHEN DISC O	HOW REC O	MAL EFF 1								
DELAY			WUC 00			TIPIID ,			TI MANHOURS			

DA FORM 2408-13-1-SG, OCT 1997

DA FORM 2408-13-1, OCT 91, MAY BE USED

AIRCRAFT INSPECTION AND MAINTENANCE RECORD

For use of this form, see DA PAM 738-751; the proponent agency is DCSLOG

APD PE v3.00

1. AIRCRAFT SERIAL NUMBER 7923328				2. MODEL UH-60A			3. DATE			4. PAGE 10		
PART I - FAULT INFORMATION						PART II - CORRECTING INFORMATION						
STATUS X	SYS E	DATE 04 Oct 20	NO 1	TIME 00:01	PID Generated, Cor	DATE	TIME	ACFT HRS				
						ROUNDS	ACTION CODE	WUC				
FAULTS/REMARKS INSP E220 EMERGENCY LOCATOR TRANSMITTER SELF-TEST (AS REQUIRED) FOR HCPTR UTILITY UH-60A CAGE: 78286 PN: UH-60A NSN: 1520010350266 SN: 7923328 WAS DUE. STATUS UPGRADED TO X ON: 03 OCT 2020 OR 6438.1 AIRCRAFT HOURS REFERENCE: AWR 1516 R12						ACTION						
						PID	CAT	HRS	PID	CAT	HRS	
ACFT HRS 6327.2		WHEN DISC O	HOW REC O	MAL EFF 1								
DELAY			WUC 00			TIPIID ,			TI MANHOURS			
STATUS X	SYS A	DATE 04 Oct 20	NO 1	TIME 00:01	PID Generated, Com	DATE	TIME	ACFT HRS				
						ROUNDS	ACTION CODE	WUC				
FAULTS/REMARKS INSP A092 30 DAY SLAB BATTERY INSPECTION (D8565/11-1) FOR HCPTR UTILITY UH-60A CAGE: 78286 PN: UH-60A NSN: 1520010350266 SN: 7923328 WAS DUE. STATUS UPGRADED TO X ON: 03 OCT 2020 REFERENCE: TM 11-6140-203-23 P						ACTION						
						PID	CAT	HRS	PID	CAT	HRS	
ACFT HRS 6327.2		WHEN DISC O	HOW REC O	MAL EFF 1								
DELAY			WUC 00			TIPIID ,			TI MANHOURS			
STATUS X	SYS E	DATE 04 Oct 20	NO 3	TIME 00:01	PID Generated, Com	DATE	TIME	ACFT HRS				
						ROUNDS	ACTION CODE	WUC				
FAULTS/REMARKS INSP E050 ARC-220 RADIO SET BATTERY INSPECTION OR REPLACE FOR HCPTR UTILITY UH-60A CAGE: 78286 PN: UH-60A NSN: 1520010350266 SN: 7923328 WAS DUE. STATUS UPGRADED TO X ON: 03 OCT 2020 REFERENCE: TM 11-5821-357-12P						ACTION						
						PID	CAT	HRS	PID	CAT	HRS	
ACFT HRS 6327.2		WHEN DISC O	HOW REC O	MAL EFF 1								
DELAY			WUC 00			TIPIID ,			TI MANHOURS			

DA FORM 2408-13-1-SG, OCT 1997

DA FORM 2408-13-1, OCT 91, MAY BE USED

AIRCRAFT INSPECTION AND MAINTENANCE RECORD

For use of this form, see DA PAM 738-751; the proponent agency is DCSLOG

APD PE v3.00

1. AIRCRAFT SERIAL NUMBER 7923328				2. MODEL UH-60A			3. DATE			4. PAGE 11		
PART I - FAULT INFORMATION						PART II - CORRECTING INFORMATION						
STATUS /	SYS A	DATE 04 Oct 20	NO 2	TIME 14:52	PID VASQUEZ, BENJ	DATE	TIME	ACFT HRS				
FAULTS/REMARKS co-pilots dorr vent came off during taxing, not recovered						ACTION						
ACFT HRS 6327.2						WHEN DISC X		HOW REC G		MAL EFF 4		
DELAY						WUC 02						
						TIPIID ,			TI MANHOURS			
STATUS X	SYS A	DATE 12 Oct 20	NO 1	TIME 00:00	PID Generated, Com	DATE	TIME	ACFT HRS				
FAULTS/REMARKS INSP A115 LUBE REQUIRMENTS FOR HCPTX UTILITY UH-60A CAGE: 78286 PN: UH-60A NSN: 1520010350266 SN: 7923328 WAS DUE. STATUS UPGRADED TO X ON: 11 OCT 2020 OR 6361.3 AIRCRAFT HOURS REFERENCE: TM 1-1520-237-23&P						ACTION						
ACFT HRS 6327.2						WHEN DISC O		HOW REC O		MAL EFF 1		
DELAY						WUC 00						
						TIPIID ,			TI MANHOURS			
STATUS X	SYS A	DATE 14 Oct 20	NO 1	TIME 15:15	PID MONAREZ, SAU	DATE	TIME	ACFT HRS				
FAULTS/REMARKS left and right foward air duct behind pilots and copilots seat rmvd by request of NGB CW4 Matt Ingmire						ACTION						
ACFT HRS 6327.2						WHEN DISC B		HOW REC G		MAL EFF 1		
DELAY						WUC 02						
						TIPIID ,			TI MANHOURS			

DA FORM 2408-13-1-SG, OCT 1997

DA FORM 2408-13-1, OCT 91, MAY BE USED

AIRCRAFT INSPECTION AND MAINTENANCE RECORD

For use of this form, see DA PAM 738-751; the proponent agency is DCSLOG

APD PE v3.00

1. AIRCRAFT SERIAL NUMBER 7923328				2. MODEL UH-60A			3. DATE			4. PAGE 12		
PART I - FAULT INFORMATION						PART II - CORRECTING INFORMATION						
STATUS X	SYS A	DATE 16 Oct 20	NO 1	TIME 00:00	PID Generated, Cor	DATE	TIME	ACFT HRS				
						ROUNDS	ACTION CODE	WUC				
FAULTS/REMARKS INSP A230 INSPECT BATTERY COMPARTMENT FOR CORROSION (SLAB) FOR HCPTR UTILITY UH-60A CAGE: 78286 PN: UH-60A NSN: 1520010350266 SN: 7923328 WAS DUE. STATUS UPGRADED TO X ON: 15 OCT 2020 REFERENCE: MWO 1-1520-237-50-77						ACTION						
						PID	CAT	HRS	PID	CAT	HRS	
ACFT HRS 6327.2		WHEN DISC O	HOW REC O	MAL EFF 1								
DELAY				WUC 00		TIPIID ,			TI MANHOURS			
STATUS X	SYS A	DATE 22 Oct 20	NO 2	TIME 14:37	PID OLSON, MICHA	DATE	TIME	ACFT HRS				
						ROUNDS	ACTION CODE	WUC				
FAULTS/REMARKS #1 Hyd pump, pressure side, differential pressure switch pops and resets on its own.						ACTION						
						PID	CAT	HRS	PID	CAT	HRS	
ACFT HRS 6327.2		WHEN DISC K	HOW REC G	MAL EFF 2								
DELAY				WUC 02		TIPIID ,			TI MANHOURS			
STATUS X	SYS A	DATE 25 Oct 20	NO 1	TIME 00:01	PID Generated, Com	DATE	TIME	ACFT HRS				
						ROUNDS	ACTION CODE	WUC				
FAULTS/REMARKS INSP A177 90 DAY REVIEW/UPDATE OF 365-4 ENTRIES FOR HCPTR UTILITY UH-60A CAGE: 78286 PN: UH-60A NSN: 1520010350266 SN: 7923328 WAS DUE. STATUS UPGRADED TO X ON: 24 OCT 2020 REFERENCE: AR 95-1						ACTION						
						PID	CAT	HRS	PID	CAT	HRS	
ACFT HRS 6327.2		WHEN DISC O	HOW REC O	MAL EFF 1								
DELAY				WUC 00		TIPIID ,			TI MANHOURS			

DA FORM 2408-13-1-SG, OCT 1997

DA FORM 2408-13-1, OCT 91, MAY BE USED

AIRCRAFT INSPECTION AND MAINTENANCE RECORD

For use of this form, see DA PAM 738-751; the proponent agency is DCSLOG

APD PE v3.00

1. AIRCRAFT SERIAL NUMBER 7923328				2. MODEL UH-60A			3. DATE			4. PAGE 13		
PART I - FAULT INFORMATION						PART II - CORRECTING INFORMATION						
STATUS X	SYS A	DATE 28 Oct 20	NO 2	TIME 15:28	PID MARQUEZ, GAB	DATE	TIME	ACFT HRS				
FAULTS/REMARKS RMVD TAIL ROTOR BLADES.						ROUNDS	ACTION CODE	WUC				
						ACTION						
ACFT HRS 6327.2			WHEN DISC K	HOW REC O	MAL EFF 2	PID	CAT	HRS	PID	CAT	HRS	
DELAY			WUC 00			TIPIID ,			TI MANHOURS			
STATUS X	SYS E	DATE 31 Oct 20	NO 1	TIME 00:00	PID Generated, Com	DATE	TIME	ACFT HRS				
FAULTS/REMARKS INSP E165 KIT-1C BATTERY REPLACEMENT FOR HCPTU UTILITY UH-60A CAGE: 78286 PN: UH-60A NSN: 1520010350266 SN: 7923328 WAS DUE. STATUS UPGRADED TO X ON: 30 OCT 2020 REFERENCE: TM 11-5810-389-13						ROUNDS	ACTION CODE	WUC				
						ACTION						
ACFT HRS 6327.2			WHEN DISC O	HOW REC O	MAL EFF 1	PID	CAT	HRS	PID	CAT	HRS	
DELAY			WUC 00			TIPIID ,			TI MANHOURS			
STATUS X	SYS A	DATE 02 Nov 20	NO 1	TIME 00:00	PID Generated, Com	DATE	TIME	ACFT HRS				
FAULTS/REMARKS INSP A811 LOGBOOK RECON DUE FOR HCPTU UTILITY UH-60A CAGE: 78286 PN: UH-60A NSN: 1520010350266 SN: 7923328 WAS DUE. STATUS UPGRADED TO X ON: 01 NOV 2020 REFERENCE: UNIT SOP						ROUNDS	ACTION CODE	WUC				
						ACTION						
ACFT HRS 6327.2			WHEN DISC O	HOW REC O	MAL EFF 1	PID	CAT	HRS	PID	CAT	HRS	
DELAY			WUC 00			TIPIID ,			TI MANHOURS			

DA FORM 2408-13-1-SG, OCT 1997

DA FORM 2408-13-1, OCT 91, MAY BE USED

AIRCRAFT INSPECTION AND MAINTENANCE RECORD

For use of this form, see DA PAM 738-751; the proponent agency is DCSLOG

APD PE v3.00

1. AIRCRAFT SERIAL NUMBER 7923328				2. MODEL UH-60A			3. DATE			4. PAGE 14		
PART I - FAULT INFORMATION						PART II - CORRECTING INFORMATION						
STATUS X	SYS E	DATE 05 Nov 20	NO 1	TIME 06:45	PID MONAREZ, SAU	DATE	TIME	ACFT HRS				
FAULTS/REMARKS faulty fuel boost control head doesnt illuminate No.1 boost pump light when on						ACTION						
						ROUNDS	ACTION CODE		WUC			
ACFT HRS 6327.2			WHEN DISC K	HOW REC G	MAL EFF 1	PID	CAT	HRS	PID	CAT	HRS	
DELAY				WUC 00		TIPIID ,			TI MANHOURS			
STATUS X	SYS E	DATE 10 Nov 20	NO 1	TIME 00:00	PID Generated, Com	DATE	TIME	ACFT HRS				
FAULTS/REMARKS INSP E040 APR-39 RADAR/LASER WARNING OPNL CHECK, 5841-01-236-8951 FOR HCPTR UTILITY UH-60A CAGE: 78286 PN: UH-60A NSN: 1520010350266 SN: 7923328 WAS DUE. STATUS UPGRADED TO X ON: 09 NOV 2020 REFERENCE: TM 11-5841-294-12						ACTION						
						ROUNDS	ACTION CODE		WUC			
ACFT HRS 6327.2			WHEN DISC O	HOW REC O	MAL EFF 1	PID	CAT	HRS	PID	CAT	HRS	
DELAY				WUC 00		TIPIID ,			TI MANHOURS			
STATUS X	SYS E	DATE 16 Nov 20	NO 1	TIME 09:38	PID Generated, Com	DATE	TIME	ACFT HRS				
FAULTS/REMARKS INSP E125 KY-58 PMCS/OPNL CHECK FOR HCPTR UTILITY UH-60A CAGE: 78286 PN: UH-60A NSN: 1520010350266 SN: 7923328 WAS DUE. STATUS UPGRADED TO X ON: 15 NOV 2020 REFERENCE: TM 11-5810-262-23						ACTION						
						ROUNDS	ACTION CODE		WUC			
ACFT HRS 6327.2			WHEN DISC O	HOW REC O	MAL EFF 1	PID	CAT	HRS	PID	CAT	HRS	
DELAY				WUC 00		TIPIID ,			TI MANHOURS			

DA FORM 2408-13-1-SG, OCT 1997

DA FORM 2408-13-1, OCT 91, MAY BE USED

AIRCRAFT INSPECTION AND MAINTENANCE RECORD

For use of this form, see DA PAM 738-751; the proponent agency is DCSLOG

APD PE v3.00

1. AIRCRAFT SERIAL NUMBER 7923328				2. MODEL UH-60A			3. DATE			4. PAGE 15		
PART I - FAULT INFORMATION						PART II - CORRECTING INFORMATION						
STATUS X	SYS E	DATE 01 Dec 20	NO 1	TIME 00:00	PID Generated, Cor	DATE	TIME	ACFT HRS				
						ROUNDS	ACTION CODE	WUC				
FAULTS/REMARKS INSP E331 UNDER WATER ACOUSTIC BEACON TEST AND CLEAN FOR HCPTR UTILITY UH-60A CAGE: 78286 PN: UH-60A NSN: 1520010350266 SN: 7923328 WAS DUE. STATUS UPGRADED TO X ON: 30 NOV 2020 OR 6721.5 AIRCRAFT HOURS REFERENCE: TM 1-1520-237-23_P						ACTION						
						PID	CAT	HRS	PID	CAT	HRS	
ACFT HRS 6327.2		WHEN DISC O	HOW REC O	MAL EFF 1								
DELAY			WUC 00			TIPIID ,			TI MANHOURS			
STATUS X	SYS E	DATE 01 Dec 20	NO 2	TIME 00:00	PID Generated, Com	DATE	TIME	ACFT HRS				
						ROUNDS	ACTION CODE	WUC				
FAULTS/REMARKS INSP E135 AN/ARC-201(V) SINCGARS RADIO HUB BATT REPL FOR HCPTR UTILITY UH-60A CAGE: 78286 PN: UH-60A NSN: 1520010350266 SN: 7923328 WAS DUE. STATUS UPGRADED TO X ON: 30 NOV 2020 REFERENCE: TM 11-5821-333-12						ACTION						
						PID	CAT	HRS	PID	CAT	HRS	
ACFT HRS 6327.2		WHEN DISC O	HOW REC O	MAL EFF 1								
DELAY			WUC 00			TIPIID ,			TI MANHOURS			
STATUS X	SYS E	DATE 01 Dec 20	NO 3	TIME 00:00	PID Generated, Com	DATE	TIME	ACFT HRS				
						ROUNDS	ACTION CODE	WUC				
FAULTS/REMARKS INSP E351 REPLACE APX-118 TRANSPONDER BATTERY FOR HCPTR UTILITY UH-60A CAGE: 78286 PN: UH-60A NSN: 1520010350266 SN: 7923328 WAS DUE. STATUS UPGRADED TO X ON: 30 NOV 2020 REFERENCE: TM 11-5895-1841-13P						ACTION						
						PID	CAT	HRS	PID	CAT	HRS	
ACFT HRS 6327.2		WHEN DISC O	HOW REC O	MAL EFF 1								
DELAY			WUC 00			TIPIID ,			TI MANHOURS			

DA FORM 2408-13-1-SG, OCT 1997

DA FORM 2408-13-1, OCT 91, MAY BE USED

AIRCRAFT INSPECTION AND MAINTENANCE RECORD

For use of this form, see DA PAM 738-751; the proponent agency is DCSLOG

APD PE v3.00

1. AIRCRAFT SERIAL NUMBER 7923328				2. MODEL UH-60A			3. DATE			4. PAGE 16		
PART I - FAULT INFORMATION						PART II - CORRECTING INFORMATION						
STATUS X	SYS A	DATE 02 Dec 20	NO 1	TIME 00:00	PID Generated, Cor	DATE	TIME	ACFT HRS				
FAULTS/REMARKS INSP A496 CF3BR FIRE EXTINGUISHER WEIGHT TEST INSPECTION FOR HCPTTR UTILITY UH-60A CAGE: 78286 PN: UH-60A NSN: 1520010350266 SN: 7923328 WAS DUE. STATUS UPGRADED TO X ON: 01 DEC 2020 REFERENCE: TM 1-1520-237-23&P						ROUNDS	ACTION CODE		WUC			
						ACTION						
ACFT HRS 6327.2			WHEN DISC O	HOW REC O	MAL EFF 1	PID	CAT	HRS	PID	CAT	HRS	
DELAY				WUC 00		TIPIID ,			TI MANHOURS			
STATUS X	SYS E	DATE 04 Dec 20	NO 1	TIME 00:00	PID Generated, Com	DATE	TIME	ACFT HRS				
FAULTS/REMARKS INSP E015 ASN 128D DOPPLER GPS BATTERY REPLACEMENT FOR HCPTTR UTILITY UH-60A CAGE: 78286 PN: UH-60A NSN: 1520010350266 SN: 7923328 WAS DUE. STATUS UPGRADED TO X ON: 03 DEC 2020 REFERENCE: MWO 1-1520-237-50-92						ROUNDS	ACTION CODE		WUC			
						ACTION						
ACFT HRS 6327.2			WHEN DISC O	HOW REC O	MAL EFF 1	PID	CAT	HRS	PID	CAT	HRS	
DELAY				WUC 00		TIPIID ,			TI MANHOURS			
STATUS X	SYS A	DATE 04 Dec 20	NO 1	TIME 00:00	PID Generated, Com	DATE	TIME	ACFT HRS				
FAULTS/REMARKS INSP A160 90 DAY CORROSION INSPECTION FOR HCPTTR UTILITY UH-60A CAGE: 78286 PN: UH-60A NSN: 1520010350266 SN: 7923328 WAS DUE. STATUS UPGRADED TO X ON: 03 DEC 2020 REFERENCE: TM 1-1520-237-23&P						ROUNDS	ACTION CODE		WUC			
						ACTION						
ACFT HRS 6327.2			WHEN DISC O	HOW REC O	MAL EFF 1	PID	CAT	HRS	PID	CAT	HRS	
DELAY				WUC 00		TIPIID ,			TI MANHOURS			

DA FORM 2408-13-1-SG, OCT 1997

DA FORM 2408-13-1, OCT 91, MAY BE USED

AIRCRAFT INSPECTION AND MAINTENANCE RECORD

For use of this form, see DA PAM 738-751; the proponent agency is DCSLOG

APD PE v3.00

1. AIRCRAFT SERIAL NUMBER 7923328				2. MODEL UH-60A			3. DATE			4. PAGE 17		
PART I - FAULT INFORMATION						PART II - CORRECTING INFORMATION						
STATUS X	SYS A	DATE 04 Dec 20	NO 2	TIME 12:45	PID SCHMIDT, NATI	DATE	TIME	ACFT HRS				
FAULTS/REMARKS RMVD M/R BLADE A007-11384 FROM ACFT FOR GROUND TRANSPORT						ROUNDS	ACTION CODE	WUC				
						ACTION						
ACFT HRS 6327.2			WHEN DISC B	HOW REC G	MAL EFF 5	PID	CAT	HRS	PID	CAT	HRS	
DELAY			WUC 05			TIPIID ,			TI MANHOURS			
STATUS X	SYS A	DATE 04 Dec 20	NO 3	TIME 12:54	PID SCHMIDT, NATI	DATE	TIME	ACFT HRS				
FAULTS/REMARKS RMVD M/R BLADE A007-02625 FROM ACFT FOR GROUND TRANSPORT						ROUNDS	ACTION CODE	WUC				
						ACTION						
ACFT HRS 6327.2			WHEN DISC B	HOW REC G	MAL EFF 5	PID	CAT	HRS	PID	CAT	HRS	
DELAY			WUC 05			TIPIID ,			TI MANHOURS			
STATUS X	SYS A	DATE 04 Dec 20	NO 4	TIME 12:58	PID SCHMIDT, NATI	DATE	TIME	ACFT HRS				
FAULTS/REMARKS RMVD M/R BLADE A007-05591 FROM ACFT FOR GROUND TRANSPORT						ROUNDS	ACTION CODE	WUC				
						ACTION						
ACFT HRS 6327.2			WHEN DISC B	HOW REC G	MAL EFF 5	PID	CAT	HRS	PID	CAT	HRS	
DELAY			WUC 05			TIPIID ,			TI MANHOURS			

DA FORM 2408-13-1-SG, OCT 1997

DA FORM 2408-13-1, OCT 91, MAY BE USED

AIRCRAFT INSPECTION AND MAINTENANCE RECORD

For use of this form, see DA PAM 738-751; the proponent agency is DCSLOG

APD PE v3.00

1. AIRCRAFT SERIAL NUMBER 7923328				2. MODEL UH-60A			3. DATE			4. PAGE 18		
PART I - FAULT INFORMATION						PART II - CORRECTING INFORMATION						
STATUS X	SYS E	DATE 05 Dec 20	NO 1	TIME 00:00	PID Generated, Cor	DATE	TIME	ACFT HRS				
FAULTS/REMARKS INSP E356 REPLACE GMR BATTERY (BLUE FORCE TRACKER) FOR HCPT UTILITY UH-60A CAGE: 78286 PN: UH-60A NSN: 1520010350266 SN: 7923328 WAS DUE. STATUS UPGRADED TO X ON: 04 DEC 2020 REFERENCE: MWO 1-1520-237-50-114						ROUNDS	ACTION CODE	WUC				
ACTION												
ACFT HRS 6327.2						WHEN DISC O	HOW REC O	MAL EFF 1				
DELAY						WUC 00			TI MANHOURS			
STATUS X	SYS A	DATE 07 Dec 20	NO 1	TIME 09:27	PID SCHMIDT, NAT-	DATE	TIME	ACFT HRS				
FAULTS/REMARKS Backup Hydraulic Pump made loud grinding noise when ON that could be heard in the cabin. Verified when hydraulic deck was open that the source of the noise was from the backup pump						ROUNDS	ACTION CODE	WUC				
ACTION												
ACFT HRS 6327.2						WHEN DISC K	HOW REC B	MAL EFF 5				
DELAY						WUC 09			TI MANHOURS			
STATUS X	SYS A	DATE 07 Dec 20	NO 2	TIME 09:31	PID SCHMIDT, NAT-	DATE	TIME	ACFT HRS				
FAULTS/REMARKS tail position light is burnt out						ROUNDS	ACTION CODE	WUC				
ACTION												
ACFT HRS 6327.2						WHEN DISC B	HOW REC G	MAL EFF 5				
DELAY						WUC 09			TI MANHOURS			

DA FORM 2408-13-1-SG, OCT 1997

DA FORM 2408-13-1, OCT 91, MAY BE USED

AIRCRAFT INSPECTION AND MAINTENANCE RECORD

For use of this form, see DA PAM 738-751; the proponent agency is DCSLOG

APD PE v3.00

1. AIRCRAFT SERIAL NUMBER 7923328				2. MODEL UH-60A			3. DATE			4. PAGE 19		
PART I - FAULT INFORMATION						PART II - CORRECTING INFORMATION						
STATUS X	SYS A	DATE 07 Dec 20	NO 3	TIME 09:41	PID SCHMIDT, NATI	DATE	TIME	ACFT HRS				
FAULTS/REMARKS #1 fuel boost pump control indicator light will not illuminate when pressed to start pump. Light illuminates when press to test is conducted.						ROUNDS	ACTION CODE	WUC				
						ACTION						
ACFT HRS 6327.2			WHEN DISC K	HOW REC C	MAL EFF 5	PID	CAT	HRS	PID	CAT	HRS	
DELAY				WUC 10		TIPIID ,			TI MANHOURS			
STATUS O	SYS A	DATE 07 Dec 20	NO 4	TIME 12:47	PID SCHMIDT, NATI	DATE	TIME	ACFT HRS				
FAULTS/REMARKS ACFT RESTRICTED FROM NIGHT FLIGHT. CO-PILOT RADAR ALTIMETER DIGITAL READOUT DOES NOT DISPLAY, ANALOG STILL WORKS.						ROUNDS	ACTION CODE	WUC				
						ACTION						
ACFT HRS 6327.2			WHEN DISC G	HOW REC C	MAL EFF 4	PID	CAT	HRS	PID	CAT	HRS	
DELAY				WUC 08		TIPIID ,			TI MANHOURS			
STATUS X	SYS A	DATE 08 Dec 20	NO 2	TIME 07:57	PID SCHMIDT, NATI	DATE	TIME	ACFT HRS				
FAULTS/REMARKS ALL HYD PUMP QD'S DISCONNECTED FOR GROUND TRANSPORT 6EA						ROUNDS	ACTION CODE	WUC				
						ACTION						
ACFT HRS 6327.2			WHEN DISC B	HOW REC G	MAL EFF 5	PID	CAT	HRS	PID	CAT	HRS	
DELAY				WUC 07		TIPIID ,			TI MANHOURS			

DA FORM 2408-13-1-SG, OCT 1997

DA FORM 2408-13-1, OCT 91, MAY BE USED

AIRCRAFT INSPECTION AND MAINTENANCE RECORD

For use of this form, see DA PAM 738-751; the proponent agency is DCSLOG

APD PE v3.00

1. AIRCRAFT SERIAL NUMBER 7923328				2. MODEL UH-60A			3. DATE			4. PAGE 20		
PART I - FAULT INFORMATION						PART II - CORRECTING INFORMATION						
STATUS X	SYS A	DATE 08 Dec 20	NO 6	TIME 14:37	PID MAESTAS, JESU	DATE	TIME	ACFT HRS				
FAULTS/REMARKS ENGINE GEE374385C REQUIRES REMOVAL IAW NGB AND THE BEST PROGRAM.						ACTION						
						PID	CAT	HRS	PID	CAT	HRS	
ACFT HRS 6327.2						WHEN DISC K	HOW REC O	MAL EFF 2				
DELAY						WUC 04A			TI MANHOURS			
STATUS X	SYS E	DATE 09 Dec 20	NO 1	TIME 00:01	PID Generated, Com	DATE	TIME	ACFT HRS				
FAULTS/REMARKS INSP E145 AN/ARC-201A(V) SINGGARS HUB BATT REPL FOR HCPTR UTILITY UH-60A CAGE: 78286 PN: UH-60A NSN: 1520010350266 SN: 7923328 WAS DUE. STATUS UPGRADED TO X ON: 08 DEC 2020 REFERENCE: TM 11-5821-333-12						ACTION						
						PID	CAT	HRS	PID	CAT	HRS	
ACFT HRS 6327.2						WHEN DISC O	HOW REC O	MAL EFF 1				
DELAY						WUC 00			TI MANHOURS			
STATUS /	SYS A	DATE 09 Dec 20	NO 2	TIME 11:00	PID MARQUEZ, GAB	DATE	TIME	ACFT HRS				
FAULTS/REMARKS IVHMS SCREEN SHOWS "DTU COMMS FAIL"						ACTION						
						PID	CAT	HRS	PID	CAT	HRS	
ACFT HRS 6327.2						WHEN DISC K	HOW REC G	MAL EFF 2				
DELAY						WUC 19			TI MANHOURS			

DA FORM 2408-13-1-SG, OCT 1997

DA FORM 2408-13-1, OCT 91, MAY BE USED

AIRCRAFT INSPECTION AND MAINTENANCE RECORD

For use of this form, see DA PAM 738-751; the proponent agency is DCSLOG

APD PE v3.00

1. AIRCRAFT SERIAL NUMBER 7923328				2. MODEL UH-60A			3. DATE			4. PAGE 21		
PART I - FAULT INFORMATION						PART II - CORRECTING INFORMATION						
STATUS X	SYS A	DATE 13 Dec 20	NO 1	TIME 00:01	PID Generated, Cor	DATE	TIME	ACFT HRS				
FAULTS/REMARKS INSP A541 REPLACE DIGITAL CLOCK BATTERY FOR HCPTR UTILITY UH-60A CAGE: 78286 PN: UH-60A NSN: 1520010350266 SN: 7923328 WAS DUE. STATUS UPGRADED TO X ON: 12 DEC 2020 REFERENCE: TM 1-1520-237-23&P						ROUNDS	ACTION CODE	WUC				
						ACTION						
						PID	CAT	HRS	PID	CAT	HRS	
ACFT HRS 6327.2		WHEN DISC O	HOW REC O	MAL EFF 1								
DELAY				WUC 00		TIPIID ,			TI MANHOURS			
STATUS X	SYS A	DATE 13 Dec 20	NO 2	TIME 00:01	PID Generated, Com	DATE	TIME	ACFT HRS				
FAULTS/REMARKS INSP A550 REPLACE IVHMU AA LITHIUM BATTERY FOR HCPTR UTILITY UH-60A CAGE: 78286 PN: UH-60A NSN: 1520010350266 SN: 7923328 WAS DUE. STATUS UPGRADED TO X ON: 12 DEC 2020 REFERENCE: AWR1346R25/AWR1823R6						ROUNDS	ACTION CODE	WUC				
						ACTION						
						PID	CAT	HRS	PID	CAT	HRS	
ACFT HRS 6327.2		WHEN DISC O	HOW REC O	MAL EFF 1								
DELAY				WUC 00		TIPIID ,			TI MANHOURS			
STATUS X	SYS A	DATE 17 Dec 20	NO 1	TIME 00:01	PID Generated, Com	DATE 28 Dec 20	TIME 07:58	ACFT HRS 6327.2				
FAULTS/REMARKS INSP A100 LH/RH ENGINE HISTORY RECORDER READINGS DUE FOR HCPTR UTILITY UH-60A CAGE: 78286 PN: UH-60A NSN: 1520010350266 SN: 7923328 WAS DUE. STATUS UPGRADED TO X ON: 16 DEC 2020 REFERENCE: DA PAM 738-751						ROUNDS	ACTION CODE 3	WUC 00				
						ACTION completed 12/16/20						
						PID	CAT	HRS	PID	CAT	HRS	
						Mirabal, J.	F	0.4				
ACFT HRS 6327.2		WHEN DISC O	HOW REC O	MAL EFF 1								
DELAY				WUC 00		TIPIID ,			TI MANHOURS			

DA FORM 2408-13-1-SG, OCT 1997

DA FORM 2408-13-1, OCT 91, MAY BE USED

AIRCRAFT INSPECTION AND MAINTENANCE RECORD

For use of this form, see DA PAM 738-751; the proponent agency is DCSLOG

APD PE v3.00

1. AIRCRAFT SERIAL NUMBER 7923328				2. MODEL UH-60A			3. DATE			4. PAGE 22				
PART I - FAULT INFORMATION						PART II - CORRECTING INFORMATION								
STATUS X	SYS A	DATE 21 Dec 20	NO 1	TIME 00:01	PID Generated, Cor	DATE	TIME	ACFT HRS						
FAULTS/REMARKS INSP A538 FAT/OAT GAUGE INSPECTION/TEST FOR HCPTR UTILITY UH-60A CAGE: 78286 PN: UH-60A NSN: 1520010350266 SN: 7923328 WAS DUE. STATUS UPGRADED TO X ON: 20 DEC 2020 REFERENCE: TM 1-1520-237-23&P						ROUNDS	ACTION CODE	WUC						
						ACTION								
						PID	CAT	HRS	PID	CAT	HRS	PID	CAT	HRS
ACFT HRS 6327.2	WHEN DISC O	HOW REC O	MAL EFF 1											
DELAY				WUC 00		TIPIID ,			TI MANHOURS					
STATUS X	SYS A	DATE 23 Dec 20	NO 2	TIME 09:50	PID SCHMIDT, NATI-	DATE	TIME	ACFT HRS						
FAULTS/REMARKS AFT PRIMARY SERVO LEAKING AT NIPPLE BELOW THE OUTPUT PISTONS AND IS SAFETIED WITH A DEPOT LEVEL TAGGED SAFETY.						ROUNDS	ACTION CODE	WUC						
						ACTION								
						PID	CAT	HRS	PID	CAT	HRS	PID	CAT	HRS
ACFT HRS 6327.2	WHEN DISC X	HOW REC G	MAL EFF 5											
DELAY				WUC 11		TIPIID ,			TI MANHOURS					
STATUS X	SYS A	DATE 26 Dec 20	NO 1	TIME 00:01	PID Generated, Com	DATE	TIME	ACFT HRS						
FAULTS/REMARKS INSP A501 MAIN ROTOR BLADE SPAR PRESSURE CHECK FOR HCPTR UTILITY UH-60A CAGE: 78286 PN: UH-60A NSN: 1520010350266 SN: 7923328 WAS DUE. STATUS UPGRADED TO X ON: 25 DEC 2020 REFERENCE: TM 1-1520-237-23&P						ROUNDS	ACTION CODE	WUC						
						ACTION								
						PID	CAT	HRS	PID	CAT	HRS	PID	CAT	HRS
ACFT HRS 6327.2	WHEN DISC O	HOW REC O	MAL EFF 1											
DELAY				WUC 00		TIPIID ,			TI MANHOURS					

DA FORM 2408-13-1-SG, OCT 1997

DA FORM 2408-13-1, OCT 91, MAY BE USED

AIRCRAFT INSPECTION AND MAINTENANCE RECORD

For use of this form, see DA PAM 738-751; the proponent agency is DCSLOG

APD PE v3.00

1. AIRCRAFT SERIAL NUMBER 7923328				2. MODEL UH-60A			3. DATE			4. PAGE 23		
PART I - FAULT INFORMATION						PART II - CORRECTING INFORMATION						
STATUS X	SYS A	DATE 28 Dec 20	NO 1	TIME 07:19	PID LAUMBACH, AD	DATE	TIME	ACFT HRS				
FAULTS/REMARKS During FLT control Check, unusual noise heard on co-pilot side when collective was being moved from full up position to full down position. Noise was more pronounced when the pedal trim release switch was pressed during collective movement.						ACTION						
						PID	CAT	HRS	PID	CAT	HRS	
ACFT HRS 6327.2						WHEN DISC B	HOW REC G	MAL EFF 2				
DELAY						WUC 00			TI MANHOURS			
STATUS X	SYS A	DATE 07 Jan 21	NO 1	TIME 14:35	PID SCHMIDT, NATI-	DATE	TIME	ACFT HRS				
FAULTS/REMARKS r/h mlg axle outer journal has a 1/8 " square chip of nickel plating						ACTION						
						PID	CAT	HRS	PID	CAT	HRS	
ACFT HRS 6327.2						WHEN DISC X	HOW REC G	MAL EFF 5				
DELAY						WUC 03			TI MANHOURS			
STATUS X	SYS E	DATE 10 Jan 21	NO 1	TIME 00:01	PID Generated, Com	DATE	TIME	ACFT HRS				
FAULTS/REMARKS INSP E108 KY-58 PMCS/OPNL CHECK (STANDBY) FOR HCPTX UTILITY UH-60A CAGE: 78286 PN: UH-60A NSN: 1520010350266 SN: 7923328 WAS DUE. STATUS UPGRADED TO X ON: 09 JAN 2021 REFERENCE: TM 11-5810-262-23						ACTION						
						PID	CAT	HRS	PID	CAT	HRS	
ACFT HRS 6327.2						WHEN DISC O	HOW REC O	MAL EFF 1				
DELAY						WUC 00			TI MANHOURS			

DA FORM 2408-13-1-SG, OCT 1997

DA FORM 2408-13-1, OCT 91, MAY BE USED

AIRCRAFT INSPECTION AND MAINTENANCE RECORD

For use of this form, see DA PAM 738-751; the proponent agency is DCSLOG

APD PE v3.00

1. AIRCRAFT SERIAL NUMBER 7923328				2. MODEL UH-60A			3. DATE			4. PAGE 24		
PART I - FAULT INFORMATION						PART II - CORRECTING INFORMATION						
STATUS X	SYS E	DATE 10 Jan 21	NO 2	TIME 00:01	PID Generated, Cor	DATE	TIME	ACFT HRS				
FAULTS/REMARKS INSP E822 BLUE FORCE TRACKER POWER ON DUE EVERY 30 DAYS FOR HCPTR UTILITY UH-60A CAGE: 78286 PN: UH-60A NSN: 1520010350266 SN: 7923328 WAS DUE. STATUS UPGRADED TO X ON: 09 JAN 2021 REFERENCE: AWR 1801						ROUNDS	ACTION CODE	WUC				
						ACTION						
ACFT HRS 6327.2			WHEN DISC O	HOW REC O	MAL EFF 1	PID	CAT	HRS	PID	CAT	HRS	
DELAY				WUC 00		TIPIID ,			TI MANHOURS			
STATUS X	SYS A	DATE 12 Jan 21	NO 1	TIME 09:13	PID Generated, Com	DATE	TIME	ACFT HRS				
FAULTS/REMARKS INSP A502 INSPECT AND TEST GROUND RECEPTACLE IAW TM 1-1500-204-23 FOR HCPTR UTILITY UH-60A CAGE: 78286 PN: UH-60A NSN: 1520010350266 SN: 7923328 WAS DUE. STATUS UPGRADED TO X ON: 11 JAN 2021 REFERENCE: TM 1-1520-237-23&P						ROUNDS	ACTION CODE	WUC				
						ACTION						
ACFT HRS 6327.2			WHEN DISC O	HOW REC O	MAL EFF 1	PID	CAT	HRS	PID	CAT	HRS	
DELAY				WUC 00		TIPIID ,			TI MANHOURS			
STATUS /	SYS A	DATE 12 Jan 21	NO 2	TIME 10:29	PID MONAREZ, SAU	DATE	TIME	ACFT HRS				
FAULTS/REMARKS #2 engine inlet shroud fairing cracked						ROUNDS	ACTION CODE	WUC				
						ACTION						
ACFT HRS 6327.2			WHEN DISC B	HOW REC G	MAL EFF 2	PID	CAT	HRS	PID	CAT	HRS	
DELAY				WUC 00		TIPIID ,			TI MANHOURS			

DA FORM 2408-13-1-SG, OCT 1997

DA FORM 2408-13-1, OCT 91, MAY BE USED

AIRCRAFT INSPECTION AND MAINTENANCE RECORD

For use of this form, see DA PAM 738-751; the proponent agency is DCSLOG

APD PE v3.00

1. AIRCRAFT SERIAL NUMBER 7923328				2. MODEL UH-60A			3. DATE			4. PAGE 25		
PART I - FAULT INFORMATION						PART II - CORRECTING INFORMATION						
STATUS ⊙	SYS A	DATE 20 Jan 21	NO 1	TIME 12:39	PID LUNA, GABRIEL	DATE	TIME	ACFT HRS				
FAULTS/REMARKS RESTRICTED FROM IMC DUE TO INOPERABLE GPS CONTROL HEAD						ROUNDS			ACTION CODE			WUC
						ACTION						
ACFT HRS 6327.2			WHEN DISC B	HOW REC G	MAL EFF 4	PID	CAT	HRS	PID	CAT	HRS	
DELAY				WUC 00		TIPIID ,			TI MANHOURS			
STATUS ×	SYS A	DATE 20 Jan 21	NO 2	TIME 12:54	PID LAUMBACH, AD	DATE	TIME	ACFT HRS				
FAULTS/REMARKS swap of #1 engine air inlet from afct 79-3328 to 83-23918 required for unit readiness						ROUNDS			ACTION CODE			WUC
						ACTION						
ACFT HRS 6327.2			WHEN DISC O	HOW REC G	MAL EFF 2	PID	CAT	HRS	PID	CAT	HRS	
DELAY				WUC 00		TIPIID ,			TI MANHOURS			
STATUS /	SYS E	DATE 27 Jan 21	NO 1	TIME 16:38	PID LUNA, GABRIEL	DATE	TIME	ACFT HRS				
FAULTS/REMARKS Ky-58 FM.1 fill cable not installed						ROUNDS			ACTION CODE			WUC
						ACTION						
ACFT HRS 6327.2			WHEN DISC B	HOW REC G	MAL EFF 4	PID	CAT	HRS	PID	CAT	HRS	
DELAY				WUC 00		TIPIID ,			TI MANHOURS			

DA FORM 2408-13-1-SG, OCT 1997

DA FORM 2408-13-1, OCT 91, MAY BE USED

AIRCRAFT INSPECTION AND MAINTENANCE RECORD

For use of this form, see DA PAM 738-751; the proponent agency is DCSLOG

APD PE v3.00

1. AIRCRAFT SERIAL NUMBER 7923328				2. MODEL UH-60A			3. DATE			4. PAGE 26		
PART I - FAULT INFORMATION						PART II - CORRECTING INFORMATION						
STATUS —	SYS A	DATE 28 Jan 21	NO 1	TIME 00:00	PID Generated, Cor	DATE	TIME	ACFT HRS	ROUNDS	ACTION CODE	WUC	
FAULTS/REMARKS INSP A532 COMPASS SWING / RMI FOR HCPTX UTILITY UH-60A CAGE: 78286 PN: UH-60A NSN: 1520010350266 SN: 7923328 IS DUE. STATUS WILL UPGRADE TO X ON: 29 MAR 2021 REFERENCE: TM 1-1500-204-23-4						ACTION						
						PID	CAT	HRS	PID	CAT	HRS	PID
ACFT HRS 6327.2	WHEN DISC O	HOW REC O	MAL EFF 1									
DELAY				WUC 00		TIPIID ,			TI MANHOURS			
STATUS X	SYS A	DATE 29 Jan 21	NO 1	TIME 08:51	PID OLSON, MICHA	DATE	TIME	ACFT HRS	ROUNDS	ACTION CODE	WUC	
FAULTS/REMARKS #2 side crew seat, forward hanger broken.						ACTION						
						PID	CAT	HRS	PID	CAT	HRS	PID
ACFT HRS 6327.2	WHEN DISC O	HOW REC G	MAL EFF 2									
DELAY				WUC 02		TIPIID ,			TI MANHOURS			
STATUS X	SYS A	DATE 07 Feb 21	NO 1	TIME 00:01	PID Generated, Com	DATE	TIME	ACFT HRS	ROUNDS	ACTION CODE	WUC	
FAULTS/REMARKS INSP A553 AIRCRAFT WEIGHING INVENTORY (365-1) FOR HCPTX UTILITY UH-60A CAGE: 78286 PN: UH-60A NSN: 1520010350266 SN: 7923328 WAS DUE. STATUS UPGRADED TO X ON: 06 FEB 2021 REFERENCE: AR 95-1						ACTION						
						PID	CAT	HRS	PID	CAT	HRS	PID
ACFT HRS 6327.2	WHEN DISC O	HOW REC O	MAL EFF 1									
DELAY				WUC 00		TIPIID ,			TI MANHOURS			

DA FORM 2408-13-1-SG, OCT 1997

DA FORM 2408-13-1, OCT 91, MAY BE USED

AIRCRAFT INSPECTION AND MAINTENANCE RECORD

For use of this form, see DA PAM 738-751; the proponent agency is DCSLOG

APD PE v3.00

1. AIRCRAFT SERIAL NUMBER 7923328				2. MODEL UH-60A			3. DATE			4. PAGE 27		
PART I - FAULT INFORMATION						PART II - CORRECTING INFORMATION						
STATUS X	SYS E	DATE 12 Feb 21	NO 1	TIME 00:00	PID Generated, Cor	DATE	TIME	ACFT HRS	ROUNDS	ACTION CODE	WUC	
FAULTS/REMARKS INSP E155 KY-58 BATTERY REPLACEMENT FOR HCPTR UTILITY UH-60A CAGE: 78286 PN: UH-60A NSN: 1520010350266 SN: 7923328 WAS DUE. STATUS UPGRADED TO X ON: 11 FEB 2021 REFERENCE: TM 11-5810-262-23						ACTION						
ACFT HRS 6327.2						WHEN DISC O	HOW REC O	MAL EFF 1				
DELAY						WUC 00			TIPIID ,			TI MANHOURS
STATUS X	SYS E	DATE 19 Feb 21	NO 1	TIME 00:01	PID Generated, Com	DATE	TIME	ACFT HRS	ROUNDS	ACTION CODE	WUC	
FAULTS/REMARKS INSP E222 EMERGENCY LOCATOR TRANSMITTER (ELT) REGISTRATION UPDATE FOR HCPTR UTILITY UH-60A CAGE: 78286 PN: UH-60A NSN: 1520010350266 SN: 7923328 WAS DUE. STATUS UPGRADED TO X ON: 18 FEB 2021 REFERENCE: GEN-16-AMAM-05						ACTION						
ACFT HRS 6327.2						WHEN DISC O	HOW REC O	MAL EFF 1				
DELAY						WUC 00			TIPIID ,			TI MANHOURS
STATUS X	SYS A	DATE 25 Feb 21	NO 1	TIME 07:22	PID SCHMIDT, NAT-	DATE	TIME	ACFT HRS	ROUNDS	ACTION CODE	WUC	
FAULTS/REMARKS Ground transport configuration "In Process"						ACTION						
ACFT HRS 6327.2						WHEN DISC K	HOW REC O	MAL EFF 1				
DELAY						WUC 02			TIPIID ,			TI MANHOURS

DA FORM 2408-13-1-SG, OCT 1997

DA FORM 2408-13-1, OCT 91, MAY BE USED

AIRCRAFT INSPECTION AND MAINTENANCE RECORD

For use of this form, see DA PAM 738-751; the proponent agency is DCSLOG

APD PE v3.00

1. AIRCRAFT SERIAL NUMBER 7923328				2. MODEL UH-60A			3. DATE			4. PAGE 28		
PART I - FAULT INFORMATION						PART II - CORRECTING INFORMATION						
STATUS X	SYS A	DATE 18 Mar 21	NO 1	TIME 13:21	PID BROWN, MICHA	DATE	TIME	ACFT HRS				
						ROUNDS	ACTION CODE	WUC				
FAULTS/REMARKS AIRCRAFT INDUCTED INTO BEST PROGRAM ON 18 MARCH 2021, NO SCHEDULED MAINTENANCE PERFORMED AFTER THIS DATE.						ACTION						
						PID	CAT	HRS	PID	CAT	HRS	
ACFT HRS 6327.2		WHEN DISC E	HOW REC G	MAL EFF 2								
DELAY			WUC 02			TIPIID ,			TI MANHOURS			
STATUS ⊗	SYS A	DATE 18 Mar 21	NO 2	TIME 13:22	PID BROWN, MICHA	DATE	TIME	ACFT HRS				
						ROUNDS	ACTION CODE	WUC				
FAULTS/REMARKS REMARK/NOTICE TO BUYER: PRIOR TO DELIVERY OF THE AIRCRAFT TO THE BUYER THE FOLLOWING ITEMS WILL BE REMOVED FROM THE AIRCRAFT AT THE DIRECTION OF THE US GOVERNMENT; TO INCLUDE BUT NOT LIMITED TO: CMWS JUNCTION BOX; SA-26669/ALE-47 (V) CMWS SEQUENCER; SENSOR ELECTRO-OPTIC MISSILE CM-SU-202/AAR-57 (V); DIGITAL COCKPIT DISPLAY UNIT (CMWS); SAFE/ARM CONTROL PANEL (CMWS); CMWS RELAY BOX; MEMORY CARD PMCIA (UDM) MU-1126/AAR-57(V) (CMWS); RECEIVER/TRANSMITTER, RT-1477/ARC-201; CONTROL, C-11466A/ARC-201; KY-58(3EA); KY-58 CONTROL HEAD (3EA); KY-100 AIRTERM; ARC-220/						ACTION						
						PID	CAT	HRS	PID	CAT	HRS	
ACFT HRS 6327.2		WHEN DISC E	HOW REC G	MAL EFF 2								
DELAY			WUC 02			TIPIID ,			TI MANHOURS			
STATUS X	SYS A	DATE 19 Mar 21	NO 1	TIME 00:00	PID Generated, Com	DATE	TIME	ACFT HRS				
						ROUNDS	ACTION CODE	WUC				
FAULTS/REMARKS INSP A533 PITOT STATIC SYSTEM INSPECTION FOR HCPTTR UTILITY UH-60A CAGE: 78286 PN: UH-60A NSN: 1520010350266 SN: 7923328 WAS DUE. STATUS UPGRADED TO X ON: 12 MAR 2021 REFERENCE: TM 1-1520-237-23P						ACTION						
						PID	CAT	HRS	PID	CAT	HRS	
ACFT HRS 6327.2		WHEN DISC O	HOW REC O	MAL EFF 1								
DELAY			WUC 00			TIPIID ,			TI MANHOURS			

DA FORM 2408-13-1-SG, OCT 1997

DA FORM 2408-13-1, OCT 91, MAY BE USED

AIRCRAFT INSPECTION AND MAINTENANCE RECORD

For use of this form, see DA PAM 738-751; the proponent agency is DCSLOG

APD PE v3.00

1. AIRCRAFT SERIAL NUMBER 7923328				2. MODEL UH-60A			3. DATE			4. PAGE 29		
PART I - FAULT INFORMATION						PART II - CORRECTING INFORMATION						
STATUS —	SYS A	DATE 19 Mar 21	NO 2	TIME 00:00	PID Generated, Cor	DATE	TIME	ACFT HRS				
FAULTS/REMARKS INSP A534 FIRST AID KIT INSPECTION FOR HCPTR UTILITY UH-60A CAGE: 78286 PN: UH-60A NSN: 1520010350266 SN: 7923328 IS DUE. STATUS WILL UPGRADE TO X ON: 14 APR 2021 REFERENCE: TM 1-1500-204-23-1						ACTION						
ACFT HRS 6327.2						WHEN DISC O	HOW REC O	MAL EFF 1				
DELAY						WUC 00			TI MANHOURS			
STATUS ×	SYS A	DATE 22 Mar 21	NO 1	TIME 12:17	PID CRABB, ARLANA	DATE	TIME	ACFT HRS				
FAULTS/REMARKS AIRCRAFT DEPANELED FOR INDUCTION INTO BEST STORAGE PER CUSTOMER REQUEST. USED TM 1-1520-237-23&P, BEST SOW AND SES GOP AS A REFERENCE.						ACTION						
ACFT HRS 6327.2						WHEN DISC E	HOW REC G	MAL EFF 1				
DELAY						WUC 00			TI MANHOURS			
STATUS ×	SYS A	DATE 22 Mar 21	NO 2	TIME 12:19	PID CRABB, ARLANA	DATE	TIME	ACFT HRS				
FAULTS/REMARKS REMOVED COMMON MISSILE WARNING SYSTEM JUNCTION BOX (SN 01009) PER CUSTOMER REQUEST. USED TM 1-1520-237-23&P WP 1915 AS A REFERENCE.						ACTION						
ACFT HRS 6327.2						WHEN DISC E	HOW REC G	MAL EFF 1				
DELAY						WUC 00			TI MANHOURS			

DA FORM 2408-13-1-SG, OCT 1997

DA FORM 2408-13-1, OCT 91, MAY BE USED

AIRCRAFT INSPECTION AND MAINTENANCE RECORD

For use of this form, see DA PAM 738-751; the proponent agency is DCSLOG

APD PE v3.00

1. AIRCRAFT SERIAL NUMBER 7923328				2. MODEL UH-60A			3. DATE			4. PAGE 30		
PART I - FAULT INFORMATION						PART II - CORRECTING INFORMATION						
STATUS X	SYS A	DATE 22 Mar 21	NO 3	TIME 12:26	PID CRABB, ARLAN	DATE	TIME	ACFT HRS				
FAULTS/REMARKS REMOVED COMMON MISSILE WARNING SYSTEM SAFE/ARM CONTROL PANEL (SN 1050) PER CUSTOMER REQUEST. USED TM 1-1520-237-23&P WP 1911 AS A REFERENCE.						ROUNDS	ACTION CODE	WUC				
						ACTION						
ACFT HRS 6327.2			WHEN DISC E	HOW REC G	MAL EFF 1	PID	CAT	HRS	PID	CAT	HRS	
DELAY			WUC 00			TI MANHOURS						
STATUS X	SYS A	DATE 22 Mar 21	NO 4	TIME 12:29	PID CRABB, ARLAN	DATE	TIME	ACFT HRS				
FAULTS/REMARKS REMOVEVD COMMON MISSILE WARNING SYSTEM SAFETY SWITCH (SN 22830-0810) PER CUSTOMER REQUEST. USED TM 1-1520-237-23&P WP 1917 AS A REFERENCE.						ROUNDS	ACTION CODE	WUC				
						ACTION						
ACFT HRS 6327.2			WHEN DISC E	HOW REC G	MAL EFF 1	PID	CAT	HRS	PID	CAT	HRS	
DELAY			WUC 00			TI MANHOURS						
STATUS X	SYS A	DATE 22 Mar 21	NO 5	TIME 12:35	PID CRABB, ARLAN	DATE	TIME	ACFT HRS				
FAULTS/REMARKS REMOVED COMMON MISSILE WARNING SYSTEM RELAY BOX (SN 01009) PER CUSTOMER REQUEST. USED TM 1-1520-237-23&P WP 1913 AS A REFERENCE.						ROUNDS	ACTION CODE	WUC				
						ACTION						
ACFT HRS 6327.2			WHEN DISC E	HOW REC G	MAL EFF 1	PID	CAT	HRS	PID	CAT	HRS	
DELAY			WUC 00			TI MANHOURS						

DA FORM 2408-13-1-SG, OCT 1997

DA FORM 2408-13-1, OCT 91, MAY BE USED

AIRCRAFT INSPECTION AND MAINTENANCE RECORD

For use of this form, see DA PAM 738-751; the proponent agency is DCSLOG

APD PE v3.00

1. AIRCRAFT SERIAL NUMBER 7923328				2. MODEL UH-60A			3. DATE			4. PAGE 31		
PART I - FAULT INFORMATION						PART II - CORRECTING INFORMATION						
STATUS X	SYS A	DATE 22 Mar 21	NO 6	TIME 12:36	PID CRABB, ARLAN	DATE	TIME	ACFT HRS				
FAULTS/REMARKS REMOVED ARC-201 SINGARS RADIO FM 1&2 RADIO FREQUENCY AMPLIFIER (SN 1471BB) PER CUSTOMER REQUEST. USED TM 1-1520-237-23&P WP 4225 AS A REFERENCE.						ROUNDS	ACTION CODE	WUC				
						ACTION						
						PID	CAT	HRS	PID	CAT	HRS	
ACFT HRS 6327.2		WHEN DISC E	HOW REC G	MAL EFF 1								
DELAY				WUC 00		TIPIID ,			TI MANHOURS			
STATUS X	SYS A	DATE 22 Mar 21	NO 7	TIME 12:51	PID CRABB, ARLAN	DATE	TIME	ACFT HRS				
FAULTS/REMARKS REMOVED CARGO HOOK SQUIB (SN 0306) PER CUSTOMER REQUEST. USED TM 1-1520-237-23&P WP 1504 AS A REFERENCE.						ROUNDS	ACTION CODE	WUC				
						ACTION						
						PID	CAT	HRS	PID	CAT	HRS	
ACFT HRS 6327.2		WHEN DISC E	HOW REC G	MAL EFF 1								
DELAY				WUC 00		TIPIID ,			TI MANHOURS			
STATUS X	SYS A	DATE 22 Mar 21	NO 8	TIME 12:52	PID CRABB, ARLAN	DATE	TIME	ACFT HRS				
FAULTS/REMARKS REMOVED APX TRANSPONDER B-KIT TRANSMITTER CONTROL (SN 2810) PER CUSTOMER REQUEST. USED TM 1-1520-237-23&P WP 4337 AS A REFERENCE.						ROUNDS	ACTION CODE	WUC				
						ACTION						
						PID	CAT	HRS	PID	CAT	HRS	
ACFT HRS 6327.2		WHEN DISC E	HOW REC G	MAL EFF 1								
DELAY				WUC 00		TIPIID ,			TI MANHOURS			

DA FORM 2408-13-1-SG, OCT 1997

DA FORM 2408-13-1, OCT 91, MAY BE USED

AIRCRAFT INSPECTION AND MAINTENANCE RECORD

For use of this form, see DA PAM 738-751; the proponent agency is DCSLOG

APD PE v3.00

1. AIRCRAFT SERIAL NUMBER 7923328				2. MODEL UH-60A			3. DATE			4. PAGE 32		
PART I - FAULT INFORMATION						PART II - CORRECTING INFORMATION						
STATUS X	SYS A	DATE 22 Mar 21	NO 9	TIME 13:01	PID CRABB, ARLAN	DATE	TIME	ACFT HRS	ROUNDS	ACTION CODE	WUC	
FAULTS/REMARKS REMOVED APS TRANSPONDER B-KIT RECIEVER-TRANSMITTER 118 (SN 3703) PER CUSTOMER REQUEST. USED TM 1-1520-237-23&P WP 4338 AS A REFERENCE.						ACTION						
												PID
ACFT HRS 6327.2		WHEN DISC E	HOW REC G	MAL EFF 1								
DELAY				WUC 00		TIPIID ,			TI MANHOURS			
STATUS X	SYS A	DATE 22 Mar 21	NO 10	TIME 13:03	PID CRABB, ARLANA	DATE	TIME	ACFT HRS	ROUNDS	ACTION CODE	WUC	
FAULTS/REMARKS REMOVED UHF RDO-XMITER RT-1518C (SN M01983) PER CUSTOMER REQUEST. USED TM 1-1520-237-23&P WP 4189 AS A REFERENCE.						ACTION						
												PID
ACFT HRS 6327.2		WHEN DISC E	HOW REC G	MAL EFF 1								
DELAY				WUC 00		TIPIID ,			TI MANHOURS			
STATUS X	SYS A	DATE 22 Mar 21	NO 11	TIME 13:04	PID CRABB, ARLANA	DATE	TIME	ACFT HRS	ROUNDS	ACTION CODE	WUC	
FAULTS/REMARKS REMOVED DOPPLER SDC ASN-128 (SN 2744) PER CUSTOMER REQUEST. USED TM 1-1520-237-23&P WP 4079 AS A REFERENCE.						ACTION						
												PID
ACFT HRS 6327.2		WHEN DISC E	HOW REC G	MAL EFF 1								
DELAY				WUC 00		TIPIID ,			TI MANHOURS			

DA FORM 2408-13-1-SG, OCT 1997

DA FORM 2408-13-1, OCT 91, MAY BE USED

AIRCRAFT INSPECTION AND MAINTENANCE RECORD

For use of this form, see DA PAM 738-751; the proponent agency is DCSLOG

APD PE v3.00

1. AIRCRAFT SERIAL NUMBER 7923328				2. MODEL UH-60A			3. DATE			4. PAGE 33							
PART I - FAULT INFORMATION						PART II - CORRECTING INFORMATION											
STATUS X		SYS A	DATE 22 Mar 21		NO 12	TIME 13:05		PID CRABB, ARLAN/			DATE		TIME		ACFT HRS		
FAULTS/REMARKS REMOVED DOPPLER CDU ASN-128 (SN 1576) PER CUSTOMER REQUEST. USED TM 1-1520-237-23&P WP 4073 AS A REFERENCE.						ACTION						ROUNDS		ACTION CODE		WUC	
ACFT HRS 6327.2		WHEN DISC E		HOW REC G		MAL EFF 1											
DELAY						WUC 00						TIPIID ,		TI MANHOURS			
STATUS X		SYS A	DATE 23 Mar 21		NO 1	TIME 07:07		PID Generated, Com			DATE		TIME		ACFT HRS		
FAULTS/REMARKS INSP A211 APU OIL SAMPLE FOR AUXILIARY POWER UNIT CAGE: 55820 PN: 116305-302 NSN: 2835013692818 SN: 836267 WAS DUE. STATUS UPGRADED TO X ON: 22 MAR 2021 OR 6679.8 AIRCRAFT HOURS REFERENCE: H-60-10-AMAM-11						ACTION						ROUNDS		ACTION CODE		WUC	
ACFT HRS 6327.2		WHEN DISC O		HOW REC O		MAL EFF 1											
DELAY						WUC 00						TIPIID ,		TI MANHOURS			
STATUS X		SYS A	DATE 23 Mar 21		NO 2	TIME 07:07		PID Generated, Com			DATE		TIME		ACFT HRS		
FAULTS/REMARKS INSP A117 TAIL GEARBOX OIL SAMPLE FOR TAIL ROTOR GEARBOX ASSY CAGE: 78286 PN: 70358-06600-046 NSN: 1615013765089 SN: A00602507 WAS DUE. STATUS UPGRADED TO X ON: 6679.8 AIRCRAFT HOURS OR 22 MAR 2021 REFERENCE: H-60-10-AMAM-11						ACTION						ROUNDS		ACTION CODE		WUC	
ACFT HRS 6327.2		WHEN DISC O		HOW REC O		MAL EFF 1											
DELAY						WUC 00						TIPIID ,		TI MANHOURS			

DA FORM 2408-13-1-SG, OCT 1997

DA FORM 2408-13-1, OCT 91, MAY BE USED

AIRCRAFT INSPECTION AND MAINTENANCE RECORD

For use of this form, see DA PAM 738-751; the proponent agency is DCSLOG

APD PE v3.00

1. AIRCRAFT SERIAL NUMBER 7923328				2. MODEL UH-60A			3. DATE			4. PAGE 34				
PART I - FAULT INFORMATION						PART II - CORRECTING INFORMATION								
STATUS X	SYS A	DATE 23 Mar 21	NO 3	TIME 07:07	PID Generated, Cor	DATE	TIME	ACFT HRS						
FAULTS/REMARKS INSP A116 INTERMEDIATE GEARBOX OIL SAMPLE FOR INTERMEDIATE GEARBOX CAGE: 78286 PN: 70357-06300-042 NSN: 1680010745152 SN: A00500228 WAS DUE. STATUS UPGRADED TO X ON: 22 MAR 2021 OR 6679.8 AIRCRAFT HOURS REFERENCE: H-60-10-AMAM-11						ROUNDS	ACTION CODE	WUC						
						ACTION								
						PID	CAT	HRS	PID	CAT	HRS	PID	CAT	HRS
ACFT HRS 6327.2		WHEN DISC O	HOW REC O	MAL EFF 1										
DELAY			WUC 00			TIPIID ,			TI MANHOURS					
STATUS X	SYS A	DATE 23 Mar 21	NO 4	TIME 07:07	PID CRABB, ARLANA	DATE	TIME	ACFT HRS						
FAULTS/REMARKS REMOVED DOPPLER RT/ANTENNA ASN-128 (SN 30930) PER CUSTOMER REQUEST. USED TM 1-1520-237-23&P WP 4076 AS A REFERENCE.						ROUNDS	ACTION CODE	WUC						
						ACTION								
						PID	CAT	HRS	PID	CAT	HRS	PID	CAT	HRS
ACFT HRS 6327.2		WHEN DISC E	HOW REC G	MAL EFF 1										
DELAY			WUC 00			TIPIID ,			TI MANHOURS					
STATUS X	SYS A	DATE 23 Mar 21	NO 5	TIME 07:10	PID CRABB, ARLANA	DATE	TIME	ACFT HRS						
FAULTS/REMARKS REMOVED RESCUE HOIST CONTROL (SN 83MEE-17-4QTAO) PER CUSTOMER REQUEST. USED TM 1-1520-237-23&P WP 1583 AS A REFERENCE						ROUNDS	ACTION CODE	WUC						
						ACTION								
						PID	CAT	HRS	PID	CAT	HRS	PID	CAT	HRS
ACFT HRS 6327.2		WHEN DISC E	HOW REC G	MAL EFF 1										
DELAY			WUC 00			TIPIID ,			TI MANHOURS					

DA FORM 2408-13-1-SG, OCT 1997

DA FORM 2408-13-1, OCT 91, MAY BE USED

AIRCRAFT INSPECTION AND MAINTENANCE RECORD

For use of this form, see DA PAM 738-751; the proponent agency is DCSLOG

APD PE v3.00

1. AIRCRAFT SERIAL NUMBER 7923328				2. MODEL UH-60A			3. DATE			4. PAGE 35		
PART I - FAULT INFORMATION						PART II - CORRECTING INFORMATION						
STATUS X	SYS A	DATE 23 Mar 21	NO 6	TIME 07:16	PID CRABB, ARLAN	DATE	TIME	ACFT HRS				
FAULTS/REMARKS REMOVED VIBRATION ANALYSIS AND CONTROL SYSTEM INTERGRATED VEHILCE HEALTH MANAGEMENT UNIT (SN 00921) PER CUSTOMER REQUEST. USED TM 1-1520-237-23&P WP 1969 AS A REFERENCE						ROUNDS	ACTION CODE	WUC				
ACTION												
						PID	CAT	HRS	PID	CAT	HRS	
ACFT HRS 6327.2		WHEN DISC E	HOW REC G	MAL EFF 1								
DELAY			WUC 00			TIPIID ,			TI MANHOURS			
STATUS X	SYS A	DATE 23 Mar 21	NO 7	TIME 07:22	PID CRABB, ARLANA	DATE	TIME	ACFT HRS				
FAULTS/REMARKS REMOVED BFT PALLET ASSY (SN 318) PER CUSTOMER REQUEST. USED UH60A/L BFT GPS MESSAGE ROUTER AS A REFERENCE.						ROUNDS	ACTION CODE	WUC				
ACTION												
						PID	CAT	HRS	PID	CAT	HRS	
ACFT HRS 6327.2		WHEN DISC E	HOW REC G	MAL EFF 1								
DELAY			WUC 00			TIPIID ,			TI MANHOURS			
STATUS X	SYS A	DATE 23 Mar 21	NO 8	TIME 07:25	PID CRABB, ARLANA	DATE	TIME	ACFT HRS				
FAULTS/REMARKS REMOVED VIBRATION ANALYSIS AND CONTROL SYSTEM MEMORY UNIT, DATA STORAGE DTU (SN 10011527) PER CUSTOMER REQUEST. USED TM 1-1520-237-23&P WP 1972 AS A REFERENCE.						ROUNDS	ACTION CODE	WUC				
ACTION												
						PID	CAT	HRS	PID	CAT	HRS	
ACFT HRS 6327.2		WHEN DISC E	HOW REC G	MAL EFF 1								
DELAY			WUC 00			TIPIID ,			TI MANHOURS			

DA FORM 2408-13-1-SG, OCT 1997

DA FORM 2408-13-1, OCT 91, MAY BE USED

AIRCRAFT INSPECTION AND MAINTENANCE RECORD

For use of this form, see DA PAM 738-751; the proponent agency is DCSLOG

APD PE v3.00

1. AIRCRAFT SERIAL NUMBER 7923328				2. MODEL UH-60A			3. DATE			4. PAGE 36		
PART I - FAULT INFORMATION						PART II - CORRECTING INFORMATION						
STATUS X	SYS A	DATE 23 Mar 21	NO 9	TIME 07:28	PID CRABB, ARLAN/	DATE	TIME	ACFT HRS				
FAULTS/REMARKS REMOVED VIBRATION ANALYSIS AND CONTROL SYSTEM REMOTE DATA CONCENTRATOR (SN 1595) PER CUSTOMER REQUEST. USED TM 1-1520-237-23&P WP 2015 AS A REFERENCE.						ROUNDS	ACTION CODE	WUC				
						ACTION						
						PID	CAT	HRS	PID	CAT	HRS	
ACFT HRS 6327.2		WHEN DISC E	HOW REC G	MAL EFF 1								
DELAY			WUC 00			TIPIID ,			TI MANHOURS			
STATUS —	SYS A	DATE 23 Mar 21	NO 10	TIME 08:44	PID BROWN, MICHA	DATE	TIME	ACFT HRS				
FAULTS/REMARKS DURING THE BEST PROGRAM INDUCTION PROCESS, THE FOLLOWING COMPONENTS WERE UNABLE TO HAVE THE S/N'S VERIFIED. ALL OF THESE COMPONENTS HAVE BEEN S/N MATCHED AGAINST MCDS AND THE RECORDS MATCH BETWEEN ACN AND MCDS. THESE COMPONENTS REQUIRE S/N VERIFICATION AT THE NEXT MAJOR MAINT EVENT: ACCESSORY MODULE P/N 70351-08080-043, S/N A258-00331; AFT TIE ROD SUPPORT FITTING P/N 70400-08112-045, S/N A391-01777; RIGHT TIE ROD ASSY P/N 70400-08165-043, S/N D36611901						ROUNDS	ACTION CODE	WUC				
						ACTION						
						PID	CAT	HRS	PID	CAT	HRS	
ACFT HRS 6327.2		WHEN DISC E	HOW REC G	MAL EFF 2								
DELAY			WUC 02			TIPIID ,			TI MANHOURS			
STATUS —	SYS A	DATE 23 Mar 21	NO 12	TIME 13:49	PID BROWN, MICHA	DATE	TIME	ACFT HRS				
FAULTS/REMARKS COMPLY WITH H-60-21-AMAM-01 MAIN LANDING GEAR DRAG BEAM INSP'S NT 6 JUL 21						ROUNDS	ACTION CODE	WUC				
						ACTION						
						PID	CAT	HRS	PID	CAT	HRS	
ACFT HRS 6327.2		WHEN DISC E	HOW REC G	MAL EFF 2								
DELAY			WUC 02B08C			TIPIID ,			TI MANHOURS			

DA FORM 2408-13-1-SG, OCT 1997

DA FORM 2408-13-1, OCT 91, MAY BE USED

AIRCRAFT INSPECTION AND MAINTENANCE RECORD


For use of this form, see DA PAM 738-751; the proponent agency is DCSLOG

APD PE v3.00

1. STATUS ×	2. SERIAL NUMBER 7923328	3. SYSTEM CODE A	4. TIME 07:22		
5. FAULT DATE 16 Sep 20		6. FAULT NUMBER 1			
7. FAULT T/R servo pushrod tri pivot free spinning bolt and bushing and possibly push rod are elongated. radial play beyond limits					
8. STA	9. RELATED MAINTENANCE ACTIONS	10. ACTION	11. PID	12. CAT	13. MMH
×	rmvd 2ea tri-pivot 3/8 bolt, washers and bushing stackups from quadrant end flt control push rod				
×	rmvd 2ea tri-pivot 3/8 bolt, washers and bushing stackups from servo end flt control push rod				
×	rmvd 1ea tri-pivot 7/16 bolt, washers stackups from quadrant end flt control push rod				
×	rmvd 1ea tri-pivot 7/16 bolt, washers stackups from servo end flt control push rod				
×	rmvd t/r push rod				
×	fod check due				
—	toolbox inventory due				

DA FORM 2408-13-2-SG, OCT 97
 DA FORM 2408-13-2, NOV 91, MAY BE USED

RELATED MAINTENANCE ACTIONS RECORD
 For use of this form see DA PAM 738-751, the proponent agency is DCSLOG

1. STATUS ×	2. SERIAL NUMBER 7923328	3. SYSTEM CODE A	4. TIME 07:31		
	5. FAULT DATE 17 Sep 20	6. FAULT NUMBER 1			
7. FAULT Pilot Side door handle spun freely while door was locked. When PI tried to open door, handle came off. Door had to be jettisoned to release pilot.					
8. STA	9. RELATED MAINTENANCE ACTIONS	10. ACTION	11. PID	12. CAT	13. MMH
×	rmvd (3 ea) qd pins from door hinges and anti swing	reinstalled (3 ea)	ESCALANTE,	F	0.1
×	rmvd door from acft	replaced with control echange door from acft 88-26055	ESCALANTE,	F	0.2
×	Broke tq on upper and lower door hinge jam nuts 2 ea for door adjustment	re-tightened 2 ea	ESCALANTE,	F	0.2
×	Loosened upper and lower door catches	adjusted and tightened	ESCALANTE,	F	0.1
×	fod check due	completed	ESCALANTE,	F	0.1
— 	toolbox inventory due	completed	ESCALANTE,	F	0.1

DA FORM 2408-13-2-SG, OCT 97
 DA FORM 2408-13-2, NOV 91, MAY BE USED

RELATED MAINTENANCE ACTIONS RECORD
 For use of this form see DA PAM 738-751, the proponent agency is DCSLOG

1. STATUS X	2. SERIAL NUMBER 7923328	3. SYSTEM CODE A	4. TIME 11:50		
5. FAULT DATE 17 Sep 20		6. FAULT NUMBER 2			
7. FAULT ace inspection in progress					
8. STA	9. RELATED MAINTENANCE ACTIONS	10. ACTION	11. PID	12. CAT	13. MMH
X	rmvd trans drip pan.				
X	rmvd lower hinged sound proofing.				
X	rmvd left aft bulkhead sound proofing.				
X	rmvd right aft bulkhead sound proofing.				
X	rmvd LH forward hinged sound proofing.				
X	rmvd RH forward hinged sound proofing.				
X	rmvd LH crew seat.				
X	rmvd RH crew seat.				

DA FORM 2408-13-2-SG, OCT 97
 DA FORM 2408-13-2, NOV 91, MAY BE USED

RELATED MAINTENANCE ACTIONS RECORD
 For use of this form see DA PAM 738-751, the proponent agency is DCSLOG

1. STATUS X	2. SERIAL NUMBER 7923328	3. SYSTEM CODE A	4. TIME 15:15		
5. FAULT DATE 14 Oct 20		6. FAULT NUMBER 1			
7. FAULT left and right foward air duct behind pilots and copilots seat rmvd by request of NGB CW4 Matt Ingmire					
8. STA	9. RELATED MAINTENANCE ACTIONS	10. ACTION	11. PID	12. CAT	13. MMH
X	lowered MO side upper sound proofing				
X	lowered CE side upper sound proofing				
X	lowered MO side broom closet				
X	lowered CE side broom closet				
X	rmvd hdwr securing MO side pilot vent tubing fwd of flt control rods				
X	rmvd hdwr securing CE side pilot vent tubing fwd of flt control rods				
X	rmvd CE side pilot vent tubing fwd of flt control rods				
X	rmvd MO side pilot vent tubing fwd of flt control rods				

DA FORM 2408-13-2-SG, OCT 97
 DA FORM 2408-13-2, NOV 91, MAY BE USED

RELATED MAINTENANCE ACTIONS RECORD
 For use of this form see DA PAM 738-751, the proponent agency is DCSLOG

1. STATUS X	2. SERIAL NUMBER 7923328	3. SYSTEM CODE A	4. TIME 15:28		
5. FAULT DATE 28 Oct 20		6. FAULT NUMBER 2			
7. FAULT RMVD TAIL ROTOR BLADES.					
8. STA	9. RELATED MAINTENANCE ACTIONS	10. ACTION	11. PID	12. CAT	13. MMH
X	RMVD PITCH BEAM				
X	RMVD PC LINK SAFETY 8 EA.				
X	RMVD PC LINK HARDWARE 8 EA.				
X	RMVD PITCH BEAM SAFETY.				
X	RMVD PITCH BEAM NUT.				
X	RMVD RETENTION PLATE HARDWARE.				
X	RMVD OUTBOARD RETENTION PLATE.				
X	RMVD TAIL ROTOR BLADES.				

DA FORM 2408-13-2-SG, OCT 97
 DA FORM 2408-13-2, NOV 91, MAY BE USED

RELATED MAINTENANCE ACTIONS RECORD
 For use of this form see DA PAM 738-751, the proponent agency is DCSLOG

1. STATUS ×		2. SERIAL NUMBER 7923328		3. SYSTEM CODE A		4. TIME 12:45	
		5. FAULT DATE 04 Dec 20		6. FAULT NUMBER 2			
7. FAULT RMVD M/R BLADE A007-11384 FROM ACFT FOR GROUND TRANSPORT							
8. STA	9. RELATED MAINTENANCE ACTIONS	10. ACTION	11. PID	12. CAT	13. MMH		
×	RMVD 8EA COTTER PINS FROM M/R BLADE PINS ON ALL 4 BLADES						
×	RMVD 8EA M/R BLADE PINS ON ALL 4 BLADES						
×	ZIP TIED 4EA ANTI FLAPS ON ALL SPINDLES						
×	DISCONNECTED DE-ICE ELECT CONNECTOR						
×	RMVD BLADE						

DA FORM 2408-13-2-SG, OCT 97
 DA FORM 2408-13-2, NOV 91, MAY BE USED

RELATED MAINTENANCE ACTIONS RECORD
 For use of this form see DA PAM 738-751, the proponent agency is DCSLOG

1. STATUS ×		2. SERIAL NUMBER 7923328		3. SYSTEM CODE A		4. TIME 12:54	
		5. FAULT DATE 04 Dec 20		6. FAULT NUMBER 3			
7. FAULT RMVD M/R BLADE A007-02625 FROM ACFT FOR GROUND TRANSPORT							
8. STA	9. RELATED MAINTENANCE ACTIONS	10. ACTION	11. PID	12. CAT	13. MMH		
×	RMVD 2EA BLADE PIN COTTER PINS						
×	ZIP TIED ANTI-FLAP						
×	DISCONNECTED DE-ICE ELECT CONNECTOR						
×	RMVD 2EA BLADE PINS						
×	RMVD BLADE						

DA FORM 2408-13-2-SG, OCT 97
 DA FORM 2408-13-2, NOV 91, MAY BE USED

RELATED MAINTENANCE ACTIONS RECORD
 For use of this form see DA PAM 738-751, the proponent agency is DCSLOG

1. STATUS X	2. SERIAL NUMBER 7923328	3. SYSTEM CODE A		4. TIME 12:58	
	5. FAULT DATE 04 Dec 20	6. FAULT NUMBER 4			
7. FAULT RMVD M/R BLADE A007-05591 FROM ACFT FOR GROUND TRANSPORT					
8. STA	9. RELATED MAINTENANCE ACTIONS	10. ACTION	11. PID	12. CAT	13. MMH
X	RMVD 2EA BLADE PIN COTTER PINS				
X	DISCONNECTED DE-ICE ELECT CONNECTOR				
X	ZIP TIED ANTI-FLAP				
X	RMVD 2EA BLADE PINS				
X	RMVD BLADE				

DA FORM 2408-13-2-SG, OCT 97
 DA FORM 2408-13-2, NOV 91, MAY BE USED

RELATED MAINTENANCE ACTIONS RECORD
 For use of this form see DA PAM 738-751, the proponent agency is DCSLOG

1. STATUS ×	2. SERIAL NUMBER 7923328	3. SYSTEM CODE A	4. TIME 09:27		
	5. FAULT DATE 07 Dec 20	6. FAULT NUMBER 1			
7. FAULT Backup Hydraulic Pump made loud grinding noise when ON that could be heard in the cabin. Verified when hydraulic deck was open that the source of the noise was from the backup pump					
8. STA	9. RELATED MAINTENANCE ACTIONS	10. ACTION	11. PID	12. CAT	13. MMH
×	disconnected pressure and return QD's from the pump				
×	loosened bolts securing pump to motor assy				
×	loosened clamp securing front pump body				
×	loosened pump motor mount hdwr				
×	disconnected elect. connectors from motor				

DA FORM 2408-13-2-SG, OCT 97
 DA FORM 2408-13-2, NOV 91, MAY BE USED

RELATED MAINTENANCE ACTIONS RECORD
 For use of this form see DA PAM 738-751, the proponent agency is DCSLOG

1. STATUS X	2. SERIAL NUMBER 7923328	3. SYSTEM CODE A	4. TIME 09:41		
	5. FAULT DATE 07 Dec 20	6. FAULT NUMBER 3			
7. FAULT #1 fuel boost pump control indicator light will not illuminate when pressed to start pump. Light illuminates when press to test is conducted.					
8. STA	9. RELATED MAINTENANCE ACTIONS	10. ACTION	11. PID	12. CAT	13. MMH
X	rmvd L/H and R/H fuel enclosure panels				
X	loosened pressure swich				

DA FORM 2408-13-2-SG, OCT 97
DA FORM 2408-13-2, NOV 91, MAY BE USED

RELATED MAINTENANCE ACTIONS RECORD
For use of this form see DA PAM 738-751, the proponent agency is DCSLOG

1. STATUS ×	2. SERIAL NUMBER 7923328	3. SYSTEM CODE A	4. TIME 14:37		
	5. FAULT DATE 08 Dec 20	6. FAULT NUMBER 6			
7. FAULT ENGINE GEE374385C REQUIRES REMOVAL IAW NGB AND THE BEST PROGRAM.					
8. STA	9. RELATED MAINTENANCE ACTIONS	10. ACTION	11. PID	12. CAT	13. MMH
×	DISCONNECTED ELECTRICAL CONNECTOR P818 FROM AIR INLET RECEPTACLE.				
×	LOOSENEED CLAMP SECURING FLEXIBLE COUPLING @ AIR INLET.				
×	REMOVED CLAMP SECURING WATERWASH HOSE @ AIR INLET.				
×	DISCONNECTED FIRE EXT. TUBE FITTING @ FIREWALL.				
×	REMOVED DISCHARGE TUBE FROM AIR INLET.				
×	DISCONNECTED ICE DETECTOR ELECTRICAL CONNECTOR P819 FROM FIREWALL.				
×	REMOVED COUPLING CLAMP SECURING AIR INLET TO ENGINE SWIRL FRAME.				
×	REMOVED AIR INLET FROM HELICOPTER.				
×	DISCONNECTED FUEL HOSE FROM PUMP ELBOW.				
×	DISCONNECTED ENGINE DRAIN HOSES FROM ELBOWS ON REAR ENGINE DECK.				
×	DISCONNECTED ELECTRICAL CONNECTOR P814 FROM FIREWALL RECEPTACLE.				
×	DISCONNECTED ELECTRICAL CONNECTOR P824 FROM FIREWALL RECEPTACLE.				
×	DISCONNECTED POWER AVAILABLE INPUT FROM HMU.				

DA FORM 2408-13-2-SG, OCT 97

DA FORM 2408-13-2, NOV 91, MAY BE USED

RELATED MAINTENANCE ACTIONS RECORD

For use of this form see DA PAM 738-751, the proponent agency is DCSLOG

1. STATUS ×	2. SERIAL NUMBER 7923328	3. SYSTEM CODE A	4. TIME 14:37		
	5. FAULT DATE 08 Dec 20	6. FAULT NUMBER 6			
7. FAULT ENGINE GEE374385C REQUIRES REMOVAL IAW NGB AND THE BEST PROGRAM.					
8. STA	9. RELATED MAINTENANCE ACTIONS	10. ACTION	11. PID	12. CAT	13. MMH
×	DISCONNECTED LOAD DEMAND ROTARY INPUT FROM HMU.				
×	REMOVED SCREW SECURING LOAD & DEMAND CONTROL CABLES TO IPS BLOWER DUCT.				
×	REMOVED STARTER BLEED AIR TUBE FROM HELICOPTER.				
×	REMOVED COUPLING FROM CROSS-BLEED AIR TUBE @ FIREWALL.				
×	DISCONNECTED COUPLING CLAMP SECURING IPS DUCT TO BLOWER.				
×	REMOVED PARTICLE SEPARATOR DUCT FROM HELICOPTER.				
×	REMOVED COUPLING CLAMP SECURING DESWIRL DUCT TO POWER TURBINE FLANGE.				
×	REMOVED BOLTS SECURING DISC PACK COUPLING TO INPUT MODULE FLANGE.				
×	REMOVED BOLTS SECURING FOWARD TUBE TO GIMBAL.				
×	REMOVED BOLT SECURING INNER MOUNT TO MOUNT LINKS.				
×	REMOVED BOLT SECURING OUTER MOUNT TO MOUNT LINKS.				
×	REMOVED BOLT SECURING CENTER MOUNT LINKS TO MOUNT SUPPORT ON DECK.				
×	REMOVED BOLTS SECURING AFT MOUNT TO ENGINE COMBUSTER SECTION (BOTTOM).				

DA FORM 2408-13-2-SG, OCT 97

DA FORM 2408-13-2, NOV 91, MAY BE USED

RELATED MAINTENANCE ACTIONS RECORD

For use of this form see DA PAM 738-751, the proponent agency is DCSLOG

1. STATUS ×	2. SERIAL NUMBER 7923328	3. SYSTEM CODE A	4. TIME 14:37		
	5. FAULT DATE 08 Dec 20	6. FAULT NUMBER 6			
7. FAULT ENGINE GEE374385C REQUIRES REMOVAL IAW NGB AND THE BEST PROGRAM.					
8. STA	9. RELATED MAINTENANCE ACTIONS	10. ACTION	11. PID	12. CAT	13. MMH
×	REMOVED #2 ENGINE.				

DA FORM 2408-13-2-SG, OCT 97
 DA FORM 2408-13-2, NOV 91, MAY BE USED

RELATED MAINTENANCE ACTIONS RECORD
 For use of this form see DA PAM 738-751, the proponent agency is DCSLOG

1. STATUS ×	2. SERIAL NUMBER 7923328	3. SYSTEM CODE A		4. TIME 09:50	
	5. FAULT DATE 23 Dec 20	6. FAULT NUMBER 2			
7. FAULT AFT PRIMARY SERVO LEAKING AT NIPPLE BELOW THE OUTPUT PISTONS AND IS SAFETIED WITH A DEPOT LEVEL TAGGED SAFETY.					
8. STA	9. RELATED MAINTENANCE ACTIONS	10. ACTION	11. PID	12. CAT	13. MMH
×	DISCONNECTED 2EA ELECTRICAL CONNECTORS				
×	REMOVED SAFETIES FROM MOUNT BOLTS				
×	REMOVED MOUNT BOLTS				
×	RMVD SERVO				

DA FORM 2408-13-2-SG, OCT 97
 DA FORM 2408-13-2, NOV 91, MAY BE USED

RELATED MAINTENANCE ACTIONS RECORD
 For use of this form see DA PAM 738-751, the proponent agency is DCSLOG

1. STATUS X	2. SERIAL NUMBER 7923328	3. SYSTEM CODE A	4. TIME 07:19		
5. FAULT DATE 28 Dec 20		6. FAULT NUMBER 1			
7. FAULT During FLT control Check, unusual noise heard on co-pilot side when collective was being moved from full up position to full down position. Noise was more pronounced when the pedal trim release switch was pressed during collective movement.					
8. STA	9. RELATED MAINTENANCE ACTIONS	10. ACTION	11. PID	12. CAT	13. MMH
X	rmvd cotter pin from trim servo crank arm				
X	rmvd hrwr from trim servo crank arm				
X	rmvd bolts securing yaw trim servo				
X	rmvd yaw trim servo				
—	fod check due				
—	fod check due				
X	disconnected electrical connecter from trim servo				

DA FORM 2408-13-2-SG, OCT 97
 DA FORM 2408-13-2, NOV 91, MAY BE USED

RELATED MAINTENANCE ACTIONS RECORD
 For use of this form see DA PAM 738-751, the proponent agency is DCSLOG

1. STATUS ×	2. SERIAL NUMBER 7923328	3. SYSTEM CODE A	4. TIME 12:54		
	5. FAULT DATE 20 Jan 21	6. FAULT NUMBER 2			
7. FAULT swap of #1 engine air inlet from afct 79-3328 to 83-23918 required for unit readiness					
8. STA	9. RELATED MAINTENANCE ACTIONS	10. ACTION	11. PID	12. CAT	13. MMH
×	disconnected electrical connector p823				
×	disconnected fire extinguisher discharge tube from firewall				
×	unclamped waterwash hose				
×	rmvd clamp from air inlet to bleed tube				
×	rmvd vband clamp from engine swirl frame to air inlet				
×	rmvd #1 engine air inlet				

DA FORM 2408-13-2-SG, OCT 97
 DA FORM 2408-13-2, NOV 91, MAY BE USED

RELATED MAINTENANCE ACTIONS RECORD
 For use of this form see DA PAM 738-751, the proponent agency is DCSLOG

1. STATUS ×	2. SERIAL NUMBER 7923328	3. SYSTEM CODE A	4. TIME 07:22		
5. FAULT DATE 25 Feb 21		6. FAULT NUMBER 1			
7. FAULT Ground transport configuration "In Process"					
8. STA	9. RELATED MAINTENANCE ACTIONS	10. ACTION	11. PID	12. CAT	13. MMH
×	tail whip antenna rmvd				
×	rmvd upper anti-collision attachment strap				
×	rmvd upper anti-collision light				
×	rmvd HF antenna HDWR				
×	rmvd HF antenna				
×	rmvd hdwr from lower strut cowlings				
×	rmvd lower strut cowlings				
×	rmvd hdwr securing L/H stab fitting cowling				
×	rmvd hdwr securing R/H stab fitting cowling				
×	rmvd L/H stab fitting cowling				
×	rmvd R/H stab fitting cowling				
×	disconnected L/H stab formation light elect connector				
×	disconnected R/H stab formation light elect connector				

DA FORM 2408-13-2-SG, OCT 97
 DA FORM 2408-13-2, NOV 91, MAY BE USED

RELATED MAINTENANCE ACTIONS RECORD
 For use of this form see DA PAM 738-751, the proponent agency is DCSLOG

1. STATUS ×	2. SERIAL NUMBER 7923328	3. SYSTEM CODE A	4. TIME 07:22		
	5. FAULT DATE 25 Feb 21	6. FAULT NUMBER 1			
7. FAULT Ground transport configuration "In Process"					
8. STA	9. RELATED MAINTENANCE ACTIONS	10. ACTION	11. PID	12. CAT	13. MMH
×	disconnected L/H stab bonding jumper				
×	disconnected R/H stab bonding jumper				
×	rmvd L/H stab attach hdwr cotter pin				
×	rmvd R/H stab attach hdwr cotter pin				
×	rmvd L/H stab attach hdwr				
×	rmvd R/H stab attach hdwr				
×	rmvd stab accuator to stab attachment hdwr cotter pin				
×	rmvd stab accuator to stab attachment hdwr				
×	rmvd stab position switch hdwr cotter pin				
×	rmvd stab position switch hdwr				
—	toolbox inventory due				
×	FOD check due				

DA FORM 2408-13-2-SG, OCT 97
 DA FORM 2408-13-2, NOV 91, MAY BE USED

RELATED MAINTENANCE ACTIONS RECORD
 For use of this form see DA PAM 738-751, the proponent agency is DCSLOG