

**IMPORTANT INFORMATION ABOUT YOUR DRINKING WATER
MONITORING REQUIREMENTS NOT MET FOR**

MOUNTAIN TOP PSD, WV3301205

We are required to monitor your drinking water on a regular basis. Results of regular monitoring are an indicator of whether or not our drinking water meets health standards. Between 5/1/2025 and 5/31/2025, we failed to maintain turbidity levels less than or equal to 0.3 NTU for a least 95% of the monthly readings and therefore cannot be sure of the quality of our drinking water during that time.

What should I do?

There is nothing you need to do at this time.

The table below lists the required monitoring and the compliance period.

Required Monitoring	Compliance Period
44, MONTHLY COMB FLTR EFFLUENT (IESWTR/LT1) TURBIDITY Failure to Maintain Turbidity Below 0.3 NTU For At Least 95% of measurements	5/1/2025 to 5/31/2025

What happened? What is being done? (Describe corrective action)

We had newly installed equipment during our 2024-2025 upgrade project. One of our filtrate pumps was malfunctioning which caused the plant to have a variation in the filter rate. This in turn caused inconsistent turbidity.
We isolated the pump that was causing the variation so that it was not the lead pump. The pump will remain isolated until repaired.

For more information, please contact Joe Harvey at 304-693-7667
(Contact name) (Phone number)
Or PO Box 236, Mount Storm WV 26739
(Mailing address)

Please share this information with all the other people who drink this water, especially those who may not have received this notice directly (for example, people in apartments, nursing homes, schools and businesses). You can do this by posting this notice in a public place or distributing copies by hand or mail.

This notice is being sent to you by: **MOUNTAIN TOP PSD**

State Water System ID #: WV3301205

Date Distributed: August 12, 2025