

The Village Inn South Ockenden Essex

Dated 18/03/1998

Dear Sir,

Following our recent Service Call to your pub:-

The Casio TK2200 Cash Register taken to our Workshop is unfortunately uneconomical to repair due to the damage sustained.

Please note the TK2200 was replaced by the Casio Tk2300, the cost of replacement is £898.00 + VAT which includes programming and installation.

I now await your further instructions.

Yours Sincerely

PP Tony Hull