



SPEEDFRAC BALL ACTIVATED FRAC SLEEVE

Casing Size (in)	Maximum OD (in.)	Minimum Seat ID (in.)	Maximum Temp (°F)	Maximum Working Pressure
3.50	4.380	0.908	300	10,000
4.50	5.600	0.908	300	10,000
5.50	7.000	0.908	300	10,000

FEATURES:

- Field proven, ball actuated frac sleeve
- Large exit ports for maximum flow
- Drillable cast iron non-rotational seats
- Full drift ID after drills out
- Short slim-hole design eliminates need for pup joints
- Available for 10K and 15K applications
- P110 material construction
- Variable set opening pressure
- Standard LTC threaded connections

The **SPEDFRAC Ball Activated Frac Sleeve** is designed for horizontal completions and serves as a single point of entry into the formation allowing communication between formation and casing. Generally run in multiples, the frac sleeve is closed and is not affected by deferential casing pressure until the ball has seated. The frac sleeve is installed in the closed position and only activated mechanically by pumping a corresponding sized frac ball from the surface down to the sleeve ball seat. Once actuated, the inner sleeve valves are locked open to prevent closure during well production.



Office Location:





SPEEDFRACBALL ACTIVATED 4-1/2" FRAC SLEEVE SPECIFICATIONS

MAXIMUM OD				
5.60 inches				
MINIMUM DRILL OUT ID				
4.00 INCHES				
BODY MATERIAL				
P-110				
BALL SEAT MATERIAL				
Cast Iron				
PRESSURE RATING				
10,000 psi				
PRESSURE VALUE/SHEAR PIN				
450 psi				
NUMBER OF SHEAR SCREWS				
10				
EXIT FLOW AREA OF PORTS				
15.88 in²				
MAXIMUM # OF BALL SEATS				
*29				
TORQUE RATING				
16,000 ft-lb				
THREAD CONNECTION				
4-1/2" LTC std.				

