



## ATV OR SXS SERVICE AND CHECK OVER



Starts at \$165.98 +HST and supplies. Varies by model but most times will include:

1.  Engine oil/filter change.
2.  Air filter check, clean or replace (if required). Extra cost may apply to clean and re-oil foam filters.
3.  Front differential fluid replace.
4.  Rear differential/transaxle fluid check.
5.  Grease fittings as required (suspension, drive, steering).
6.  Coolant level check and top up.
7.  Check cooling system operation/condition (radiator condition, cooling fan operation, visible cooling hose condition, visible system leaks).
8.  Battery load test
9.  Check all lights and display meters.
10.  Verify that add on electrical accessories are functioning (winch, light bars, etc.)
11.  Steering components check over (tie rod ends, tie rods, steering rack boots, etc.)
12.  Suspension components check. (springs, shock leaks, bushings, mounts, etc.)
13.  Check drive components (axle cv boots/joints, u-joints, wheel bearings, etc.)
14.  Check brake fluid level/condition.
15.  Check brake pad/shoe wear.
16.  Check brake operation.
17.  Check/adjust controls and cables as required.
18.  Check tire condition (uneven tread, tread wear, etc.).
19.  Check tire pressures and set to spec (report on odd tire pressures).
20.  Reset service clock (if applicable).
21.  Yard test drive and check for any operational issues.
22.  DETAILED VIDEO OF ANY SERVICE-RELATED PROBLEMS.

**IMPORTANT:** Note that 4 door UTV's, HVAC models, models with extensive mods that restrict service access or units that are excessively dirty when serviced will have extra costs applied for service due to the extra service time required. ATV's with extensive mods that restrict service access or are excessively dirty may also have extra costs applied.



## NOTES:



**IMPORTANT:** Note that 4 door UTV's, HVAC models, models with extensive mods that restrict service access or units that are excessively dirty when serviced will have extra costs applied for service due to the extra service time required. ATV's with extensive mods that restrict service access or are excessively dirty may also have extra costs applied.