




Hot Rod Institute

A Division of HRI, Inc.
2402 N. Maple Ave PO Box 1456
Rapid City, SD 57709-1456




Required Tool List for HRC, HRB, HRBA, HRR, HRP, HRU.

- Air Hose (3/8, 50 ft. with type M fittings)
- Electrical Cord (50ft.)
- Flash Light
- Safety Glasses
- Leather Work Boots
- Dark Cutting Glasses
- Screwdriver Set (Phillips and Straight blade)
- 1/2" Drive Socket Set (Standard and Metric)
- 3/8" Drive Socket Set (Standard and Metric)
- 1/4" Socket Set
- Combination hand wrenches (Standard and Metric)
- Allen Wrench Set (Standard and Metric)
- Ball Peen Hammer
- Small Sledge Hammer (3 lb)
- Welding Helmet (Auto Darkening)
- Welding Gloves (thin)
- Mechanics Gloves
- Welding Sleeve
- Plier Set
- Punch & Chisel Set
- Die Grinder
- Cut-Off Saw
- Combination Square
- Tape Measure
- High Crown Body Hammer
- Low Crown Body Hammer
- Heel Dolly
- General Purpose Body Hammer
- Center Punch
- Scratch Awl or Scribe
- Air Blower



Hot Rod Institute

A Division of HRI, Inc.
2402 N. Maple Ave PO Box 1456
Rapid City, SD 57709-1456



- Tin Snips (Left & Right) (Red & Green Handle)
- Vise Grips
- Drill Bit Set
- Scraper or putty knife
- Body filler board and spreaders
- Long Sanding Board
- 3" or 5" Air Grinder / Sander
- 3M Paint Mask with replaceable filters
- Dual Action Orbital Sander
- Assortment of Durablock Sanding Blocks
- Paint Suit
- Paint gun kit (primer & paint)
- Air File (Pneumatic Long Board)
- DVOM Multi Meter
- 12 Volt Test Light
- Compression Gauge Set
- Vernier Calipers (Dial or Digital)
- 10" Shears for Upholstery
- Staple Remover
- Tucking Tools
- Tack Hammer
- Metal Ruler 36"
- 3/8's Cordless Drill