

4/25/2024

Contact: pearl@ustcflorida.com
Phone Number: 7863017601

AIRFRAME

AIRCRAFT MAKE	HS-125
AIRCRAFT MODEL	700
AIRCRAFT YEAR	1983
SERIAL NUMBER	257208
AIRCRAFT REGISTRATION NO.	N2787
TOTAL TIME AIRFRAME	11196.3
TOTAL AIRCRAFT LANDINGS	9615
INSPECTION PROGRAM	FAR 91.409(f,3)
TOTAL TIME APU	3831.8
TOTAL CYCLES APU	3831
GTCP30-92/C(a)	P-140

LEFTHAND ENGINE

SERIAL NUMBER	P84484
MAKE	GARRETT
MODEL	TFE731-3R-1H
TIME SINCE NEW	10382.9
CYCLES SINCE NEW	9051
TIME SINCE CORE	2982.7
CYCLES SINCE CORE	2637
TIME SINCE MAJOR PERIODIC	1612.8
CYCLES SINCE MAJOR PERIODIC	1303
CORE INTERVAL	4200

RIGHTHAND ENGINE

SERIAL NUMBER	P84497
MAKE	GARRETT
MODEL	TFE731-3R-1H
TIME SINCE NEW	10529.4
CYCLES SINCE NEW	9049
TIME SINCE CORE	3364.8
CYCLES SINCE CORE	2859
TIME SINCE MAJOR PERIODIC	922.3
CYCLES SINCE MAJOR PERIODIC	532
CORE INTERVAL	4200

All target dates projected in this report have been calculated using your estimated MONTHLY AVERAGE utilization of **30 HOURS AND 30 CYCLES**.

If your utilization is higher than the one's listed above then **BEWARE THE ITEMS WILL COME DUE EARLIER THAN THE PROJECTED TARGET DATES.**

COMPUTERIZED AIRCRAFT MAINTENANCE SYSTEMS

TABLE OF CONTENTS

SUBJECT

PAGE

ATA CODES	1
60 DAY SUMMARY PROJECTION	2
ITEM CHANGE	11
ITEM CHANGE REPORT ADS & SBS	12
AIRFRAME HOURS REPORT	13
CALENDAR REPORT	15
AIRCRAFT LANDINGS REPORT	20
AIRCRAFT UTILIZATION REPORT	25
LH ENGINE HOURS REPORT	26
LH ENGINE CYCLES REPORT	28
RH ENGINE HOURS REPORT	29
RH ENGINE CYCLES REPORT	31
MASTER REPORT (A.T.A. CODES)	32
LONG RANGE PROJECTION REPORT	64
COMPONENT INVENTORY REPORT	74
AIRFRAME AIRWORTHINESS DIRECTIVE REPORT	89
LH ENGINE AIRWORTHINESS DIRECTIVE REPORT	96
RH ENGINE AIRWORTHINESS DIRECTIVE REPORT	98
AIRFRAME SERVICE BULLETIN REPORT	96
LH ENGINE SERVICE BULLETIN REPORT	98
RH ENGINE SERVICE BULLETIN REPORT	113

A.T.A. CODES

CODE	SYSTEM	CODE	SYSTEM
05	INSPECTIONS	54	NACELLES/PYLONS
21	AIR CONDITIONING	55	STABILIZERS
22	AUTOPILOT	56	WINDOWS
23	COMMUNICATIONS	57	WINGS
24	ELECTRICAL POWER	60	STANDARD PRACTICES - PROPELLERS/ROTORS
25	EQUIPMENT & FURNISHINGS	61	PROPELLERS
26	FIRE PROTECTION	65	ROTORS
27	FLIGHT CONTROLS	70	STANDARD PRACTICES - ENGINES
28	FUEL	71	POWER PLANT
29	HYDRAULIC POWER	72	ENGINES
30	ICE & RAIN PROTECTION	73	ENGINE FUEL & CONTROL
31	INDICATOR & RECORDING SYSTEMS	75	IGNITION
32	LANDING GEAR	76	ENGINE CONTROLS
33	LIGHTS	77	ENGINE INDICATING
34	NAVIGATION	78	EXHAUST
35	OXYGEN	79	OIL
36	PNEUMATICS	80	STARTING
37	VACUUM	81	TURBINE
38	WATER/WASTE	82	WATER INJECTION
39	ELECTRICAL/ELECTRONIC PANELS & MULTI PURPOSE COMPONENTS	83	ACCESSORY GEARBOX
49	AIRBORNE AUXILIARY POWER	91	CHARTS
51	STRUCTURES	97	ENGINE SERVICE BULLETINS
52	DOORS	98	AIRFRAME SERVICE BULLETINS
53	FUSELAGE	99	AIRWORTHINESS DIRECTIVES

60 DAY SUMMARY REPORT
HS-125257208

4/25/2024
N2787

TASK NUMBER MAINTENANCE REF	F A A	D E S C R I P T I O N		L O C A T I O N A C T I O N	F I L E I N T E R V A L	L A S T A C C O M P L I S H	R E M A I N I N G H R / C Y C / L D G	T o l e r a n c e	N E X T D U E
		P A R T N U M B E R	P A R T S E R I A L N U M B E R						
25 COMPONENT P.3	*	LIFE VEST RECERTIFICATION			DATE 5 yrs	12/01/1984 0.0		End of Month	12/01/1989
		ALL	UNKNOWN						
340015 OUT PHASE P.9	*	STALL WARNING SYSTEM PIPELINES			DATE 8 yrs	8/29/2008 9680.0		3 Mos Window	8/29/2016
		N/A	N/A	INSPECT					
30 COMPONENT P.5		AIRFRAME DE-ICE SYS RESTRICTOR VAL			DATE 4 yrs	9/13/2012 10184.6			9/13/2016
		150-10B	8004098	OVERHAUL					
30 COMPONENT P.5		WINDSHIELD DE-ICE NON RETURN VALVE			DATE 4 yrs	9/13/2012 10184.6			9/13/2016
		150-9A	7812105	OVERHAUL					
30 COMPONENT P.4		AIRFRAME DE-ICE SYS CHECK VALVE			DATE 4 yrs	9/13/2012 10184.6			9/13/2016
		WGE150/9	UNKNOWN	OVERHAUL					
33 COMPONENT P.8-9		EMERGENCY EXIT LIGHT UNIT			DATE 1 yrs	2/09/2016 10342.2		End of Month	2/09/2017
		N/A	N/A	TEST					
33 COMPONENT P.8-9		EMERGENCY EXIT LIGHT		FWD	DATE 12 mos	2/09/2016 10342.2		End of Month	2/09/2017
		N/A	N/A	BENCH CK					
33 COMPONENT P.8-9		EMERGENCY EXIT LIGHT		AFT	DATE 12 mos	2/09/2016 10342.2		End of Month	2/09/2017
		N/A	N/A	BENCH CK					
99 SEE AD	*	AD 2015-08-07 OXY MASK REG HARNESS			DATE 24 mos				6/16/2017
32 COMPONENT P.7		MAIN GEAR REVERSING VALVE		RH	DATE 12 yrs	7/01/2005			7/01/2017
		AIR48543-1	LK0747	OVERHAUL					
32 COMPONENT P.6		MAIN GEAR LEG ASSEMBLY		LH	DATE 12 yrs	7/01/2005			7/01/2017
		25-6UM1AG	DHL/DH/1231	OVERHAUL					
32 COMPONENT P.6		MAIN GEAR LEG ASSEMBLY		RH	DATE 12 yrs	7/01/2005			7/01/2017
		25-6UM2AG	DHL/DH1183	OVERHAUL					
32 COMPONENT P.6		MAIN GEAR SIDE STAY		LH	DATE 12 yrs	7/01/2005			7/01/2017
		257-UM121AB	DHL/DHI069	OVERHAUL					
32 COMPONENT P.6		MAIN GEAR SIDE STAY		RH	DATE 12 yrs	7/01/2005			7/01/2017
		25-7UM122AB	DHL/DH1064	OVERHAUL					

60 DAY SUMMARY REPORT
HS-125257208

4/25/2024
N2787

TASK NUMBER MAINTENANCE REF	F A A	D E S C R I P T I O N		L O C A T I O N A C T I O N	F I L E I N T E R V A L	L A S T A C C O M P L I S H	R E M A I N I N G H R / C Y C / L D G	T o l e r a n c e	N E X T D U E
		P A R T N U M B E R	P A R T S E R I A L N U M B E R						
32 COMPONENT P.6		NOSE GEAR DRAG STAY		OVERHAUL	DATE 12 yrs	7/01/2005			7/01/2017
		25-8UN3AG	DHL/DH/465						
26 LIFE LIMITS REV 10	*	FIRE EXTINGUISHER FIRED FUSE		#1 REPLACE	DATE 3 yrs	9/15/2014 10286.8			9/15/2017
		A1003(1)	N/A						
26 LIFE LIMITS REV 10	*	FIRE EXTINGUISHER FIRED FUSE		#2 REPLACE	DATE 3 yrs	9/15/2014 10286.8			9/15/2017
		A1003(1)	N/A						
32 COMPONENT P.7		MAIN GEAR REVERSING VALVE		LH OVERHAUL	DATE 12 yrs	1/20/2006 9322.0			1/20/2018
		AIR48542/1	APB012087						
32 COMPONENT P.7		MAIN GEAR SEQUENCE VALVE		LH OVERHAUL	DATE 12 yrs	1/20/2006 9322.0			1/20/2018
		AIR48540/1	LK0582						
32 COMPONENT P.7		MAIN GEAR SEQUENCE VALVE		RH OVERHAUL	DATE 12 yrs	1/20/2006 9322.0			1/20/2018
		AIR48540/1	LK0587						
32 COMPONENT P.6		NOSE GEAR LEG ASSEMBLY		OVERHAUL	DATE 12 yrs	4/24/2006 9368.5			4/24/2018
		25-UN1AZ	DHL/DH/727						
320039 OUT PHASE P.8	*	NOSE STEERING PIVOT PIN		MAG PART	DATE 12 yrs	4/24/2006 9368.5			4/24/2018
		N/A	N/A						
26 LIFE LIMITS REV 10	*	FIRE EXTINGUISHER FIRED FUSE (MFG)		#1 REPLACE	DATE 4 yrs	4/30/2014			4/30/2018
		A1003(1)	N/A						
26 LIFE LIMITS REV 10	*	FIRE EXTINGUISHER FIRED FUSE (MFG)		#2 REPLACE	DATE 4 yrs	4/30/2014			4/30/2018
		A1003(1)	N/A						
24 COMPONENT P.2		AC GENERATOR		RH OVERHAUL	DATE 5 yrs	1/06/2014 10275.1			1/06/2019
		BA00501-1	0076						
33 COMPONENT P.6		INERTIA SWITCH, EMERG LIGHTING		OVERHAUL	DATE 3 yrs	2/09/2016 10342.2			2/09/2019
		18C-2-1-5G	AT9938						
26 COMPONENT P.3	*	OVERHEAT DETECTOR SWITCHES		EQUIP BAY CALIBRATE	DATE 5 yrs	9/15/2014 10286.8			9/15/2019
		N/A	N/A						
21 COMPONENT P.2	*	DUCT TEMP SWITCH OVERHEAT WARNING		LH CALIBRATE	DATE 5 yrs	9/15/2014 10286.8			9/15/2019
		N/A	N/A						

60 DAY SUMMARY REPORT
HS-125257208

4/25/2024
N2787

TASK NUMBER MAINTENANCE REF	FAA	DESCRIPTION		LOCATION ACTION	FILE INTERVAL	LAST ACCOMPLISH	REMAINING HR/CYC/LDG	Tolerance	NEXT DUE
		PART NUMBER	PART SERIAL NUMBER						
21	*	DUCT TEMP SWITCH OVERHEAT WARNING		RH	DATE	9/15/2014			9/15/2019
COMPONENT P.2		N/A	N/A	CALIBRATE	5 yrs	10286.8			
26	*	OVERHEAT DETECT SWTCH PYLON FILLETS		LH AFT	DATE	9/15/2014			9/15/2019
COMPONENT P.3		N/A	N/A	CALIBRATE	5 yrs	10286.8			
26	*	OVERHEAT DETECT SWTCH PYLON FILLETS		LH FWD	DATE	9/15/2014			9/15/2019
COMPONENT P.3		N/A	N/A	CALIBRATE	5 yrs	10286.8			
26	*	OVERHEAT DETECT SWTCH PYLON FILLETS		RH FWD	DATE	9/15/2014			9/15/2019
COMPONENT P.3		N/A	N/A	CALIBRATE	5 yrs	10286.8			
26	*	OVERHEAT DETECT SWTCH PYLON FILLETS		RH AFT	DATE	9/15/2014			9/15/2019
COMPONENT P.3		N/A	N/A	CALIBRATE	5 yrs	10286.8			
26	*	APU HSRS FIRE DETECTOR		UPPER	DATE	9/15/2014			9/15/2019
COMPONENT P.3		N/A	N/A	CALIBRATE	5 yrs	10286.8			
26	*	APU HSRS FIRE DETECTOR		LOWER	DATE	9/15/2014			9/15/2019
COMPONENT P.3		N/A	N/A	CALIBRATE	5 yrs	10286.8			
26	*	ENGINE FIRE EXTINGUISHER CARTRIDGE		FWD HEAD A	DATE	1/18/2010			1/18/2020
LIFE LIMITS REV 10		UNKNOWN	809KL	REPLACE	10 yrs	9865.9			
26	*	ENGINE FIRE EXTINGUISHER CARTRIDGE		FWD HEAD B	DATE	1/18/2010			1/18/2020
LIFE LIMITS REV 10		UNKNOWN	0801KL	REPLACE	10 yrs	9865.9			
26	*	ENGINE FIRE EXTINGUISHER CARTRIDGE		AFT HEAD A	DATE	1/18/2010			1/18/2020
LIFE LIMITS REV 10		UNKNOWN	0806KL	REPLACE	10 yrs	9865.9			
26	*	ENGINE FIRE EXTINGUISHER CARTRIDGE		AFT HEAD B	DATE	1/18/2010			1/18/2020
LIFE LIMITS REV 10		UNKNOWN	0789KL	REPLACE	10 yrs	9865.9			
29		EMER BRAKE ACC LOW PRES WARN SWITCH			AF HRS	9/21/1992			3/13/2020
COMPONENT P.4		TP42001	240	OVERHAUL	5000	4693.2	-1503.1		9693.2
24		INVERTER SUPPLY CONTACTOR		#2	AF HRS	5/09/1993			12/25/2020
COMPONENT P.2		LDA200B-18C	084348	OVERHAUL	5000	4980.0	-1216.3		9980.0
24		AC GENERATOR		LH	DATE	7/10/2016			7/10/2021
COMPONENT P.2		UNKNOWN	UNKNOWN	OVERHAUL	5 yrs	10361.8			

60 DAY SUMMARY REPORT
HS-125257208

4/25/2024
N2787

TASK NUMBER MAINTENANCE REF	F A A	D E S C R I P T I O N		LOCATION	FILE	LAST	REMAINING HR/CYC/LDG	Tolerance	NEXT DUE
		PART NUMBER	PART SERIAL NUMBER	ACTION	INTERVAL	ACCOMPLISH			
280015 OUT PHASE P.4	*	FUEL BOOST PUMP BRUSHES WEAR		LH	AF HRS	12/05/2000	-1007.6	200 Hrs Window	7/22/2021 10188.7
		2070C-11	164	INSPECT	2000	8188.7			
35 COMPONENT P.7		OXYGEN MASK		PILOT	DATE	2/09/2016			2/09/2022
		MC10-14-01	60862	OVERHAUL	6 yrs	10342.2			
210022 OUT PHASE P.2	*	COOLING TURBINE OIL DRAIN			AF HRS	7/10/2016	-784.5	5 Hrs Window	3/02/2022 10411.8
		N/A	N/A		50	10361.8			
33 COMPONENT P.7	*	STROBE LIGHT		LH WING	AF HRS	9/15/2014	-759.5		3/27/2022 10436.8
		N/A	N/A	TEST	150	10286.8			
33 COMPONENT P.7	*	STROBE LIGHT		RH WING	AF HRS	9/15/2014	-759.5		3/27/2022 10436.8
		N/A	N/A	TEST	150	10286.8			
33 COMPONENT P.7	*	STROBE LIGHT		TAIL	AF HRS	9/15/2014	-759.5		3/27/2022 10436.8
		N/A	N/A	TEST	150	10286.8			
98		SB 71-036		LH	AF HRS	7/10/2016	-694.0		6/01/2022 10502.3
					150	10352.3			
710001 OUT PHASE P.10,11	*	ENGINE COWLING		RH	AF HRS	7/10/2016	-694.0	15 Hrs Window	6/01/2022 10502.3
		N/A	N/A	INSPECT	150	10352.3			
98		SB 71-036		RH	AF HRS	7/10/2016	-694.0		6/01/2022 10502.3
					150	10352.3			
710001 OUT PHASE P.10,11	*	ENGINE COWLING		LH	AF HRS	7/10/2016	-684.5	15 Hrs Window	6/10/2022 10511.8
		N/A	N/A	INSPECT	150	10361.8			
72 TABLE 603,604	*	150-250 HOUR ENG INSPECT		RH	ENG HRS	6/04/2013	-672.3		6/22/2022 9857.1
		TFE731-3R-1H	P-84484		250	9607.1			
79 TABLE 603,604	*	SOAP CHECK		RH	ENG HRS	6/04/2013	-672.3		6/22/2022 9857.1
		TFE731-3R-1H	P-84484		250	9607.1			
72 TABLE 603,604	*	150-250 HOUR ENG INSPECT		LH	ENG HRS	12/23/2014	-636.4		7/28/2022 9746.5
		TFE731-3R-1H	P84497		250	9496.5			
79 TABLE 603,604	*	SOAP CHECK		LH	ENG HRS	12/23/2014	-636.4		7/28/2022 9746.5
		TFE731-3R-1H	P84497		250	9496.5			

60 DAY SUMMARY REPORT
HS-125257208

4/25/2024
N2787

TASK NUMBER MAINTENANCE REF	FAA	DESCRIPTION		LOCATION	FILE	LAST	REMAINING HR/CYC/LDG	Tolerance	NEXT DUE
		PART NUMBER	PART SERIAL NUMBER	ACTION	INTERVAL	ACCOMPLISH			
24 EMERGENCY 5-0167	*	BATTERY		#3	DATE	8/20/2021		End of Month	8/20/2022
		UNKNOWN	UNKNOWN	CAP CHK	12 mos	10559.0			
34 COMPONENT P.7		ELEVATOR TRIM SERVO/MOTOR			AF HRS	11/30/1994			10/08/2022 10631.6
		622-3260-001	480	OVERHAUL	5000	5631.6	-564.7		
72 TABLE 603,604	*	300-400 HOUR ENG INSPECT		LH	ENG HRS	6/07/2013			11/19/2022 9860.6
		TFE731-3R-1H	P84497		400	9460.6	-522.3		
72 TABLE 603,604	*	300-400 HOUR ENG INSPECT		RH	ENG HRS	6/04/2013			11/19/2022 10007.1
		TFE731-3R-1H	P-84484		400	9607.1	-522.3		
320038 OUT PHASE P.8	*	BRAKE PAD WEAR		LH	LANDING	2/05/2013		7 Ldg Window	1/05/2023 9139
		N/A	N/A	INSPECT	75	9064	-476		
320038 OUT PHASE P.8	*	BRAKE PAD WEAR		RH	LANDING	2/05/2013		7 Ldg Window	1/05/2023 9139
		N/A	N/A	INSPECT	75	9064	-476		
35 LIFE LIMITS REV 10		PROTECTIVE BREATHING EQUIPMENT			DATE	2/27/2013			2/27/2023
		E28180-20-0001	BEEB-0405	REPLACE	10 yrs	10275.1			
73 TABLE 603,604	*	FUEL FILTER ELEMENT		LH	ENG HRS	7/17/2012			4/14/2023 10006.6
		897830-1	N/A	REPLACE	650	9356.6	-376.3		
73 TABLE 603,604	*	FUEL FILTER ELEMENT		RH	ENG HRS	6/04/2013			7/27/2023 10257.1
		UNKNOWN	N/A	REPLACE	650	9607.1	-272.3		
98	*	SB 32-184 (NOSE BRIDGE CAST INSP)			DATE	8/20/2021			8/20/2023
					24 mos	10559.0			
320036 STRUCT INSP P.4	*	NOSE LANDING GEAR BRIDGE CASTING			DATE	8/20/2021			8/20/2023
		N/A	N/A	DYE PEN	2 yrs	10559.0			
99 SEE AD	*	AD 80-12-05 (NOSE GEAR BRIDGE CAST)			DATE	8/20/2021			8/20/2023
					2 yrs	10559.0			
12 LUBRICATION	*	150 HOUR AIRCRAFT LUBE			AF HRS	9/20/2022		15 Hrs Window	8/27/2023 10954.5
		N/A	N/A		150	10804.5	-241.8		
24 COMPONENT P.2		STARTER GENERATOR		LH	AF HRS	2/11/2011			9/18/2023 10976.5
		23080-005	1763	OVERHAUL	1000	9976.5	-219.8		

60 DAY SUMMARY REPORT
HS-125257208

4/25/2024
N2787

TASK NUMBER MAINTENANCE REF	FAA	DESCRIPTION		LOCATION ACTION	FILE INTERVAL	LAST ACCOMPLISH	REMAINING HR/CYC/LDG	Tolerance	NEXT DUE
		PART NUMBER	PART SERIAL NUMBER						
24 COMPONENT P.2		STARTER GENERATOR		RH OVERHAUL	AF HRS 1000	2/11/2011 9976.5	-219.8		9/18/2023 10976.5
		23080-005	Y0571						
72 SB 72-3106 R15	*	ENGINE MAJOR PERIODIC INSPECTION		LH	ENG HRS 1400	8/02/2007 8770.1	-212.8	100 Hrs Window	9/25/2023 10170.1
		TFE731-3R-1H	P84497						
72 SB 72-3106 R15	*	COMBUSTION PLENUM CASE INSPECTION		LH	ENG HRS 1400	8/02/2007 8770.1	-212.8	100 Hrs Window	9/25/2023 10170.1
		TFE731-3R-1H	P84497						
97 SEE SB		SB 72-3494 (TURBINE BLADES)		LH	ENG HRS 1400	8/02/2007 8770.1	-212.8		9/25/2023 10170.1
99 SEE AD	*	AD 74-08-09 (FIRE PROTECT LAVATORY)			AF HRS 1000	6/06/2011 10006.6	-189.7		10/18/2023 11006.6
72 TABLE 603,604	*	600-800 HOUR ENG INSPECT		LH	ENG HRS 800	6/07/2013 9460.6	-122.3		12/24/2023 10260.6
		TFE731-3R-1H	P84497						
72 TABLE 603,604	*	600-800 HOUR ENG INSPECT		RH	ENG HRS 800	6/04/2013 9607.1	-122.3		12/24/2023 10407.1
		TFE731-3R-1H	P-84484						
34 24-20-03 P.108	*	EMERGENCY POWER SUPPLY		#2 TEST	DATE 3 mos	9/25/2023 11156.2		End of Month	12/25/2023
		501-1075-06	1660						
300012 OUT PHASE P.6	*	WINDSHIELD FLUID DEICING SYSTEM			DATE 3 mos	9/25/2023 11156.2			12/25/2023
		N/A	N/A	FUNC TEST					
340016 OUT PHASE P.9	*	EMERGENCY POWER SUPPLY		#1 CAP CHK	DATE 3 mos	9/25/2023 11156.2		End of Month	12/25/2023
		501-1075-06	1664						
240031 OUT PHASE P.3	*	APU STARTER/GENERATOR SPLINE LUBE			APU HRS 300	9/13/2012 3414.8	-117.0	30 Hrs Window	12/30/2023 3714.8
		23080-005	3477						
240031 OUT PHASE P.3	*	APU STARTER/GENERATOR BRUSH WEAR			APU HRS 300	9/13/2012 3414.8	-117.0	30 Hrs Window	12/30/2023 3714.8
		23080-005	3477	INSPECT					
72 TABLE 603,604	*	1000-1500 HOUR ENG INSPECT		LH	ENG HRS 1500	8/02/2007 8770.1	-112.8		1/03/2024 10270.1
		TFE731-3R-1H	P84497						
490003 49-20-00	*	APU 500 HOUR INSPECTION			APU HRS 500	9/09/2009 3221.2	-110.6		1/05/2024 3721.2
		GTCP30-92/C(A)	P140						

60 DAY SUMMARY REPORT

HS-125257208

4/25/2024
N2787

TASK NUMBER MAINTENANCE REF	FAA	DESCRIPTION		LOCATION ACTION	FILE INTERVAL	LAST ACCOMPLISH	REMAINING HR/CYC/LDG	Tolerance	NEXT DUE
		PART NUMBER	PART SERIAL NUMBER						
24 COMPONENT P.2		BUS TIE CONTACTOR		OVERHAUL	AF HRS 5000	1/25/1996 6109.1	-87.2		1/28/2024 11109.1
		LDA15088C	P36443						
33 COMPONENT P.8-9		EMERGENCY LIGHT FILAMENT		REPLACE	DATE 6 mos	9/25/2023 11156.2			3/25/2024
		N/A	N/A						
24 DOC 5-0171	*	BATTERY		#1 (MAIN)	DATE 6 mos	9/25/2023 11156.2		End of Month	3/25/2024
		RG390E	40340718	CAP CHK					
24 DOC 5-0171	*	BATTERY		#2 (MAIN)	DATE 6 mos	9/25/2023 11156.2		End of Month	3/25/2024
		RG390E	40594653	CAP CHK					
490002 49-20-00	*	APU 250 HOUR INSPECTION			APU HRS 250	8/10/2016 3582.3	0.5		4/25/2024 3832.3
		GTCP30-92/C(A)	P140						
050250 INSPECTION C	*	INSPECTION C			AF HRS 1200	6/03/2011 10006.6	10.3	50 Hrs Window	5/05/2024 11206.6
		N/A	N/A						
12 LUBRICATION	*	1200 HOUR AIRCRAFT LUBE			AF HRS 1200	6/03/2011 10006.6	10.3	100 Hrs Window	5/05/2024 11206.6
		N/A	N/A						
050380 INSPECTION D	*	INSPECTION D			AF HRS 2400	9/02/2003 8822.0	25.7	50 Hrs Window	5/20/2024 11222.0
		N/A	N/A						
12 LUBRICATION	*	2400 HOUR AIRCRAFT LUBE			AF HRS 2400	9/02/2003 8822.0	25.7	50 Hrs Window	5/20/2024 11222.0
		N/A	N/A						
32 LIFE LIMITS REV 10	*	MAIN GEAR JACK CYLINDER HEAD		LH	LANDING 5000	11/26/1993 4642	27		5/22/2024 9642
		AIR127866	UNKNOWN	REPLACE					
32 LIFE LIMITS REV 10	*	MAIN GEAR JACK CYLINDER HEAD		RH	LANDING 5000	7/01/2005 7901	27		5/22/2024 9642
		UNKNOWN	UNKNOWN	REPLACE					
27 LIFE LIMITS REV 10	*	FLAP SYNCHRO CABLE ASSY (INNER)		LH FORWARD	LANDING 5000	11/26/1993 4642	27		5/22/2024 9642
		25CF3225-17	UNKNOWN	REPLACE					
27 LIFE LIMITS REV 10	*	FLAP SYNCHRO CABLE ASSY (INNER)		LH AFT	LANDING 5000	11/26/1993 4642	27		5/22/2024 9642
		25CF3225-19	UNKNOWN	REPLACE					
27 LIFE LIMITS REV 10	*	FLAP SYNCHRO CABLE ASSY (OUTER)		LH FORWARD	LANDING 5000	11/26/1993 4642	27		5/22/2024 9642
		25CF3225-3	UNKNOWN	REPLACE					

60 DAY SUMMARY REPORT
HS-125257208

4/25/2024
N2787

TASK NUMBER MAINTENANCE REF	F A A	D E S C R I P T I O N		LOCATION	FILE	LAST	REMAINING HR/CYC/LDG	Tolerance	NEXT DUE
		PART NUMBER	PART SERIAL NUMBER	ACTION	INTERVAL	ACCOMPLISH			
27	*	FLAP SYNCHRO CABLE ASSY (OUTER)		LH AFT	LANDING	11/26/1993	27		5/22/2024 9642
LIFE LIMITS REV 10	25CF3225-15	UNKNOWN	REPLACE	5000	4642				
27	*	FLAP SYNCHRO CABLE ASSY (OUTER)		RH AFT	LANDING	11/26/1993	27		5/22/2024 9642
LIFE LIMITS REV 10	25CF3225-15	UNKNOWN	REPLACE	5000	4642				
27	*	FLAP SYNCHRO CABLE ASSY (INNER)		RH FORWARD	LANDING	11/26/1993	27		5/22/2024 9642
LIFE LIMITS REV 10	25CF3225-9	UNKNOWN	REPLACE	5000	4642				
27	*	FLAP SYNCHRO CABLE ASSY (INNER)		RH AFT	LANDING	11/26/1993	27		5/22/2024 9642
LIFE LIMITS REV 10	25CF3225-9	UNKNOWN	REPLACE	5000	4642				
32		NOSE GEAR RETRACT JACK			LANDING	11/26/1993	27		5/22/2024 9642
COMPONENT P. 6	AIR45404-1	LK8200318	OVERHAUL	5000	4642				
32		MAIN GEAR RETRACT JACK		LH	LANDING	11/26/1993	27		5/22/2024 9642
COMPONENT P. 6	AIR48502-4	LK0166	OVERHAUL	5000	4642				
32		MAIN GEAR DOOR JACK		LH	LANDING	11/26/1993	27		5/22/2024 9642
COMPONENT P. 7	AIR48485-3	LK8205648	OVERHAUL	5000	4642				

ITEM CHANGE REPORT
HS-125 257208

4/25/2024
N2787

NO ITEMS CHANGED ON THIS REPORT

AD & SB ITEM CHANGE REPORT
HS-125 257208

4/25/2024
N2787

NO AD'S OR SB'S CHANGED ON THIS REPORT

AIRFRAME HOURS REPORT

HS-125 257208

4/25/2024

N2787

ATA CODE	F A	DESCRIPTION	LOCATION	ACTION	ACCOMPLISHED		INTERVAL	HOURS			TARGET DATE
					DATE	HOURS		NEXT DUE	CURRENT	REMAINING	
30		AIRFRAME DE-ICE SYS RESTRICTOR VAL		OVERHAUL	9/13/2012	10184.6	3000 hrs	13184.6	1011.7	1988.3	09/13/2016
30		WINDSHIELD DE-ICE NON RETURN VALVE		OVERHAUL	9/13/2012	10184.6	3000 hrs	13184.6	1011.7	1988.3	09/13/2016
30		AIRFRAME DE-ICE SYS CHECK VALVE		OVERHAUL	9/13/2012	10184.6	3000 hrs	13184.6	1011.7	1988.3	09/13/2016
24		AC GENERATOR	RH	OVERHAUL	1/06/2014	10275.1	2500 hrs	12775.1	921.2	1578.8	01/06/2019
29		EMER BRAKE ACC LOW PRES WARN SWITCH		OVERHAUL	9/21/1992	4693.2	5000 hrs	9693.2	6503.1	-1503.1	03/13/2020
24		INVERTER SUPPLY CONTACTOR	#2	OVERHAUL	5/09/1993	4980.0	5000 hrs	9980.0	6216.3	-1216.3	12/25/2020
24		AC GENERATOR	LH	OVERHAUL	7/10/2016	10361.8	2500 hrs	12861.8	834.5	1665.5	07/10/2021
280015	*	FUEL BOOST PUMP BRUSHES WEAR	LH	INSPECT	12/05/2000	8188.7	2000 hrs	10188.7	3007.6	-1007.6	07/22/2021
210022	*	COOLING TURBINE OIL DRAIN			7/10/2016	10361.8	50 hrs	10411.8	834.5	-784.5	03/02/2022
33	*	STROBE LIGHT	LH WING	TEST	9/15/2014	10286.8	150 hrs	10436.8	909.5	-759.5	03/27/2022
33	*	STROBE LIGHT	RH WING	TEST	9/15/2014	10286.8	150 hrs	10436.8	909.5	-759.5	03/27/2022
33	*	STROBE LIGHT	TAIL	TEST	9/15/2014	10286.8	150 hrs	10436.8	909.5	-759.5	03/27/2022
98		SB 71-036	LH		7/10/2016	10352.3	150 hrs	10502.3	844.0	-694.0	06/01/2022
710001	*	ENGINE COWLING	RH	INSPECT	7/10/2016	10352.3	150 hrs	10502.3	844.0	-694.0	06/01/2022
98		SB 71-036	RH		7/10/2016	10352.3	150 hrs	10502.3	844.0	-694.0	06/01/2022
710001	*	ENGINE COWLING	LH	INSPECT	7/10/2016	10361.8	150 hrs	10511.8	834.5	-684.5	06/10/2022
34		ELEVATOR TRIM SERVO/MOTOR		OVERHAUL	11/30/1994	5631.6	5000 hrs	10631.6	5564.7	-564.7	10/08/2022
12	*	150 HOUR AIRCRAFT LUBE			9/20/2022	10804.5	150 hrs	10954.5	391.8	-241.8	08/27/2023
24		STARTER GENERATOR	LH	OVERHAUL	2/11/2011	9976.5	1000 hrs	10976.5	1219.8	-219.8	09/18/2023
24		STARTER GENERATOR	RH	OVERHAUL	2/11/2011	9976.5	1000 hrs	10976.5	1219.8	-219.8	09/18/2023
99	*	AD 74-08-09 (FIRE PROTECT LAVATORY)			6/06/2011	10006.6	1000 hrs	11006.6	1189.7	-189.7	10/18/2023
34	*	EMERGENCY POWER SUPPLY	#2	TEST	9/25/2023	11156.2	100 hrs	11256.2	40.1	59.9	12/25/2023
24		BUS TIE CONTACTOR		OVERHAUL	1/25/1996	6109.1	5000 hrs	11109.1	5087.2	-87.2	01/28/2024
050250	*	INSPECTION C			6/03/2011	10006.6	1200 hrs	11206.6	1189.7	10.3	05/05/2024
12	*	1200 HOUR AIRCRAFT LUBE			6/03/2011	10006.6	1200 hrs	11206.6	1189.7	10.3	05/05/2024
050380	*	INSPECTION D			9/02/2003	8822.0	2400 hrs	11222.0	2374.3	25.7	05/20/2024
12	*	2400 HOUR AIRCRAFT LUBE			9/02/2003	8822.0	2400 hrs	11222.0	2374.3	25.7	05/20/2024
33		EMERGENCY LIGHT INERTIA SWITCH		BENCH CK	2/09/2016	10342.2	1000 hrs	11342.2	854.1	145.9	09/17/2024
050050	*	INSPECTION A			6/23/2023	11099.8	300 hrs	11399.8	96.5	203.5	11/14/2024
12	*	300 HOUR AIRCRAFT LUBE			6/23/2023	11099.8	300 hrs	11399.8	96.5	203.5	11/14/2024
050120	*	INSPECTION B			5/26/2023	10959.7	600 hrs	11559.7	236.6	363.4	04/23/2025
12	*	600 HOUR AIRCRAFT LUBE			5/26/2023	10959.7	600 hrs	11559.7	236.6	363.4	04/23/2025
260014	*	ENGINE FIRE EXTINGUISHING	LH	INSPECT	6/07/2013	10274.0	1400 hrs	11674.0	922.3	477.7	08/15/2025
260014	*	ENGINE FIRE EXTINGUISHING	RH	INSPECT	6/07/2013	10274.0	1400 hrs	11674.0	922.3	477.7	08/15/2025
290021	*	ENGINE DRIVEN HYDRAULIC PUMP	LH	INSPECT	6/07/2013	10274.0	1400 hrs	11674.0	922.3	477.7	08/15/2025
290021	*	ENGINE DRIVEN HYDRAULIC PUMP	RH	INSPECT	6/07/2013	10274.0	1400 hrs	11674.0	922.3	477.7	08/15/2025
570017	*	AILERON ROD END BEARINGS		LUBE	8/20/2021	10559.0	2400 hrs	12959.0	637.3	1762.7	08/20/2025
570016	*	AILERON (REMOVED)		INSPECT	8/20/2021	10559.0	2400 hrs	12959.0	637.3	1762.7	08/20/2025
570018	*	AILERON 'A' LEVERS/CONNECTING LINKS		INSPECT	8/20/2021	10559.0	2400 hrs	12959.0	637.3	1762.7	08/20/2025
570020	*	AILERON PULLEY DRUMS		INSPECT	8/20/2021	10559.0	2400 hrs	12959.0	637.3	1762.7	08/20/2025
570021	*	AILERON HINGES & ATTACHMENTS		INSPECT	8/20/2021	10559.0	2400 hrs	12959.0	637.3	1762.7	08/20/2025
570019	*	AILERON TRIM SCREWJACKS		INSPECT	8/20/2021	10559.0	2400 hrs	12959.0	637.3	1762.7	08/20/2025
570024	*	FLAP AND FLAP VANES (X-RAY)	LH	NDT	8/20/2021	10559.0	2400 hrs	12959.0	637.3	1762.7	08/20/2025
570024	*	FLAP AND FLAP VANES (X-RAY)	RH	NDT	8/20/2021	10559.0	2400 hrs	12959.0	637.3	1762.7	08/20/2025

AIRFRAME HOURS REPORT

4/25/2024

HS-125 257208

N2787

ATA CODE	F A	DESCRIPTION	LOCATION	ACTION	ACCOMPLISHED		INTERVAL	HOURS			TARGET DATE
					DATE	HOURS		NEXT DUE	CURRENT	REMAINING	
570022	*	AIRBRAKE HINGES	LH UPPER	INSPECT	8/20/2021	10559.0	2400 hrs	12959.0	637.3	1762.7	08/20/2025
570014	*	WING FRONT SPAR	LH	INSPECT	8/20/2021	10559.0	2400 hrs	12959.0	637.3	1762.7	08/20/2025
570014	*	WING FRONT SPAR	RH	INSPECT	8/20/2021	10559.0	2400 hrs	12959.0	637.3	1762.7	08/20/2025
570015	*	WING REAR SPAR	LH	INSPECT	8/20/2021	10559.0	2400 hrs	12959.0	637.3	1762.7	08/20/2025
570015	*	WING REAR SPAR	RH	INSPECT	8/20/2021	10559.0	2400 hrs	12959.0	637.3	1762.7	08/20/2025
570022	*	AIRBRAKE HINGES	RH UPPER	INSPECT	8/20/2021	10559.0	2400 hrs	12959.0	637.3	1762.7	08/20/2025
570022	*	AIRBRAKE HINGES	LH LOWER	INSPECT	8/20/2021	10559.0	2400 hrs	12959.0	637.3	1762.7	08/20/2025
570022	*	AIRBRAKE HINGES	RH LOWER	INSPECT	8/20/2021	10559.0	2400 hrs	12959.0	637.3	1762.7	08/20/2025
570023	*	AILERON ASSEMBLY & TABS (X-RAY)	LH	NDT	8/20/2021	10559.0	2400 hrs	12959.0	637.3	1762.7	08/20/2025
570023	*	AILERON ASSEMBLY & TABS (X-RAY)	RH	NDT	8/20/2021	10559.0	2400 hrs	12959.0	637.3	1762.7	08/20/2025
29		ENGINE HYDRAULIC PUMP	LH	OVERHAUL	8/29/2008	9680.0	2000 hrs	11680.0	1516.3	483.7	08/21/2025
550002	*	VERTICAL STABILIZER RIB 6		INSPECT	9/25/2023	11156.2	1200 hrs	12356.2	40.1	1159.9	09/25/2025
550003	*	HORIZ/VERT STAB ATTACH FITTINGS		INSPECT	9/25/2023	11156.2	1200 hrs	12356.2	40.1	1159.9	09/25/2025
550004	*	HORIZ/VERT STAB ATTACH FITTINGS	REAR	INSPECT	9/25/2023	11156.2	1200 hrs	12356.2	40.1	1159.9	09/25/2025
530014	*	WINDSHIELD CENTR POST CAPPING STRIP	TOP	INSPECT	8/20/2021	10559.0	1200 hrs	11759.0	637.3	562.7	11/08/2025
720001	*	ENGINE MOUNT BRACKETS (FWD)	LH	MAG PART	8/20/2021	10559.0	1400 hrs	11959.0	637.3	762.7	05/27/2026
720001	*	ENGINE MOUNT BRACKETS (FWD)	RH	MAG PART	8/20/2021	10559.0	1400 hrs	11959.0	637.3	762.7	05/27/2026
21		MAIN SUPPLY CABIN NON RETURN VALVE		OVERHAUL	11/30/1994	5631.6	12000 hrs	12000.0	11196.3	803.7	07/07/2026
24		GROUND SUPPLY START CONTACTOR		OVERHAUL	11/30/1995	6048.1	6000 hrs	12048.1	5148.2	851.8	08/24/2026
28		FUEL BOOST PUMP	LH	OVERHAUL	12/05/2000	8188.7	4000 hrs	12188.7	3007.6	992.4	01/12/2027
29		ENGINE HYDRAULIC PUMP	RH	OVERHAUL	6/07/2013	10274.0	2000 hrs	12274.0	922.3	1077.7	04/07/2027
27		AIRBRAKE JACK	RH	OVERHAUL	10/21/2005	9284.7	3000 hrs	12284.7	1911.6	1088.4	04/18/2027
71	*	ENGINE REAR MOUNT ATTACH BOLT	RH	REPLACE	6/07/2013	10274.0	2100 hrs	12374.0	922.3	1177.7	07/16/2027
530033	*	FUSELAGE SKIN ADJ CAB WINDOW CUTOUT		INSPECT	8/20/2021	10559.0	2400 hrs	12959.0	637.3	1762.7	02/20/2029
27		AIRBRAKE JACK	LH	OVERHAUL	2/04/2012	10126.5	3000 hrs	13126.5	1069.8	1930.2	08/07/2029
570025	*	WING STRUCTURE FWD OF CENTER SPAR	LH	INSPECT	8/20/2021	10559.0	4800 hrs	15359.0	637.3	4162.7	08/20/2029
570025	*	WING STRUCTURE FWD OF CENTER SPAR	RH	INSPECT	8/20/2021	10559.0	4800 hrs	15359.0	637.3	4162.7	08/20/2029
24		INVERTER SUPPLY CONTACTOR	#1	OVERHAUL	2/11/2011	9976.5	5000 hrs	14976.5	1219.8	3780.2	08/31/2034
32		BRAKE EMERGENCY SYS PRESSURE SWITCH	LH	OVERHAUL	9/13/2012	10184.6	5000 hrs	15184.6	1011.7	3988.3	03/27/2035
32		BRAKE EMERGENCY SYS PRESSURE SWITCH	RH	OVERHAUL	9/13/2012	10184.6	5000 hrs	15184.6	1011.7	3988.3	03/27/2035
570026	*	WING BOTTOM SKIN @ ATTACH FRT SPAR	LH	INSPECT	8/20/2021	10559.0	4800 hrs	15359.0	637.3	4162.7	09/17/2035
570026	*	WING BOTTOM SKIN @ ATTACH FRT SPAR	RH	INSPECT	8/20/2021	10559.0	4800 hrs	15359.0	637.3	4162.7	09/17/2035
570027	*	LOWER WING SKIN CNTRLNE JOINT STRAP	LH	INSPECT	8/20/2021	10559.0	9600 hrs	20159.0	637.3	8962.7	11/07/2048
570027	*	LOWER WING SKIN CNTRLNE JOINT STRAP	RH	INSPECT	8/20/2021	10559.0	9600 hrs	20159.0	637.3	8962.7	11/07/2048
570028	*	UPR SURFACE OF LWR WING SKIN(X-RAY)	LH	NDT	8/20/2021	10559.0	9600 hrs	20159.0	637.3	8962.7	11/07/2048
570028	*	UPR SURFACE OF LWR WING SKIN(X-RAY)	RH	NDT	8/20/2021	10559.0	9600 hrs	20159.0	637.3	8962.7	11/07/2048
530030	*	ENGINE BEAM INSPECTION	LH		8/20/2021	10559.0	10000 hrs	20559.0	637.3	9362.7	12/12/2049
530030	*	ENGINE BEAM INSPECTION	RH		8/20/2021	10559.0	10000 hrs	20559.0	637.3	9362.7	12/12/2049
530031	*	ENG MAIN MOUNT ATTACH FITTNG (INSP)	LH	NDT	8/20/2021	10559.0	10000 hrs	20559.0	637.3	9362.7	12/12/2049
530031	*	ENG MAIN MOUNT ATTACH FITTNG (INSP)	RH	NDT	8/20/2021	10559.0	10000 hrs	20559.0	637.3	9362.7	12/12/2049
570029	*	WING SKIN CNTR BUTT STRAP (INSPECT)	LH LOWER	NDT	8/20/2021	10559.0	12000 hrs	22559.0	637.3	11362.7	06/04/2055
570029	*	WING SKIN CNTR BUTT STRAP (INSPECT)	RH LOWER	NDT	8/20/2021	10559.0	12000 hrs	22559.0	637.3	11362.7	06/04/2055
530032	*	ENG REAR MOUNT ATTACH FITTNG (INSP)	LH	NDT	8/20/2021	10559.0	20000 hrs	30559.0	637.3	19362.7	04/29/2077
530032	*	ENG REAR MOUNT ATTACH FITTNG (INSP)	RH	NDT	8/20/2021	10559.0	20000 hrs	30559.0	637.3	19362.7	04/29/2077

AIRFRAME HOURS REPORT

4/25/2024

HS-125 257208

N2787

ATA CODE	F A A	D E S C R I P T I O N	LOCATION	ACTION	ACCOMPLISHED		INTERVAL	HOURS			TARGET DATE
					DATE	HOURS		NEXT DUE	CURRENT	REMAINING	
23		COCKPIT VOICE RECORDER		MTBF	2/09/2016	10342.2	30000 hrs	40286.8	909.5	29090.5	12/18/2103
550021	*	VERT STAB ROOT ATTACH TO FUSE (X-RAY)		NDT	8/20/2021	10559.0	30000 hrs	40559.0	637.3	29362.7	09/15/2104

NOTE: * INDICATES FAA MANDATORY REQUIREMENT.

CALENDAR REPORT

4/25/2024

HS-125 257208

N2787

ATA CODE	F A A	DESCRIPTION	LOCATION	ACTION	DATE ACCOMPLISHED	INTERVAL	DATE DUE
25	*	LIFE VEST RECERTIFICATION			12/01/1984	5 yrs	12/01/1989
340015	*	STALL WARNING SYSTEM PIPELINES		INSPECT	8/29/2008	8 yrs	08/29/2016
30		AIRFRAME DE-ICE SYS RESTRICTOR VAL		OVERHAUL	9/13/2012	4 yrs	09/13/2016
30		WINDSHIELD DE-ICE NON RETURN VALVE		OVERHAUL	9/13/2012	4 yrs	09/13/2016
30		AIRFRAME DE-ICE SYS CHECK VALVE		OVERHAUL	9/13/2012	4 yrs	09/13/2016
33		EMERGENCY EXIT LIGHT UNIT		TEST	2/09/2016	1 yrs	02/09/2017
33		EMERGENCY EXIT LIGHT	FWD	BENCH CK	2/09/2016	12 mos	02/09/2017
33		EMERGENCY EXIT LIGHT	AFT	BENCH CK	2/09/2016	12 mos	02/09/2017
99	*	AD 2015-08-07 OXY MASK REG HARNESS				24 mos	06/16/2017
32		MAIN GEAR REVERSING VALVE	RH	OVERHAUL	7/01/2005	12 yrs	07/01/2017
32		MAIN GEAR LEG ASSEMBLY	LH	OVERHAUL	7/01/2005	12 yrs	07/01/2017
32		MAIN GEAR LEG ASSEMBLY	RH	OVERHAUL	7/01/2005	12 yrs	07/01/2017
32		MAIN GEAR SIDE STAY	LH	OVERHAUL	7/01/2005	12 yrs	07/01/2017
32		MAIN GEAR SIDE STAY	RH	OVERHAUL	7/01/2005	12 yrs	07/01/2017
32		NOSE GEAR DRAG STAY		OVERHAUL	7/01/2005	12 yrs	07/01/2017
26	*	FIRE EXTINGUISHER FIRED FUSE	#1	REPLACE	9/15/2014	3 yrs	09/15/2017
26	*	FIRE EXTINGUISHER FIRED FUSE	#2	REPLACE	9/15/2014	3 yrs	09/15/2017
32		MAIN GEAR REVERSING VALVE	LH	OVERHAUL	1/20/2006	12 yrs	01/20/2018
32		MAIN GEAR SEQUENCE VALVE	LH	OVERHAUL	1/20/2006	12 yrs	01/20/2018
32		MAIN GEAR SEQUENCE VALVE	RH	OVERHAUL	1/20/2006	12 yrs	01/20/2018
32		NOSE GEAR LEG ASSEMBLY		OVERHAUL	4/24/2006	12 yrs	04/24/2018
320039	*	NOSE STEERING PIVOT PIN		MAG PART	4/24/2006	12 yrs	04/24/2018
26	*	FIRE EXTINGUISHER FIRED FUSE (MFG)	#1	REPLACE	4/30/2014	4 yrs	04/30/2018
26	*	FIRE EXTINGUISHER FIRED FUSE (MFG)	#2	REPLACE	4/30/2014	4 yrs	04/30/2018
24		AC GENERATOR	RH	OVERHAUL	1/06/2014	5 yrs	01/06/2019
33		INERTIA SWITCH, EMERG LIGHTING		OVERHAUL	2/09/2016	3 yrs	02/09/2019
26	*	OVERHEAT DETECTOR SWITCHES	EQUIP BAY	CALIBRATE	9/15/2014	5 yrs	09/15/2019
21	*	DUCT TEMP SWITCH OVERHEAT WARNING	LH	CALIBRATE	9/15/2014	5 yrs	09/15/2019
21	*	DUCT TEMP SWITCH OVERHEAT WARNING	RH	CALIBRATE	9/15/2014	5 yrs	09/15/2019
26	*	OVERHEAT DETECT SWTCH PYLON FILLETS	LH AFT	CALIBRATE	9/15/2014	5 yrs	09/15/2019
26	*	OVERHEAT DETECT SWTCH PYLON FILLETS	LH FWD	CALIBRATE	9/15/2014	5 yrs	09/15/2019
26	*	OVERHEAT DETECT SWTCH PYLON FILLETS	RH FWD	CALIBRATE	9/15/2014	5 yrs	09/15/2019
26	*	OVERHEAT DETECT SWTCH PYLON FILLETS	RH AFT	CALIBRATE	9/15/2014	5 yrs	09/15/2019
26	*	APU HSRS FIRE DETECTOR	UPPER	CALIBRATE	9/15/2014	5 yrs	09/15/2019
26	*	APU HSRS FIRE DETECTOR	LOWER	CALIBRATE	9/15/2014	5 yrs	09/15/2019
26	*	ENGINE FIRE EXTINGUISHER CARTRIDGE	FWD HEAD A	REPLACE	1/18/2010	10 yrs	01/18/2020
26	*	ENGINE FIRE EXTINGUISHER CARTRIDGE	FWD HEAD B	REPLACE	1/18/2010	10 yrs	01/18/2020
26	*	ENGINE FIRE EXTINGUISHER CARTRIDGE	AFT HEAD A	REPLACE	1/18/2010	10 yrs	01/18/2020
26	*	ENGINE FIRE EXTINGUISHER CARTRIDGE	AFT HEAD B	REPLACE	1/18/2010	10 yrs	01/18/2020
24		AC GENERATOR	LH	OVERHAUL	7/10/2016	5 yrs	07/10/2021
35		OXYGEN MASK	PILOT	OVERHAUL	2/09/2016	6 yrs	02/09/2022
24	*	BATTERY	#3	CAP CHK	8/20/2021	12 mos	08/20/2022
35		PROTECTIVE BREATHING EQUIPMENT		REPLACE	2/27/2013	10 yrs	02/27/2023
98	*	SB 32-184 (NOSE BRIDGE CAST INSP)			8/20/2021	24 mos	08/20/2023

CALENDAR REPORT

4/25/2024

HS-125 257208

N2787

ATA CODE	F A	D E S C R I P T I O N	L O C A T I O N	A C T I O N	D A T E A C C O M P L I S H E D	I N T E R V A L	D A T E D U E
320036	*	NOSE LANDING GEAR BRIDGE CASTING		DYE PEN	8/20/2021	2 yrs	08/20/2023
99	*	AD 80-12-05 (NOSE GEAR BRIDGE CAST)			8/20/2021	2 yrs	08/20/2023
34	*	EMERGENCY POWER SUPPLY	#2	TEST	9/25/2023	3 mos	12/25/2023
300012	*	WINDSHIELD FLUID DEICING SYSTEM		FUNC TEST	9/25/2023	3 mos	12/25/2023
340016	*	EMERGENCY POWER SUPPLY	#1	CAP CHK	9/25/2023	3 mos	12/25/2023
33		EMERGENCY LIGHT FILAMENT		REPLACE	9/25/2023	6 mos	03/25/2024
24	*	BATTERY	#1 (MAIN)	CAP CHK	9/25/2023	6 mos	03/25/2024
24	*	BATTERY	#2 (MAIN)	CAP CHK	9/25/2023	6 mos	03/25/2024
340013	*	COMPASS SWING	MAIN		8/20/2021	36 mos	08/20/2024
340014	*	COMPASS SWING	STANDBY		8/20/2021	36 mos	08/20/2024
12	*	12 MONTH AIRCRAFT LUBE			9/25/2023	12 mos	09/25/2024
26	*	CABIN FIRE EXTINGUISHER		WEIGH	9/25/2023	1 yrs	09/25/2024
26	*	COCKPIT FIRE EXTINGUISHER		WEIGH	9/25/2023	1 yrs	09/25/2024
25	*	LIFE RAFT RECERTIFICATION	#2		9/25/2023	12 mos	09/25/2024
490005	*	APU OIL FILTER ELEMENT		REPLACE	9/25/2023	12 mos	09/25/2024
490004	*	APU OIL CHANGE			9/25/2023	12 mos	09/25/2024
050510	*	INSPECTION E			9/25/2023	12 mos	09/25/2024
25	*	LIFE RAFT RECERTIFICATION	#1		9/25/2023	12 mos	09/25/2024
24	*	EMERGENCY POWER SUPPLY	#2	DEEP CYL	9/25/2023	12 mos	09/25/2024
34	*	EMERGENCY POWER SUPPLY		DEEP CYL	9/25/2023	12 mos	09/25/2024
25	*	ELT (FAR 91.207)		INSPECT	9/25/2023	12 mos	09/25/2024
26	*	ENGINE FIRE EXT CARTRIDGE MANUF DAT	AFT HEAD B	REPLACE	1/18/2010	15 yrs	01/18/2025
26	*	ENGINE FIRE EXT CARTRIDGE MANUF DAT	AFT HEAD A	REPLACE	1/18/2010	15 yrs	01/18/2025
26	*	ENGINE FIRE EXT CARTRIDGE MANUF DAT	FWD HEAD B	REPLACE	1/18/2010	15 yrs	01/18/2025
26	*	ENGINE FIRE EXT CARTRIDGE MANUF DAT	FWD HEAD A	REPLACE	1/18/2010	15 yrs	01/18/2025
550015	*	RUDDER HINGE BRACKETS		INSPECT	8/20/2021	4 yrs	08/20/2025
570012	*	WING TOP SKIN IN AREA OF WING FENCE	LH	INSPECT	8/20/2021	4 yrs	08/20/2025
570024	*	FLAP AND FLAP VANES (X-RAY)	LH	NDT	8/20/2021	4 yrs	08/20/2025
570012	*	WING TOP SKIN IN AREA OF WING FENCE	RH	INSPECT	8/20/2021	4 yrs	08/20/2025
570024	*	FLAP AND FLAP VANES (X-RAY)	RH	NDT	8/20/2021	4 yrs	08/20/2025
570022	*	AIRBRAKE HINGES	LH UPPER	INSPECT	8/20/2021	4 yrs	08/20/2025
530018	*	STRUCTURE ABOVE FLOOR (SOUNDPROOF)		INSPECT	8/20/2021	4 yrs	08/20/2025
530003	*	SKIN UNDER DORSAL INTAKE FWD FRM 19		INSPECT	8/20/2021	4 yrs	08/20/2025
530005	*	SKIN UNDER WING TO FUSELAGE FAIRING	LH	INSPECT	8/20/2021	4 yrs	08/20/2025
530005	*	SKIN UNDER WING TO FUSELAGE FAIRING	RH	INSPECT	8/20/2021	4 yrs	08/20/2025
570011	*	INTERNAL STRUCTURE FRONT/REAR SPAR	LH	INSPECT	8/20/2021	4 yrs	08/20/2025
570014	*	WING FRONT SPAR	LH	INSPECT	8/20/2021	4 yrs	08/20/2025
570011	*	INTERNAL STRUCTURE FRONT/REAR SPAR	RH	INSPECT	8/20/2021	4 yrs	08/20/2025
570014	*	WING FRONT SPAR	RH	INSPECT	8/20/2021	4 yrs	08/20/2025
570015	*	WING REAR SPAR	LH	INSPECT	8/20/2021	4 yrs	08/20/2025
570015	*	WING REAR SPAR	RH	INSPECT	8/20/2021	4 yrs	08/20/2025
570022	*	AIRBRAKE HINGES	RH UPPER	INSPECT	8/20/2021	4 yrs	08/20/2025
570009	*	WING SKINS (X-RAY)	LH LOWER	NDT	8/20/2021	4 yrs	08/20/2025
570009	*	WING SKINS (X-RAY)	RH LOWER	NDT	8/20/2021	4 yrs	08/20/2025

CALENDAR REPORT

4/25/2024

HS-125 257208

N2787

ATA CODE	F A	D E S C R I P T I O N	L O C A T I O N	A C T I O N	D A T E A C C O M P L I S H E D	I N T E R V A L	D A T E D U E
570022	*	AIRBRAKE HINGES	LH LOWER	INSPECT	8/20/2021	4 yrs	08/20/2025
570022	*	AIRBRAKE HINGES	RH LOWER	INSPECT	8/20/2021	4 yrs	08/20/2025
530004	*	SKIN REAR FR 19, UNDER DORSAL TANK		INSPECT	8/20/2021	4 yrs	08/20/2025
530010	*	FLT COMP SKIN & WINDOW FRAME (INSP)		NDT	8/20/2021	4 yrs	08/20/2025
530028	*	ENTRY DOOR SURROUND (OUTWARD OPEN)		INSPECT	8/20/2021	4 yrs	08/20/2025
530019	*	DV WINDOW PANS (DYE PENETRANT)	LH	INSPECT	8/20/2021	4 yrs	08/20/2025
530019	*	DV WINDOW PANS (DYE PENETRANT)	RH	INSPECT	8/20/2021	4 yrs	08/20/2025
570010	*	MAIN GEAR SIDESTAY ATTACH FITTINGS	RH	INSPECT	8/20/2021	4 yrs	08/20/2025
050770	*	INSPECTION G			8/20/2021	48 mos	08/20/2025
530023	*	REAR PRESSURE BULKHEAD (LH)	FRONT FACE	INSPECT	8/20/2021	4 yrs	08/20/2025
550011	*	ELEVATOR BEARINGS/HINGE BRACKETS	LH	INSPECT	8/20/2021	4 yrs	08/20/2025
550011	*	ELEVATOR BEARINGS/HINGE BRACKETS	RH	INSPECT	8/20/2021	4 yrs	08/20/2025
550013	*	ELEVATOR TRIM TAB RODS END BEARINGS	LH	LUBE/REPL	8/20/2021	4 yrs	08/20/2025
550013	*	ELEVATOR TRIM TAB RODS END BEARINGS	RH	LUBE/REPL	8/20/2021	4 yrs	08/20/2025
550016	*	RUDDER BEARINGS		INSPECT	8/20/2021	4 yrs	08/20/2025
550018	*	RUDDER ROD END BEARINGS		LUBE	8/20/2021	4 yrs	08/20/2025
320037	*	MAIN LANDING GEAR FAIRING STRUT	LH	NDT	8/20/2021	4 yrs	08/20/2025
570017	*	AILERON ROD END BEARINGS		LUBE	8/20/2021	4 yrs	08/20/2025
570016	*	AILERON (REMOVED)		INSPECT	8/20/2021	4 yrs	08/20/2025
570018	*	AILERON 'A' LEVERS/CONNECTING LINKS		INSPECT	8/20/2021	4 yrs	08/20/2025
570023	*	AILERON ASSEMBLY & TABS (X-RAY)	LH	NDT	8/20/2021	4 yrs	08/20/2025
570020	*	AILERON PULLEY DRUMS		INSPECT	8/20/2021	4 yrs	08/20/2025
570023	*	AILERON ASSEMBLY & TABS (X-RAY)	RH	NDT	8/20/2021	4 yrs	08/20/2025
570021	*	AILERON HINGES & ATTACHMENTS		INSPECT	8/20/2021	4 yrs	08/20/2025
550014	*	ELEVATOR TRIM SCREWJACKS		INSPECT	8/20/2021	4 yrs	08/20/2025
570019	*	AILERON TRIM SCREWJACKS		INSPECT	8/20/2021	4 yrs	08/20/2025
12	*	48 MONTH AIRCRAFT LUBE			8/20/2021	48 mos	08/20/2025
520006	*	ESCAPE HATCH		INSPECT	8/20/2021	4 yrs	08/20/2025
550005	*	HORIZONTAL STABILIZER ASSEMBLY		INSPECT	8/20/2021	4 yrs	08/20/2025
320037	*	MAIN LANDING GEAR FAIRING STRUT	RH	NDT	8/20/2021	4 yrs	08/20/2025
550012	*	ELEVATOR ASSEMBLY (X-RAY)	LH	NDT	8/20/2021	4 yrs	08/20/2025
550012	*	ELEVATOR ASSEMBLY (X-RAY)	RH	NDT	8/20/2021	4 yrs	08/20/2025
550017	*	RUDDER ASSEMBLY & TABS (X-RAY)		NDT	8/20/2021	4 yrs	08/20/2025
570010	*	MAIN GEAR SIDESTAY ATTACH FITTINGS	LH	INSPECT	8/20/2021	4 yrs	08/20/2025
34	*	STATIC SYSTEM LEAK CHECK	LH	TEST	9/25/2023	24 mos	09/25/2025
34	*	STATIC SYSTEM LEAK CHECK	RH	TEST	9/25/2023	24 mos	09/25/2025
34	*	TRANSPONDER	#1	TEST	9/25/2023	24 mos	09/25/2025
34	*	TRANSPONDER	#2	TEST	9/25/2023	24 mos	09/25/2025
26	*	APU FIRE EXT CARTRIDGE	FWD	REPLACE	9/25/2023	2 yrs	09/25/2025
23	*	UNDERWATER LOCATOR BEACON/BATTERY	CVR	OPS TEST	9/25/2023	24 mos	09/25/2025
34	*	ALTIMETER	RH	CALIBRATE	9/25/2023	24 mos	09/25/2025
12	*	24 MONTH AIRCRAFT LUBE			9/25/2023	24 mos	09/25/2025
550002	*	VERTICAL STABILIZER RIB 6		INSPECT	9/25/2023	2 yrs	09/25/2025
550003	*	HORIZ/VERT STAB ATTACH FITTINGS		INSPECT	9/25/2023	2 yrs	09/25/2025

CALENDAR REPORT

4/25/2024

HS-125 257208

N2787

ATA CODE	F A	D E S C R I P T I O N	L O C A T I O N	A C T I O N	D A T E A C C O M P L I S H E D	I N T E R V A L	D A T E D U E
34	*	ALTIMETER	LH	CALIBRATE	9/25/2023	24 mos	09/25/2025
050640	*	INSPECTION F			9/25/2023	24 mos	09/25/2025
34	*	RVSM SYSTEM			9/25/2023	24 mos	09/25/2025
550004	*	HORIZ/VERT STAB ATTACH FITTINGS	REAR	INSPECT	9/25/2023	2 yrs	09/25/2025
550023	*	SIDEPLATES,ELEVATOR MASS BAL WT		ANTI CORR	9/25/2023	2 yrs	09/25/2025
34	*	ALTIMETER	STANDBY	CALIBRATE	9/25/2023	24 mos	09/25/2025
34	*	STATIC SYSTEM LEAK CHECK	STAND-BY	TEST	9/25/2023	24 mos	09/25/2025
34	*	AIR DATA COMPUTER	#1	CALIBRATE	9/25/2023	24 mos	09/25/2025
34	*	AIR DATA COMPUTER	#2	CALIBRATE	9/25/2023	24 mos	09/25/2025
26	*	APU FIRE EXTING OPERATING HEAD		REPLACE	2/09/2016	10 yrs	02/09/2026
26	*	APU FIRE EXTINGUISHER		OVERHAUL	8/20/2021	5 yrs	08/20/2026
35	*	OXYGEN CONTAINER (750 LITRE) HYDRO	LH	OVERHAUL	8/20/2021	5 yrs	08/20/2026
35	*	OXYGEN CONTAINER (750 LITRE) HYDRO	RH	OVERHAUL	8/20/2021	5 yrs	08/20/2026
26	*	APU FIRE EXTING PRESS RELIEF PLUG		REPLACE	8/20/2021	5 yrs	08/20/2026
35	*	OXYGEN CONTAINER HYDRO	#3	OVERHAUL	8/20/2021	5 yrs	08/20/2026
25	*	ELT BATTERY REPLACE			8/01/2022	5 yrs	08/01/2027
26	*	COCKPIT FIRE EXTINGUISHER		RECHARGE	8/20/2021	6 yrs	08/20/2027
26	*	CABIN FIRE EXTINGUISHER		RECHARGE	8/20/2021	6 yrs	08/20/2027
35	*	OXYGEN MASK	COPILOT	OVERHAUL	8/20/2021	6 yrs	08/20/2027
26	*	APU FIRE EXT CARTRIDGE MANUF DATE	FWD	REPLACE	9/25/2023	5 yrs	09/25/2028
570025	*	WING STRUCTURE FWD OF CENTER SPAR	LH	INSPECT	8/20/2021	8 yrs	08/20/2029
530024	*	PRESSURE BULKHEAD (FRONT FACE)	REAR	INSPECT	8/20/2021	8 yrs	08/20/2029
530011	*	WING ATTACH LINKS,BRACKETS & BOLTS	LH	INSPECT	8/20/2021	8 yrs	08/20/2029
530011	*	WING ATTACH LINKS,BRACKETS & BOLTS	RH	INSPECT	8/20/2021	8 yrs	08/20/2029
530009	*	VENTRAL FUEL TANK TO FUSELG FAIRING		INSPECT	8/20/2021	8 yrs	08/20/2029
570025	*	WING STRUCTURE FWD OF CENTER SPAR	RH	INSPECT	8/20/2021	8 yrs	08/20/2029
550010	*	HORIZONTAL STAB FOKKER BOND TEST	LH	NDT	8/20/2021	8 yrs	08/20/2029
550010	*	HORIZONTAL STAB FOKKER BOND TEST	RH	NDT	8/20/2021	8 yrs	08/20/2029
530025	*	FUSELAGE STRUCTR BELOW ESCAPE HATCH	FRME 13/14	INSPECT	8/20/2021	8 yrs	08/20/2029
530027	*	FUSELAGE STRUCT FRAME 13-16 (X-RAY)	BLW FLOOR	NDT	8/20/2021	8 yrs	08/20/2029
530026	*	FUSE STRUCT NLG-13 & 16-19(X-RAY)	BLW FLOOR	NDT	8/20/2021	8 yrs	08/20/2029
520007	*	ENTRY DOOR ,OUTWARD OPENING (X-RAY)		NDT	8/20/2021	8 yrs	08/20/2029
550007	*	VERTICAL STABILIZER ASSEMBLY (X-RAY)		NDT	8/20/2021	8 yrs	08/20/2029
530022	*	FUSE STRUCT NLG-13 & 16-19(X-RAY)	BLW FLOOR	NDT	8/20/2021	8 yrs	08/20/2029
550008	*	HORIZ STAB (INTERNAL STRUCTURE)		INSPECT	8/20/2021	8 yrs	08/20/2029
550006	*	HORIZONTAL STABILIZER (FRONT SPAR)		INSPECT	8/20/2021	8 yrs	08/20/2029
530008	*	KEEL SKIN BEHIND VENTRAL FUEL TANK		INSPECT	8/20/2021	8 yrs	08/20/2029
530017	*	COCKPIT STRUCTURE ABOVE FLOOR		INSPECT	8/20/2021	8 yrs	08/20/2029
530029	*	CENTER FUSELAGE STRUCTURE (X-RAY)	ABV FLOOR	NDT	8/20/2021	8 yrs	08/20/2029
530007	*	FUSELAGE SKIN COVER BY VENTRAL TANK		INSPECT	8/20/2021	8 yrs	08/20/2029
530006	*	VENTRAL FUEL TANK & ATTACHMENTS		INSPECT	8/20/2021	8 yrs	08/20/2029
550019	*	HORIZONTAL STAB ASSEMBLY (X-RAY)		NDT	8/20/2021	8 yrs	08/20/2029
550009	*	HORIZ/VERT STAB ATTACH FITTINGS		INSPECT	8/20/2021	8 yrs	08/20/2029
550020	*	HORZ STAB T FITTING & JOINT STRAP		INSPECT	8/20/2021	8 yrs	08/20/2029

CALENDAR REPORT

4/25/2024

HS-125 257208

N2787

ATA CODE	F A A	D E S C R I P T I O N	L O C A T I O N	A C T I O N	D A T E A C C O M P L I S H E D	I N T E R V A L	D A T E D U E
23		UNDERWATER LOCATOR BEACON BATT-CVR		REPLACE	9/25/2023	6 yrs	09/25/2029
05	*	AIRCRAFT REGISTRATION			10/31/2023	7 yrs	10/31/2030
26	*	ENGINE FIRE EXTINGUISHER	RH (FWD)	HYDRO	8/20/2021	10 yrs	08/20/2031
26	*	ENGINE FIRE EXTINGUISHER	LH (AFT)	HYDRO	8/20/2021	10 yrs	08/20/2031
26	*	COCKPIT FIRE EXTINGUISHER		HYDRO	8/20/2021	12 yrs	08/20/2033
26	*	CABIN FIRE EXTINGUISHER		HYDRO	8/20/2021	12 yrs	08/20/2033
530015	*	NOSE LANDING GEAR BAY SIDEWALLS		INSPECT	8/20/2021	12 yrs	08/20/2033

NOTE: * INDICATES FAA MANDATORY REQUIREMENT.

AIRFRAME LANDINGS REPORT

HS-125 257208

4/25/2024

N2787

ATA CODE	F A	DESCRIPTION	LOCATION	ACTION	ACCOMPLISHED		INTERVAL	LANDINGS			TARGET DATE
					DATE	LANDINGS		NEXT DUE	CURRENT	REMAINING	
32		MAIN GEAR REVERSING VALVE	RH	OVERHAUL	7/01/2005	7901	5000 ldg	12788	1827	3173	07/01/2017
32		MAIN GEAR LEG ASSEMBLY	LH	OVERHAUL	7/01/2005	7901	5000 ldg	12901	1714	3286	07/01/2017
32		MAIN GEAR LEG ASSEMBLY	RH	OVERHAUL	7/01/2005	7901	5000 ldg	12901	1714	3286	07/01/2017
32		MAIN GEAR SIDE STAY	LH	OVERHAUL	7/01/2005	7901	5000 ldg	12901	1714	3286	07/01/2017
32		MAIN GEAR SIDE STAY	RH	OVERHAUL	7/01/2005	7901	5000 ldg	12901	1714	3286	07/01/2017
32		NOSE GEAR DRAG STAY		OVERHAUL	7/01/2005	7901	5000 ldg	12901	1714	3286	07/01/2017
32		MAIN GEAR REVERSING VALVE	LH	OVERHAUL	1/20/2006	8013	5000 ldg	13013	1602	3398	01/20/2018
32		MAIN GEAR SEQUENCE VALVE	LH	OVERHAUL	1/20/2006	8013	5000 ldg	13013	1602	3398	01/20/2018
32		MAIN GEAR SEQUENCE VALVE	RH	OVERHAUL	1/20/2006	8013	5000 ldg	13013	1602	3398	01/20/2018
32		NOSE GEAR LEG ASSEMBLY		OVERHAUL	4/24/2006	8062	5000 ldg	13062	1553	3447	04/24/2018
320039	*	NOSE STEERING PIVOT PIN		MAG PART	4/24/2006	8062	5000 ldg	13062	1553	3447	04/24/2018
320038	*	BRAKE PAD WEAR	LH	INSPECT	2/05/2013	9064	75 ldg	9139	551	-476	01/05/2023
320038	*	BRAKE PAD WEAR	RH	INSPECT	2/05/2013	9064	75 ldg	9139	551	-476	01/05/2023
98	*	SB 32-184 (NOSE BRIDGE CAST INSP)			8/20/2021	9221	900 ldg	10121	394	506	08/20/2023
320036	*	NOSE LANDING GEAR BRIDGE CASTING		DYE PEN	8/20/2021	9221	900 ldg	10121	394	506	08/20/2023
99	*	AD 80-12-05 (NOSE GEAR BRIDGE CAST)			8/20/2021	9221	900 ldg	10121	394	506	08/20/2023
32	*	MAIN GEAR JACK CYLINDER HEAD	LH	REPLACE	11/26/1993	4642	5000 ldg	9642	4973	27	05/22/2024
32	*	MAIN GEAR JACK CYLINDER HEAD	RH	REPLACE	7/01/2005	7901	5000 ldg	9642	4973	27	05/22/2024
27	*	FLAP SYNCHRO CABLE ASSY (INNER)	LH	REPLACE	11/26/1993	4642	5000 ldg	9642	4973	27	05/22/2024
27	*	FLAP SYNCHRO CABLE ASSY (INNER)	LH AFT	REPLACE	11/26/1993	4642	5000 ldg	9642	4973	27	05/22/2024
27	*	FLAP SYNCHRO CABLE ASSY (OUTER)	LH	REPLACE	11/26/1993	4642	5000 ldg	9642	4973	27	05/22/2024
27	*	FLAP SYNCHRO CABLE ASSY (OUTER)	LH AFT	REPLACE	11/26/1993	4642	5000 ldg	9642	4973	27	05/22/2024
27	*	FLAP SYNCHRO CABLE ASSY (OUTER)	RH AFT	REPLACE	11/26/1993	4642	5000 ldg	9642	4973	27	05/22/2024
27	*	FLAP SYNCHRO CABLE ASSY (INNER)	RH	REPLACE	11/26/1993	4642	5000 ldg	9642	4973	27	05/22/2024
27	*	FLAP SYNCHRO CABLE ASSY (INNER)	RH AFT	REPLACE	11/26/1993	4642	5000 ldg	9642	4973	27	05/22/2024
32		NOSE GEAR RETRACT JACK		OVERHAUL	11/26/1993	4642	5000 ldg	9642	4973	27	05/22/2024
32		MAIN GEAR RETRACT JACK	LH	OVERHAUL	11/26/1993	4642	5000 ldg	9642	4973	27	05/22/2024
32		MAIN GEAR DOOR JACK	LH	OVERHAUL	11/26/1993	4642	5000 ldg	9642	4973	27	05/22/2024
32		BRAKE MAXARET	LH INBD	OVERHAUL	12/28/1999	6688	3000 ldg	9688	2927	73	07/07/2024
570013	*	LOWER WING SKIN AT FLAP OUTBD HINGE	LH	INSPECT	8/20/2021	9221	600 ldg	9821	394	206	11/17/2024
570013	*	LOWER WING SKIN AT FLAP OUTBD HINGE	RH	INSPECT	8/20/2021	9221	600 ldg	9821	394	206	11/17/2024
27	*	FLAP SYNCHRO CABLE ASSY (OUTER)	RH	REPLACE	11/30/1994	4975	5000 ldg	9975	4640	360	04/20/2025
57	*	AIRBRAKE INBD ATTACH PIVOT BOLT	LH TOP	REPLACE	12/15/1983	0	10000 ldg	10000	9615	385	05/15/2025
57	*	AIRBRAKE INBD ATTACH PIVOT BOLT	RH TOP	REPLACE	12/15/1983	0	10000 ldg	10000	9615	385	05/15/2025
28	*	VENTRAL TANK PICK-UP LINK BOLT	REAR	REPLACE	12/01/1984	0	10000 ldg	10000	9615	385	05/15/2025
530020	*	PRESSURE BULKHEAD SIDE WALL BEAMS	FRONT	INSPECT	8/20/2021	9221	1000 ldg	10221	394	606	12/22/2025
32	*	BRAKE CONTROL VALVE KNIFE EDGE	LH OUTER	REPLACE	6/28/1999	6509	4500 ldg	11009	3106	1394	02/18/2028
32	*	BRAKE CONTROL VALVE KNIFE EDGE	RH OUTER	REPLACE	6/28/1999	6509	4500 ldg	11009	3106	1394	02/18/2028
32	*	BRAKE CONTROL VALVE KNIFE EDGE	INNER	REPLACE	6/28/1999	6509	4500 ldg	11009	3106	1394	02/18/2028
99	*	AD 77-13-02 (BRAKE KNIFE EDGE)			6/28/1999	6509	4500 ldg	11009	3106	1394	02/18/2028
32		BRAKE MAXARET	RH OTBD	OVERHAUL	8/06/2010	8671	3000 ldg	11671	944	2056	12/11/2029
32		BRAKE MAXARET	RH INBD	OVERHAUL	4/04/2012	8923	3000 ldg	11923	692	2308	08/20/2030
32		BRAKE MAXARET	LH OTBD	OVERHAUL	9/13/2012	8987	3000 ldg	11987	628	2372	10/23/2030
32	*	MAIN GEAR SIDESTAY UPPER ARM	LH	REPLACE	12/01/1984	0	12000 ldg	12000	9615	2385	11/05/2030

AIRFRAME LANDINGS REPORT

HS-125 257208

4/25/2024

N2787

ATA CODE	F A	DESCRIPTION	LOCATION	ACTION	ACCOMPLISHED		INTERVAL	LANDINGS			TARGET DATE
					DATE	LANDINGS		NEXT DUE	CURRENT	REMAINING	
32	*	MAIN GEAR SIDESTAY UPPER ARM	RH	REPLACE	12/01/1984	0	12000 ldg	12000	9615	2385	11/05/2030
32	*	MAIN GEAR RETRACTION ARM	LH	REPLACE	12/01/1984	0	12000 ldg	12000	9615	2385	11/05/2030
32	*	MAIN GEAR RETRACTION ARM	RH	REPLACE	12/01/1984	0	12000 ldg	12000	9615	2385	11/05/2030
27		FLAP SCREWJACK & REDUCTION GEARBOX	LH	OVERHAUL	1/20/2006	8013	4000 ldg	12013	1602	2398	11/18/2030
27		FLAP SCREWJACK & REDUCTION GEARBOX	RH	OVERHAUL	1/20/2006	8013	4000 ldg	12013	1602	2398	11/18/2030
29		PRESSURE MAINTAINING VALVE		OVERHAUL	9/02/2003	7520	5000 ldg	12520	2095	2905	04/08/2032
32	*	BRAKE EMER REDUCING VALVE KNIFE EDG	LH	REPLACE	8/29/2008	8411	4500 ldg	12911	1204	3296	05/04/2033
32	*	BRAKE EMER REDUCING VALVE KNIFE EDG	RH	REPLACE	8/29/2008	8411	4500 ldg	12911	1204	3296	05/04/2033
99	*	AD 77-13-11 (BRAKE EMER KNIFE EDGE)			8/29/2008	8411	4500 ldg	12911	1204	3296	05/04/2033
27		FLAP SYNCHRONIZ SYS RECEIVER UNIT		OVERHAUL	8/29/2008	8411	4500 ldg	12911	1204	3296	05/04/2033
98		SB 32-167 (FAIL OF BRAKE KNIFE EDG)	LH/RH		8/29/2008	8411	4500 ldg	12911	1204	3296	05/04/2033
530015	*	NOSE LANDING GEAR BAY SIDEWALLS		INSPECT	8/20/2021	9221	5000 ldg	14221	394	4606	08/20/2033
32		MAIN GEAR DOOR JACK	RH	OVERHAUL	8/29/2008	8411	5000 ldg	13411	1204	3796	09/16/2034
29		FULL FLOW RELIEF VALVE	#2	OVERHAUL	7/17/2012	8971	4500 ldg	13471	644	3856	11/15/2034
29		FULL FLOW RELIEF VALVE	#1	OVERHAUL	7/17/2012	8971	4500 ldg	13471	644	3856	11/15/2034
530013	*	FUSELAGE LAP JOINTS (INSPECT)		NDT	8/20/2021	9221	4500 ldg	13721	394	4106	07/23/2035
32	*	DRAG STRUT PICK UP		REPLACE	12/01/1984	0	13900 ldg	13900	9615	4285	01/18/2036
32		MAIN GEAR RETRACT JACK	RH	OVERHAUL	6/07/2013	9083	5000 ldg	14083	532	4468	07/19/2036
27		FLAP CONTROL UNIT		OVERHAUL	7/14/2006	8105	6000 ldg	14105	1510	4490	08/10/2036
57	*	FLAP HINGE ATTACH ANGLE BOLTS	LH INNER	REPLACE	12/15/1983	0	16000 ldg	16000	9615	6385	10/18/2041
57	*	FLAP HINGE ATTACH ANGLE BOLTS	RH INNER	REPLACE	12/15/1983	0	16000 ldg	16000	9615	6385	10/18/2041
32	*	NOSE LANDING GEAR PIVOT PIN		REPLACE	4/24/2006	8062	16000 ldg	16356	9259	6741	10/09/2042
32	*	MAIN GEAR JACK EYE END	LH	REPLACE	12/01/1984	0	10000 ldg	16944	2671	7329	05/19/2044
32	*	MAIN GEAR JACK EYE END	RH	REPLACE	12/01/1984	0	10000 ldg	16944	2671	7329	05/19/2044
32	*	NOSE STEERING JACK PICK UP		REPLACE	12/01/1984	0	18000 ldg	18000	9615	8385	04/10/2047
32	*	NOSE GEAR PICK-UP TRUNNION BOLTS		REPLACE	4/24/2006	8062	10000 ldg	18062	1553	8447	06/11/2047
32	*	NOSE GEAR RADIUS ROD PICK-UP BOLTS		REPLACE	4/24/2006	8062	10000 ldg	18062	1553	8447	06/11/2047
32	*	NOSE GEAR CONNECTING ROD		REPLACE	12/01/1984	0	20000 ldg	20000	9615	10385	09/30/2052
32	*	NOSE STEERING SLEEVE		REPLACE	12/01/1984	0	20000 ldg	20000	9615	10385	09/30/2052
32	*	MAIN GEAR TORQUE LINK PIN	LH UPPER	REPLACE	12/01/1984	0	20000 ldg	20000	9615	10385	09/30/2052
32	*	MAIN GEAR TORQUE LINK PIN	RH UPPER	REPLACE	12/01/1984	0	20000 ldg	20000	9615	10385	09/30/2052
32	*	MAIN GEAR TORQUE LINK PIN	LH LOWER	REPLACE	12/01/1984	0	20000 ldg	20000	9615	10385	09/30/2052
32	*	MAIN GEAR TORQUE LINK PIN	RH LOWER	REPLACE	12/01/1984	0	20000 ldg	20000	9615	10385	09/30/2052
32	*	NOSE GEAR STEERING JACK EYE END		REPLACE	6/07/2013	9083	14400 ldg	21983	2032	12368	03/06/2058
32	*	MAIN LANDING GEAR JACK DISTANCE PIN	RH	REPLACE	12/01/1984	0	24000 ldg	24000	9615	14385	09/13/2063
32	*	MAIN GEAR UPPER CASING	LH	REPLACE	12/01/1984	0	24000 ldg	24000	9615	14385	09/13/2063
32	*	MAIN GEAR UPPER CASING	RH	REPLACE	12/01/1984	0	24000 ldg	24000	9615	14385	09/13/2063
27	*	AIRBRAKE JACK BODY	LH	REPLACE	12/01/1984	0	25000 ldg	25000	9615	15385	06/09/2066
27	*	AIRBRAKE JACK BODY	RH	REPLACE	12/01/1984	0	25000 ldg	25000	9615	15385	06/09/2066
32	*	MAIN GEAR SIDESTAY LOWER ARM	LH	REPLACE	12/01/1984	0	27000 ldg	27000	9615	17385	11/30/2071
32	*	MAIN GEAR SIDESTAY LOWER ARM	RH	REPLACE	12/01/1984	0	27000 ldg	27000	9615	17385	11/30/2071
32	*	MAIN GEAR PLUNGER TUBE	LH	REPLACE	12/01/1984	0	27000 ldg	27000	9615	17385	11/30/2071
32	*	MAIN GEAR PLUNGER TUBE	RH	REPLACE	12/01/1984	0	27000 ldg	27000	9615	17385	11/30/2071
32	*	NOSE GEAR PLUNGER TUBE		REPLACE	4/24/2006	8062	20000 ldg	28062	1553	18447	10/27/2074

AIRFRAME LANDINGS REPORT

4/25/2024

HS-125 257208

N2787

ATA CODE	F A A	DESCRIPTION	LOCATION	ACTION	ACCOMPLISHED		INTERVAL	LANDINGS			TARGET DATE
					DATE	LANDINGS		NEXT DUE	CURRENT	REMAINING	
530021	*	UPPER CANOPY RAIL AT CANOPY POSTS		INSPECT	8/20/2021	9221	20000 ldg	29221	394	19606	12/29/2077
32	*	MAIN GEAR JACK PIVOT BOLT	RH	REPLACE	12/01/1984	0	30000 ldg	30000	9615	20385	02/16/2080
32	*	NOSE GEAR JACK LOWER PIVOT PIN		REPLACE	4/24/2006	8062	22000 ldg	30062	1553	20447	04/18/2080
32	*	NOSE GEAR AXLE BARREL		REPLACE	4/24/2006	8062	30000 ldg	30356	9259	20741	02/06/2081
32	*	MAIN LANDING GEAR JACK DISTANCE PIN	LH	REPLACE	12/01/1984	0	24000 ldg	31901	1714	22286	05/01/2085
32	*	NOSE GEAR TORQUE LINK	LOWER	REPLACE	12/01/1984	0	32000 ldg	32000	9615	22385	08/08/2085
32	*	MAIN GEAR RETRACTION ARM PIN	LH	REPLACE	12/01/1984	0	32000 ldg	32000	9615	22385	08/08/2085
32	*	MAIN GEAR RETRACTION ARM PIN	RH	REPLACE	12/01/1984	0	32000 ldg	32000	9615	22385	08/08/2085
32	*	NOSE GEAR TORQUE LINK	UPPER	REPLACE	12/01/1984	0	32000 ldg	32000	9615	22385	08/08/2085
32	*	NOSE STEERING PIN		REPLACE	4/24/2006	8062	25000 ldg	33062	1553	23447	07/05/2088
32	*	NOSE STEERING MAIN MEMBER	UPPER	REPLACE	12/01/1984	0	35000 ldg	35000	9615	25385	10/25/2093
32	*	NOSE STEERING MAIN MEMBER	LOWER	REPLACE	12/01/1984	0	35000 ldg	35000	9615	25385	10/25/2093
32	*	MAIN GEAR JACK PIVOT BOLT	LH	REPLACE	12/01/1984	0	30000 ldg	37901	1714	28286	10/05/2101
32	*	NOSE GEAR DRAG STAY BRIDGE CASTING		REPLACE	11/30/1994	4975	33000 ldg	37975	4640	28360	12/18/2101
32	*	NOSE GEAR MAIN CASING BOLT		REPLACE	4/24/2006	8062	33000 ldg	41062	1553	31447	06/01/2110

NOTE: * INDICATES FAA MANDATORY REQUIREMENT.

NON-DESTRUCTIVE TEST REPORT

HS-125 257208

4/25/2024

N2787

ATA CODE	FAA	DESCRIPTION	LOCATION	ACTION	ACCOMPLISHED		INTERVAL	HR/LDG			TARGET DATE
					DATE	HR/LDG		NEXT DUE	CURRENT	REMAINING	
570024	*	FLAP AND FLAP VANES (X-RAY)	LH	NDT	8/20/2021	10559.0	4 yrs				08/20/2025
570024	*	FLAP AND FLAP VANES (X-RAY)	RH	NDT	8/20/2021	10559.0	4 yrs				08/20/2025
570009	*	WING SKINS (X-RAY)	LH LOWER	NDT	8/20/2021	10559.0	4 yrs				08/20/2025
570009	*	WING SKINS (X-RAY)	RH LOWER	NDT	8/20/2021	10559.0	4 yrs				08/20/2025
530010	*	FLT COMP SKIN & WINDOW FRAME (INSP)		NDT	8/20/2021	10559.0	4 yrs				08/20/2025
570024	*	FLAP AND FLAP VANES (X-RAY)	LH	NDT	8/20/2021	10559.0	2400 hrs	12959.0	637.3	1762.7	08/20/2025
570024	*	FLAP AND FLAP VANES (X-RAY)	RH	NDT	8/20/2021	10559.0	2400 hrs	12959.0	637.3	1762.7	08/20/2025
320037	*	MAIN LANDING GEAR FAIRING STRUT	LH	NDT	8/20/2021	10559.0	4 yrs				08/20/2025
570023	*	AILERON ASSEMBLY & TABS (X-RAY)	LH	NDT	8/20/2021	10559.0	4 yrs				08/20/2025
570023	*	AILERON ASSEMBLY & TABS (X-RAY)	RH	NDT	8/20/2021	10559.0	4 yrs				08/20/2025
570023	*	AILERON ASSEMBLY & TABS (X-RAY)	LH	NDT	8/20/2021	10559.0	2400 hrs	12959.0	637.3	1762.7	08/20/2025
570023	*	AILERON ASSEMBLY & TABS (X-RAY)	RH	NDT	8/20/2021	10559.0	2400 hrs	12959.0	637.3	1762.7	08/20/2025
320037	*	MAIN LANDING GEAR FAIRING STRUT	RH	NDT	8/20/2021	10559.0	4 yrs				08/20/2025
550012	*	ELEVATOR ASSEMBLY (X-RAY)	LH	NDT	8/20/2021	10559.0	4 yrs				08/20/2025
550012	*	ELEVATOR ASSEMBLY (X-RAY)	RH	NDT	8/20/2021	10559.0	4 yrs				08/20/2025
550017	*	RUDDER ASSEMBLY & TABS (X-RAY)		NDT	8/20/2021	10559.0	4 yrs				08/20/2025
550010	*	HORIZONTAL STAB FOKKER BOND TEST	LH	NDT	8/20/2021	10559.0	8 yrs				08/20/2029
550010	*	HORIZONTAL STAB FOKKER BOND TEST	RH	NDT	8/20/2021	10559.0	8 yrs				08/20/2029
530027	*	FUSELAGE STRUCT FRAME 13-16 (X-RAY)	BLW FLOOR	NDT	8/20/2021	10559.0	8 yrs				08/20/2029
530026	*	FUSE STRUCT NLG-13 & 16-19 (X-RAY)	BLW FLOOR	NDT	8/20/2021	10559.0	8 yrs				08/20/2029
520007	*	ENTRY DOOR ,OUTWARD OPENING (X-RAY)		NDT	8/20/2021	10559.0	8 yrs				08/20/2029
550007	*	VERTICAL STABILIZER ASSEMBLY (X-RAY)		NDT	8/20/2021	10559.0	8 yrs				08/20/2029
530022	*	FUSE STRUCT NLG-13 & 16-19 (X-RAY)	BLW FLOOR	NDT	8/20/2021	10559.0	8 yrs				08/20/2029
530029	*	CENTER FUSELAGE STRUCTURE (X-RAY)	ABV FLOOR	NDT	8/20/2021	10559.0	8 yrs				08/20/2029
550019	*	HORIZONTAL STAB ASSEMBLY (X-RAY)		NDT	8/20/2021	10559.0	8 yrs				08/20/2029
530013	*	FUSELAGE LAP JOINTS (INSPECT)		NDT	8/20/2021	9221	4500 ldg	13721	394	4106	07/23/2035
570028	*	UPR SURFACE OF LWR WING SKIN (X-RAY)	LH	NDT	8/20/2021	10559.0	9600 hrs	20159.0	637.3	8962.7	11/07/2048
570028	*	UPR SURFACE OF LWR WING SKIN (X-RAY)	RH	NDT	8/20/2021	10559.0	9600 hrs	20159.0	637.3	8962.7	11/07/2048
530031	*	ENG MAIN MOUNT ATTACH FITTNG (INSP)	LH	NDT	8/20/2021	10559.0	10000 hrs	20559.0	637.3	9362.7	12/12/2049
530031	*	ENG MAIN MOUNT ATTACH FITTNG (INSP)	RH	NDT	8/20/2021	10559.0	10000 hrs	20559.0	637.3	9362.7	12/12/2049
570029	*	WING SKIN CNTR BUTT STRAP (INSPECT)	LH LOWER	NDT	8/20/2021	10559.0	12000 hrs	22559.0	637.3	11362.7	06/04/2055
570029	*	WING SKIN CNTR BUTT STRAP (INSPECT)	RH LOWER	NDT	8/20/2021	10559.0	12000 hrs	22559.0	637.3	11362.7	06/04/2055
530032	*	ENG REAR MOUNT ATTACH FITTNG (INSP)	LH	NDT	8/20/2021	10559.0	20000 hrs	30559.0	637.3	19362.7	04/29/2077
530032	*	ENG REAR MOUNT ATTACH FITTNG (INSP)	RH	NDT	8/20/2021	10559.0	20000 hrs	30559.0	637.3	19362.7	04/29/2077
550021	*	VERT STAB ROOT ATTACH TO FUSE (X-RAY)		NDT	8/20/2021	10559.0	30000 hrs	40559.0	637.3	29362.7	09/15/2104

NOTE: * INDICATES FAA MANDATORY REQUIREMENT.

APU REPORT
HS-125 257208

4/25/2024
N2787

ATA CODE	F A A	DESCRIPTION	LOCATION	ACTION	ACCOMPLISHED		INTERVAL	HR/CYC			TARGET DATE
					DATE	HR/CYC		NEXT DUE	CURRENT	REMAINING	
26	*	APU HSRS FIRE DETECTOR	UPPER	CALIBRATE	9/15/2014	10286.8	5 yrs				09/15/2019
26	*	APU HSRS FIRE DETECTOR	LOWER	CALIBRATE	9/15/2014	10286.8	5 yrs				09/15/2019
240031	*	APU STARTER/GENERATOR SPLINE LUBE			9/13/2012	3414.8	300 hrs	3714.8	417.0	-117.0	12/30/2023
240031	*	APU STARTER/GENERATOR BRUSH WEAR		INSPECT	9/13/2012	3414.8	300 hrs	3714.8	417.0	-117.0	12/30/2023
490003	*	APU 500 HOUR INSPECTION			9/09/2009	3221.2	500 hrs	3721.2	610.6	-110.6	01/05/2024
490002	*	APU 250 HOUR INSPECTION			8/10/2016	3582.3	250 hrs	3832.3	249.5	0.5	04/25/2024
490005	*	APU OIL FILTER ELEMENT		REPLACE	9/25/2023	3821.8	12 mos				09/25/2024
490004	*	APU OIL CHANGE			9/25/2023	3821.8	12 mos				09/25/2024
490005	*	APU OIL FILTER ELEMENT		REPLACE	9/25/2023	3821.8	250 hrs	4071.8	10.0	240.0	09/25/2024
490004	*	APU OIL CHANGE			9/25/2023	3821.8	250 hrs	4071.8	10.0	240.0	09/25/2024
26	*	APU FIRE EXT CARTRIDGE	FWD	REPLACE	9/25/2023	11156.2	2 yrs				09/25/2025
49		APU STARTER/GENERATOR		OVERHAUL	9/13/2012	3414.8	1000 hrs	4414.8	417.0	583.0	11/29/2025
26	*	APU FIRE EXTING OPERATING HEAD		REPLACE	2/09/2016	10343.8	10 yrs				02/09/2026
26	*	APU FIRE EXTINGUISHER		OVERHAUL	8/20/2021	10559.0	5 yrs				08/20/2026
26	*	APU FIRE EXTING PRESS RELIEF PLUG		REPLACE	8/20/2021	10559.0	5 yrs				08/20/2026
26	*	APU FIRE EXT CARTRIDGE MANUF DATE	FWD	REPLACE	9/25/2023	11156.2	5 yrs				09/25/2028
490007	*	APU HOT SECTION INSPECTION			9/09/2009	3221.2	2500 hrs	5721.2	610.6	1889.4	06/27/2029

NOTE: * INDICATES FAA MANDATORY REQUIREMENT.

AIRCRAFT UTILIZATION
HS-125 257208

4/25/2024
 N2787

DATE	AIRFRAME		TOTAL FLOWN		LEFT ENGINE		RIGHT ENGINE		APU	APU
	TTSN	LDGS	TTSN	LDGS	TTSN	TCSN	TTSN	TCSN	TTSN	TCSN
4/25/2024	11196.3	9615	40.1	34	10382.9	9051	10529.4	9049	3831.8	3831

**LEFT ENGINE HOURS REPORT
GARRETT P84484**

**4/25/2024
N2787**

TASK NUMBER MAINTENANCE REF	F A A	D E S C R I P T I O N		L O C A T I O N A C T I O N	C O M P #	F I L E I N T E R V A L	L A S T A C C O M P L I S H	R E M A I N I N G H R / C Y C / L D G	C O S T	N E X T D U E
		P A R T N U M B E R	P A R T S E R I A L N U M B E R							
72 TABLE 603,604	*	150-250 HOUR ENG INSPECT		LH		ENG HRS 250 eng	12/23/2014 9496.5	-636.4	PART \$ 0.00 LBR \$ 0.00 MHR: 0.0	07/28/2022 9746.5
		TFE731-3R-1H	P84497							
79 TABLE 603,604	*	SOAP CHECK		LH		ENG HRS 250 eng	12/23/2014 9496.5	-636.4	PART \$ 0.00 LBR \$ 0.00 MHR: 0.0	07/28/2022 9746.5
		TFE731-3R-1H	P84497							
72 TABLE 603,604	*	300-400 HOUR ENG INSPECT		LH		ENG HRS 400 eng	6/07/2013 9460.6	-522.3	PART \$ 0.00 LBR \$ 0.00 MHR: 0.0	11/19/2022 9860.6
		TFE731-3R-1H	P84497							
73 TABLE 603,604	*	FUEL FILTER ELEMENT		LH		ENG HRS 650 eng	7/17/2012 9356.6	-376.3	PART \$ 0.00 LBR \$ 0.00 MHR: 0.0	04/14/2023 10006.6
		897830-1	N/A	REPLACE						
72 SB 72-3106 R15	*	ENGINE MAJOR PERIODIC INSPECTION		LH		ENG HRS 1400 eng	8/02/2007 8770.1	-212.8	PART \$ 0.00 LBR \$ 0.00 MHR: 0.0	09/25/2023 10170.1
		TFE731-3R-1H	P84497							
72 SB 72-3106 R15	*	COMBUSTION PLENUM CASE INSPECTION		LH		ENG HRS 1400 eng	8/02/2007 8770.1	-212.8	PART \$ 0.00 LBR \$ 0.00 MHR: 0.0	09/25/2023 10170.1
		TFE731-3R-1H	P84497							
97 SEE SB		SB 72-3494 (TURBINE BLADES)		LH		ENG HRS 1400 eng	8/02/2007 8770.1	-212.8	PART \$ 0.00 LBR \$ 0.00 MHR: 0.0	09/25/2023 10170.1
72 TABLE 603,604	*	600-800 HOUR ENG INSPECT		LH		ENG HRS 800 eng	6/07/2013 9460.6	-122.3	PART \$ 0.00 LBR \$ 0.00 MHR: 0.0	12/24/2023 10260.6
		TFE731-3R-1H	P84497							
72 TABLE 603,604	*	1000-1500 HOUR ENG INSPECT		LH		ENG HRS 1500 eng	8/02/2007 8770.1	-112.8	PART \$ 0.00 LBR \$ 0.00 MHR: 0.0	01/03/2024 10270.1
		TFE731-3R-1H	P84497							
790002 72-00-00 P.313	*	ENGINE OIL CHANGE		LH		ENG HRS 1200 eng	7/17/2012 9356.6	173.7	PART \$ 0.00 LBR \$ 0.00 MHR: 0.0	10/15/2024 10556.6
		MOBIL 254	N/A							
12 LUBRICATION	*	THRUST CONTROL TELEFLEX CABLE/COUPL		LH		ENG HRS 1400 eng	6/07/2013 9460.6	477.7	PART \$ 0.00 LBR \$ 0.00 MHR: 0.0	08/15/2025 10860.6
		N/A	N/A	LUBE						
72 SB 72-3106 R15	*	ACCESSORY GEARBOX		LH		ENG HRS 4200 eng	12/14/2000 7400.2	1217.3	PART \$ 0.00 LBR \$ 0.00 MHR: 0.0	08/25/2027 11600.2
		TFE731-3R-1H	P84487	INSPECT						
72 SB 72-3106 R15	*	ENGINE COMPRESSOR ZONE INSPECTION		LH		ENG HRS 4200 eng	12/14/2000 7400.2	1217.3	PART \$ 0.00 LBR \$ 0.00 MHR: 0.0	08/25/2027 11600.2
		TFE731-3R-1H	P84487							
97 SEE SB		SB A72-3641 (HP IMPELLER)		LH		ENG HRS 4200 eng	12/14/2000 7400.2	1217.3	PART \$ 0.00 LBR \$ 0.00 MHR: 0.0	08/25/2027 11600.2

**LEFT ENGINE HOURS REPORT
GARRETT P84484**

4/25/2024
N2787

TASK NUMBER MAINTENANCE REF	F A A	D E S C R I P T I O N		LOCATION	COMP #	FILE	LAST	REMAINING HR/CYC/LDG	C O S T		NEXT D U E
		PART NUMBER	PART SERIAL NUMBER	ACTION		INTERVAL	ACCOMPLISH				
99	*	AD 2000-15-09 (HPC IMPELLER)		LH		ENG HRS	12/14/2000	1217.3	PART \$	0.00	08/25/2027
SEE AD						4200 eng	7400.2		LBR \$	0.00	11600.2
									MHR:	0.0	
72	*	FAN SUPPORT ASSEMBLY		LH		ENG HRS	8/02/2007	3277.7	PART \$	0.00	04/15/2033
SB 72-3106 R15		TFE731-3R-1H	P84487	INSPECT		4200 eng	9460.6		LBR \$	0.00	13660.6
									MHR:	0.0	

**LEFT ENGINE CYCLES REPORT
GARRETT P84484**

**4/25/2024
N2787**

TASK NUMBER MAINTENANCE REF	F A A	D E S C R I P T I O N		LOCATION	COMP #	FILE	LAST	REMAINING HR/CYC/LDG	C O S T		NEXT D U E
		PART NUMBER	PART SERIAL NUMBER	ACTION		INTERVAL	ACCOMPLISH				
72 SB 72-3001 R56	*	LP 1ST STAGE AXIAL COMPRESSOR DISC		LH		ENG CYC	7/20/1983	949	PART \$	0.00	11/30/2026
		3072395-1	2-03501-5687	REPLACE		10000	0		LBR \$	0.00	10000
72 SB 72-3001 R56	*	LP 2ND STAGE AXIAL COMPRESSOR DISC		LH		ENG CYC	7/20/1983	949	PART \$	0.00	11/30/2026
		3072396-1	2-12112-842	REPLACE		10000	0		LBR \$	0.00	10000
72 SB 72-3001 R56	*	LP 3RD STAGE AXIAL COMPRESSOR DISC		LH		ENG CYC	7/20/1983	949	PART \$	0.00	11/30/2026
		3072397-1	2-12112-1372	REPLACE		10000	0		LBR \$	0.00	10000
72 SB 72-3001 R56	*	LP 4TH STAGE AXIAL COMPRESSOR DISC		LH		ENG CYC	7/20/1983	949	PART \$	0.00	11/30/2026
		3072398-1	2-03160-2714	REPLACE		10000	0		LBR \$	0.00	10000
72 SB 72-3001 R56	*	LP 2ND STAGE TURBINE ROTOR DISC		LH		ENG CYC	8/02/2007	1697	PART \$	0.00	12/17/2028
		3072542-5	060322905473	REPLACE		3000 cyc	7748		LBR \$	0.00	10748
72 SB 72-3001 R56	*	LP 1ST STAGE TURBINE ROTOR DISC		LH		ENG CYC	8/02/2007	1697	PART \$	0.00	12/17/2028
		3075830-1	060322903237	REPLACE		3000 cyc	7748		LBR \$	0.00	10748
72 SB 72-3001 R56	*	HP ROTOR SEAL PLATE		LH		ENG CYC	7/31/1997	2166	PART \$	0.00	03/31/2030
		3072411-1	1-18040-0307	REPLACE		10000	5388		LBR \$	0.00	11217
72 SB 72-3001 R56	*	LP 3RD STAGE TURBINE ROTOR DISC		LH		ENG CYC	7/31/1997	3337	PART \$	0.00	06/14/2033
		3074096-2	965332201051	REPLACE		7000 cyc	5388		LBR \$	0.00	12388
72 SB 72-3001 R56	*	HP TURBINE WHEEL ROTOR		LH		ENG CYC	12/14/2000	4363	PART \$	0.00	04/05/2036
		3072316-3	000322900544	REPLACE		7000 cyc	6414		LBR \$	0.00	13414
72 SB 72-3001 R56	*	FAN ROTOR DISC & HUB		LH		ENG CYC	11/23/1995	5868	PART \$	0.00	05/19/2040
		3073563-2	5-03229-2571	REPLACE		10000	4919		LBR \$	0.00	14919
72 SB 72-3001 R56	*	HP COMPRESSOR RADIAL IMPELLER		LH		ENG CYC	12/14/2000	7363	PART \$	0.00	06/22/2044
		3075765-1	000322902584	REPLACE		10000	6414		LBR \$	0.00	16414
72 SB 72-3001 R56	*	HP SHOULDERED SHAFT		LH		ENG CYC	12/14/2000	9363	PART \$	0.00	12/13/2049
		3072545-1	00P24042	REPLACE		12000	6414		LBR \$	0.00	18414

RIGHT ENGINE HOURS REPORT GARRETT P84497

4/25/2024
N2787

TASK NUMBER MAINTENANCE REF	F A A	D E S C R I P T I O N		L O C A T I O N A C T I O N	C O M P #	F I L E I N T E R V A L	L A S T A C C O M P L I S H	R E M A I N I N G H R / C Y C / L D G	C O S T	N E X T D U E
		P A R T N U M B E R	P A R T S E R I A L N U M B E R							
72 TABLE 603,604	*	150-250 HOUR ENG INSPECT		RH		ENG HRS 250 eng	6/04/2013 9607.1	-672.3	PART \$ 0.00 LBR \$ 0.00 MHR: 0.0	06/22/2022 9857.1
		TFE731-3R-1H	P-84484							
79 TABLE 603,604	*	SOAP CHECK		RH		ENG HRS 250 eng	6/04/2013 9607.1	-672.3	PART \$ 0.00 LBR \$ 0.00 MHR: 0.0	06/22/2022 9857.1
		TFE731-3R-1H	P-84484							
72 TABLE 603,604	*	300-400 HOUR ENG INSPECT		RH		ENG HRS 400 eng	6/04/2013 9607.1	-522.3	PART \$ 0.00 LBR \$ 0.00 MHR: 0.0	11/19/2022 10007.1
		TFE731-3R-1H	P-84484							
73 TABLE 603,604	*	FUEL FILTER ELEMENT		RH		ENG HRS 650 eng	6/04/2013 9607.1	-272.3	PART \$ 0.00 LBR \$ 0.00 MHR: 0.0	07/27/2023 10257.1
		UNKNOWN	N/A	REPLACE						
72 TABLE 603,604	*	600-800 HOUR ENG INSPECT		RH		ENG HRS 800 eng	6/04/2013 9607.1	-122.3	PART \$ 0.00 LBR \$ 0.00 MHR: 0.0	12/24/2023 10407.1
		TFE731-3R-1H	P-84484							
790002 72-00-00 P.313	*	ENGINE OIL CHANGE		RH		ENG HRS 1200 eng	6/04/2013 9607.1	277.7	PART \$ 0.00 LBR \$ 0.00 MHR: 0.0	01/27/2025 10807.1
		N/A	N/A							
72 SB 72-3106 R15	*	ENGINE MAJOR PERIODIC INSPECTION		RH		ENG HRS 1400 eng	6/04/2013 9607.1	477.7	PART \$ 0.00 LBR \$ 0.00 MHR: 0.0	08/15/2025 11007.1
		TFE731-3R-1H	P-84484							
72 SB 72-3106 R15	*	COMBUSTION PLENUM CASE INSPECTION		RH		ENG HRS 1400 eng	6/04/2013 9607.1	477.7	PART \$ 0.00 LBR \$ 0.00 MHR: 0.0	08/15/2025 11007.1
		3072443-4	1P-42356							
97 SEE SB		SB 72-3494 (TURBINE BLADES)		RH		ENG HRS 1400 eng	6/04/2013 9607.1	477.7	PART \$ 0.00 LBR \$ 0.00 MHR: 0.0	08/15/2025 11007.1
12 LUBRICATION	*	THRUST CONTROL TELEFLEX CABLE/COUPL		RH		ENG HRS 1400 eng	6/07/2013 9607.1	477.7	PART \$ 0.00 LBR \$ 0.00 MHR: 0.0	08/15/2025 11007.1
		N/A	N/A	LUBE						
72 TABLE 603,604	*	1000-1500 HOUR ENG INSPECT		RH		ENG HRS 1500 eng	6/04/2013 9607.1	577.7	PART \$ 0.00 LBR \$ 0.00 MHR: 0.0	11/23/2025 11107.1
		TFE731-3R-1H	P-84484							
72 SB 72-3106 R15	*	ACCESSORY GEARBOX		RH		ENG HRS 4200 eng	1/11/2000 7164.6	835.2	PART \$ 0.00 LBR \$ 0.00 MHR: 0.0	08/08/2026 11364.6
		3070003-11	P-3323	INSPECT						
72 SB 72-3106 R15	*	ENGINE COMPRESSOR ZONE INSPECTION		RH		ENG HRS 4200 eng	1/11/2000 7164.6	835.2	PART \$ 0.00 LBR \$ 0.00 MHR: 0.0	08/08/2026 11364.6
		TFE731-3R-1H	P-84484							
99 SEE AD	*	AD 2000-15-09 (HPC IMPELLER)		RH		ENG HRS 4200 eng	1/11/2000 7164.6	835.2	PART \$ 0.00 LBR \$ 0.00 MHR: 0.0	08/08/2026 11364.6

**RIGHT ENGINE HOURS REPORT
GARRETT P84497**

4/25/2024
N2787

TASK NUMBER MAINTENANCE REF	F A A	D E S C R I P T I O N		LOCATION	COMP #	FILE	LAST	REMAINING HR/CYC/LDG	C O S T		NEXT D U E
		PART NUMBER	PART SERIAL NUMBER	ACTION		INTERVAL	ACCOMPLISH				
97		SB A72-3641 (HP IMPELLER)		RH		ENG HRS	1/11/2000	835.2	PART \$	0.00	08/08/2026
SEE SB						4200 eng	7164.6		LBR \$	0.00	11364.6
								MHR:	0.0		
72	*	FAN SUPPORT ASSEMBLY		RH		ENG HRS	6/04/2013	3277.7	PART \$	0.00	04/15/2033
SB 72-3106 R15		TFE731-3R-1H	P-84484	INSPECT		4200 eng	9607.1		LBR \$	0.00	13807.1
								MHR:	0.0		

**RIGHT ENGINE CYCLES REPORT
GARRETT P84497**

**4/25/2024
N2787**

TASK NUMBER MAINTENANCE REF	F A A	D E S C R I P T I O N		L O C A T I O N A C T I O N	C O M P #	F I L E I N T E R V A L	L A S T A C C O M P L I S H	R E M A I N I N G H R / C Y C / L D G	C O S T	N E X T D U E
		P A R T N U M B E R	P A R T S E R I A L N U M B E R							
72 SB 72-3001 R56	*	LP 1ST STAGE AXIAL COMPRESSOR DISC		RH		ENG CYC 10000 ----	4/07/1983 0	951	PART \$ 0.00 LBR \$ 0.00 MHR: 0.0	12/02/2026 10000
		3072395-1	2-03501-01433	REPLACE						
72 SB 72-3001 R56	*	LP 2ND STAGE AXIAL COMPRESSOR DISC		RH		ENG CYC 10000 ----	9/27/1996 5179	951	PART \$ 0.00 LBR \$ 0.00 MHR: 0.0	12/02/2026 10000
		3072396-1	2-12112-1080	REPLACE						
72 SB 72-3001 R56	*	LP 4TH STAGE AXIAL COMPRESSOR DISC		RH		ENG CYC 10000 ----	4/07/1983 0	951	PART \$ 0.00 LBR \$ 0.00 MHR: 0.0	12/02/2026 10000
		3072398-1	2-03160-2561	REPLACE						
72 SB 72-3001 R56	*	HP ROTOR SEAL PLATE		RH		ENG CYC 10000 ----	4/07/1983 0	951	PART \$ 0.00 LBR \$ 0.00 MHR: 0.0	12/02/2026 10000
		3072411-1	2-18040-3339	REPLACE						
72 SB 72-3001 R56	*	LP 2ND STAGE TURBINE ROTOR DISC		RH		ENG CYC 3000 cyc	2/08/2005 7264	1215	PART \$ 0.00 LBR \$ 0.00 MHR: 0.0	08/23/2027 10264
		3072542-5	040322901958	REPLACE						
72 SB 72-3001 R56	*	LP 1ST STAGE TURBINE ROTOR DISC		RH		ENG CYC 3000 cyc	2/08/2005 7264	1215	PART \$ 0.00 LBR \$ 0.00 MHR: 0.0	08/23/2027 10264
		3075830-1	040322901963	REPLACE						
72 SB 72-3001 R56	*	HP SHOULDERED SHAFT		RH		ENG CYC 12000 ----	4/07/1983 0	2951	PART \$ 0.00 LBR \$ 0.00 MHR: 0.0	05/24/2032 12000
		3072545-1	3P-5547	REPLACE						
72 SB 72-3001 R56	*	HP TURBINE WHEEL ROTOR		RH		ENG CYC 7000 cyc	1/11/2000 6190	4141	PART \$ 0.00 LBR \$ 0.00 MHR: 0.0	08/27/2035 13190
		3072316-3	980322902885	REPLACE						
72 SB 72-3001 R56	*	LP 3RD STAGE TURBINE ROTOR DISC		RH		ENG CYC 7000 cyc	1/11/2000 6190	4141	PART \$ 0.00 LBR \$ 0.00 MHR: 0.0	08/27/2035 13190
		3074096-2	995332200279	REPLACE						
72 SB 72-3001 R56	*	HP COMPRESSOR RADIAL IMPELLER		RH		ENG CYC 10000 ----	6/04/2013 8517	4611	PART \$ 0.00 LBR \$ 0.00 MHR: 0.0	12/09/2036 13660
		3073394-1	9-23365-1736	REPLACE						
72 SB 72-3001 R56	*	LP 3RD STAGE AXIAL COMPRESSOR DISC		RH		ENG CYC 10000 ----	6/04/2013 8517	5302	PART \$ 0.00 LBR \$ 0.00 MHR: 0.0	10/31/2038 14351
		3072397-1	1-03160-1549	REPLACE						
72 SB 72-3001 R56	*	FAN ROTOR DISC & HUB		RH		ENG CYC 10000 ----	6/19/1995 4761	5712	PART \$ 0.00 LBR \$ 0.00 MHR: 0.0	12/15/2039 14761
		3073563-2	5-03229-502	REPLACE						
72 SB 72-3001 R56	*	LP 2ND STAGE AXIAL COMPRESSOR DISC		RH		ENG CYC 20000 ----	6/04/2013 8517	19468	PART \$ 0.00 LBR \$ 0.00 MHR: 0.0	08/13/2077 28517
		3075839-1	12-16204-2164	REPLACE						

MASTER REPORT

4/25/2024

HS-125 257208

N2787

ATA CODE	F A A	DESCRIPTION		ACTION	PART NUMBER PART SERIAL NUMBER	FILE INTERVAL	LAST ACCOMPLISH	TSO/CSO	REMAINING HR/CYC/LDG	NEXT DUE
		LOCATION	MAINTENACE REFERENCE							
05	*	AIRCRAFT REGISTRATION				DATE 7 yrs	10/31/2023			10/31/2030
			FAR							
050050	*	INSPECTION A			N/A	AF HRS 300 hrs	6/23/2023 11099.8	0.0	203.5	11/14/2024 11399.8
			INSPECTION A		N/A					
050120	*	INSPECTION B			N/A	AF HRS 600 hrs	5/26/2023 10959.7	0.0	363.4	4/23/2025 11559.7
			INSPECTION B		N/A					
050250	*	INSPECTION C			N/A	AF HRS 1200 hrs	6/03/2011 10006.6	0.0	10.3	5/05/2024 11206.6
			INSPECTION C		N/A					
050380	*	INSPECTION D			N/A	AF HRS 2400 hrs	9/02/2003 8822.0	0.0	25.7	5/20/2024 11222.0
			INSPECTION D		N/A					
050510	*	INSPECTION E			N/A	DATE 12 mos	9/25/2023 11156.2	0.0		9/25/2024
			INSPECTION E		N/A					
050640	*	INSPECTION F			N/A	DATE 24 mos	9/25/2023 11156.2	0.0		9/25/2025
			INSPECTION F		N/A					
050770	*	INSPECTION G				DATE 48 mos	8/20/2021 10559.0	0.0		8/20/2025
			INSPECTION G							
12	*	12 MONTH AIRCRAFT LUBE			N/A	DATE 12 mos	9/25/2023 11156.2	0.0		9/25/2024
			LUBRICATION		N/A					
12	*	1200 HOUR AIRCRAFT LUBE			N/A	AF HRS 1200 hrs	6/03/2011 10006.6	0.0	10.3	5/05/2024 11206.6
			LUBRICATION		N/A					
12	*	150 HOUR AIRCRAFT LUBE			N/A	AF HRS 150 hrs	9/20/2022 10804.5	0.0	-241.8	OVERDUE 10954.5
			LUBRICATION		N/A					
12	*	24 MONTH AIRCRAFT LUBE			N/A	DATE 24 mos	9/25/2023 11156.2	0.0		9/25/2025
			LUBRICATION		N/A					
12	*	2400 HOUR AIRCRAFT LUBE			N/A	AF HRS 2400 hrs	9/02/2003 8822.0	0.0	25.7	5/20/2024 11222.0
			LUBRICATION		N/A					
12	*	300 HOUR AIRCRAFT LUBE			N/A	AF HRS 300 hrs	6/23/2023 11099.8	0.0	203.5	11/14/2024 11399.8
			LUBRICATION		N/A					

MASTER REPORT

HS-125 257208

4/25/2024

N2787

ATA CODE	F A A	DESCRIPTION		ACTION	PART NUMBER PART SERIAL NUMBER	FILE INTERVAL	LAST ACCOMPLISH	TSO/CSO	REMAINING HR/CYC/LDG	NEXT DUE
		LOCATION	MAINTENACE REFERENCE							
12	*	48 MONTH AIRCRAFT LUBE			N/A	DATE	8/20/2021	0.0		8/20/2025
			LUBRICATION		N/A	48 mos	10559.0			
12	*	600 HOUR AIRCRAFT LUBE			N/A	AF HRS	5/26/2023	0.0	363.4	4/23/2025 11559.7
			LUBRICATION		N/A	600 hrs	10959.7			
12	*	THRUST CONTROL TELEFLEX CABLE/COUPL		LUBE	N/A	ENG HRS	6/07/2013	0.0	477.7	8/15/2025 10860.6
		LH	LUBRICATION		N/A	1400 eng	9460.6			
12	*	THRUST CONTROL TELEFLEX CABLE/COUPL		LUBE	N/A	ENG HRS	6/07/2013	0.0	477.7	8/15/2025 11007.1
		RH	LUBRICATION		N/A	1400 eng	9607.1			
21	*	DUCT TEMP SWITCH OVERHEAT WARNING		CALIBRATE	N/A	DATE	9/15/2014	0.0		OVERDUE
		LH	COMPONENT P.2		N/A	5 yrs	10286.8			
21	*	DUCT TEMP SWITCH OVERHEAT WARNING		CALIBRATE	N/A	DATE	9/15/2014	0.0		OVERDUE
		RH	COMPONENT P.2		N/A	5 yrs	10286.8			
21		MAIN SUPPLY CABIN NON RETURN VALVE		OVERHAUL	AWE124-51A	AF HRS	11/30/1994	5631.6	803.7	7/07/2026 12000.0
			COMPONENT P.2		8910025	12000 hrs	5631.6			
210022	*	COOLING TURBINE OIL DRAIN			N/A	AF HRS	7/10/2016	0.0	-784.5	OVERDUE 10411.8
			OUT PHASE P.2		N/A	50 hrs	10361.8			
23		COCKPIT VOICE RECORDER		MTBF	1603-02-03	AF HRS	2/09/2016	55.4	29090.5	12/18/2103 40286.8
			23-70-03		1279	30000 hrs	10342.2			
23		UNDERWATER LOCATOR BEACON BATT-CVR		REPLACE	266-E0305-00	DATE	9/25/2023	0.0		9/25/2029
			COMPONENT P.2		ST11432	6 yrs	11156.2			
23	*	UNDERWATER LOCATOR BEACON/BATTERY		OPS TEST	266-E0305-00	DATE	9/25/2023	0.0		9/25/2025
		CVR	DUKANE		ST11432	24 mos	11156.2			
24		AC GENERATOR		OVERHAUL	UNKNOWN	DATE	7/10/2016	0.0		OVERDUE
		LH	COMPONENT P.2		UNKNOWN	5 yrs	10361.8			
24		AC GENERATOR		OVERHAUL	UNKNOWN	AF HRS	7/10/2016	0.0	1665.5	OVERDUE 12861.8
		LH	COMPONENT P.2		UNKNOWN	2500 hrs	10361.8			
24		AC GENERATOR		OVERHAUL	BA00501-1	DATE	1/06/2014	0.0		OVERDUE
		RH	COMPONENT P.2		0076	5 yrs	10275.1			

MASTER REPORT

4/25/2024

HS-125 257208

N2787

ATA CODE	F A A	DESCRIPTION		ACTION	PART NUMBER PART SERIAL NUMBER	FILE INTERVAL	LAST ACCOMPLISH	TSO/CSO	REMAINING HR/CYC/LDG	NEXT DUE
		LOCATION	MAINTENACE REFERENCE							
24		AC GENERATOR		OVERHAUL	BA00501-1 0076	AF HRS 2500 hrs	1/06/2014 10275.1	0.0	1578.8	OVERDUE 12775.1
		RH	COMPONENT P.2							
24	*	BATTERY		CAP CHK	RG390E 40340718	DATE 6 mos	9/25/2023 11156.2	0.0		OVERDUE
		#1 (MAIN)	DOC 5-0171							
24	*	BATTERY		CAP CHK	RG390E 40594653	DATE 6 mos	9/25/2023 11156.2	0.0		OVERDUE
		#2 (MAIN)	DOC 5-0171							
24	*	BATTERY		CAP CHK	UNKNOWN UNKNOWN	DATE 12 mos	8/20/2021 10559.0	0.0		OVERDUE
		#3	EMERGENCY 5-0167							
24		BUS TIE CONTACTOR		OVERHAUL	LDA15088C P36443	AF HRS 5000 hrs	1/25/1996 6109.1	0.0	-87.2	OVERDUE 11109.1
			COMPONENT P.2							
24	*	EMERGENCY POWER SUPPLY		DEEP CYL	501-1075-06 1660	DATE 12 mos	9/25/2023 11156.2	0.0		9/25/2024
		#2	24-20-03 P.108							
24		GROUND SUPPLY START CONTACTOR		OVERHAUL	LDG150-Y4 1445	AF HRS 6000 hrs	11/30/1995 6048.1	0.0	851.8	8/24/2026 12048.1
			COMPONENT P.2							
24		INVERTER SUPPLY CONTACTOR		OVERHAUL	LDA200-B18C Y3261	AF HRS 5000 hrs	2/11/2011 9976.5	0.0	3780.2	8/31/2034 14976.5
		#1	COMPONENT P.2							
24		INVERTER SUPPLY CONTACTOR		OVERHAUL	LDA200B-18C 084348	AF HRS 5000 hrs	5/09/1993 4980.0	0.0	-1216.3	OVERDUE 9980.0
		#2	COMPONENT P.2							
24		STARTER GENERATOR		OVERHAUL	23080-005 1763	AF HRS 1000 hrs	2/11/2011 9976.5	0.0	-219.8	OVERDUE 10976.5
		LH	COMPONENT P.2							
24		STARTER GENERATOR		OVERHAUL	23080-005 Y0571	AF HRS 1000 hrs	2/11/2011 9976.5	0.0	-219.8	OVERDUE 10976.5
		RH	COMPONENT P.2							
240031	*	APU STARTER/GENERATOR BRUSH WEAR		INSPECT	23080-005 3477	APU HRS 300 hrs	9/13/2012 3414.8	0.0	-117.0	OVERDUE 3714.8
			OUT PHASE P.3							
240031	*	APU STARTER/GENERATOR SPLINE LUBE			23080-005 3477	APU HRS 300 hrs	9/13/2012 3414.8	0.0	-117.0	OVERDUE 3714.8
			OUT PHASE P.3							
25	*	ELT (FAR 91.207)		INSPECT	N/A N/A	DATE 12 mos	9/25/2023 11156.2	0.0		9/25/2024
			FAR91.207							

MASTER REPORT

4/25/2024

HS-125 257208

N2787

ATA CODE	F A A	DESCRIPTION		ACTION	PART NUMBER PART SERIAL NUMBER	FILE INTERVAL	LAST ACCOMPLISH	TSO/CSO	REMAINING HR/CYC/LDG	NEXT DUE
		LOCATION	MAINTENACE REFERENCE							
25	*	ELT BATTERY REPLACE			452-0133	DATE	8/01/2022			8/01/2027
			FAR91.207		361351-039	5 yrs	11156.2	0.0		
25	*	LIFE RAFT RECERTIFICATION			N/A	DATE	9/25/2023			9/25/2024
		#1	FAR		N/A	12 mos	11156.2	0.0		
25	*	LIFE RAFT RECERTIFICATION			N/A	DATE	9/25/2023			9/25/2024
		#2	FAR		N/A	12 mos	11156.2	0.0		
25	*	LIFE VEST RECERTIFICATION			ALL	DATE	12/01/1984			OVERDUE
			COMPONENT P.3		UNKNOWN	5 yrs	0.0	0.0		
26	*	APU FIRE EXT CARTRIDGE		REPLACE	UNKNOWN	DATE	9/25/2023			9/25/2025
		FWD	LIFE LIMITS REV 10		UNKNOWN	2 yrs	11156.2	0.0		
26	*	APU FIRE EXT CARTRIDGE MANUF DATE		REPLACE	UNKNOWN	DATE	9/25/2023			9/25/2028
		FWD	LIFE LIMITS REV 10		UNKNOWN	5 yrs	11156.2	0.0		
26	*	APU FIRE EXTING OPERATING HEAD		REPLACE	182A	DATE	2/09/2016			2/09/2026
			LIFE LIMITS REV 10		CR8071M	10 yrs	10343.8	0.0		
26	*	APU FIRE EXTING PRESS RELIEF PLUG		REPLACE	182A	DATE	8/20/2021			8/20/2026
			LIFE LIMITS REV 10		CR8071M	5 yrs	10559.0	0.0		
26	*	APU FIRE EXTINGUISHER		OVERHAUL	182A	DATE	8/20/2021			8/20/2026
			OVERHAUL P.7		CR8071M	5 yrs	10559.0	0.0		
26	*	APU HSRS FIRE DETECTOR		CALIBRATE	N/A	DATE	9/15/2014			OVERDUE
		LOWER	COMPONENT P.3		N/A	5 yrs	10286.8	0.0		
26	*	APU HSRS FIRE DETECTOR		CALIBRATE	N/A	DATE	9/15/2014			OVERDUE
		UPPER	COMPONENT P.3		N/A	5 yrs	10286.8	0.0		
26	*	CABIN FIRE EXTINGUISHER		RECHARGE	N/A	DATE	8/20/2021			8/20/2027
			NFPA 10		N/A	6 yrs	10559.0	0.0		
26	*	CABIN FIRE EXTINGUISHER		WEIGH	N/A	DATE	9/25/2023			9/25/2024
			NFPA 10		N/A	1 yrs	11156.2	0.0		
26	*	CABIN FIRE EXTINGUISHER		HYDRO	N/A	DATE	8/20/2021			8/20/2033
			NFPA 10		N/A	12 yrs	10559.0	0.0		

MASTER REPORT

4/25/2024

HS-125 257208

N2787

ATA CODE	F A A	DESCRIPTION		ACTION	PART NUMBER PART SERIAL NUMBER	FILE INTERVAL	LAST ACCOMPLISH	TSO/CSO	REMAINING HR/CYC/LDG	NEXT DUE
		LOCATION	MAINTENACE REFERENCE							
26	*	COCKPIT FIRE EXTINGUISHER		RECHARGE	N/A	DATE	8/20/2021	0.0		8/20/2027
			NFPA 10		N/A	6 yrs	10559.0			
26	*	COCKPIT FIRE EXTINGUISHER		WEIGH	N/A	DATE	9/25/2023	0.0		9/25/2024
			NFPA 10		N/A	1 yrs	11156.2			
26	*	COCKPIT FIRE EXTINGUISHER		HYDRO	N/A	DATE	8/20/2021	0.0		8/20/2033
			NFPA 10		N/A	12 yrs	10559.0			
26	*	ENGINE FIRE EXT CARTRIDGE MANUF DAT		REPLACE	UNKNOWN	DATE	1/18/2010			1/18/2025
		AFT HEAD A	LIFE LIMITS REV 10		0789KL	15 yrs				
26	*	ENGINE FIRE EXT CARTRIDGE MANUF DAT		REPLACE	UNKNOWN	DATE	1/18/2010			1/18/2025
		AFT HEAD B	LIFE LIMITS REV 10		0789KL	15 yrs				
26	*	ENGINE FIRE EXT CARTRIDGE MANUF DAT		REPLACE	UNKNOWN	DATE	1/18/2010			1/18/2025
		FWD HEAD A	LIFE LIMITS REV 10		0809KL	15 yrs				
26	*	ENGINE FIRE EXT CARTRIDGE MANUF DAT		REPLACE	UNKNOWN	DATE	1/18/2010			1/18/2025
		FWD HEAD B	LIFE LIMITS REV 10		0801KL	15 yrs				
26	*	ENGINE FIRE EXTINGUISHER		HYDRO	33200002-3	DATE	8/20/2021	0.0		8/20/2031
		LH (AFT)	COMPONENT P.3		16224C1	10 yrs	10559.0			
26	*	ENGINE FIRE EXTINGUISHER		HYDRO	33200002-3	DATE	8/20/2021	0.0		8/20/2031
		RH (FWD)	COMPONENT P.3		16223C1	10 yrs	10559.0			
26	*	ENGINE FIRE EXTINGUISHER CARTRIDGE		REPLACE	UNKNOWN	DATE	1/18/2010	0.0		OVERDUE
		AFT HEAD A	LIFE LIMITS REV 10		0806KL	10 yrs	9865.9			
26	*	ENGINE FIRE EXTINGUISHER CARTRIDGE		REPLACE	UNKNOWN	DATE	1/18/2010	0.0		OVERDUE
		AFT HEAD B	LIFE LIMITS REV 10		0789KL	10 yrs	9865.9			
26	*	ENGINE FIRE EXTINGUISHER CARTRIDGE		REPLACE	UNKNOWN	DATE	1/18/2010	0.0		OVERDUE
		FWD HEAD A	LIFE LIMITS REV 10		809KL	10 yrs	9865.9			
26	*	ENGINE FIRE EXTINGUISHER CARTRIDGE		REPLACE	UNKNOWN	DATE	1/18/2010	0.0		OVERDUE
		FWD HEAD B	LIFE LIMITS REV 10		0801KL	10 yrs	9865.9			
26	*	FIRE EXTINGUISHER FIRED FUSE		REPLACE	A1003(1)	DATE	9/15/2014	0.0		OVERDUE
		#1	LIFE LIMITS REV 10		N/A	3 yrs	10286.8			

MASTER REPORT

HS-125 257208

4/25/2024

N2787

ATA CODE	F A A	DESCRIPTION		ACTION	PART NUMBER PART SERIAL NUMBER	FILE INTERVAL	LAST ACCOMPLISH	TSO/CSO	REMAINING HR/CYC/LDG	NEXT DUE
		LOCATION	MAINTENACE REFERENCE							
26	*	FIRE EXTINGUISHER FIRED FUSE #2	LIFE LIMITS REV 10	REPLACE	A1003(1) N/A	DATE 3 yrs	9/15/2014 10286.8	0.0		OVERDUE
26	*	FIRE EXTINGUISHER FIRED FUSE (MFG) #1	LIFE LIMITS REV 10	REPLACE	A1003(1) N/A	DATE 4 yrs	4/30/2014			OVERDUE
26	*	FIRE EXTINGUISHER FIRED FUSE (MFG) #2	LIFE LIMITS REV 10	REPLACE	A1003(1) N/A	DATE 4 yrs	4/30/2014	0.0		OVERDUE
26	*	OVERHEAT DETECT SWTCH PYLON FILLETS LH AFT	COMPONENT P.3	CALIBRATE	N/A N/A	DATE 5 yrs	9/15/2014 10286.8	0.0		OVERDUE
26	*	OVERHEAT DETECT SWTCH PYLON FILLETS LH FWD	COMPONENT P.3	CALIBRATE	N/A N/A	DATE 5 yrs	9/15/2014 10286.8	0.0		OVERDUE
26	*	OVERHEAT DETECT SWTCH PYLON FILLETS RH AFT	COMPONENT P.3	CALIBRATE	N/A N/A	DATE 5 yrs	9/15/2014 10286.8	0.0		OVERDUE
26	*	OVERHEAT DETECT SWTCH PYLON FILLETS RH FWD	COMPONENT P.3	CALIBRATE	N/A N/A	DATE 5 yrs	9/15/2014 10286.8	0.0		OVERDUE
26	*	OVERHEAT DETECTOR SWITCHES EQUIP BAY	COMPONENT P.3	CALIBRATE	N/A N/A	DATE 5 yrs	9/15/2014 10286.8	0.0		OVERDUE
260014	*	ENGINE FIRE EXTINGUISHING LH	OUT PHASE P.3	INSPECT	N/A N/A	AF HRS 1400 hrs	6/07/2013 10274.0	0.0	477.7	8/15/2025 11674.0
260014	*	ENGINE FIRE EXTINGUISHING RH	OUT PHASE P.3	INSPECT	N/A N/A	AF HRS 1400 hrs	6/07/2013 10274.0	0.0	477.7	8/15/2025 11674.0
27		AIRBRAKE JACK LH	COMPONENT P.4	OVERHAUL	AIR46520-2 APB3277	AF HRS 3000 hrs	2/04/2012 10126.5	0.0	1930.2	8/07/2029 13126.5
27		AIRBRAKE JACK RH	COMPONENT P.4	OVERHAUL	AIR46521-1 LK0053	AF HRS 3000 hrs	10/21/2005 9284.7	0.0	1088.4	4/18/2027 12284.7
27	*	AIRBRAKE JACK BODY LH	LIFE LIMITS REV 10	REPLACE	AIR111462 UNKNOWN	LANDING 25000 ldg	12/01/1984 0	0	15385	6/09/2066 25000
27	*	AIRBRAKE JACK BODY RH	LIFE LIMITS REV 10	REPLACE	AIR111463 UNKNOWN	LANDING 25000 ldg	12/01/1984 0	0	15385	6/09/2066 25000

MASTER REPORT

HS-125 257208

4/25/2024

N2787

ATA CODE	F A A	DESCRIPTION		ACTION	PART NUMBER PART SERIAL NUMBER	FILE INTERVAL	LAST ACCOMPLISH	TSO/CSO	REMAINING HR/CYC/LDG	NEXT DUE
		LOCATION	MAINTENACE REFERENCE							
27		FLAP CONTROL UNIT		OVERHAUL	614MK2	LANDING 6000 ldg	7/14/2006	0	4490	8/10/2036
			COMPONENT P.4		614-E-535		8105			14105
27		FLAP SCREWJACK & REDUCTION GEARBOX		OVERHAUL	25-8CW-159AB	LANDING 4000 ldg	1/20/2006	0	2398	11/18/2030
		LH	COMPONENT P.4		MEC/DHB/244		8013			12013
27		FLAP SCREWJACK & REDUCTION GEARBOX		OVERHAUL	25-8CW-161AB	LANDING 4000 ldg	1/20/2006	0	2398	11/18/2030
		RH	COMPONENT P.4		MEC/DHB/240		8013			12013
27	*	FLAP SYNCHRO CABLE ASSY (INNER)		REPLACE	25CF3225-19	LANDING 5000 ldg	11/26/1993	0	27	5/22/2024
		LH AFT	LIFE LIMITS REV 10		UNKNOWN		4642			9642
27	*	FLAP SYNCHRO CABLE ASSY (INNER)		REPLACE	25CF3225-17	LANDING 5000 ldg	11/26/1993	0	27	5/22/2024
		LH FORWARD	LIFE LIMITS REV 10		UNKNOWN		4642			9642
27	*	FLAP SYNCHRO CABLE ASSY (INNER)		REPLACE	25CF3225-9	LANDING 5000 ldg	11/26/1993	0	27	5/22/2024
		RH AFT	LIFE LIMITS REV 10		UNKNOWN		4642			9642
27	*	FLAP SYNCHRO CABLE ASSY (INNER)		REPLACE	25CF3225-9	LANDING 5000 ldg	11/26/1993	0	27	5/22/2024
		RH FORWARD	LIFE LIMITS REV 10		UNKNOWN		4642			9642
27	*	FLAP SYNCHRO CABLE ASSY (OUTER)		REPLACE	25CF3225-15	LANDING 5000 ldg	11/26/1993	0	27	5/22/2024
		LH AFT	LIFE LIMITS REV 10		UNKNOWN		4642			9642
27	*	FLAP SYNCHRO CABLE ASSY (OUTER)		REPLACE	25CF3225-3	LANDING 5000 ldg	11/26/1993	0	27	5/22/2024
		LH FORWARD	LIFE LIMITS REV 10		UNKNOWN		4642			9642
27	*	FLAP SYNCHRO CABLE ASSY (OUTER)		REPLACE	25CF3225-15	LANDING 5000 ldg	11/26/1993	0	27	5/22/2024
		RH AFT	LIFE LIMITS REV 10		UNKNOWN		4642			9642
27	*	FLAP SYNCHRO CABLE ASSY (OUTER)		REPLACE	25CF3225-13	LANDING 5000 ldg	11/30/1994	0	360	4/20/2025
		RH FORWARD	LIFE LIMITS REV 10		UNKNOWN		4975			9975
27		FLAP SYNCHRONIZ SYS RECEIVER UNIT		OVERHAUL	617 MK4	LANDING 4500 ldg	8/29/2008	0	3296	5/04/2033
			COMPONENT P.4		M764		8411			12911
28		FUEL BOOST PUMP		OVERHAUL	2070C-11	AF HRS 4000 hrs	12/05/2000	0.0	992.4	1/12/2027
		LH	COMPONENT P.4		164		8188.7			12188.7
28	*	VENTRAL TANK PICK-UP LINK BOLT		REPLACE	25FT373	LANDING 10000 ldg	12/01/1984	0	385	5/15/2025
		REAR	LIFE LIMITS REV 10		UNKNOWN		0			10000

MASTER REPORT

4/25/2024

HS-125 257208

N2787

ATA CODE	F A A	DESCRIPTION		ACTION	PART NUMBER PART SERIAL NUMBER	FILE INTERVAL	LAST ACCOMPLISH	TSO/CSO	REMAINING HR/CYC/LDG	NEXT DUE
		LOCATION	MAINTENACE REFERENCE							
280015	*	FUEL BOOST PUMP BRUSHES WEAR		INSPECT	2070C-11	AF HRS	12/05/2000	0.0	-1007.6	OVERDUE 10188.7
		LH	OUT PHASE P.4		164	2000 hrs	8188.7			
29		EMER BRAKE ACC LOW PRES WARN SWITCH		OVERHAUL	TP42001	AF HRS	9/21/1992	0.0	-1503.1	OVERDUE 9693.2
			COMPONENT P.4		240	5000 hrs	4693.2			
29		ENGINE HYDRAULIC PUMP		OVERHAUL	65WE01030-3-6	AF HRS	8/29/2008	0.0	483.7	8/21/2025 11680.0
		LH	COMPONENT P.4		AO-72-03-D3	2000 hrs	9680.0			
29		ENGINE HYDRAULIC PUMP		OVERHAUL	65WE01030-3-6	AF HRS	6/07/2013	0.0	1077.7	4/07/2027 12274.0
		RH	COMPONENT P.4		A2-245-B3-C3-D3	2000 hrs	10274.0			
29		FULL FLOW RELIEF VALVE		OVERHAUL	AIR45394-0	LANDING	7/17/2012	0	3856	11/15/2034 13471
		#1	COMPONENT P.4		LK8601709	4500 ldg	8971			
29		FULL FLOW RELIEF VALVE		OVERHAUL	AIR45394-0	LANDING	7/17/2012	0	3856	11/15/2034 13471
		#2	COMPONENT P.4		LK8601710	4500 ldg	8971			
29		PRESSURE MAINTAINING VALVE		OVERHAUL	AIR45474-0	LANDING	9/02/2003	0	2905	4/08/2032 12520
			COMPONENT P.4		APB981228	5000 ldg	7520			
290021	*	ENGINE DRIVEN HYDRAULIC PUMP		INSPECT	N/A	AF HRS	6/07/2013	0.0	477.7	8/15/2025 11674.0
		LH	OUT PHASE P.5		N/A	1400 hrs	10274.0			
290021	*	ENGINE DRIVEN HYDRAULIC PUMP		INSPECT	N/A	AF HRS	6/07/2013	0.0	477.7	8/15/2025 11674.0
		RH	OUT PHASE P.5		N/A	1400 hrs	10274.0			
30		AIRFRAME DE-ICE SYS CHECK VALVE		OVERHAUL	WGE150/9	DATE	9/13/2012	0.0		OVERDUE
			COMPONENT P.4		UNKNOWN	4 yrs	10184.6			
30		AIRFRAME DE-ICE SYS CHECK VALVE		OVERHAUL	WGE150/9	AF HRS	9/13/2012	0.0	1988.3	OVERDUE 13184.6
			COMPONENT P.4		UNKNOWN	3000 hrs	10184.6			
30		AIRFRAME DE-ICE SYS RESTRICTOR VAL		OVERHAUL	150-10B	DATE	9/13/2012	0.0		OVERDUE
			COMPONENT P.5		8004098	4 yrs	10184.6			
30		AIRFRAME DE-ICE SYS RESTRICTOR VAL		OVERHAUL	150-10B	AF HRS	9/13/2012	0.0	1988.3	OVERDUE 13184.6
			COMPONENT P.5		8004098	3000 hrs	10184.6			
30		WINDSHIELD DE-ICE NON RETURN VALVE		OVERHAUL	150-9A	DATE	9/13/2012	0.0		OVERDUE
			COMPONENT P.5		7812105	4 yrs	10184.6			

MASTER REPORT

4/25/2024

HS-125 257208

N2787

ATA CODE	F A A	DESCRIPTION		ACTION	PART NUMBER PART SERIAL NUMBER	FILE INTERVAL	LAST ACCOMPLISH	TSO/CSO	REMAINING HR/CYC/LDG	NEXT DUE
		LOCATION	MAINTENACE REFERENCE							
30		WINDSHIELD DE-ICE NON RETURN VALVE		OVERHAUL	150-9A	AF HRS	9/13/2012	0.0	1988.3	OVERDUE 13184.6
			COMPONENT P.5		7812105	3000 hrs	10184.6			
300012	*	WINDSHIELD FLUID DEICING SYSTEM		FUNC TEST	N/A	DATE	9/25/2023	0.0		OVERDUE
			OUT PHASE P.6		N/A	3 mos	11156.2			
32	*	BRAKE CONTROL VALVE KNIFE EDGE		REPLACE	ACO25106	LANDING	6/28/1999	0	1394	2/18/2028 11009
		INNER	LIFE LIMITS REV 10		UNKNOWN	4500 ldg	6509			
32	*	BRAKE CONTROL VALVE KNIFE EDGE		REPLACE	ACO25103	LANDING	6/28/1999	0	1394	2/18/2028 11009
		LH OUTER	LIFE LIMITS REV 10		UNKNOWN	4500 ldg	6509			
32	*	BRAKE CONTROL VALVE KNIFE EDGE		REPLACE	ACO25104	LANDING	6/28/1999	0	1394	2/18/2028 11009
		RH OUTER	LIFE LIMITS REV 10		UNKNOWN	4500 ldg	6509			
32	*	BRAKE EMER REDUCING VALVE KNIFE EDG		REPLACE	ACO34629	LANDING	8/29/2008	0	3296	5/04/2033 12911
		LH	LIFE LIMITS REV 10		UNKNOWN	4500 ldg	8411			
32	*	BRAKE EMER REDUCING VALVE KNIFE EDG		REPLACE	ACO34630	LANDING	8/29/2008	0	3296	5/04/2033 12911
		RH	LIFE LIMITS REV 10		UNKNOWN	4500 ldg	8411			
32		BRAKE EMERGENCY SYS PRESSURE SWITCH		OVERHAUL	TP42000	AF HRS	9/13/2012	0.0	3988.3	3/27/2035 15184.6
		LH	COMPONENT P.7		1146	5000 hrs	10184.6			
32		BRAKE EMERGENCY SYS PRESSURE SWITCH		OVERHAUL	TP42000	AF HRS	9/13/2012	0.0	3988.3	3/27/2035 15184.6
		RH	COMPONENT P.7		1211	5000 hrs	10184.6			
32		BRAKE MAXARET		OVERHAUL	AC65216	LANDING	12/28/1999	0	73	7/07/2024 9688
		LH INBD	COMPONENT P.7		02012	3000 ldg	6688			
32		BRAKE MAXARET		OVERHAUL	AC65218	LANDING	9/13/2012	0	2372	10/23/2030 11987
		LH OTBD	COMPONENT P.7		VP036	3000 ldg	8987			
32		BRAKE MAXARET		OVERHAUL	AC65218	LANDING	4/04/2012	0	2308	8/20/2030 11923
		RH INBD	COMPONENT P.7		NM435	3000 ldg	8923			
32		BRAKE MAXARET		OVERHAUL	AC65216	LANDING	8/06/2010	0	2056	12/11/2029 11671
		RH OTBD	COMPONENT P.7		ZJ120	3000 ldg	8671			
32	*	DRAG STRUT PICK UP		REPLACE	25UN9A	LANDING	12/01/1984	0	4285	1/18/2036 13900
			LIFE LIMITS REV 10		UNKNOWN	13900 ldg	0			

MASTER REPORT

HS-125 257208

4/25/2024

N2787

ATA CODE	F A A	DESCRIPTION		ACTION	PART NUMBER PART SERIAL NUMBER	FILE INTERVAL	LAST ACCOMPLISH	TSO/CSO	REMAINING HR/CYC/LDG	NEXT DUE
		LOCATION	MAINTENACE REFERENCE							
32		MAIN GEAR DOOR JACK		OVERHAUL	AIR48485-3	LANDING 5000 ldg	11/26/1993 4642	0	27	5/22/2024 9642
		LH	COMPONENT P.7		LK8205648					
32		MAIN GEAR DOOR JACK		OVERHAUL	AIR48484-3	LANDING 5000 ldg	8/29/2008 8411	0	3796	9/16/2034 13411
		RH	COMPONENT P.7		APB971635					
32	*	MAIN GEAR JACK CYLINDER HEAD		REPLACE	AIR127866	LANDING 5000 ldg	11/26/1993 4642	0	27	5/22/2024 9642
		LH	LIFE LIMITS REV 10		UNKNOWN					
32	*	MAIN GEAR JACK CYLINDER HEAD		REPLACE	UNKNOWN	LANDING 5000 ldg	7/01/2005 7901	3259	27	5/22/2024 9642
		RH	LIFE LIMITS REV 10		UNKNOWN					
32	*	MAIN GEAR JACK EYE END		REPLACE	AIR158922	LANDING 10000 ldg	12/01/1984 0	-6944	7329	5/19/2044 16944
		LH	LIFE LIMITS REV 10		UNKNOWN					
32	*	MAIN GEAR JACK EYE END		REPLACE	UNKNOWN	LANDING 10000 ldg	12/01/1984 0	-6944	7329	5/19/2044 16944
		RH	LIFE LIMITS REV 10		UNKNOWN					
32	*	MAIN GEAR JACK PIVOT BOLT		REPLACE	25UM153A	LANDING 30000 ldg	12/01/1984 0	-7901	28286	10/05/2101 37901
		LH	LIFE LIMITS REV 10		UNKNOWN					
32	*	MAIN GEAR JACK PIVOT BOLT		REPLACE	UNKNOWN	LANDING 30000 ldg	12/01/1984 0	0	20385	2/16/2080 30000
		RH	LIFE LIMITS REV 10		UNKNOWN					
32		MAIN GEAR LEG ASSEMBLY		OVERHAUL	25-6UM1AG	DATE 12 yrs	7/01/2005	0.0		OVERDUE
		LH	COMPONENT P.6		DHL/DH/1231					
32		MAIN GEAR LEG ASSEMBLY		OVERHAUL	25-6UM1AG	LANDING 5000 ldg	7/01/2005 7901	0	3286	OVERDUE 12901
		LH	COMPONENT P.6		DHL/DH/1231					
32		MAIN GEAR LEG ASSEMBLY		OVERHAUL	25-6UM2AG	DATE 12 yrs	7/01/2005	0.0		OVERDUE
		RH	COMPONENT P.6		DHL/DH1183					
32		MAIN GEAR LEG ASSEMBLY		OVERHAUL	25-6UM2AG	LANDING 5000 ldg	7/01/2005 7901	0	3286	OVERDUE 12901
		RH	COMPONENT P.6		DHL/DH1183					
32	*	MAIN GEAR PLUNGER TUBE		REPLACE	25-8UM-6	LANDING 27000 ldg	12/01/1984 0	0	17385	11/30/2071 27000
		LH	LIFE LIMITS REV 10		UNKNOWN					
32	*	MAIN GEAR PLUNGER TUBE		REPLACE	25-8UM-6	LANDING 27000 ldg	12/01/1984 0	0	17385	11/30/2071 27000
		RH	LIFE LIMITS REV 10		UNKNOWN					

MASTER REPORT

4/25/2024

HS-125 257208

N2787

ATA CODE	F A A	DESCRIPTION		ACTION	PART NUMBER PART SERIAL NUMBER	FILE INTERVAL	LAST ACCOMPLISH	TSO/CSO	REMAINING HR/CYC/LDG	NEXT DUE
		LOCATION	MAINTENACE REFERENCE							
32		MAIN GEAR RETRACT JACK		OVERHAUL	AIR48502-4	LANDING 5000 ldg	11/26/1993	0	27	5/22/2024
		LH	COMPONENT P.6		LK0166		4642			9642
32		MAIN GEAR RETRACT JACK		OVERHAUL	AIR48503-4	LANDING 5000 ldg	6/07/2013	0	4468	7/19/2036
		RH	COMPONENT P.6		LK0087		9083			14083
32	*	MAIN GEAR RETRACTION ARM		REPLACE	UNKNOWN	LANDING 12000 ldg	12/01/1984	0	2385	11/05/2030
		LH	LIFE LIMITS REV 10		UNKNOWN		0			12000
32	*	MAIN GEAR RETRACTION ARM		REPLACE	UNKNOWN	LANDING 12000 ldg	12/01/1984	0	2385	11/05/2030
		RH	LIFE LIMITS REV 10		UNKNOWN		0			12000
32	*	MAIN GEAR RETRACTION ARM PIN		REPLACE	UNKNOWN	LANDING 32000 ldg	12/01/1984	0	22385	8/08/2085
		LH	LIFE LIMITS REV 10		UNKNOWN		0			32000
32	*	MAIN GEAR RETRACTION ARM PIN		REPLACE	UNKNOWN	LANDING 32000 ldg	12/01/1984	0	22385	8/08/2085
		RH	LIFE LIMITS REV 10		UNKNOWN		0			32000
32		MAIN GEAR REVERSING VALVE		OVERHAUL	AIR48542/1	DATE 12 yrs	1/20/2006	0.0		OVERDUE
		LH	COMPONENT P.7		APB012087		9322.0			
32		MAIN GEAR REVERSING VALVE		OVERHAUL	AIR48542/1	LANDING 5000 ldg	1/20/2006	0	3398	OVERDUE
		LH	COMPONENT P.7		APB012087		8013			13013
32		MAIN GEAR REVERSING VALVE		OVERHAUL	AIR48543-1	DATE 12 yrs	7/01/2005	0.0		OVERDUE
		RH	COMPONENT P.7		LK0747					
32		MAIN GEAR REVERSING VALVE		OVERHAUL	AIR48543-1	LANDING 5000 ldg	7/01/2005	113	3173	OVERDUE
		RH	COMPONENT P.7		LK0747		7901			12788
32		MAIN GEAR SEQUENCE VALVE		OVERHAUL	AIR48540/1	DATE 12 yrs	1/20/2006	0.0		OVERDUE
		LH	COMPONENT P.7		LK0582		9322.0			
32		MAIN GEAR SEQUENCE VALVE		OVERHAUL	AIR48540/1	LANDING 5000 ldg	1/20/2006	0	3398	OVERDUE
		LH	COMPONENT P.7		LK0582		8013			13013
32		MAIN GEAR SEQUENCE VALVE		OVERHAUL	AIR48540/1	DATE 12 yrs	1/20/2006	0.0		OVERDUE
		RH	COMPONENT P.7		LK0587		9322.0			
32		MAIN GEAR SEQUENCE VALVE		OVERHAUL	AIR48540/1	LANDING 5000 ldg	1/20/2006	0	3398	OVERDUE
		RH	COMPONENT P.7		LK0587		8013			13013

MASTER REPORT

4/25/2024

HS-125 257208

N2787

ATA CODE	F A A	DESCRIPTION		ACTION	PART NUMBER PART SERIAL NUMBER	FILE INTERVAL	LAST ACCOMPLISH	TSO/CSO	REMAINING HR/CYC/LDG	NEXT DUE
		LOCATION	MAINTENACE REFERENCE							
32		MAIN GEAR SIDE STAY		OVERHAUL	257-UM121AB	DATE	7/01/2005	0.0		OVERDUE
		LH	COMPONENT P.6		DHL/DHI069	12 yrs				
32		MAIN GEAR SIDE STAY		OVERHAUL	257-UM121AB	LANDING	7/01/2005	0	3286	OVERDUE 12901
		LH	COMPONENT P.6		DHL/DHI069	5000 ldg 7901				
32		MAIN GEAR SIDE STAY		OVERHAUL	25-7UM122AB	DATE	7/01/2005	0.0		OVERDUE
		RH	COMPONENT P.6		DHL/DH1064	12 yrs				
32		MAIN GEAR SIDE STAY		OVERHAUL	25-7UM122AB	LANDING	7/01/2005	0	3286	OVERDUE 12901
		RH	COMPONENT P.6		DHL/DH1064	5000 ldg 7901				
32	*	MAIN GEAR SIDESTAY LOWER ARM		REPLACE	25-8UM31-1A	LANDING	12/01/1984	0	17385	11/30/2071 27000
		LH	LIFE LIMITS REV 10		UNKNOWN	27000 ldg				
32	*	MAIN GEAR SIDESTAY LOWER ARM		REPLACE	UNKNOWN	LANDING	12/01/1984	0	17385	11/30/2071 27000
		RH	LIFE LIMITS REV 10		UNKNOWN	27000 ldg				
32	*	MAIN GEAR SIDESTAY UPPER ARM		REPLACE	25-6UM35A/	LANDING	12/01/1984	0	2385	11/05/2030 12000
		LH	LIFE LIMITS REV 10		DHL/DHI069	12000 ldg				
32	*	MAIN GEAR SIDESTAY UPPER ARM		REPLACE	UNKNOWN	LANDING	12/01/1984	0	2385	11/05/2030 12000
		RH	LIFE LIMITS REV 10		UNKNOWN	12000 ldg				
32	*	MAIN GEAR TORQUE LINK PIN		REPLACE	25UM99A	LANDING	12/01/1984	0	10385	9/30/2052 20000
		LH LOWER	LIFE LIMITS REV 10		UNKNOWN	20000 ldg				
32	*	MAIN GEAR TORQUE LINK PIN		REPLACE	25UM99A	LANDING	12/01/1984	0	10385	9/30/2052 20000
		LH UPPER	LIFE LIMITS REV 10		UNKNOWN	20000 ldg				
32	*	MAIN GEAR TORQUE LINK PIN		REPLACE	25UM99A	LANDING	12/01/1984	0	10385	9/30/2052 20000
		RH LOWER	LIFE LIMITS REV 10		UNKNOWN	20000 ldg				
32	*	MAIN GEAR TORQUE LINK PIN		REPLACE	25UM99A	LANDING	12/01/1984	0	10385	9/30/2052 20000
		RH UPPER	LIFE LIMITS REV 10		UNKNOWN	20000 ldg				
32	*	MAIN GEAR UPPER CASING		REPLACE	UNKNOWN	LANDING	12/01/1984	0	14385	9/13/2063 24000
		LH	LIFE LIMITS REV 10		UNKNOWN	24000 ldg				
32	*	MAIN GEAR UPPER CASING		REPLACE	UNKNOWN	LANDING	12/01/1984	0	14385	9/13/2063 24000
		RH	LIFE LIMITS REV 10		UNKNOWN	24000 ldg				

MASTER REPORT

4/25/2024

HS-125 257208

N2787

ATA CODE	F A A	DESCRIPTION		ACTION	PART NUMBER PART SERIAL NUMBER	FILE INTERVAL	LAST ACCOMPLISH	TSO/CSO	REMAINING HR/CYC/LDG	NEXT DUE
		LOCATION	MAINTENACE REFERENCE							
32	*	MAIN LANDING GEAR JACK DISTANCE PIN		REPLACE	25UM423	LANDING 24000 ldg	12/01/1984	-7901	22286	5/01/2085
		LH	LIFE LIMITS REV 10		UNKNOWN		0			31901
32	*	MAIN LANDING GEAR JACK DISTANCE PIN		REPLACE	25UM423	LANDING 24000 ldg	12/01/1984	0	14385	9/13/2063
		RH	LIFE LIMITS REV 10		UNKNOWN		0			24000
32	*	NOSE GEAR AXLE BARREL		REPLACE	25-8UN257-27A	LANDING 30000 ldg	4/24/2006	7706	20741	2/06/2081
			LIFE LIMITS REV 10		UNKNOWN		8062			30356
32	*	NOSE GEAR CONNECTING ROD		REPLACE	UNKNOWN	LANDING 20000 ldg	12/01/1984	0	10385	9/30/2052
			LIFE LIMITS REV 10		UNKNOWN		0			20000
32		NOSE GEAR DRAG STAY		OVERHAUL	25-8UN3AG	DATE 12 yrs	7/01/2005			OVERDUE
			COMPONENT P.6		DHL/DH/465					
32		NOSE GEAR DRAG STAY		OVERHAUL	25-8UN3AG	LANDING 5000 ldg	7/01/2005	0	3286	OVERDUE
			COMPONENT P.6		DHL/DH/465		7901			12901
32	*	NOSE GEAR DRAG STAY BRIDGE CASTING		REPLACE	25UN671-1A	LANDING 33000 ldg	11/30/1994	0	28360	12/18/2101
			LIFE LIMITS REV 10		BA326		4975			37975
32	*	NOSE GEAR JACK LOWER PIVOT PIN		REPLACE	25UN597	LANDING 22000 ldg	4/24/2006	0	20447	4/18/2080
			LIFE LIMITS REV 10		UNKNOWN		8062			30062
32		NOSE GEAR LEG ASSEMBLY		OVERHAUL	25-UN1AZ	DATE 12 yrs	4/24/2006	0.0		OVERDUE
			COMPONENT P.6		DHL/DH/727		9368.5			
32		NOSE GEAR LEG ASSEMBLY		OVERHAUL	25-UN1AZ	LANDING 5000 ldg	4/24/2006	0	3447	OVERDUE
			COMPONENT P.6		DHL/DH/727		8062			13062
32	*	NOSE GEAR MAIN CASING BOLT		REPLACE	25UN603	LANDING 33000 ldg	4/24/2006	0	31447	6/01/2110
			LIFE LIMITS REV 10		UNKNOWN		8062			41062
32	*	NOSE GEAR PICK-UP TRUNNION BOLTS		REPLACE	A102-28J	LANDING 10000 ldg	4/24/2006	0	8447	6/11/2047
			LIFE LIMITS REV 10		UNKNOWN		8062			18062
32	*	NOSE GEAR PLUNGER TUBE		REPLACE	25UN649	LANDING 20000 ldg	4/24/2006	0	18447	10/27/2074
			LIFE LIMITS REV 10		UNKNOWN		8062			28062
32	*	NOSE GEAR RADIUS ROD PICK-UP BOLTS		REPLACE	A102-21J	LANDING 10000 ldg	4/24/2006	0	8447	6/11/2047
			LIFE LIMITS REV 10		UNKNOWN		8062			18062

MASTER REPORT

4/25/2024

HS-125 257208

N2787

ATA CODE	F A A	DESCRIPTION		ACTION	PART NUMBER PART SERIAL NUMBER	FILE INTERVAL	LAST ACCOMPLISH	TSO/CSO	REMAINING HR/CYC/LDG	NEXT DUE
		LOCATION	MAINTENACE REFERENCE							
32		NOSE GEAR RETRACT JACK		OVERHAUL	AIR45404-1	LANDING	11/26/1993	0	27	5/22/2024
			COMPONENT P.6		LK8200318	5000 ldg	4642			9642
32	*	NOSE GEAR STEERING JACK EYE END		REPLACE	AIR110646	LANDING	6/07/2013	1500	12368	3/06/2058
			LIFE LIMITS REV 10		24252	14400 ldg	9083			21983
32	*	NOSE GEAR TORQUE LINK		REPLACE	UNKNOWN	LANDING	12/01/1984	0	22385	8/08/2085
		LOWER	LIFE LIMITS REV 10		UNKNOWN	32000 ldg	0			32000
32	*	NOSE GEAR TORQUE LINK		REPLACE	UNKNOWN	LANDING	12/01/1984	0	22385	8/08/2085
		UPPER	LIFE LIMITS REV 10		UNKNOWN	32000 ldg	0			32000
32	*	NOSE LANDING GEAR PIVOT PIN		REPLACE	25UN645A	LANDING	4/24/2006	7706	6741	10/09/2042
			LIFE LIMITS REV 10		UNKNOWN	16000 ldg	8062			16356
32	*	NOSE STEERING JACK PICK UP		REPLACE	25UN7A/B	LANDING	12/01/1984	0	8385	4/10/2047
			LIFE LIMITS REV 10		UNKNOWN	18000 ldg	0			18000
32	*	NOSE STEERING MAIN MEMBER		REPLACE	UNKNOWN	LANDING	12/01/1984	0	25385	10/25/2093
		LOWER	LIFE LIMITS REV 10		UNKNOWN	35000 ldg	0			35000
32	*	NOSE STEERING MAIN MEMBER		REPLACE	UNKNOWN	LANDING	12/01/1984	0	25385	10/25/2093
		UPPER	LIFE LIMITS REV 10		UNKNOWN	35000 ldg	0			35000
32	*	NOSE STEERING PIN		REPLACE	25UN605	LANDING	4/24/2006	0	23447	7/05/2088
			LIFE LIMITS REV 10			25000 ldg	8062			33062
32	*	NOSE STEERING SLEEVE		REPLACE	UNKNOWN	LANDING	12/01/1984	0	10385	9/30/2052
			LIFE LIMITS REV 10		UNKNOWN	20000 ldg	0			20000
320036	*	NOSE LANDING GEAR BRIDGE CASTING		DYE PEN	N/A	DATE	8/20/2021	0.0		OVERDUE
			STRUCT INSP P.4		N/A	2 yrs	10559.0			
320036	*	NOSE LANDING GEAR BRIDGE CASTING		DYE PEN	N/A	LANDING	8/20/2021	0	506	OVERDUE
			STRUCT INSP P.4		N/A	900 ldg	9221			10121
320037	*	MAIN LANDING GEAR FAIRING STRUT		NDT	N/A	DATE	8/20/2021	0.0		8/20/2025
		LH	STRUCT INSP P.25		N/A	4 yrs	10559.0			
320037	*	MAIN LANDING GEAR FAIRING STRUT		NDT	N/A	DATE	8/20/2021	0.0		8/20/2025
		RH	STRUCT INSP P.25		N/A	4 yrs	10559.0			

MASTER REPORT

HS-125 257208

4/25/2024

N2787

ATA CODE	F A A	DESCRIPTION		ACTION	PART NUMBER PART SERIAL NUMBER	FILE INTERVAL	LAST ACCOMPLISH	TSO/CSO	REMAINING HR/CYC/LDG	NEXT DUE
		LOCATION	MAINTENACE REFERENCE							
320038	*	BRAKE PAD WEAR		INSPECT	N/A	LANDING 75 ldg	2/05/2013 9064	0	-476	OVERDUE 9139
		LH	OUT PHASE P.8		N/A					
320038	*	BRAKE PAD WEAR		INSPECT	N/A	LANDING 75 ldg	2/05/2013 9064	0	-476	OVERDUE 9139
		RH	OUT PHASE P.8		N/A					
320039	*	NOSE STEERING PIVOT PIN		MAG PART	N/A	DATE 12 yrs	4/24/2006 9368.5	0.0		OVERDUE
			OUT PHASE P.8		N/A					
320039	*	NOSE STEERING PIVOT PIN		MAG PART	N/A	LANDING 5000 ldg	4/24/2006 8062	0	3447	OVERDUE 13062
			OUT PHASE P.8		N/A					
33		EMERGENCY EXIT LIGHT		BENCH CK	N/A	DATE 12 mos	2/09/2016 10342.2	0.0		OVERDUE
		AFT	COMPONENT P.8-9		N/A					
33		EMERGENCY EXIT LIGHT		BENCH CK	N/A	DATE 12 mos	2/09/2016 10342.2	0.0		OVERDUE
		FWD	COMPONENT P.8-9		N/A					
33		EMERGENCY EXIT LIGHT UNIT		TEST	N/A	DATE 1 yrs	2/09/2016 10342.2	0.0		OVERDUE
			COMPONENT P.8-9		N/A					
33		EMERGENCY LIGHT FILAMENT		REPLACE	N/A	DATE 6 mos	9/25/2023 11156.2	0.0		OVERDUE
			COMPONENT P.8-9		N/A					
33		EMERGENCY LIGHT INERTIA SWITCH		BENCH CK	18C2-1-5G	AF HRS 1000 hrs	2/09/2016 10342.2	0.0	145.9	9/17/2024 11342.2
			COMPONENT P.8-9		AT9938					
33		INERTIA SWITCH, EMERG LIGHTING		OVERHAUL	18C-2-1-5G	DATE 3 yrs	2/09/2016 10342.2	0.0		OVERDUE
			COMPONENT P.6		AT9938					
33	*	STROBE LIGHT		TEST	N/A	AF HRS 150 hrs	9/15/2014 10286.8	0.0	-759.5	OVERDUE 10436.8
		LH WING	COMPONENT P.7		N/A					
33	*	STROBE LIGHT		TEST	N/A	AF HRS 150 hrs	9/15/2014 10286.8	0.0	-759.5	OVERDUE 10436.8
		RH WING	COMPONENT P.7		N/A					
33	*	STROBE LIGHT		TEST	N/A	AF HRS 150 hrs	9/15/2014 10286.8	0.0	-759.5	OVERDUE 10436.8
		TAIL	COMPONENT P.7		N/A					
34	*	AIR DATA COMPUTER		CALIBRATE	622-5465-651	DATE 24 mos	9/25/2023 11156.2	0.0		9/25/2025
		#1	FAR91.411, 413		2233					

MASTER REPORT

HS-125 257208

4/25/2024

N2787

ATA CODE	F A A	DESCRIPTION		ACTION	PART NUMBER PART SERIAL NUMBER	FILE INTERVAL	LAST ACCOMPLISH	TSO/CSO	REMAINING HR/CYC/LDG	NEXT DUE
		LOCATION	MAINTENACE REFERENCE							
34	*	AIR DATA COMPUTER		CALIBRATE	622-5465-651	DATE	9/25/2023	0.0		9/25/2025
		#2	FAR91.411, 413		158	24 mos	11156.2			
34	*	ALTIMETER		CALIBRATE	UNKNOWN	DATE	9/25/2023	0.0		9/25/2025
		LH	FAR91.411, 413		UNKNOWN	24 mos	11156.2			
34	*	ALTIMETER		CALIBRATE	UNKNOWN	DATE	9/25/2023	0.0		9/25/2025
		RH	FAR91.411, 413		UNKNOWN	24 mos	11156.2			
34	*	ALTIMETER		CALIBRATE	8047/10	DATE	9/25/2023	0.0		9/25/2025
		STANDBY	FAR91.411, 413		06125433B	24 mos	11156.2			
34		ELEVATOR TRIM SERVO/MOTOR		OVERHAUL	622-3260-001	AF HRS	11/30/1994	0.0	-564.7	OVERDUE 10631.6
			COMPONENT P.7		480	5000 hrs	5631.6			
34	*	EMERGENCY POWER SUPPLY		DEEP CYL	501-1075-06	DATE	9/25/2023	0.0		9/25/2024
			24-20-03 P.108		1664	12 mos	11156.2			
34	*	EMERGENCY POWER SUPPLY		TEST	501-1075-06	DATE	9/25/2023	0.0		OVERDUE
		#2	24-20-03 P.108		1660	3 mos	11156.2			
34	*	EMERGENCY POWER SUPPLY		TEST	501-1075-06	AF HRS	9/25/2023	0.0	59.9	OVERDUE 11256.2
		#2	24-20-03 P.108		1660	100 hrs	11156.2			
34	*	RVSM SYSTEM			N/A	DATE	9/25/2023	0.0		9/25/2025
					N/A	24 mos	11156.2			
34	*	STATIC SYSTEM LEAK CHECK		TEST	N/A	DATE	9/25/2023	0.0		9/25/2025
		LH	FAR91.411, 413		N/A	24 mos	11156.2			
34	*	STATIC SYSTEM LEAK CHECK		TEST	N/A	DATE	9/25/2023	0.0		9/25/2025
		RH	FAR91.411, 413		N/A	24 mos	11156.2			
34	*	STATIC SYSTEM LEAK CHECK		TEST	N/A	DATE	9/25/2023	0.0		9/25/2025
		STAND-BY	FAR91.411, 413		N/A	24 mos	11156.2			
34	*	TRANSPONDER		TEST	011-03303-00	DATE	9/25/2023	0.0		9/25/2025
		#1	FAR91.411, 413		3EH026439	24 mos	11156.2			
34	*	TRANSPONDER		TEST	011-03303-00	DATE	9/25/2023	0.0		9/25/2025
		#2	FAR91.411, 413		3EH026856	24 mos	11156.2			

MASTER REPORT

HS-125 257208

4/25/2024

N2787

ATA CODE	F A A	DESCRIPTION		ACTION	PART NUMBER PART SERIAL NUMBER	FILE INTERVAL	LAST ACCOMPLISH	TSO/CSO	REMAINING HR/CYC/LDG	NEXT DUE
		LOCATION	MAINTENACE REFERENCE							
340013	*	COMPASS SWING			N/A	DATE	8/20/2021	0.0		8/20/2024
		MAIN	OUT PHASE P.9		N/A	36 mos	10559.0			
340014	*	COMPASS SWING			N/A	DATE	8/20/2021	0.0		8/20/2024
		STANDBY	OUT PHASE P.9		N/A	36 mos	10559.0			
340015	*	STALL WARNING SYSTEM PIPELINES		INSPECT	N/A	DATE	8/29/2008	0.0		OVERDUE
			OUT PHASE P.9		N/A	8 yrs	9680.0			
340016	*	EMERGENCY POWER SUPPLY		CAP CHK	501-1075-06	DATE	9/25/2023	0.0		OVERDUE
		#1	OUT PHASE P.9		1664	3 mos	11156.2			
35	*	OXYGEN CONTAINER (750 LITRE) HYDRO		OVERHAUL	UNKNOWN	DATE	8/20/2021	0.0		8/20/2026
		LH	COMPONENT P.7		UNKNOWN	5 yrs	10559.0			
35	*	OXYGEN CONTAINER (750 LITRE) HYDRO		OVERHAUL	UNKNOWN	DATE	8/20/2021	0.0		8/20/2026
		RH	COMPONENT P.7		UNKNOWN	5 yrs	10559.0			
35	*	OXYGEN CONTAINER HYDRO		OVERHAUL	UNKNOWN	DATE	8/20/2021	0.0		8/20/2026
		#3	COMPONENT P.7		UNKNOWN	5 yrs	10559.0			
35		OXYGEN MASK		OVERHAUL	UNKNOWN	DATE	8/20/2021	0.0		8/20/2027
		COPILOT	COMPONENT P.7		UNKNOWN	6 yrs	10559.0			
35		OXYGEN MASK		OVERHAUL	MC10-14-01	DATE	2/09/2016	0.0		OVERDUE
		PILOT	COMPONENT P.7		60862	6 yrs	10342.2			
35		PROTECTIVE BREATHING EQUIPMENT		REPLACE	E28180-20-0001	DATE	2/27/2013	0.0		OVERDUE
			LIFE LIMITS REV 10		BEEB-0405	10 yrs	10275.1			
49		APU STARTER/GENERATOR		OVERHAUL	23080-005	APU HRS	9/13/2012	0.0	583.0	11/29/2025
			COMPONENT P.2		3477	1000 hrs	3414.8			
490002	*	APU 250 HOUR INSPECTION			GTCP30-92/C(A)	APU HRS	8/10/2016	0.0	0.5	4/25/2024
			49-20-00		P140	250 hrs	3582.3			
490003	*	APU 500 HOUR INSPECTION			GTCP30-92/C(A)	APU HRS	9/09/2009	0.0	-110.6	OVERDUE
			49-20-00		P140	500 hrs	3221.2			
490004	*	APU OIL CHANGE			N/A	DATE	9/25/2023	0.0		9/25/2024
			49-20-00		N/A	12 mos	3821.8			

MASTER REPORT

HS-125 257208

4/25/2024

N2787

ATA CODE	F A A	DESCRIPTION		ACTION	PART NUMBER PART SERIAL NUMBER	FILE INTERVAL	LAST ACCOMPLISH	TSO/CSO	REMAINING HR/CYC/LDG	NEXT DUE
		LOCATION	MAINTENACE REFERENCE							
490004	*	APU OIL CHANGE			N/A	APU HRS 250 hrs	9/25/2023 3821.8	0.0	240.0	9/25/2024 4071.8
			49-20-00		N/A					
490005	*	APU OIL FILTER ELEMENT		REPLACE	N/A	DATE 12 mos	9/25/2023 3821.8			9/25/2024
			49-20-00		N/A					
490005	*	APU OIL FILTER ELEMENT		REPLACE	N/A	APU HRS 250 hrs	9/25/2023 3821.8		240.0	9/25/2024 4071.8
			49-20-00		N/A					
490007	*	APU HOT SECTION INSPECTION			GTCP30-92/C(A)	APU HRS 2500 hrs	9/09/2009 3221.2	0.0	1889.4	6/27/2029 5721.2
			49-20-00		P140					
520006	*	ESCAPE HATCH		INSPECT	N/A	DATE 4 yrs	8/20/2021 10559.0	0.0		8/20/2025
			STRUCT INSP P.10		N/A					
520007	*	ENTRY DOOR ,OUTWARD OPENING (X-RAY)		NDT	N/A	DATE 8 yrs	8/20/2021 10559.0	0.0		8/20/2029
			STRUCT INSP P.11		N/A					
530003	*	SKIN UNDER DORSAL INTAKE FWD FRM 19		INSPECT	N/A	DATE 4 yrs	8/20/2021 10559.0	0.0		8/20/2025
			STRUCT INSP P.2		N/A					
530004	*	SKIN REAR FR 19,UNDER DORSAL TANK		INSPECT	N/A	DATE 4 yrs	8/20/2021 10559.0	0.0		8/20/2025
			STRUCT INSP P.2		N/A					
530005	*	SKIN UNDER WING TO FUSELAGE FAIRING		INSPECT	N/A	DATE 4 yrs	8/20/2021 10559.0	0.0		8/20/2025
		LH	STRUCT INSP P.2		N/A					
530005	*	SKIN UNDER WING TO FUSELAGE FAIRING		INSPECT	N/A	DATE 4 yrs	8/20/2021 10559.0	0.0		8/20/2025
		RH	STRUCT INSP P.2		N/A					
530006	*	VENTRAL FUEL TANK & ATTACHMENTS		INSPECT	N/A	DATE 8 yrs	8/20/2021 10559.0	0.0		8/20/2029
			STRUCT INSP P.3		N/A					
530007	*	FUSELAGE SKIN COVER BY VENTRAL TANK		INSPECT	N/A	DATE 8 yrs	8/20/2021 10559.0	0.0		8/20/2029
			STRUCT INSP P.3		N/A					
530008	*	KEEL SKIN BEHIND VENTRAL FUEL TANK		INSPECT	N/A	DATE 8 yrs	8/20/2021 10559.0	0.0		8/20/2029
			STRUCT INSP P.3		N/A					
530009	*	VENTRAL FUEL TANK TO FUSELG FAIRING		INSPECT	N/A	DATE 8 yrs	8/20/2021 10559.0	0.0		8/20/2029
			STRUCT INSP P.4		N/A					

MASTER REPORT

HS-125 257208

4/25/2024

N2787

ATA CODE	F A A	DESCRIPTION		ACTION	PART NUMBER PART SERIAL NUMBER	FILE INTERVAL	LAST ACCOMPLISH	TSO/CSO	REMAINING HR/CYC/LDG	NEXT DUE
		LOCATION	MAINTENACE REFERENCE							
530010	*	FLT COMP SKIN & WINDOW FRAME (INSP)		NDT	N/A	DATE	8/20/2021	0.0		8/20/2025
			STRUCT INSP P.4		N/A	4 yrs	10559.0			
530011	*	WING ATTACH LINKS, BRACKETS & BOLTS		INSPECT	N/A	DATE	8/20/2021	0.0		8/20/2029
		LH	STRUCT INSP P.4		N/A	8 yrs	10559.0			
530011	*	WING ATTACH LINKS, BRACKETS & BOLTS		INSPECT	N/A	DATE	8/20/2021	0.0		8/20/2029
		RH	STRUCT INSP P.4		N/A	8 yrs	10559.0			
530013	*	FUSELAGE LAP JOINTS (INSPECT)		NDT	N/A	LANDING	8/20/2021	0	4106	7/23/2035 13721
			STRUCT INSP P.5		N/A	4500 ldg	9221			
530014	*	WINDSHIELD CENTR POST CAPPING STRIP		INSPECT	N/A	AF HRS	8/20/2021	0.0	562.7	11/08/2025 11759.0
		TOP	STRUCT INSP P.5		N/A	1200 hrs	10559.0			
530015	*	NOSE LANDING GEAR BAY SIDEWALLS		INSPECT	N/A	DATE	8/20/2021	0.0		8/20/2033
			STRUCT INSP P.5		N/A	12 yrs	10559.0			
530015	*	NOSE LANDING GEAR BAY SIDEWALLS		INSPECT	N/A	LANDING	8/20/2021	0	4606	8/20/2033 14221
			STRUCT INSP P.5		N/A	5000 ldg	9221			
530017	*	COCKPIT STRUCTURE ABOVE FLOOR		INSPECT	N/A	DATE	8/20/2021	0.0		8/20/2029
			STRUCT INSP P.7		N/A	8 yrs	10559.0			
530018	*	STRUCTURE ABOVE FLOOR (SOUNDPROOF)		INSPECT	N/A	DATE	8/20/2021	0.0		8/20/2025
			STRUCT INSP P.7		N/A	4 yrs	10559.0			
530019	*	DV WINDOW PANS (DYE PENETRANT)		INSPECT	N/A	DATE	8/20/2021	0.0		8/20/2025
		LH	STRUCT INSP P.7		N/A	4 yrs	10559.0			
530019	*	DV WINDOW PANS (DYE PENETRANT)		INSPECT	N/A	DATE	8/20/2021	0.0		8/20/2025
		RH	STRUCT INSP P.7		N/A	4 yrs	10559.0			
530020	*	PRESSURE BULKHEAD SIDE WALL BEAMS		INSPECT	N/A	LANDING	8/20/2021	0	606	12/22/2025 10221
		FRONT	STRUCT INSP P.8		N/A	1000 ldg	9221			
530021	*	UPPER CANOPY RAIL AT CANOPY POSTS		INSPECT	N/A	LANDING	8/20/2021	0	19606	12/29/2077 29221
			STRUCT INSP P.8		N/A	20000 ldg	9221			
530022	*	FUSE STRUCT NLG-13 & 16-19 (X-RAY)		NDT	N/A	DATE	8/20/2021	0.0		8/20/2029
		BLW FLOOR	STRUCT INSP P.9		N/A	8 yrs	10559.0			

MASTER REPORT

4/25/2024

HS-125 257208

N2787

ATA CODE	F A A	DESCRIPTION		ACTION	PART NUMBER PART SERIAL NUMBER	FILE INTERVAL	LAST ACCOMPLISH	TSO/CSO	REMAINING HR/CYC/LDG	NEXT DUE
		LOCATION	MAINTENACE REFERENCE							
530023	*	REAR PRESSURE BULKHEAD (LH)		INSPECT	N/A	DATE	8/20/2021	0.0		8/20/2025
		FRONT FACE	STRUCT INSP P.9		N/A	4 yrs	10559.0			
530024	*	PRESSURE BULKHEAD (FRONT FACE)		INSPECT	N/A	DATE	8/20/2021	0.0		8/20/2029
		REAR	STRUCT INSP P.10		N/A	8 yrs	10559.0			
530025	*	FUSELAGE STRUCTR BELOW ESCAPE HATCH		INSPECT	N/A	DATE	8/20/2021	0.0		8/20/2029
		FRME 13/14	STRUCT INSP P.10		N/A	8 yrs	10559.0			
530026	*	FUSE STRUCT NLG-13 & 16-19(X-RAY)		NDT	N/A	DATE	8/20/2021	0.0		8/20/2029
		BLW FLOOR	STRUCT INSP P.11		N/A	8 yrs	10559.0			
530027	*	FUSELAGE STRUCT FRAME 13-16 (X-RAY)		NDT	N/A	DATE	8/20/2021	0.0		8/20/2029
		BLW FLOOR	STRUCT INSP P.11		N/A	8 yrs	10559.0			
530028	*	ENTRY DOOR SURROUND (OUTWARD OPEN)		INSPECT	N/A	DATE	8/20/2021	0.0		8/20/2025
			STRUCT INSP P.12		N/A	4 yrs	10559.0			
530029	*	CENTER FUSELAGE STRUCTURE (X-RAY)		NDT	N/A	DATE	8/20/2021	0.0		8/20/2029
		ABV FLOOR	STRUCT INSP P.13		N/A	8 yrs	10559.0			
530030	*	ENGINE BEAM INSPECTION			N/A	AF HRS	8/20/2021	0.0	9362.7	12/12/2049
		LH	STRUCT INSP P.14		N/A	10000 hrs	10559.0			
530030	*	ENGINE BEAM INSPECTION			N/A	AF HRS	8/20/2021	0.0	9362.7	12/12/2049
		RH	STRUCT INSP P.14		N/A	10000 hrs	10559.0			
530031	*	ENG MAIN MOUNT ATTACH FITTNG (INSP)		NDT	N/A	AF HRS	8/20/2021	0.0	9362.7	12/12/2049
		LH	STRUCT INSP P.14		N/A	10000 hrs	10559.0			
530031	*	ENG MAIN MOUNT ATTACH FITTNG (INSP)		NDT	N/A	AF HRS	8/20/2021	0.0	9362.7	12/12/2049
		RH	STRUCT INSP P.14		N/A	10000 hrs	10559.0			
530032	*	ENG REAR MOUNT ATTACH FITTNG (INSP)		NDT	N/A	AF HRS	8/20/2021	0.0	19362.7	4/29/2077
		LH	STRUCT INSP P.14		N/A	20000 hrs	10559.0			
530032	*	ENG REAR MOUNT ATTACH FITTNG (INSP)		NDT	N/A	AF HRS	8/20/2021	0.0	19362.7	4/29/2077
		RH	STRUCT INSP P.14		N/A	20000 hrs	10559.0			
530033	*	FUSELAGE SKIN ADJ CAB WINDOW CUTOUT		INSPECT	N/A	AF HRS	8/20/2021	0.0	1762.7	2/20/2029
			STRUCT INSP P.6		N/A	2400 hrs	10559.0			

MASTER REPORT

4/25/2024

HS-125 257208

N2787

ATA CODE	F A A	DESCRIPTION		ACTION	PART NUMBER PART SERIAL NUMBER	FILE INTERVAL	LAST ACCOMPLISH	TSO/CSO	REMAINING HR/CYC/LDG	NEXT DUE
		LOCATION	MAINTENACE REFERENCE							
550002	*	VERTICAL STABILIZER RIB 6		INSPECT	N/A	DATE	9/25/2023	0.0		9/25/2025
			STRUCT INSP P.15		N/A	2 yrs	11156.2			
550002	*	VERTICAL STABILIZER RIB 6		INSPECT	N/A	AF HRS	9/25/2023	0.0	1159.9	9/25/2025 12356.2
			STRUCT INSP P.15		N/A	1200 hrs	11156.2			
550003	*	HORIZ/VERT STAB ATTACH FITTINGS		INSPECT	N/A	DATE	9/25/2023	0.0		9/25/2025
			STRUCT INSP P.15		N/A	2 yrs	11156.2			
550003	*	HORIZ/VERT STAB ATTACH FITTINGS		INSPECT	N/A	AF HRS	9/25/2023	0.0	1159.9	9/25/2025 12356.2
			STRUCT INSP P.15		N/A	1200 hrs	11156.2			
550004	*	HORIZ/VERT STAB ATTACH FITTINGS		INSPECT	N/A	DATE	9/25/2023	0.0		9/25/2025
		REAR	STRUCT INSP P.15		N/A	2 yrs	11156.2			
550004	*	HORIZ/VERT STAB ATTACH FITTINGS		INSPECT	N/A	AF HRS	9/25/2023	0.0	1159.9	9/25/2025 12356.2
		REAR	STRUCT INSP P.15		N/A	1200 hrs	11156.2			
550005	*	HORIZONTAL STABILIZER ASSEMBLY		INSPECT	N/A	DATE	8/20/2021	0.0		8/20/2025
			STRUCT INSP P.16		N/A	4 yrs	10559.0			
550006	*	HORIZONTAL STABILIZER (FRONT SPAR)		INSPECT	N/A	DATE	8/20/2021	0.0		8/20/2029
			STRUCT INSP P.16		N/A	8 yrs	10559.0			
550007	*	VERTICAL STABILIZER ASSEMBLY (X-RAY		NDT	N/A	DATE	8/20/2021	0.0		8/20/2029
			STRUCT INSP P.17		N/A	8 yrs	10559.0			
550008	*	HORIZ STAB (INTERNAL STRUCTURE)		INSPECT	N/A	DATE	8/20/2021	0.0		8/20/2029
			STRUCT INSP P.17		N/A	8 yrs	10559.0			
550009	*	HORIZ/VERT STAB ATTACH FITTINGS		INSPECT	N/A	DATE	8/20/2021	0.0		8/20/2029
			STRUCT INSP P.18		N/A	8 yrs	10559.0			
550010	*	HORIZONTAL STAB FOKKER BOND TEST		NDT	N/A	DATE	8/20/2021	0.0		8/20/2029
		LH	STRUCT INSP P.19		N/A	8 yrs	10559.0			
550010	*	HORIZONTAL STAB FOKKER BOND TEST		NDT	N/A	DATE	8/20/2021	0.0		8/20/2029
		RH	STRUCT INSP P.19		N/A	8 yrs	10559.0			
550011	*	ELEVATOR BEARINGS/HINGE BRACKETS		INSPECT	N/A	DATE	8/20/2021	0.0		8/20/2025
		LH	STRUCT INSP P.20		N/A	4 yrs	10559.0			

MASTER REPORT

4/25/2024

HS-125 257208

N2787

ATA CODE	F A A	DESCRIPTION		ACTION	PART NUMBER PART SERIAL NUMBER	FILE INTERVAL	LAST ACCOMPLISH	TSO/CSO	REMAINING HR/CYC/LDG	NEXT DUE
		LOCATION	MAINTENACE REFERENCE							
550011	*	ELEVATOR BEARINGS/HINGE BRACKETS		INSPECT	N/A	DATE	8/20/2021	0.0		8/20/2025
		RH	STRUCT INSP P.19		N/A	4 yrs	10559.0			
550012	*	ELEVATOR ASSEMBLY (X-RAY)		NDT	N/A	DATE	8/20/2021	0.0		8/20/2025
		LH	STRUCT INSP P.21		N/A	4 yrs	10559.0			
550012	*	ELEVATOR ASSEMBLY (X-RAY)		NDT	N/A	DATE	8/20/2021	0.0		8/20/2025
		RH	STRUCT INSP P.21		N/A	4 yrs	10559.0			
550013	*	ELEVATOR TRIM TAB RODS END BEARINGS		LUBE/REPL	N/A	DATE	8/20/2021	0.0		8/20/2025
		LH	STRUCT INSP P.21		N/A	4 yrs	10559.0			
550013	*	ELEVATOR TRIM TAB RODS END BEARINGS		LUBE/REPL	N/A	DATE	8/20/2021	0.0		8/20/2025
		RH	STRUCT INSP P.21		N/A	4 yrs	10559.0			
550014	*	ELEVATOR TRIM SCREWJACKS		INSPECT	N/A	DATE	8/20/2021	0.0		8/20/2025
			STRUCT INSP P.21		N/A	4 yrs	10559.0			
550015	*	RUDDER HINGE BRACKETS		INSPECT	N/A	DATE	8/20/2021	0.0		8/20/2025
			STRUCT INSP P.22		N/A	4 yrs	10559.0			
550016	*	RUDDER BEARINGS		INSPECT	N/A	DATE	8/20/2021	0.0		8/20/2025
			STRUCT INSP P.22		N/A	4 yrs	10559.0			
550017	*	RUDDER ASSEMBLY & TABS (X-RAY)		NDT	N/A	DATE	8/20/2021	0.0		8/20/2025
			STRUCT INSP P.22		N/A	4 yrs	10559.0			
550018	*	RUDDER ROD END BEARINGS		LUBE	N/A	DATE	8/20/2021	0.0		8/20/2025
			STRUCT INSP P.23		N/A	4 yrs	10559.0			
550019	*	HORIZONTAL STAB ASSEMBLY (X-RAY)		NDT	N/A	DATE	8/20/2021	0.0		8/20/2029
			STRUCT INSP P.23		N/A	8 yrs	10559.0			
550020	*	HORZ STAB T FITTING & JOINT STRAP		INSPECT	N/A	DATE	8/20/2021	0.0		8/20/2029
			STRUCT INSP P.23		N/A	8 yrs	10559.0			
550021	*	VERT STAB ROOT ATTACH TO FUSE(X-RAY)		NDT	N/A	AF HRS	8/20/2021	0.0	29362.7	9/15/2104
			STRUCT INSP P.23		N/A	30000 hrs	10559.0			40559.0
550023	*	SIDEPLATES, ELEVATOR MASS BAL WT		ANTI CORR	N/A	DATE	9/25/2023	0.0		9/25/2025
			STRUCT INSP P.20		N/A	2 yrs	11156.2			

MASTER REPORT

HS-125 257208

4/25/2024

N2787

ATA CODE	F A A	DESCRIPTION		ACTION	PART NUMBER PART SERIAL NUMBER	FILE INTERVAL	LAST ACCOMPLISH	TSO/CSO	REMAINING HR/CYC/LDG	NEXT DUE
		LOCATION	MAINTENACE REFERENCE							
57	*	AIRBRAKE INBD ATTACH PIVOT BOLT		REPLACE	25WB171 UNKNOWN	LANDING 10000 ldg	12/15/1983 0	0	385	5/15/2025 10000
		LH TOP	LIFE LIMITS REV 10							
57	*	AIRBRAKE INBD ATTACH PIVOT BOLT		REPLACE	25WB171 UNKNOWN	LANDING 10000 ldg	12/15/1983 0	0	385	5/15/2025 10000
		RH TOP	LIFE LIMITS REV 10							
57	*	FLAP HINGE ATTACH ANGLE BOLTS		REPLACE	25WB297 UNKNOWN	LANDING 16000 ldg	12/15/1983 0	0	6385	10/18/2041 16000
		LH INNER	LIFE LIMITS REV 10							
57	*	FLAP HINGE ATTACH ANGLE BOLTS		REPLACE	25WB297 UNKNOWN	LANDING 16000 ldg	12/15/1983 0	0	6385	10/18/2041 16000
		RH INNER	LIFE LIMITS REV 10							
570009	*	WING SKINS (X-RAY)		NDT	N/A N/A	DATE 4 yrs	8/20/2021 10559.0	0.0		8/20/2025
		LH LOWER	STRUCT INSP P.25							
570009	*	WING SKINS (X-RAY)		NDT	N/A N/A	DATE 4 yrs	8/20/2021 10559.0	0.0		8/20/2025
		RH LOWER	STRUCT INSP P.25							
570010	*	MAIN GEAR SIDESTAY ATTACH FITTINGS		INSPECT	N/A N/A	DATE 4 yrs	8/20/2021 10559.0	0.0		8/20/2025
		LH	STRUCT INSP P.26							
570010	*	MAIN GEAR SIDESTAY ATTACH FITTINGS		INSPECT	N/A N/A	DATE 4 yrs	8/20/2021 10559.0	0.0		8/20/2025
		RH	STRUCT INSP P.26							
570011	*	INTERNAL STRUCTURE FRONT/REAR SPAR		INSPECT	N/A N/A	DATE 4 yrs	8/20/2021 10559.0	0.0		8/20/2025
		LH	STRUCT INSP P.26							
570011	*	INTERNAL STRUCTURE FRONT/REAR SPAR		INSPECT	N/A N/A	DATE 4 yrs	8/20/2021 10559.0	0.0		8/20/2025
		RH	STRUCT INSP P.26							
570012	*	WING TOP SKIN IN AREA OF WING FENCE		INSPECT	N/A N/A	DATE 4 yrs	8/20/2021 10559.0	0.0		8/20/2025
		LH	STRUCT INSP P.27							
570012	*	WING TOP SKIN IN AREA OF WING FENCE		INSPECT	N/A N/A	DATE 4 yrs	8/20/2021 10559.0	0.0		8/20/2025
		RH	STRUCT INSP P.27							
570013	*	LOWER WING SKIN AT FLAP OUTBD HINGE		INSPECT	N/A N/A	LANDING 600 ldg	8/20/2021 9221	0	206	11/17/2024 9821
		LH	STRUCT INSP P.27							
570013	*	LOWER WING SKIN AT FLAP OUTBD HINGE		INSPECT	N/A N/A	LANDING 600 ldg	8/20/2021 9221	0	206	11/17/2024 9821
		RH	STRUCT INSP P.27							

MASTER REPORT

HS-125 257208

4/25/2024

N2787

ATA CODE	F A A	DESCRIPTION		ACTION	PART NUMBER PART SERIAL NUMBER	FILE INTERVAL	LAST ACCOMPLISH	TSO/CSO	REMAINING HR/CYC/LDG	NEXT DUE
		LOCATION	MAINTENACE REFERENCE							
570014	*	WING FRONT SPAR		INSPECT	N/A	DATE	8/20/2021	0.0		8/20/2025
		LH	STRUCT INSP P.27		N/A	4 yrs	10559.0			
570014	*	WING FRONT SPAR		INSPECT	N/A	AF HRS	8/20/2021	0.0	1762.7	8/20/2025
		LH	STRUCT INSP P.27		N/A	2400 hrs	10559.0			
570014	*	WING FRONT SPAR		INSPECT	N/A	DATE	8/20/2021	0.0		8/20/2025
		RH	STRUCT INSP P.27		N/A	4 yrs	10559.0			
570014	*	WING FRONT SPAR		INSPECT	N/A	AF HRS	8/20/2021	0.0	1762.7	8/20/2025
		RH	STRUCT INSP P.27		N/A	2400 hrs	10559.0			
570015	*	WING REAR SPAR		INSPECT	N/A	DATE	8/20/2021	0.0		8/20/2025
		LH	STRUCT INSP P.29		N/A	4 yrs	10559.0			
570015	*	WING REAR SPAR		INSPECT	N/A	AF HRS	8/20/2021	0.0	1762.7	8/20/2025
		LH	STRUCT INSP P.29		N/A	2400 hrs	10559.0			
570015	*	WING REAR SPAR		INSPECT	N/A	DATE	8/20/2021	0.0		8/20/2025
		RH	STRUCT INSP P.29		N/A	4 yrs	10559.0			
570015	*	WING REAR SPAR		INSPECT	N/A	AF HRS	8/20/2021	0.0	1762.7	8/20/2025
		RH	STRUCT INSP P.29		N/A	2400 hrs	10559.0			
570016	*	AILERON (REMOVED)		INSPECT	N/A	DATE	8/20/2021	0.0		8/20/2025
			STRUCT INSP P.29		N/A	4 yrs	10559.0			
570016	*	AILERON (REMOVED)		INSPECT	N/A	AF HRS	8/20/2021	0.0	1762.7	8/20/2025
			STRUCT INSP P.29		N/A	2400 hrs	10559.0			
570017	*	AILERON ROD END BEARINGS		LUBE	N/A	DATE	8/20/2021	0.0		8/20/2025
			STRUCT INSP P.29		N/A	4 yrs	10559.0			
570017	*	AILERON ROD END BEARINGS		LUBE	N/A	AF HRS	8/20/2021	0.0	1762.7	8/20/2025
			STRUCT INSP P.29		N/A	2400 hrs	10559.0			
570018	*	AILERON 'A' LEVERS/CONNECTING LINKS		INSPECT	N/A	DATE	8/20/2021	0.0		8/20/2025
			STRUCT INSP P.29		N/A	4 yrs	10559.0			
570018	*	AILERON 'A' LEVERS/CONNECTING LINKS		INSPECT	N/A	AF HRS	8/20/2021	0.0	1762.7	8/20/2025
			STRUCT INSP P.29		N/A	2400 hrs	10559.0			

MASTER REPORT

HS-125 257208

4/25/2024

N2787

ATA CODE	F A A	DESCRIPTION		ACTION	PART NUMBER PART SERIAL NUMBER	FILE INTERVAL	LAST ACCOMPLISH	TSO/CSO	REMAINING HR/CYC/LDG	NEXT DUE
		LOCATION	MAINTENACE REFERENCE							
570019	*	AILERON TRIM SCREWJACKS		INSPECT	N/A	DATE	8/20/2021	0.0		8/20/2025
			STRUCT INSP P.30		N/A	4 yrs	10559.0			
570019	*	AILERON TRIM SCREWJACKS		INSPECT	N/A	AF HRS	8/20/2021	0.0	1762.7	8/20/2025
			STRUCT INSP P.30		N/A	2400 hrs	10559.0			
570020	*	AILERON PULLEY DRUMS		INSPECT	N/A	DATE	8/20/2021	0.0		8/20/2025
			STRUCT INSP P.30		N/A	4 yrs	10559.0			
570020	*	AILERON PULLEY DRUMS		INSPECT	N/A	AF HRS	8/20/2021	0.0	1762.7	8/20/2025
			STRUCT INSP P.30		N/A	2400 hrs	10559.0			
570021	*	AILERON HINGES & ATTACHMENTS		INSPECT	N/A	DATE	8/20/2021	0.0		8/20/2025
			STRUCT INSP P.30		N/A	4 yrs	10559.0			
570021	*	AILERON HINGES & ATTACHMENTS		INSPECT	N/A	AF HRS	8/20/2021	0.0	1762.7	8/20/2025
			STRUCT INSP P.30		N/A	2400 hrs	10559.0			
570022	*	AIRBRAKE HINGES		INSPECT	N/A	DATE	8/20/2021	0.0		8/20/2025
		LH LOWER	STR INSP P.31-32		N/A	4 yrs	10559.0			
570022	*	AIRBRAKE HINGES		INSPECT	N/A	AF HRS	8/20/2021	0.0	1762.7	8/20/2025
		LH LOWER	STR INSP P.31-32		N/A	2400 hrs	10559.0			
570022	*	AIRBRAKE HINGES		INSPECT	N/A	DATE	8/20/2021	0.0		8/20/2025
		LH UPPER	STR INSP P.31-32		N/A	4 yrs	10559.0			
570022	*	AIRBRAKE HINGES		INSPECT	N/A	AF HRS	8/20/2021	0.0	1762.7	8/20/2025
		LH UPPER	STR INSP P.31-32		N/A	2400 hrs	10559.0			
570022	*	AIRBRAKE HINGES		INSPECT	N/A	DATE	8/20/2021	0.0		8/20/2025
		RH LOWER	STR INSP P.31-32		N/A	4 yrs	10559.0			
570022	*	AIRBRAKE HINGES		INSPECT	N/A	AF HRS	8/20/2021	0.0	1762.7	8/20/2025
		RH LOWER	STR INSP P.31-32		N/A	2400 hrs	10559.0			
570022	*	AIRBRAKE HINGES		INSPECT	N/A	DATE	8/20/2021	0.0		8/20/2025
		RH UPPER	STR INSP P.31-32		N/A	4 yrs	10559.0			
570022	*	AIRBRAKE HINGES		INSPECT	N/A	AF HRS	8/20/2021	0.0	1762.7	8/20/2025
		RH UPPER	STR INSP P.31-32		N/A	2400 hrs	10559.0			

MASTER REPORT

HS-125 257208

4/25/2024

N2787

ATA CODE	F A A	DESCRIPTION		ACTION	PART NUMBER PART SERIAL NUMBER	FILE INTERVAL	LAST ACCOMPLISH	TSO/CSO	REMAINING HR/CYC/LDG	NEXT DUE
		LOCATION	MAINTENACE REFERENCE							
570023	*	AILERON ASSEMBLY & TABS (X-RAY)		NDT	N/A	DATE	8/20/2021	0.0		8/20/2025
		LH	STR INSP P.31-32		N/A	4 yrs	10559.0			
570023	*	AILERON ASSEMBLY & TABS (X-RAY)		NDT	N/A	AF HRS	8/20/2021	0.0	1762.7	8/20/2025 12959.0
		LH	STR INSP P.31-32		N/A	2400 hrs	10559.0			
570023	*	AILERON ASSEMBLY & TABS (X-RAY)		NDT	N/A	DATE	8/20/2021	0.0		8/20/2025
		RH	STR INSP P.31-32		N/A	4 yrs	10559.0			
570023	*	AILERON ASSEMBLY & TABS (X-RAY)		NDT	N/A	AF HRS	8/20/2021	0.0	1762.7	8/20/2025 12959.0
		RH	STR INSP P.31-32		N/A	2400 hrs	10559.0			
570024	*	FLAP AND FLAP VANES (X-RAY)		NDT	N/A	DATE	8/20/2021	0.0		8/20/2025
		LH	STR INSP P.31-32		N/A	4 yrs	10559.0			
570024	*	FLAP AND FLAP VANES (X-RAY)		NDT	N/A	AF HRS	8/20/2021	0.0	1762.7	8/20/2025 12959.0
		LH	STR INSP P.31-32		N/A	2400 hrs	10559.0			
570024	*	FLAP AND FLAP VANES (X-RAY)		NDT	N/A	DATE	8/20/2021	0.0		8/20/2025
		RH	STR INSP P.31-32		N/A	4 yrs	10559.0			
570024	*	FLAP AND FLAP VANES (X-RAY)		NDT	N/A	AF HRS	8/20/2021	0.0	1762.7	8/20/2025 12959.0
		RH	STR INSP P.31-32		N/A	2400 hrs	10559.0			
570025	*	WING STRUCTURE FWD OF CENTER SPAR		INSPECT	N/A	DATE	8/20/2021	0.0		8/20/2029
		LH	STRUCT INSP P.33		N/A	8 yrs	10559.0			
570025	*	WING STRUCTURE FWD OF CENTER SPAR		INSPECT	N/A	AF HRS	8/20/2021	0.0	4162.7	8/20/2029 15359.0
		LH	STRUCT INSP P.33		N/A	4800 hrs	10559.0			
570025	*	WING STRUCTURE FWD OF CENTER SPAR		INSPECT	N/A	DATE	8/20/2021	0.0		8/20/2029
		RH	STRUCT INSP P.33		N/A	8 yrs	10559.0			
570025	*	WING STRUCTURE FWD OF CENTER SPAR		INSPECT	N/A	AF HRS	8/20/2021	0.0	4162.7	8/20/2029 15359.0
		RH	STRUCT INSP P.33		N/A	4800 hrs	10559.0			
570026	*	WING BOTTOM SKIN @ ATTACH FRT SPAR		INSPECT	N/A	AF HRS	8/20/2021	0.0	4162.7	9/17/2035 15359.0
		LH	STRUCT INSP P.34		N/A	4800 hrs	10559.0			
570026	*	WING BOTTOM SKIN @ ATTACH FRT SPAR		INSPECT	N/A	AF HRS	8/20/2021	0.0	4162.7	9/17/2035 15359.0
		RH	STRUCT INSP P.34		N/A	4800 hrs	10559.0			

MASTER REPORT

4/25/2024

HS-125 257208

N2787

ATA CODE	F A A	DESCRIPTION		ACTION	PART NUMBER PART SERIAL NUMBER	FILE INTERVAL	LAST ACCOMPLISH	TSO/CSO	REMAINING HR/CYC/LDG	NEXT DUE
		LOCATION	MAINTENACE REFERENCE							
570027	*	LOWER WING SKIN CNTRLNE JOINT STRAP		INSPECT	N/A	AF HRS	8/20/2021	0.0	8962.7	11/07/2048
		LH	STRUCT INSP P.34		N/A	9600 hrs	10559.0			
570027	*	LOWER WING SKIN CNTRLNE JOINT STRAP		INSPECT	N/A	AF HRS	8/20/2021	0.0	8962.7	11/07/2048
		RH	STRUCT INSP P.34		N/A	9600 hrs	10559.0			
570028	*	UPR SURFACE OF LWR WING SKIN(X-RAY)		NDT	N/A	AF HRS	8/20/2021	0.0	8962.7	11/07/2048
		LH	STRUCT INSP P.34		N/A	9600 hrs	10559.0			
570028	*	UPR SURFACE OF LWR WING SKIN(X-RAY)		NDT	N/A	AF HRS	8/20/2021	0.0	8962.7	11/07/2048
		RH	STRUCT INSP P.34		N/A	9600 hrs	10559.0			
570029	*	WING SKIN CNTR BUTT STRAP (INSPECT)		NDT	N/A	AF HRS	8/20/2021	0.0	11362.7	6/04/2055
		LH LOWER	STRUCT INSP P.35		N/A	12000 hrs	10559.0			
570029	*	WING SKIN CNTR BUTT STRAP (INSPECT)		NDT	N/A	AF HRS	8/20/2021	0.0	11362.7	6/04/2055
		RH LOWER	STRUCT INSP P.35		N/A	12000 hrs	10559.0			
71	*	ENGINE REAR MOUNT ATTACH BOLT		REPLACE	3073361-1	AF HRS	6/07/2013	0.0	1177.7	7/16/2027
		RH	LIFE LIMITS REV 10		N/A	2100 hrs	10274.0			
710001	*	ENGINE COWLING		INSPECT	N/A	AF HRS	7/10/2016	0.0	-684.5	OVERDUE
		LH	OUT PHASE P.10,11		N/A	150 hrs	10361.8			
710001	*	ENGINE COWLING		INSPECT	N/A	AF HRS	7/10/2016	0.0	-694.0	OVERDUE
		RH	OUT PHASE P.10,11		N/A	150 hrs	10352.3			
72	*	1000-1500 HOUR ENG INSPECT			TFE731-3R-1H	ENG HRS	8/02/2007	0.0	-112.8	OVERDUE
		LH	TABLE 603,604		P84497	1500 eng	8770.1			
72	*	1000-1500 HOUR ENG INSPECT			TFE731-3R-1H	ENG HRS	6/04/2013	0.0	577.7	11/23/2025
		RH	TABLE 603,604		P-84484	1500 eng	9607.1			
72	*	150-250 HOUR ENG INSPECT			TFE731-3R-1H	ENG HRS	12/23/2014	0.0	-636.4	OVERDUE
		LH	TABLE 603,604		P84497	250 eng	9496.5			
72	*	150-250 HOUR ENG INSPECT			TFE731-3R-1H	ENG HRS	6/04/2013	0.0	-672.3	OVERDUE
		RH	TABLE 603,604		P-84484	250 eng	9607.1			
72	*	300-400 HOUR ENG INSPECT			TFE731-3R-1H	ENG HRS	6/07/2013	0.0	-522.3	OVERDUE
		LH	TABLE 603,604		P84497	400 eng	9460.6			

MASTER REPORT

HS-125 257208

4/25/2024

N2787

ATA CODE	F A A	DESCRIPTION		ACTION	PART NUMBER PART SERIAL NUMBER	FILE INTERVAL	LAST ACCOMPLISH	TSO/CSO	REMAINING HR/CYC/LDG	NEXT DUE
		LOCATION	MAINTENACE REFERENCE							
72	*	300-400 HOUR ENG INSPECT			TFE731-3R-1H	ENG HRS	6/04/2013			OVERDUE
		RH	TABLE 603, 604		P-84484	400 eng	9607.1	0.0	-522.3	10007.1
72	*	600-800 HOUR ENG INSPECT			TFE731-3R-1H	ENG HRS	6/07/2013			OVERDUE
		LH	TABLE 603, 604		P84497	800 eng	9460.6	0.0	-122.3	10260.6
72	*	600-800 HOUR ENG INSPECT			TFE731-3R-1H	ENG HRS	6/04/2013			OVERDUE
		RH	TABLE 603, 604		P-84484	800 eng	9607.1	0.0	-122.3	10407.1
72	*	ACCESSORY GEARBOX		INSPECT	TFE731-3R-1H	ENG HRS	12/14/2000			
		LH	SB 72-3106 R15		P84487	4200 eng	7400.2	0.0	1217.3	8/25/2027 11600.2
72	*	ACCESSORY GEARBOX		INSPECT	3070003-11	ENG HRS	1/11/2000			
		RH	SB 72-3106 R15		P-3323	4200 eng	7164.6	0.0	835.2	8/08/2026 11364.6
72	*	COMBUSTION PLENUM CASE INSPECTION			TFE731-3R-1H	ENG HRS	8/02/2007			OVERDUE
		LH	SB 72-3106 R15		P84497	1400 eng	8770.1	0.0	-212.8	10170.1
72	*	COMBUSTION PLENUM CASE INSPECTION			3072443-4	ENG HRS	6/04/2013			8/15/2025
		RH	SB 72-3106 R15		1P-42356	1400 eng	9607.1	0.0	477.7	11007.1
72	*	ENGINE COMPRESSOR ZONE INSPECTION			TFE731-3R-1H	ENG HRS	12/14/2000			8/25/2027
		LH	SB 72-3106 R15		P84487	4200 eng	7400.2	0.0	1217.3	11600.2
72	*	ENGINE COMPRESSOR ZONE INSPECTION			TFE731-3R-1H	ENG HRS	1/11/2000			8/08/2026
		RH	SB 72-3106 R15		P-84484	4200 eng	7164.6	0.0	835.2	11364.6
72	*	ENGINE MAJOR PERIODIC INSPECTION			TFE731-3R-1H	ENG HRS	8/02/2007			OVERDUE
		LH	SB 72-3106 R15		P84497	1400 eng	8770.1	0.0	-212.8	10170.1
72	*	ENGINE MAJOR PERIODIC INSPECTION			TFE731-3R-1H	ENG HRS	6/04/2013			8/15/2025
		RH	SB 72-3106 R15		P-84484	1400 eng	9607.1	0.0	477.7	11007.1
72	*	FAN ROTOR DISC & HUB		REPLACE	3073563-2	ENG CYC	11/23/1995			5/19/2040
		LH	SB 72-3001 R56		5-03229-2571	10000 cyc	4919	0	5868	14919
72	*	FAN ROTOR DISC & HUB		REPLACE	3073563-2	ENG CYC	6/19/1995			12/15/2039
		RH	SB 72-3001 R56		5-03229-502	10000 cyc	4761	0	5712	14761
72	*	FAN SUPPORT ASSEMBLY		INSPECT	TFE731-3R-1H	ENG HRS	8/02/2007			4/15/2033
		LH	SB 72-3106 R15		P84487	4200 eng	9460.6	0.0	3277.7	13660.6

MASTER REPORT

4/25/2024

HS-125 257208

N2787

ATA CODE	F A A	DESCRIPTION		ACTION	PART NUMBER PART SERIAL NUMBER	FILE INTERVAL	LAST ACCOMPLISH	TSO/CSO	REMAINING HR/CYC/LDG	NEXT DUE
		LOCATION	MAINTENACE REFERENCE							
72	*	FAN SUPPORT ASSEMBLY		INSPECT	TFE731-3R-1H P-84484	ENG HRS 4200 eng	6/04/2013 9607.1	0.0	3277.7	4/15/2033 13807.1
		RH	SB 72-3106 R15							
72	*	HP COMPRESSOR RADIAL IMPELLER		REPLACE	3075765-1 000322902584	ENG CYC 10000 cyc	12/14/2000 6414	0	7363	6/22/2044 16414
		LH	SB 72-3001 R56							
72	*	HP COMPRESSOR RADIAL IMPELLER		REPLACE	3073394-1 9-23365-1736	ENG CYC 10000 cyc	6/04/2013 8517	4857	4611	12/09/2036 13660
		RH	SB 72-3001 R56							
72	*	HP ROTOR SEAL PLATE		REPLACE	3072411-1 1-18040-0307	ENG CYC 10000 cyc	7/31/1997 5388	4171	2166	3/31/2030 11217
		LH	SB 72-3001 R56							
72	*	HP ROTOR SEAL PLATE		REPLACE	3072411-1 2-18040-3339	ENG CYC 10000 cyc	4/07/1983 0	0	951	12/02/2026 10000
		RH	SB 72-3001 R56							
72	*	HP SHOULDERED SHAFT		REPLACE	3072545-1 00P24042	ENG CYC 12000 cyc	12/14/2000 6414	0	9363	12/13/2049 18414
		LH	SB 72-3001 R56							
72	*	HP SHOULDERED SHAFT		REPLACE	3072545-1 3P-5547	ENG CYC 12000 cyc	4/07/1983 0	0	2951	5/24/2032 12000
		RH	SB 72-3001 R56							
72	*	HP TURBINE WHEEL ROTOR		REPLACE	3072316-3 000322900544	ENG CYC 7000 cyc	12/14/2000 6414	0	4363	4/05/2036 13414
		LH	SB 72-3001 R56							
72	*	HP TURBINE WHEEL ROTOR		REPLACE	3072316-3 980322902885	ENG CYC 7000 cyc	1/11/2000 6190	0	4141	8/27/2035 13190
		RH	SB 72-3001 R56							
72	*	LP 1ST STAGE AXIAL COMPRESSOR DISC		REPLACE	3072395-1 2-03501-5687	ENG CYC 10000 cyc	7/20/1983 0	0	949	11/30/2026 10000
		LH	SB 72-3001 R56							
72	*	LP 1ST STAGE AXIAL COMPRESSOR DISC		REPLACE	3072395-1 2-03501-01433	ENG CYC 10000 cyc	4/07/1983 0	0	951	12/02/2026 10000
		RH	SB 72-3001 R56							
72	*	LP 1ST STAGE TURBINE ROTOR DISC		REPLACE	3075830-1 060322903237	ENG CYC 3000 cyc	8/02/2007 7748	0	1697	12/17/2028 10748
		LH	SB 72-3001 R56							
72	*	LP 1ST STAGE TURBINE ROTOR DISC		REPLACE	3075830-1 040322901963	ENG CYC 3000 cyc	2/08/2005 7264	0	1215	8/23/2027 10264
		RH	SB 72-3001 R56							
72	*	LP 2ND STAGE AXIAL COMPRESSOR DISC		REPLACE	3072396-1 2-12112-842	ENG CYC 10000 cyc	7/20/1983 0	0	949	11/30/2026 10000
		LH	SB 72-3001 R56							

MASTER REPORT

HS-125 257208

4/25/2024

N2787

ATA CODE	F A A	DESCRIPTION		ACTION	PART NUMBER PART SERIAL NUMBER	FILE INTERVAL	LAST ACCOMPLISH	TSO/CSO	REMAINING HR/CYC/LDG	NEXT DUE
		LOCATION	MAINTENACE REFERENCE							
72	*	LP 2ND STAGE AXIAL COMPRESSOR DISC		REPLACE	3075839-1 12-16204-2164	ENG CYC 20000 cyc	6/04/2013 8517	0	19468	8/13/2077 28517
		RH	SB 72-3001 R56							
72	*	LP 2ND STAGE AXIAL COMPRESSOR DISC		REPLACE	3072396-1 2-12112-1080	ENG CYC 10000 cyc	9/27/1996 5179	5179	951	12/02/2026 10000
		RH	SB 72-3001 R56							
72	*	LP 2ND STAGE TURBINE ROTOR DISC		REPLACE	3072542-5 060322905473	ENG CYC 3000 cyc	8/02/2007 7748	0	1697	12/17/2028 10748
		LH	SB 72-3001 R56							
72	*	LP 2ND STAGE TURBINE ROTOR DISC		REPLACE	3072542-5 040322901958	ENG CYC 3000 cyc	2/08/2005 7264	0	1215	8/23/2027 10264
		RH	SB 72-3001 R56							
72	*	LP 3RD STAGE AXIAL COMPRESSOR DISC		REPLACE	3072397-1 2-12112-1372	ENG CYC 10000 cyc	7/20/1983 0	0	949	11/30/2026 10000
		LH	SB 72-3001 R56							
72	*	LP 3RD STAGE AXIAL COMPRESSOR DISC		REPLACE	3072397-1 1-03160-1549	ENG CYC 10000 cyc	6/04/2013 8517	4166	5302	10/31/2038 14351
		RH	SB 72-3001 R56							
72	*	LP 3RD STAGE TURBINE ROTOR DISC		REPLACE	3074096-2 965332201051	ENG CYC 7000 cyc	7/31/1997 5388	0	3337	6/14/2033 12388
		LH	SB 72-3001 R56							
72	*	LP 3RD STAGE TURBINE ROTOR DISC		REPLACE	3074096-2 995332200279	ENG CYC 7000 cyc	1/11/2000 6190	0	4141	8/27/2035 13190
		RH	SB 72-3001 R56							
72	*	LP 4TH STAGE AXIAL COMPRESSOR DISC		REPLACE	3072398-1 2-03160-2714	ENG CYC 10000 cyc	7/20/1983 0	0	949	11/30/2026 10000
		LH	SB 72-3001 R56							
72	*	LP 4TH STAGE AXIAL COMPRESSOR DISC		REPLACE	3072398-1 2-03160-2561	ENG CYC 10000 cyc	4/07/1983 0	0	951	12/02/2026 10000
		RH	SB 72-3001 R56							
720001	*	ENGINE MOUNT BRACKETS (FWD)		MAG PART	N/A N/A	AF HRS 1400 hrs	8/20/2021 10559.0	0.0	762.7	5/27/2026 11959.0
		LH	STRUCT INSP P.36							
720001	*	ENGINE MOUNT BRACKETS (FWD)		MAG PART	N/A N/A	AF HRS 1400 hrs	8/20/2021 10559.0	0.0	762.7	5/27/2026 11959.0
		RH	STRUCT INSP P.36							
73	*	FUEL FILTER ELEMENT		REPLACE	897830-1 N/A	ENG HRS 650 eng	7/17/2012 9356.6	0.0	-376.3	OVERDUE 10006.6
		LH	TABLE 603,604							
73	*	FUEL FILTER ELEMENT		REPLACE	UNKNOWN N/A	ENG HRS 650 eng	6/04/2013 9607.1	0.0	-272.3	OVERDUE 10257.1
		RH	TABLE 603,604							

MASTER REPORT

4/25/2024

HS-125 257208

N2787

ATA CODE	F A A	DESCRIPTION		ACTION	PART NUMBER PART SERIAL NUMBER	FILE INTERVAL	LAST ACCOMPLISH	TSO/CSO	REMAINING HR/CYC/LDG	NEXT DUE
		LOCATION	MAINTENACE REFERENCE							
79	*	SOAP CHECK			TFE731-3R-1H P84497	ENG HRS 250 eng	12/23/2014 9496.5	0.0	-636.4	OVERDUE 9746.5
		LH	TABLE 603,604							
79	*	SOAP CHECK			TFE731-3R-1H P-84484	ENG HRS 250 eng	6/04/2013 9607.1	0.0	-672.3	OVERDUE 9857.1
		RH	TABLE 603,604							
790002	*	ENGINE OIL CHANGE			MOBIL 254 N/A	ENG HRS 1200 eng	7/17/2012 9356.6	0.0	173.7	10/15/2024 10556.6
		LH	72-00-00 P.313							
790002	*	ENGINE OIL CHANGE			N/A N/A	ENG HRS 1200 eng	6/04/2013 9607.1	0.0	277.7	1/27/2025 10807.1
		RH	72-00-00 P.313							
97		SB 72-3494 (TURBINE BLADES)				ENG HRS 1400 eng	8/02/2007 8770.1		-212.8	OVERDUE 10170.1
		LH	SEE SB							
97		SB 72-3494 (TURBINE BLADES)				ENG HRS 1400 eng	6/04/2013 9607.1		477.7	8/15/2025 11007.1
		RH	SEE SB							
97		SB A72-3641 (HP IMPELLER)				ENG HRS 4200 eng	12/14/2000 7400.2		1217.3	8/25/2027 11600.2
		LH	SEE SB							
97		SB A72-3641 (HP IMPELLER)				ENG HRS 4200 eng	1/11/2000 7164.6		835.2	8/08/2026 11364.6
		RH	SEE SB							
98		SB 32-167 (FAIL OF BRAKE KNIFE EDG)				LANDING 4500 ldg	8/29/2008 8411		3296	5/04/2033 12911
		LH/RH								
98	*	SB 32-184 (NOSE BRIDGE CAST INSP)				DATE 24 mos	8/20/2021 10559.0			OVERDUE
98	*	SB 32-184 (NOSE BRIDGE CAST INSP)				LANDING 900 ldg	8/20/2021 9221		506	OVERDUE 10121
98		SB 71-036				AF HRS 150 hrs	7/10/2016 10352.3		-694.0	OVERDUE 10502.3
		LH								
98		SB 71-036				AF HRS 150 hrs	7/10/2016 10352.3		-694.0	OVERDUE 10502.3
		RH								
99	*	AD 2000-15-09 (HPC IMPELLER)				ENG HRS 4200 eng	12/14/2000 7400.2		1217.3	8/25/2027 11600.2
		LH	SEE AD							

MASTER REPORT

4/25/2024

HS-125 257208

N2787

ATA CODE	F A A	D E S C R I P T I O N		ACTION	PART NUMBER PART SERIAL NUMBER	FILE INTERVAL	LAST ACCOMPLISH	TSO/CSO	REMAINING HR/CYC/LDG	N E X T D U E
		LOCATION	MAINTENACE REFERENCE							
99	*	AD 2000-15-09 (HPC IMPELLER)				ENG HRS 4200 eng	1/11/2000 7164.6		835.2	8/08/2026 11364.6
		RH	SEE AD							
99	*	AD 2015-08-07 OXY MASK REG HARNESS				DATE 24 mos				OVERDUE
			SEE AD							
99	*	AD 74-08-09 (FIRE PROTECT LAVATORY)				AF HRS 1000 hrs	6/06/2011 10006.6		-189.7	OVERDUE 11006.6
			SEE AD							
99	*	AD 77-13-02 (BRAKE KNIFE EDGE)				LANDING 4500 ldg	6/28/1999 6509		1394	2/18/2028 11009
			SEE AD							
99	*	AD 77-13-11 (BRAKE EMER KNIFE EDGE)				LANDING 4500 ldg	8/29/2008 8411		3296	5/04/2033 12911
			SEE AD							
99	*	AD 80-12-05 (NOSE GEAR BRIDGE CAST)				DATE 2 yrs	8/20/2021 10559.0			OVERDUE
			SEE AD							
99	*	AD 80-12-05 (NOSE GEAR BRIDGE CAST)				LANDING 900 ldg	8/20/2021 9221		506	OVERDUE 10121
			SEE AD							

NOTE: * INDICATES FAA MANDATORY REQUIREMENT.

LONG RANGE PROJECTION REPORT

HS-125 257208

4/25/2024

N2787

ATA CODE	F A	DESCRIPTION	LOCATION	ACTION	ACCOMPLISHED		INTERVAL	HR/CYC			TARGET DATE
					DATE	HR/CYC		NEXT DUE	CURRENT	REMAINING	
25	*	LIFE VEST RECERTIFICATION			12/01/1984	0.0	5 yrs				12/01/1989
340015	*	STALL WARNING SYSTEM PIPELINES		INSPECT	8/29/2008	9680.0	8 yrs				08/29/2016
30		AIRFRAME DE-ICE SYS CHECK VALVE		OVERHAUL	9/13/2012	10184.6	4 yrs				09/13/2016
30		AIRFRAME DE-ICE SYS RESTRICTOR VAL		OVERHAUL	9/13/2012	10184.6	4 yrs				09/13/2016
30		WINDSHIELD DE-ICE NON RETURN VALVE		OVERHAUL	9/13/2012	10184.6	4 yrs				09/13/2016
33		EMERGENCY EXIT LIGHT	AFT	BENCH CK	2/09/2016	10342.2	12 mos				02/09/2017
33		EMERGENCY EXIT LIGHT	FWD	BENCH CK	2/09/2016	10342.2	12 mos				02/09/2017
33		EMERGENCY EXIT LIGHT UNIT		TEST	2/09/2016	10342.2	1 yrs				02/09/2017
99	*	AD 2015-08-07 OXY MASK REG HARNESS					24 mos				06/16/2017
32		MAIN GEAR LEG ASSEMBLY	RH	OVERHAUL	7/01/2005		12 yrs				07/01/2017
32		MAIN GEAR LEG ASSEMBLY	LH	OVERHAUL	7/01/2005		12 yrs				07/01/2017
32		MAIN GEAR REVERSING VALVE	RH	OVERHAUL	7/01/2005		12 yrs				07/01/2017
32		MAIN GEAR SIDE STAY	RH	OVERHAUL	7/01/2005		12 yrs				07/01/2017
32		MAIN GEAR SIDE STAY	LH	OVERHAUL	7/01/2005		12 yrs				07/01/2017
32		NOSE GEAR DRAG STAY		OVERHAUL	7/01/2005		12 yrs				07/01/2017
26	*	FIRE EXTINGUISHER FIRED FUSE	#2	REPLACE	9/15/2014	10286.8	3 yrs				09/15/2017
26	*	FIRE EXTINGUISHER FIRED FUSE	#1	REPLACE	9/15/2014	10286.8	3 yrs				09/15/2017
32		MAIN GEAR REVERSING VALVE	LH	OVERHAUL	1/20/2006	9322.0	12 yrs				01/20/2018
32		MAIN GEAR SEQUENCE VALVE	RH	OVERHAUL	1/20/2006	9322.0	12 yrs				01/20/2018
32		MAIN GEAR SEQUENCE VALVE	LH	OVERHAUL	1/20/2006	9322.0	12 yrs				01/20/2018
32		NOSE GEAR LEG ASSEMBLY		OVERHAUL	4/24/2006	9368.5	12 yrs				04/24/2018
320039	*	NOSE STEERING PIVOT PIN		MAG PART	4/24/2006	9368.5	12 yrs				04/24/2018
26	*	FIRE EXTINGUISHER FIRED FUSE (MFG)	#2	REPLACE	4/30/2014		4 yrs				04/30/2018
26	*	FIRE EXTINGUISHER FIRED FUSE (MFG)	#1	REPLACE	4/30/2014		4 yrs				04/30/2018
24		AC GENERATOR	RH	OVERHAUL	1/06/2014	10275.1	5 yrs				01/06/2019
33		INERTIA SWITCH, EMERG LIGHTING		OVERHAUL	2/09/2016	10342.2	3 yrs				02/09/2019
26	*	APU HSRS FIRE DETECTOR	LOWER	CALIBRATE	9/15/2014	10286.8	5 yrs				09/15/2019
26	*	APU HSRS FIRE DETECTOR	UPPER	CALIBRATE	9/15/2014	10286.8	5 yrs				09/15/2019
21	*	DUCT TEMP SWITCH OVERHEAT WARNING	RH	CALIBRATE	9/15/2014	10286.8	5 yrs				09/15/2019
21	*	DUCT TEMP SWITCH OVERHEAT WARNING	LH	CALIBRATE	9/15/2014	10286.8	5 yrs				09/15/2019
26	*	OVERHEAT DETECT SWTCH PYLON FILLETS	RH AFT	CALIBRATE	9/15/2014	10286.8	5 yrs				09/15/2019
26	*	OVERHEAT DETECT SWTCH PYLON FILLETS	RH FWD	CALIBRATE	9/15/2014	10286.8	5 yrs				09/15/2019
26	*	OVERHEAT DETECT SWTCH PYLON FILLETS	LH FWD	CALIBRATE	9/15/2014	10286.8	5 yrs				09/15/2019
26	*	OVERHEAT DETECT SWTCH PYLON FILLETS	LH AFT	CALIBRATE	9/15/2014	10286.8	5 yrs				09/15/2019
26	*	OVERHEAT DETECTOR SWITCHES	EQUIP BAY	CALIBRATE	9/15/2014	10286.8	5 yrs				09/15/2019
26	*	ENGINE FIRE EXTINGUISHER CARTRIDGE	AFT HEAD	REPLACE	1/18/2010	9865.9	10 yrs				01/18/2020
26	*	ENGINE FIRE EXTINGUISHER CARTRIDGE	AFT HEAD	REPLACE	1/18/2010	9865.9	10 yrs				01/18/2020
26	*	ENGINE FIRE EXTINGUISHER CARTRIDGE	FWD HEAD	REPLACE	1/18/2010	9865.9	10 yrs				01/18/2020
26	*	ENGINE FIRE EXTINGUISHER CARTRIDGE	FWD HEAD	REPLACE	1/18/2010	9865.9	10 yrs				01/18/2020
29		EMER BRAKE ACC LOW PRES WARN SWITCH		OVERHAUL	9/21/1992	4693.2	5000 hrs	9693.2	6503.1	-1503.1	03/13/2020
24		INVERTER SUPPLY CONTACTOR	#2	OVERHAUL	5/09/1993	4980.0	5000 hrs	9980.0	6216.3	-1216.3	12/25/2020
24		AC GENERATOR	LH	OVERHAUL	7/10/2016	10361.8	5 yrs				07/10/2021
280015	*	FUEL BOOST PUMP BRUSHES WEAR	LH	INSPECT	12/05/2000	8188.7	2000 hrs	10188.7	3007.6	-1007.6	07/22/2021
35		OXYGEN MASK	PILOT	OVERHAUL	2/09/2016	10342.2	6 yrs				02/09/2022

LONG RANGE PROJECTION REPORT

4/25/2024

HS-125 257208

N2787

ATA CODE	F A	DESCRIPTION	LOCATION	ACTION	ACCOMPLISHED		INTERVAL	HR/CYC			TARGET DATE
					DATE	HR/CYC		NEXT DUE	CURRENT	REMAINING	
210022	*	COOLING TURBINE OIL DRAIN			7/10/2016	10361.8	50 hrs	10411.8	834.5	-784.5	03/02/2022
33	*	STROBE LIGHT	TAIL	TEST	9/15/2014	10286.8	150 hrs	10436.8	909.5	-759.5	03/27/2022
33	*	STROBE LIGHT	RH WING	TEST	9/15/2014	10286.8	150 hrs	10436.8	909.5	-759.5	03/27/2022
33	*	STROBE LIGHT	LH WING	TEST	9/15/2014	10286.8	150 hrs	10436.8	909.5	-759.5	03/27/2022
710001	*	ENGINE COWLING	RH	INSPECT	7/10/2016	10352.3	150 hrs	10502.3	844.0	-694.0	06/01/2022
98		SB 71-036	RH		7/10/2016	10352.3	150 hrs	10502.3	844.0	-694.0	06/01/2022
98		SB 71-036	LH		7/10/2016	10352.3	150 hrs	10502.3	844.0	-694.0	06/01/2022
710001	*	ENGINE COWLING	LH	INSPECT	7/10/2016	10361.8	150 hrs	10511.8	834.5	-684.5	06/10/2022
72	*	150-250 HOUR ENG INSPECT	RH		6/04/2013	9607.1	250 eng	9857.1	922.3	-672.3	06/22/2022
79	*	SOAP CHECK	RH		6/04/2013	9607.1	250 eng	9857.1	922.3	-672.3	06/22/2022
72	*	150-250 HOUR ENG INSPECT	LH		12/23/2014	9496.5	250 eng	9746.5	886.4	-636.4	07/28/2022
79	*	SOAP CHECK	LH		12/23/2014	9496.5	250 eng	9746.5	886.4	-636.4	07/28/2022
24	*	BATTERY	#3	CAP CHK	8/20/2021	10559.0	12 mos				08/20/2022
34		ELEVATOR TRIM SERVO/MOTOR		OVERHAUL	11/30/1994	5631.6	5000 hrs	10631.6	5564.7	-564.7	10/08/2022
72	*	300-400 HOUR ENG INSPECT	RH		6/04/2013	9607.1	400 eng	10007.1	922.3	-522.3	11/19/2022
72	*	300-400 HOUR ENG INSPECT	LH		6/07/2013	9460.6	400 eng	9860.6	922.3	-522.3	11/19/2022
320038	*	BRAKE PAD WEAR	RH	INSPECT	2/05/2013	9064	75 ldg	9139	551	-476	01/05/2023
320038	*	BRAKE PAD WEAR	LH	INSPECT	2/05/2013	9064	75 ldg	9139	551	-476	01/05/2023
35		PROTECTIVE BREATHING EQUIPMENT		REPLACE	2/27/2013	10275.1	10 yrs				02/27/2023
73	*	FUEL FILTER ELEMENT	LH	REPLACE	7/17/2012	9356.6	650 eng	10006.6	1026.3	-376.3	04/14/2023
73	*	FUEL FILTER ELEMENT	RH	REPLACE	6/04/2013	9607.1	650 eng	10257.1	922.3	-272.3	07/27/2023
99	*	AD 80-12-05 (NOSE GEAR BRIDGE CAST)			8/20/2021	10559.0	2 yrs				08/20/2023
320036	*	NOSE LANDING GEAR BRIDGE CASTING		DYE PEN	8/20/2021	10559.0	2 yrs				08/20/2023
98	*	SB 32-184 (NOSE BRIDGE CAST INSP)			8/20/2021	10559.0	24 mos				08/20/2023
12	*	150 HOUR AIRCRAFT LUBE			9/20/2022	10804.5	150 hrs	10954.5	391.8	-241.8	08/27/2023
24		STARTER GENERATOR	RH	OVERHAUL	2/11/2011	9976.5	1000 hrs	10976.5	1219.8	-219.8	09/18/2023
24		STARTER GENERATOR	LH	OVERHAUL	2/11/2011	9976.5	1000 hrs	10976.5	1219.8	-219.8	09/18/2023
72	*	COMBUSTION PLENUM CASE INSPECTION	LH		8/02/2007	8770.1	1400 eng	10170.1	1612.8	-212.8	09/25/2023
72	*	ENGINE MAJOR PERIODIC INSPECTION	LH		8/02/2007	8770.1	1400 eng	10170.1	1612.8	-212.8	09/25/2023
97		SB 72-3494 (TURBINE BLADES)	LH		8/02/2007	8770.1	1400 eng	10170.1	1612.8	-212.8	09/25/2023
99	*	AD 74-08-09 (FIRE PROTECT LAVATORY)			6/06/2011	10006.6	1000 hrs	11006.6	1189.7	-189.7	10/18/2023
72	*	600-800 HOUR ENG INSPECT	RH		6/04/2013	9607.1	800 eng	10407.1	922.3	-122.3	12/24/2023
72	*	600-800 HOUR ENG INSPECT	LH		6/07/2013	9460.6	800 eng	10260.6	922.3	-122.3	12/24/2023
340016	*	EMERGENCY POWER SUPPLY	#1	CAP CHK	9/25/2023	11156.2	3 mos				12/25/2023
34	*	EMERGENCY POWER SUPPLY	#2	TEST	9/25/2023	11156.2	3 mos				12/25/2023
300012	*	WINDSHIELD FLUID DEICING SYSTEM		FUNC TEST	9/25/2023	11156.2	3 mos				12/25/2023
240031	*	APU STARTER/GENERATOR BRUSH WEAR		INSPECT	9/13/2012	3414.8	300 hrs	3714.8	417.0	-117.0	12/30/2023
240031	*	APU STARTER/GENERATOR SPLINE LUBE			9/13/2012	3414.8	300 hrs	3714.8	417.0	-117.0	12/30/2023
72	*	1000-1500 HOUR ENG INSPECT	LH		8/02/2007	8770.1	1500 eng	10270.1	1612.8	-112.8	01/03/2024
490003	*	APU 500 HOUR INSPECTION			9/09/2009	3221.2	500 hrs	3721.2	610.6	-110.6	01/05/2024
24		BUS TIE CONTACTOR		OVERHAUL	1/25/1996	6109.1	5000 hrs	11109.1	5087.2	-87.2	01/28/2024
24	*	BATTERY	#2 (MAIN)	CAP CHK	9/25/2023	11156.2	6 mos				03/25/2024
24	*	BATTERY	#1 (MAIN)	CAP CHK	9/25/2023	11156.2	6 mos				03/25/2024
33		EMERGENCY LIGHT FILAMENT		REPLACE	9/25/2023	11156.2	6 mos				03/25/2024

LONG RANGE PROJECTION REPORT

HS-125 257208

4/25/2024

N2787

ATA CODE	F A	DESCRIPTION	LOCATION	ACTION	ACCOMPLISHED		INTERVAL	HR/CYC			TARGET DATE
					DATE	HR/CYC		NEXT DUE	CURRENT	REMAINING	
490002	*	APU 250 HOUR INSPECTION			8/10/2016	3582.3	250 hrs	3832.3	249.5	0.5	04/25/2024
12	*	1200 HOUR AIRCRAFT LUBE			6/03/2011	10006.6	1200 hrs	11206.6	1189.7	10.3	05/05/2024
050250	*	INSPECTION C			6/03/2011	10006.6	1200 hrs	11206.6	1189.7	10.3	05/05/2024
12	*	2400 HOUR AIRCRAFT LUBE			9/02/2003	8822.0	2400 hrs	11222.0	2374.3	25.7	05/20/2024
050380	*	INSPECTION D			9/02/2003	8822.0	2400 hrs	11222.0	2374.3	25.7	05/20/2024
27	*	FLAP SYNCHRO CABLE ASSY (INNER)	RH AFT	REPLACE	11/26/1993	4642	5000 ldg	9642	4973	27	05/22/2024
27	*	FLAP SYNCHRO CABLE ASSY (INNER)	RH	REPLACE	11/26/1993	4642	5000 ldg	9642	4973	27	05/22/2024
27	*	FLAP SYNCHRO CABLE ASSY (OUTER)	RH AFT	REPLACE	11/26/1993	4642	5000 ldg	9642	4973	27	05/22/2024
27	*	FLAP SYNCHRO CABLE ASSY (OUTER)	LH AFT	REPLACE	11/26/1993	4642	5000 ldg	9642	4973	27	05/22/2024
27	*	FLAP SYNCHRO CABLE ASSY (OUTER)	LH	REPLACE	11/26/1993	4642	5000 ldg	9642	4973	27	05/22/2024
27	*	FLAP SYNCHRO CABLE ASSY (INNER)	LH AFT	REPLACE	11/26/1993	4642	5000 ldg	9642	4973	27	05/22/2024
27	*	FLAP SYNCHRO CABLE ASSY (INNER)	LH	REPLACE	11/26/1993	4642	5000 ldg	9642	4973	27	05/22/2024
32		MAIN GEAR DOOR JACK	LH	OVERHAUL	11/26/1993	4642	5000 ldg	9642	4973	27	05/22/2024
32	*	MAIN GEAR JACK CYLINDER HEAD	RH	REPLACE	7/01/2005	7901	5000 ldg	9642	4973	27	05/22/2024
32	*	MAIN GEAR JACK CYLINDER HEAD	LH	REPLACE	11/26/1993	4642	5000 ldg	9642	4973	27	05/22/2024
32		MAIN GEAR RETRACT JACK	LH	OVERHAUL	11/26/1993	4642	5000 ldg	9642	4973	27	05/22/2024
32		NOSE GEAR RETRACT JACK		OVERHAUL	11/26/1993	4642	5000 ldg	9642	4973	27	05/22/2024
32		BRAKE MAXARET	LH INBD	OVERHAUL	12/28/1999	6688	3000 ldg	9688	2927	73	07/07/2024
340014	*	COMPASS SWING	STANDBY		8/20/2021	10559.0	36 mos				08/20/2024
340013	*	COMPASS SWING	MAIN		8/20/2021	10559.0	36 mos				08/20/2024
33		EMERGENCY LIGHT INERTIA SWITCH		BENCH CK	2/09/2016	10342.2	1000 hrs	11342.2	854.1	145.9	09/17/2024
12	*	12 MONTH AIRCRAFT LUBE			9/25/2023	11156.2	12 mos				09/25/2024
490004	*	APU OIL CHANGE			9/25/2023	3821.8	12 mos				09/25/2024
490005	*	APU OIL FILTER ELEMENT		REPLACE	9/25/2023	3821.8	12 mos				09/25/2024
26	*	CABIN FIRE EXTINGUISHER		WEIGH	9/25/2023	11156.2	1 yrs				09/25/2024
26	*	COCKPIT FIRE EXTINGUISHER		WEIGH	9/25/2023	11156.2	1 yrs				09/25/2024
25	*	ELT (FAR 91.207)		INSPECT	9/25/2023	11156.2	12 mos				09/25/2024
24	*	EMERGENCY POWER SUPPLY	#2	DEEP CYL	9/25/2023	11156.2	12 mos				09/25/2024
34	*	EMERGENCY POWER SUPPLY		DEEP CYL	9/25/2023	11156.2	12 mos				09/25/2024
050510	*	INSPECTION E			9/25/2023	11156.2	12 mos				09/25/2024
25	*	LIFE RAFT RECERTIFICATION	#2		9/25/2023	11156.2	12 mos				09/25/2024
25	*	LIFE RAFT RECERTIFICATION	#1		9/25/2023	11156.2	12 mos				09/25/2024
790002	*	ENGINE OIL CHANGE	LH		7/17/2012	9356.6	1200 eng	10556.6	1026.3	173.7	10/15/2024
12	*	300 HOUR AIRCRAFT LUBE			6/23/2023	11099.8	300 hrs	11399.8	96.5	203.5	11/14/2024
050050	*	INSPECTION A			6/23/2023	11099.8	300 hrs	11399.8	96.5	203.5	11/14/2024
570013	*	LOWER WING SKIN AT FLAP OUTBD HINGE	RH	INSPECT	8/20/2021	9221	600 ldg	9821	394	206	11/17/2024
570013	*	LOWER WING SKIN AT FLAP OUTBD HINGE	LH	INSPECT	8/20/2021	9221	600 ldg	9821	394	206	11/17/2024
26	*	ENGINE FIRE EXT CARTRIDGE MANUF DAT	FWD HEAD	REPLACE	1/18/2010		15 yrs				01/18/2025
26	*	ENGINE FIRE EXT CARTRIDGE MANUF DAT	FWD HEAD	REPLACE	1/18/2010		15 yrs				01/18/2025
26	*	ENGINE FIRE EXT CARTRIDGE MANUF DAT	AFT HEAD	REPLACE	1/18/2010		15 yrs				01/18/2025
26	*	ENGINE FIRE EXT CARTRIDGE MANUF DAT	AFT HEAD	REPLACE	1/18/2010		15 yrs				01/18/2025
790002	*	ENGINE OIL CHANGE	RH		6/04/2013	9607.1	1200 eng	10807.1	922.3	277.7	01/27/2025
27	*	FLAP SYNCHRO CABLE ASSY (OUTER)	RH	REPLACE	11/30/1994	4975	5000 ldg	9975	4640	360	04/20/2025
12	*	600 HOUR AIRCRAFT LUBE			5/26/2023	10959.7	600 hrs	11559.7	236.6	363.4	04/23/2025

LONG RANGE PROJECTION REPORT

HS-125 257208

4/25/2024

N2787

ATA CODE	F A	DESCRIPTION	LOCATION	ACTION	ACCOMPLISHED		INTERVAL	HR/CYC			TARGET DATE
					DATE	HR/CYC		NEXT DUE	CURRENT	REMAINING	
050120	*	INSPECTION B			5/26/2023	10959.7	600 hrs	11559.7	236.6	363.4	04/23/2025
57	*	AIRBRAKE INBD ATTACH PIVOT BOLT	RH TOP	REPLACE	12/15/1983	0	10000 ldg	10000	9615	385	05/15/2025
57	*	AIRBRAKE INBD ATTACH PIVOT BOLT	LH TOP	REPLACE	12/15/1983	0	10000 ldg	10000	9615	385	05/15/2025
28	*	VENTRAL TANK PICK-UP LINK BOLT	REAR	REPLACE	12/01/1984	0	10000 ldg	10000	9615	385	05/15/2025
72	*	COMBUSTION PLENUM CASE INSPECTION	RH		6/04/2013	9607.1	1400 eng	11007.1	922.3	477.7	08/15/2025
290021	*	ENGINE DRIVEN HYDRAULIC PUMP	RH	INSPECT	6/07/2013	10274.0	1400 hrs	11674.0	922.3	477.7	08/15/2025
290021	*	ENGINE DRIVEN HYDRAULIC PUMP	LH	INSPECT	6/07/2013	10274.0	1400 hrs	11674.0	922.3	477.7	08/15/2025
260014	*	ENGINE FIRE EXTINGUISHING	RH	INSPECT	6/07/2013	10274.0	1400 hrs	11674.0	922.3	477.7	08/15/2025
260014	*	ENGINE FIRE EXTINGUISHING	LH	INSPECT	6/07/2013	10274.0	1400 hrs	11674.0	922.3	477.7	08/15/2025
72	*	ENGINE MAJOR PERIODIC INSPECTION	RH		6/04/2013	9607.1	1400 eng	11007.1	922.3	477.7	08/15/2025
97		SB 72-3494 (TURBINE BLADES)	RH		6/04/2013	9607.1	1400 eng	11007.1	922.3	477.7	08/15/2025
12	*	THRUST CONTROL TELEFLEX CABLE/COUPL	RH	LUBE	6/07/2013	9607.1	1400 eng	11007.1	922.3	477.7	08/15/2025
12	*	THRUST CONTROL TELEFLEX CABLE/COUPL	LH	LUBE	6/07/2013	9460.6	1400 eng	10860.6	922.3	477.7	08/15/2025
12	*	48 MONTH AIRCRAFT LUBE			8/20/2021	10559.0	48 mos				08/20/2025
570018	*	AILERON 'A' LEVERS/CONNECTING LINKS		INSPECT	8/20/2021	10559.0	4 yrs				08/20/2025
570016	*	AILERON (REMOVED)		INSPECT	8/20/2021	10559.0	4 yrs				08/20/2025
570023	*	AILERON ASSEMBLY & TABS (X-RAY)	RH	NDT	8/20/2021	10559.0	4 yrs				08/20/2025
570023	*	AILERON ASSEMBLY & TABS (X-RAY)	LH	NDT	8/20/2021	10559.0	4 yrs				08/20/2025
570021	*	AILERON HINGES & ATTACHMENTS		INSPECT	8/20/2021	10559.0	4 yrs				08/20/2025
570020	*	AILERON PULLEY DRUMS		INSPECT	8/20/2021	10559.0	4 yrs				08/20/2025
570017	*	AILERON ROD END BEARINGS		LUBE	8/20/2021	10559.0	4 yrs				08/20/2025
570019	*	AILERON TRIM SCREWJACKS		INSPECT	8/20/2021	10559.0	4 yrs				08/20/2025
570022	*	AIRBRAKE HINGES	RH LOWER	INSPECT	8/20/2021	10559.0	4 yrs				08/20/2025
570022	*	AIRBRAKE HINGES	LH LOWER	INSPECT	8/20/2021	10559.0	4 yrs				08/20/2025
570022	*	AIRBRAKE HINGES	RH UPPER	INSPECT	8/20/2021	10559.0	4 yrs				08/20/2025
570022	*	AIRBRAKE HINGES	LH UPPER	INSPECT	8/20/2021	10559.0	4 yrs				08/20/2025
530019	*	DV WINDOW PANS (DYE PENETRANT)	RH	INSPECT	8/20/2021	10559.0	4 yrs				08/20/2025
530019	*	DV WINDOW PANS (DYE PENETRANT)	LH	INSPECT	8/20/2021	10559.0	4 yrs				08/20/2025
550012	*	ELEVATOR ASSEMBLY (X-RAY)	RH	NDT	8/20/2021	10559.0	4 yrs				08/20/2025
550012	*	ELEVATOR ASSEMBLY (X-RAY)	LH	NDT	8/20/2021	10559.0	4 yrs				08/20/2025
550011	*	ELEVATOR BEARINGS/HINGE BRACKETS	RH	INSPECT	8/20/2021	10559.0	4 yrs				08/20/2025
550011	*	ELEVATOR BEARINGS/HINGE BRACKETS	LH	INSPECT	8/20/2021	10559.0	4 yrs				08/20/2025
550014	*	ELEVATOR TRIM SCREWJACKS		INSPECT	8/20/2021	10559.0	4 yrs				08/20/2025
550013	*	ELEVATOR TRIM TAB RODS END BEARINGS	RH	LUBE/REPL	8/20/2021	10559.0	4 yrs				08/20/2025
550013	*	ELEVATOR TRIM TAB RODS END BEARINGS	LH	LUBE/REPL	8/20/2021	10559.0	4 yrs				08/20/2025
530028	*	ENTRY DOOR SURROUND (OUTWARD OPEN)		INSPECT	8/20/2021	10559.0	4 yrs				08/20/2025
520006	*	ESCAPE HATCH		INSPECT	8/20/2021	10559.0	4 yrs				08/20/2025
570024	*	FLAP AND FLAP VANES (X-RAY)	RH	NDT	8/20/2021	10559.0	4 yrs				08/20/2025
570024	*	FLAP AND FLAP VANES (X-RAY)	LH	NDT	8/20/2021	10559.0	4 yrs				08/20/2025
530010	*	FLT COMP SKIN & WINDOW FRAME (INSP)		NDT	8/20/2021	10559.0	4 yrs				08/20/2025
550005	*	HORIZONTAL STABILIZER ASSEMBLY		INSPECT	8/20/2021	10559.0	4 yrs				08/20/2025
050770	*	INSPECTION G			8/20/2021	10559.0	48 mos				08/20/2025
570011	*	INTERNAL STRUCTURE FRONT/REAR SPAR	RH	INSPECT	8/20/2021	10559.0	4 yrs				08/20/2025
570011	*	INTERNAL STRUCTURE FRONT/REAR SPAR	LH	INSPECT	8/20/2021	10559.0	4 yrs				08/20/2025

LONG RANGE PROJECTION REPORT

HS-125 257208

4/25/2024

N2787

ATA CODE	F A	DESCRIPTION	LOCATION	ACTION	ACCOMPLISHED		INTERVAL	HR/CYC			TARGET DATE
					DATE	HR/CYC		NEXT DUE	CURRENT	REMAINING	
570010	*	MAIN GEAR SIDESTAY ATTACH FITTINGS	RH	INSPECT	8/20/2021	10559.0	4 yrs				08/20/2025
570010	*	MAIN GEAR SIDESTAY ATTACH FITTINGS	LH	INSPECT	8/20/2021	10559.0	4 yrs				08/20/2025
320037	*	MAIN LANDING GEAR FAIRING STRUT	RH	NDT	8/20/2021	10559.0	4 yrs				08/20/2025
320037	*	MAIN LANDING GEAR FAIRING STRUT	LH	NDT	8/20/2021	10559.0	4 yrs				08/20/2025
530023	*	REAR PRESSURE BULKHEAD (LH)	FRONT	INSPECT	8/20/2021	10559.0	4 yrs				08/20/2025
550017	*	RUDDER ASSEMBLY & TABS (X-RAY)		NDT	8/20/2021	10559.0	4 yrs				08/20/2025
550016	*	RUDDER BEARINGS		INSPECT	8/20/2021	10559.0	4 yrs				08/20/2025
550015	*	RUDDER HINGE BRACKETS		INSPECT	8/20/2021	10559.0	4 yrs				08/20/2025
550018	*	RUDDER ROD END BEARINGS		LUBE	8/20/2021	10559.0	4 yrs				08/20/2025
530004	*	SKIN REAR FR 19, UNDER DORSAL TANK		INSPECT	8/20/2021	10559.0	4 yrs				08/20/2025
530003	*	SKIN UNDER DORSAL INTAKE FWD FRM 19		INSPECT	8/20/2021	10559.0	4 yrs				08/20/2025
530005	*	SKIN UNDER WING TO FUSELAGE FAIRING	RH	INSPECT	8/20/2021	10559.0	4 yrs				08/20/2025
530005	*	SKIN UNDER WING TO FUSELAGE FAIRING	LH	INSPECT	8/20/2021	10559.0	4 yrs				08/20/2025
530018	*	STRUCTURE ABOVE FLOOR (SOUNDPROOF)		INSPECT	8/20/2021	10559.0	4 yrs				08/20/2025
570014	*	WING FRONT SPAR	RH	INSPECT	8/20/2021	10559.0	4 yrs				08/20/2025
570014	*	WING FRONT SPAR	LH	INSPECT	8/20/2021	10559.0	4 yrs				08/20/2025
570015	*	WING REAR SPAR	RH	INSPECT	8/20/2021	10559.0	4 yrs				08/20/2025
570015	*	WING REAR SPAR	LH	INSPECT	8/20/2021	10559.0	4 yrs				08/20/2025
570009	*	WING SKINS (X-RAY)	RH LOWER	NDT	8/20/2021	10559.0	4 yrs				08/20/2025
570009	*	WING SKINS (X-RAY)	LH LOWER	NDT	8/20/2021	10559.0	4 yrs				08/20/2025
570012	*	WING TOP SKIN IN AREA OF WING FENCE	RH	INSPECT	8/20/2021	10559.0	4 yrs				08/20/2025
570012	*	WING TOP SKIN IN AREA OF WING FENCE	LH	INSPECT	8/20/2021	10559.0	4 yrs				08/20/2025
29		ENGINE HYDRAULIC PUMP	LH	OVERHAUL	8/29/2008	9680.0	2000 hrs	11680.0	1516.3	483.7	08/21/2025
12	*	24 MONTH AIRCRAFT LUBE			9/25/2023	11156.2	24 mos				09/25/2025
34	*	AIR DATA COMPUTER	#2	CALIBRATE	9/25/2023	11156.2	24 mos				09/25/2025
34	*	AIR DATA COMPUTER	#1	CALIBRATE	9/25/2023	11156.2	24 mos				09/25/2025
34	*	ALTIMETER	STANDBY	CALIBRATE	9/25/2023	11156.2	24 mos				09/25/2025
34	*	ALTIMETER	LH	CALIBRATE	9/25/2023	11156.2	24 mos				09/25/2025
34	*	ALTIMETER	RH	CALIBRATE	9/25/2023	11156.2	24 mos				09/25/2025
26	*	APU FIRE EXT CARTRIDGE	FWD	REPLACE	9/25/2023	11156.2	2 yrs				09/25/2025
550003	*	HORIZ/VERT STAB ATTACH FITTINGS		INSPECT	9/25/2023	11156.2	2 yrs				09/25/2025
550004	*	HORIZ/VERT STAB ATTACH FITTINGS	REAR	INSPECT	9/25/2023	11156.2	2 yrs				09/25/2025
050640	*	INSPECTION F			9/25/2023	11156.2	24 mos				09/25/2025
34	*	RVSM SYSTEM			9/25/2023	11156.2	24 mos				09/25/2025
550023	*	SIDEPLATES, ELEVATOR MASS BAL WT		ANTI CORR	9/25/2023	11156.2	2 yrs				09/25/2025
34	*	STATIC SYSTEM LEAK CHECK	STAND-BY	TEST	9/25/2023	11156.2	24 mos				09/25/2025
34	*	STATIC SYSTEM LEAK CHECK	RH	TEST	9/25/2023	11156.2	24 mos				09/25/2025
34	*	STATIC SYSTEM LEAK CHECK	LH	TEST	9/25/2023	11156.2	24 mos				09/25/2025
34	*	TRANSPONDER	#2	TEST	9/25/2023	11156.2	24 mos				09/25/2025
34	*	TRANSPONDER	#1	TEST	9/25/2023	11156.2	24 mos				09/25/2025
23	*	UNDERWATER LOCATOR BEACON/BATTERY	CVR	OPS TEST	9/25/2023	11156.2	24 mos				09/25/2025
550002	*	VERTICAL STABILIZER RIB 6		INSPECT	9/25/2023	11156.2	2 yrs				09/25/2025
530014	*	WINDSHIELD CENTR POST CAPPING STRIP	TOP	INSPECT	8/20/2021	10559.0	1200 hrs	11759.0	637.3	562.7	11/08/2025
72	*	1000-1500 HOUR ENG INSPECT	RH		6/04/2013	9607.1	1500 eng	11107.1	922.3	577.7	11/23/2025

LONG RANGE PROJECTION REPORT

HS-125 257208

4/25/2024

N2787

ATA CODE	F A	DESCRIPTION	LOCATION	ACTION	ACCOMPLISHED		INTERVAL	HR/CYC			TARGET DATE
					DATE	HR/CYC		NEXT DUE	CURRENT	REMAINING	
49		APU STARTER/GENERATOR		OVERHAUL	9/13/2012	3414.8	1000 hrs	4414.8	417.0	583.0	11/29/2025
530020	*	PRESSURE BULKHEAD SIDE WALL BEAMS	FRONT	INSPECT	8/20/2021	9221	1000 ldg	10221	394	606	12/22/2025
26	*	APU FIRE EXTING OPERATING HEAD		REPLACE	2/09/2016	10343.8	10 yrs				02/09/2026
720001	*	ENGINE MOUNT BRACKETS (FWD)	RH	MAG PART	8/20/2021	10559.0	1400 hrs	11959.0	637.3	762.7	05/27/2026
720001	*	ENGINE MOUNT BRACKETS (FWD)	LH	MAG PART	8/20/2021	10559.0	1400 hrs	11959.0	637.3	762.7	05/27/2026
21		MAIN SUPPLY CABIN NON RETURN VALVE		OVERHAUL	11/30/1994	5631.6	12000 hrs	12000.0	11196.3	803.7	07/07/2026
72	*	ACCESSORY GEARBOX	RH	INSPECT	1/11/2000	7164.6	4200 eng	11364.6	3364.8	835.2	08/08/2026
99	*	AD 2000-15-09 (HPC IMPELLER)	RH		1/11/2000	7164.6	4200 eng	11364.6	3364.8	835.2	08/08/2026
72	*	ENGINE COMPRESSOR ZONE INSPECTION	RH		1/11/2000	7164.6	4200 eng	11364.6	3364.8	835.2	08/08/2026
97		SB A72-3641 (HP IMPELLER)	RH		1/11/2000	7164.6	4200 eng	11364.6	3364.8	835.2	08/08/2026
26	*	APU FIRE EXTING PRESS RELIEF PLUG		REPLACE	8/20/2021	10559.0	5 yrs				08/20/2026
26	*	APU FIRE EXTINGUISHER		OVERHAUL	8/20/2021	10559.0	5 yrs				08/20/2026
35	*	OXYGEN CONTAINER (750 LITRE) HYDRO	RH	OVERHAUL	8/20/2021	10559.0	5 yrs				08/20/2026
35	*	OXYGEN CONTAINER (750 LITRE) HYDRO	LH	OVERHAUL	8/20/2021	10559.0	5 yrs				08/20/2026
35	*	OXYGEN CONTAINER HYDRO	#3	OVERHAUL	8/20/2021	10559.0	5 yrs				08/20/2026
24		GROUND SUPPLY START CONTACTOR		OVERHAUL	11/30/1995	6048.1	6000 hrs	12048.1	5148.2	851.8	08/24/2026
72	*	LP 1ST STAGE AXIAL COMPRESSOR DISC	LH	REPLACE	7/20/1983	0	10000 cyc	10000	9051	949	11/30/2026
72	*	LP 2ND STAGE AXIAL COMPRESSOR DISC	LH	REPLACE	7/20/1983	0	10000 cyc	10000	9051	949	11/30/2026
72	*	LP 3RD STAGE AXIAL COMPRESSOR DISC	LH	REPLACE	7/20/1983	0	10000 cyc	10000	9051	949	11/30/2026
72	*	LP 4TH STAGE AXIAL COMPRESSOR DISC	LH	REPLACE	7/20/1983	0	10000 cyc	10000	9051	949	11/30/2026
72	*	HP ROTOR SEAL PLATE	RH	REPLACE	4/07/1983	0	10000 cyc	10000	9049	951	12/02/2026
72	*	LP 1ST STAGE AXIAL COMPRESSOR DISC	RH	REPLACE	4/07/1983	0	10000 cyc	10000	9049	951	12/02/2026
72	*	LP 2ND STAGE AXIAL COMPRESSOR DISC	RH	REPLACE	9/27/1996	5179	10000 cyc	10000	9049	951	12/02/2026
72	*	LP 4TH STAGE AXIAL COMPRESSOR DISC	RH	REPLACE	4/07/1983	0	10000 cyc	10000	9049	951	12/02/2026
28		FUEL BOOST PUMP	LH	OVERHAUL	12/05/2000	8188.7	4000 hrs	12188.7	3007.6	992.4	01/12/2027
29		ENGINE HYDRAULIC PUMP	RH	OVERHAUL	6/07/2013	10274.0	2000 hrs	12274.0	922.3	1077.7	04/07/2027
27		AIRBRAKE JACK	RH	OVERHAUL	10/21/2005	9284.7	3000 hrs	12284.7	1911.6	1088.4	04/18/2027
71	*	ENGINE REAR MOUNT ATTACH BOLT	RH	REPLACE	6/07/2013	10274.0	2100 hrs	12374.0	922.3	1177.7	07/16/2027
25	*	ELT BATTERY REPLACE			8/01/2022	11156.2	5 yrs				08/01/2027
26	*	CABIN FIRE EXTINGUISHER		RECHARGE	8/20/2021	10559.0	6 yrs				08/20/2027
26	*	COCKPIT FIRE EXTINGUISHER		RECHARGE	8/20/2021	10559.0	6 yrs				08/20/2027
35		OXYGEN MASK	COPILOT	OVERHAUL	8/20/2021	10559.0	6 yrs				08/20/2027
72	*	LP 1ST STAGE TURBINE ROTOR DISC	RH	REPLACE	2/08/2005	7264	3000 cyc	10264	1785	1215	08/23/2027
72	*	LP 2ND STAGE TURBINE ROTOR DISC	RH	REPLACE	2/08/2005	7264	3000 cyc	10264	1785	1215	08/23/2027
72	*	ACCESSORY GEARBOX	LH	INSPECT	12/14/2000	7400.2	4200 eng	11600.2	2982.7	1217.3	08/25/2027
99	*	AD 2000-15-09 (HPC IMPELLER)	LH		12/14/2000	7400.2	4200 eng	11600.2	2982.7	1217.3	08/25/2027
72	*	ENGINE COMPRESSOR ZONE INSPECTION	LH		12/14/2000	7400.2	4200 eng	11600.2	2982.7	1217.3	08/25/2027
97		SB A72-3641 (HP IMPELLER)	LH		12/14/2000	7400.2	4200 eng	11600.2	2982.7	1217.3	08/25/2027
99	*	AD 77-13-02 (BRAKE KNIFE EDGE)			6/28/1999	6509	4500 ldg	11009	3106	1394	02/18/2028
32	*	BRAKE CONTROL VALVE KNIFE EDGE	INNER	REPLACE	6/28/1999	6509	4500 ldg	11009	3106	1394	02/18/2028
32	*	BRAKE CONTROL VALVE KNIFE EDGE	RH OUTER	REPLACE	6/28/1999	6509	4500 ldg	11009	3106	1394	02/18/2028
32	*	BRAKE CONTROL VALVE KNIFE EDGE	LH OUTER	REPLACE	6/28/1999	6509	4500 ldg	11009	3106	1394	02/18/2028
26	*	APU FIRE EXT CARTRIDGE MANUF DATE	FWD	REPLACE	9/25/2023	11156.2	5 yrs				09/25/2028
72	*	LP 1ST STAGE TURBINE ROTOR DISC	LH	REPLACE	8/02/2007	7748	3000 cyc	10748	1303	1697	12/17/2028

LONG RANGE PROJECTION REPORT

HS-125 257208

4/25/2024

N2787

ATA CODE	F A	DESCRIPTION	LOCATION	ACTION	ACCOMPLISHED		INTERVAL	HR/CYC			TARGET DATE
					DATE	HR/CYC		NEXT DUE	CURRENT	REMAINING	
72	*	LP 2ND STAGE TURBINE ROTOR DISC	LH	REPLACE	8/02/2007	7748	3000 cyc	10748	1303	1697	12/17/2028
530033	*	FUSELAGE SKIN ADJ CAB WINDOW CUTOUT		INSPECT	8/20/2021	10559.0	2400 hrs	12959.0	637.3	1762.7	02/20/2029
490007	*	APU HOT SECTION INSPECTION			9/09/2009	3221.2	2500 hrs	5721.2	610.6	1889.4	06/27/2029
27		AIRBRAKE JACK	LH	OVERHAUL	2/04/2012	10126.5	3000 hrs	13126.5	1069.8	1930.2	08/07/2029
530029	*	CENTER FUSELAGE STRUCTURE (X-RAY)	ABV FLOOR	NDT	8/20/2021	10559.0	8 yrs				08/20/2029
530017	*	COCKPIT STRUCTURE ABOVE FLOOR		INSPECT	8/20/2021	10559.0	8 yrs				08/20/2029
520007	*	ENTRY DOOR ,OUTWARD OPENING (X-RAY)		NDT	8/20/2021	10559.0	8 yrs				08/20/2029
530026	*	FUSE STRUCT NLG-13 & 16-19(X-RAY)	BLW FLOOR	NDT	8/20/2021	10559.0	8 yrs				08/20/2029
530022	*	FUSE STRUCT NLG-13 & 16-19(X-RAY)	BLW FLOOR	NDT	8/20/2021	10559.0	8 yrs				08/20/2029
530007	*	FUSELAGE SKIN COVER BY VENTRAL TANK		INSPECT	8/20/2021	10559.0	8 yrs				08/20/2029
530027	*	FUSELAGE STRUCT FRAME 13-16 (X-RAY)	BLW FLOOR	NDT	8/20/2021	10559.0	8 yrs				08/20/2029
530025	*	FUSELAGE STRUCTR BELOW ESCAPE HATCH	FRME	INSPECT	8/20/2021	10559.0	8 yrs				08/20/2029
550008	*	HORIZ STAB (INTERNAL STRUCTURE)		INSPECT	8/20/2021	10559.0	8 yrs				08/20/2029
550009	*	HORIZ/VERT STAB ATTACH FITTINGS		INSPECT	8/20/2021	10559.0	8 yrs				08/20/2029
550019	*	HORIZONTAL STAB ASSEMBLY (X-RAY)		NDT	8/20/2021	10559.0	8 yrs				08/20/2029
550010	*	HORIZONTAL STAB FOKKER BOND TEST	RH	NDT	8/20/2021	10559.0	8 yrs				08/20/2029
550010	*	HORIZONTAL STAB FOKKER BOND TEST	LH	NDT	8/20/2021	10559.0	8 yrs				08/20/2029
550006	*	HORIZONTAL STABILIZER (FRONT SPAR)		INSPECT	8/20/2021	10559.0	8 yrs				08/20/2029
550020	*	HORZ STAB T FITTING & JOINT STRAP		INSPECT	8/20/2021	10559.0	8 yrs				08/20/2029
530008	*	KEEL SKIN BEHIND VENTRAL FUEL TANK		INSPECT	8/20/2021	10559.0	8 yrs				08/20/2029
530024	*	PRESSURE BULKHEAD (FRONT FACE)	REAR	INSPECT	8/20/2021	10559.0	8 yrs				08/20/2029
530006	*	VENTRAL FUEL TANK & ATTACHMENTS		INSPECT	8/20/2021	10559.0	8 yrs				08/20/2029
530009	*	VENTRAL FUEL TANK TO FUSELG FAIRING		INSPECT	8/20/2021	10559.0	8 yrs				08/20/2029
550007	*	VERTICAL STABILIZER ASSEMBLY (X-RAY)		NDT	8/20/2021	10559.0	8 yrs				08/20/2029
530011	*	WING ATTACH LINKS,BRACKETS & BOLTS	RH	INSPECT	8/20/2021	10559.0	8 yrs				08/20/2029
530011	*	WING ATTACH LINKS,BRACKETS & BOLTS	LH	INSPECT	8/20/2021	10559.0	8 yrs				08/20/2029
570025	*	WING STRUCTURE FWD OF CENTER SPAR	RH	INSPECT	8/20/2021	10559.0	8 yrs				08/20/2029
570025	*	WING STRUCTURE FWD OF CENTER SPAR	LH	INSPECT	8/20/2021	10559.0	8 yrs				08/20/2029
23		UNDERWATER LOCATOR BEACON BATT-CVR		REPLACE	9/25/2023	11156.2	6 yrs				09/25/2029
32		BRAKE MAXARET	RH OTBD	OVERHAUL	8/06/2010	8671	3000 ldg	11671	944	2056	12/11/2029
72	*	HP ROTOR SEAL PLATE	LH	REPLACE	7/31/1997	5388	10000 cyc	11217	7834	2166	03/31/2030
32		BRAKE MAXARET	RH INBD	OVERHAUL	4/04/2012	8923	3000 ldg	11923	692	2308	08/20/2030
32		BRAKE MAXARET	LH OTBD	OVERHAUL	9/13/2012	8987	3000 ldg	11987	628	2372	10/23/2030
05	*	AIRCRAFT REGISTRATION			10/31/2023		7 yrs				10/31/2030
32	*	MAIN GEAR RETRACTION ARM	RH	REPLACE	12/01/1984	0	12000 ldg	12000	9615	2385	11/05/2030
32	*	MAIN GEAR RETRACTION ARM	LH	REPLACE	12/01/1984	0	12000 ldg	12000	9615	2385	11/05/2030
32	*	MAIN GEAR SIDESTAY UPPER ARM	RH	REPLACE	12/01/1984	0	12000 ldg	12000	9615	2385	11/05/2030
32	*	MAIN GEAR SIDESTAY UPPER ARM	LH	REPLACE	12/01/1984	0	12000 ldg	12000	9615	2385	11/05/2030
27		FLAP SCREWJACK & REDUCTION GEARBOX	RH	OVERHAUL	1/20/2006	8013	4000 ldg	12013	1602	2398	11/18/2030
27		FLAP SCREWJACK & REDUCTION GEARBOX	LH	OVERHAUL	1/20/2006	8013	4000 ldg	12013	1602	2398	11/18/2030
26	*	ENGINE FIRE EXTINGUISHER	LH (AFT)	HYDRO	8/20/2021	10559.0	10 yrs				08/20/2031
26	*	ENGINE FIRE EXTINGUISHER	RH (FWD)	HYDRO	8/20/2021	10559.0	10 yrs				08/20/2031
29		PRESSURE MAINTAINING VALVE		OVERHAUL	9/02/2003	7520	5000 ldg	12520	2095	2905	04/08/2032
72	*	HP SHOULDERED SHAFT	RH	REPLACE	4/07/1983	0	12000 cyc	12000	9049	2951	05/24/2032

LONG RANGE PROJECTION REPORT

4/25/2024

HS-125 257208

N2787

ATA CODE	F A	DESCRIPTION	LOCATION	ACTION	ACCOMPLISHED		INTERVAL	HR/CYC			TARGET DATE
					DATE	HR/CYC		NEXT DUE	CURRENT	REMAINING	
72	*	FAN SUPPORT ASSEMBLY	RH	INSPECT	6/04/2013	9607.1	4200 eng	13807.1	922.3	3277.7	04/15/2033
72	*	FAN SUPPORT ASSEMBLY	LH	INSPECT	8/02/2007	9460.6	4200 eng	13660.6	922.3	3277.7	04/15/2033
99	*	AD 77-13-11 (BRAKE EMER KNIFE EDGE)			8/29/2008	8411	4500 ldg	12911	1204	3296	05/04/2033
32	*	BRAKE EMER REDUCING VALVE KNIFE EDG	RH	REPLACE	8/29/2008	8411	4500 ldg	12911	1204	3296	05/04/2033
32	*	BRAKE EMER REDUCING VALVE KNIFE EDG	LH	REPLACE	8/29/2008	8411	4500 ldg	12911	1204	3296	05/04/2033
27		FLAP SYNCHRONIZ SYS RECEIVER UNIT		OVERHAUL	8/29/2008	8411	4500 ldg	12911	1204	3296	05/04/2033
98		SB 32-167 (FAIL OF BRAKE KNIFE EDG)	LH/RH		8/29/2008	8411	4500 ldg	12911	1204	3296	05/04/2033
72	*	LP 3RD STAGE TURBINE ROTOR DISC	LH	REPLACE	7/31/1997	5388	7000 cyc	12388	3663	3337	06/14/2033
26	*	CABIN FIRE EXTINGUISHER		HYDRO	8/20/2021	10559.0	12 yrs				08/20/2033
26	*	COCKPIT FIRE EXTINGUISHER		HYDRO	8/20/2021	10559.0	12 yrs				08/20/2033
530015	*	NOSE LANDING GEAR BAY SIDEWALLS		INSPECT	8/20/2021	10559.0	12 yrs				08/20/2033
24		INVERTER SUPPLY CONTACTOR	#1	OVERHAUL	2/11/2011	9976.5	5000 hrs	14976.5	1219.8	3780.2	08/31/2034
32		MAIN GEAR DOOR JACK	RH	OVERHAUL	8/29/2008	8411	5000 ldg	13411	1204	3796	09/16/2034
29		FULL FLOW RELIEF VALVE	#2	OVERHAUL	7/17/2012	8971	4500 ldg	13471	644	3856	11/15/2034
29		FULL FLOW RELIEF VALVE	#1	OVERHAUL	7/17/2012	8971	4500 ldg	13471	644	3856	11/15/2034
32		BRAKE EMERGENCY SYS PRESSURE SWITCH	RH	OVERHAUL	9/13/2012	10184.6	5000 hrs	15184.6	1011.7	3988.3	03/27/2035
32		BRAKE EMERGENCY SYS PRESSURE SWITCH	LH	OVERHAUL	9/13/2012	10184.6	5000 hrs	15184.6	1011.7	3988.3	03/27/2035
530013	*	FUSELAGE LAP JOINTS (INSPECT)		NDT	8/20/2021	9221	4500 ldg	13721	394	4106	07/23/2035
72	*	HP TURBINE WHEEL ROTOR	RH	REPLACE	1/11/2000	6190	7000 cyc	13190	2859	4141	08/27/2035
72	*	LP 3RD STAGE TURBINE ROTOR DISC	RH	REPLACE	1/11/2000	6190	7000 cyc	13190	2859	4141	08/27/2035
570026	*	WING BOTTOM SKIN @ ATTACH FRT SPAR	RH	INSPECT	8/20/2021	10559.0	4800 hrs	15359.0	637.3	4162.7	09/17/2035
570026	*	WING BOTTOM SKIN @ ATTACH FRT SPAR	LH	INSPECT	8/20/2021	10559.0	4800 hrs	15359.0	637.3	4162.7	09/17/2035
32	*	DRAG STRUT PICK UP		REPLACE	12/01/1984	0	13900 ldg	13900	9615	4285	01/18/2036
72	*	HP TURBINE WHEEL ROTOR	LH	REPLACE	12/14/2000	6414	7000 cyc	13414	2637	4363	04/05/2036
32		MAIN GEAR RETRACT JACK	RH	OVERHAUL	6/07/2013	9083	5000 ldg	14083	532	4468	07/19/2036
27		FLAP CONTROL UNIT		OVERHAUL	7/14/2006	8105	6000 ldg	14105	1510	4490	08/10/2036
72	*	HP COMPRESSOR RADIAL IMPELLER	RH	REPLACE	6/04/2013	8517	10000 cyc	13660	5389	4611	12/09/2036
72	*	LP 3RD STAGE AXIAL COMPRESSOR DISC	RH	REPLACE	6/04/2013	8517	10000 cyc	14351	4698	5302	10/31/2038
72	*	FAN ROTOR DISC & HUB	RH	REPLACE	6/19/1995	4761	10000 cyc	14761	4288	5712	12/15/2039
72	*	FAN ROTOR DISC & HUB	LH	REPLACE	11/23/1995	4919	10000 cyc	14919	4132	5868	05/19/2040
57	*	FLAP HINGE ATTACH ANGLE BOLTS	RH INNER	REPLACE	12/15/1983	0	16000 ldg	16000	9615	6385	10/18/2041
57	*	FLAP HINGE ATTACH ANGLE BOLTS	LH INNER	REPLACE	12/15/1983	0	16000 ldg	16000	9615	6385	10/18/2041
32	*	NOSE LANDING GEAR PIVOT PIN		REPLACE	4/24/2006	8062	16000 ldg	16356	9259	6741	10/09/2042
32	*	MAIN GEAR JACK EYE END	RH	REPLACE	12/01/1984	0	10000 ldg	16944	2671	7329	05/19/2044
32	*	MAIN GEAR JACK EYE END	LH	REPLACE	12/01/1984	0	10000 ldg	16944	2671	7329	05/19/2044
72	*	HP COMPRESSOR RADIAL IMPELLER	LH	REPLACE	12/14/2000	6414	10000 cyc	16414	2637	7363	06/22/2044
32	*	NOSE STEERING JACK PICK UP		REPLACE	12/01/1984	0	18000 ldg	18000	9615	8385	04/10/2047
32	*	NOSE GEAR PICK-UP TRUNNION BOLTS		REPLACE	4/24/2006	8062	10000 ldg	18062	1553	8447	06/11/2047
32	*	NOSE GEAR RADIUS ROD PICK-UP BOLTS		REPLACE	4/24/2006	8062	10000 ldg	18062	1553	8447	06/11/2047
570027	*	LOWER WING SKIN CNTRLNE JOINT STRAP	RH	INSPECT	8/20/2021	10559.0	9600 hrs	20159.0	637.3	8962.7	11/07/2048
570027	*	LOWER WING SKIN CNTRLNE JOINT STRAP	LH	INSPECT	8/20/2021	10559.0	9600 hrs	20159.0	637.3	8962.7	11/07/2048
570028	*	UPR SURFACE OF LWR WING SKIN(X-RAY)	RH	NDT	8/20/2021	10559.0	9600 hrs	20159.0	637.3	8962.7	11/07/2048
570028	*	UPR SURFACE OF LWR WING SKIN(X-RAY)	LH	NDT	8/20/2021	10559.0	9600 hrs	20159.0	637.3	8962.7	11/07/2048
530031	*	ENG MAIN MOUNT ATTACH FITNG (INSP)	RH	NDT	8/20/2021	10559.0	10000 hrs	20559.0	637.3	9362.7	12/12/2049

LONG RANGE PROJECTION REPORT

4/25/2024

HS-125 257208

N2787

ATA CODE	FAA	DESCRIPTION	LOCATION	ACTION	ACCOMPLISHED		INTERVAL	HR/CYC			TARGET DATE
					DATE	HR/CYC		NEXT DUE	CURRENT	REMAINING	
530031	*	ENG MAIN MOUNT ATTACH FITNG (INSP)	LH	NDT	8/20/2021	10559.0	10000 hrs	20559.0	637.3	9362.7	12/12/2049
530030	*	ENGINE BEAM INSPECTION	RH		8/20/2021	10559.0	10000 hrs	20559.0	637.3	9362.7	12/12/2049
530030	*	ENGINE BEAM INSPECTION	LH		8/20/2021	10559.0	10000 hrs	20559.0	637.3	9362.7	12/12/2049
72	*	HP SHOULDERED SHAFT	LH	REPLACE	12/14/2000	6414	12000 cyc	18414	2637	9363	12/13/2049
32	*	MAIN GEAR TORQUE LINK PIN	RH LOWER	REPLACE	12/01/1984	0	20000 ldg	20000	9615	10385	09/30/2052
32	*	MAIN GEAR TORQUE LINK PIN	LH LOWER	REPLACE	12/01/1984	0	20000 ldg	20000	9615	10385	09/30/2052
32	*	MAIN GEAR TORQUE LINK PIN	RH UPPER	REPLACE	12/01/1984	0	20000 ldg	20000	9615	10385	09/30/2052
32	*	MAIN GEAR TORQUE LINK PIN	LH UPPER	REPLACE	12/01/1984	0	20000 ldg	20000	9615	10385	09/30/2052
32	*	NOSE GEAR CONNECTING ROD		REPLACE	12/01/1984	0	20000 ldg	20000	9615	10385	09/30/2052
32	*	NOSE STEERING SLEEVE		REPLACE	12/01/1984	0	20000 ldg	20000	9615	10385	09/30/2052
570029	*	WING SKIN CNTR BUTT STRAP (INSPECT)	RH LOWER	NDT	8/20/2021	10559.0	12000 hrs	22559.0	637.3	11362.7	06/04/2055
570029	*	WING SKIN CNTR BUTT STRAP (INSPECT)	LH LOWER	NDT	8/20/2021	10559.0	12000 hrs	22559.0	637.3	11362.7	06/04/2055
32	*	NOSE GEAR STEERING JACK EYE END		REPLACE	6/07/2013	9083	14400 ldg	21983	2032	12368	03/06/2058
32	*	MAIN GEAR UPPER CASING	RH	REPLACE	12/01/1984	0	24000 ldg	24000	9615	14385	09/13/2063
32	*	MAIN GEAR UPPER CASING	LH	REPLACE	12/01/1984	0	24000 ldg	24000	9615	14385	09/13/2063
32	*	MAIN LANDING GEAR JACK DISTANCE PIN	RH	REPLACE	12/01/1984	0	24000 ldg	24000	9615	14385	09/13/2063
27	*	AIRBRAKE JACK BODY	RH	REPLACE	12/01/1984	0	25000 ldg	25000	9615	15385	06/09/2066
27	*	AIRBRAKE JACK BODY	LH	REPLACE	12/01/1984	0	25000 ldg	25000	9615	15385	06/09/2066
32	*	MAIN GEAR PLUNGER TUBE	RH	REPLACE	12/01/1984	0	27000 ldg	27000	9615	17385	11/30/2071
32	*	MAIN GEAR PLUNGER TUBE	LH	REPLACE	12/01/1984	0	27000 ldg	27000	9615	17385	11/30/2071
32	*	MAIN GEAR SIDESTAY LOWER ARM	RH	REPLACE	12/01/1984	0	27000 ldg	27000	9615	17385	11/30/2071
32	*	MAIN GEAR SIDESTAY LOWER ARM	LH	REPLACE	12/01/1984	0	27000 ldg	27000	9615	17385	11/30/2071
32	*	NOSE GEAR PLUNGER TUBE		REPLACE	4/24/2006	8062	20000 ldg	28062	1553	18447	10/27/2074
530032	*	ENG REAR MOUNT ATTACH FITNG (INSP)	RH	NDT	8/20/2021	10559.0	20000 hrs	30559.0	637.3	19362.7	04/29/2077
530032	*	ENG REAR MOUNT ATTACH FITNG (INSP)	LH	NDT	8/20/2021	10559.0	20000 hrs	30559.0	637.3	19362.7	04/29/2077
72	*	LP 2ND STAGE AXIAL COMPRESSOR DISC	RH	REPLACE	6/04/2013	8517	20000 cyc	28517	532	19468	08/13/2077
530021	*	UPPER CANOPY RAIL AT CANOPY POSTS		INSPECT	8/20/2021	9221	20000 ldg	29221	394	19606	12/29/2077
32	*	MAIN GEAR JACK PIVOT BOLT	RH	REPLACE	12/01/1984	0	30000 ldg	30000	9615	20385	02/16/2080
32	*	NOSE GEAR JACK LOWER PIVOT PIN		REPLACE	4/24/2006	8062	22000 ldg	30062	1553	20447	04/18/2080
32	*	NOSE GEAR AXLE BARREL		REPLACE	4/24/2006	8062	30000 ldg	30356	9259	20741	02/06/2081
32	*	MAIN LANDING GEAR JACK DISTANCE PIN	LH	REPLACE	12/01/1984	0	24000 ldg	31901	1714	22286	05/01/2085
32	*	MAIN GEAR RETRACTION ARM PIN	RH	REPLACE	12/01/1984	0	32000 ldg	32000	9615	22385	08/08/2085
32	*	MAIN GEAR RETRACTION ARM PIN	LH	REPLACE	12/01/1984	0	32000 ldg	32000	9615	22385	08/08/2085
32	*	NOSE GEAR TORQUE LINK	LOWER	REPLACE	12/01/1984	0	32000 ldg	32000	9615	22385	08/08/2085
32	*	NOSE GEAR TORQUE LINK	UPPER	REPLACE	12/01/1984	0	32000 ldg	32000	9615	22385	08/08/2085
32	*	NOSE STEERING PIN		REPLACE	4/24/2006	8062	25000 ldg	33062	1553	23447	07/05/2088
32	*	NOSE STEERING MAIN MEMBER	LOWER	REPLACE	12/01/1984	0	35000 ldg	35000	9615	25385	10/25/2093
32	*	NOSE STEERING MAIN MEMBER	UPPER	REPLACE	12/01/1984	0	35000 ldg	35000	9615	25385	10/25/2093
32	*	MAIN GEAR JACK PIVOT BOLT	LH	REPLACE	12/01/1984	0	30000 ldg	37901	1714	28286	10/05/2101
32	*	NOSE GEAR DRAG STAY BRIDGE CASTING		REPLACE	11/30/1994	4975	33000 ldg	37975	4640	28360	12/18/2101
23		COCKPIT VOICE RECORDER		MTBF	2/09/2016	10342.2	30000 hrs	40286.8	909.5	29090.5	12/18/2103
550021	*	VERT STAB ROOT ATTACH TO FUSE (X-RAY)		NDT	8/20/2021	10559.0	30000 hrs	40559.0	637.3	29362.7	09/15/2104
32	*	NOSE GEAR MAIN CASING BOLT		REPLACE	4/24/2006	8062	33000 ldg	41062	1553	31447	06/01/2110

NOTE: * INDICATES FAA MANDATORY REQUIREMENT.

COMPONENT INVENTORY REPORT
HS-125 257208

4/25/2024
N2787

A T A	O C	D E S C R I P T I O N	L O C A T I O N	P A R T N U M B E R	S E R I A L N U M B E R	I N S T A L L A T I O N			C U R R E N T T I M E
						D A T E	T I M E	T S O	
21		MAIN SUPPLY CABIN NON RETURN VALVE		AWE124-51A	8910025	11/30/1994	5631.6 hrs	5631.6	11196.3
21		ABSOLUTE PRESSURE CONTROL	LH	102466-5	UNKNOWN	12/01/1984	0 ldg	0	9615
21		ABSOLUTE PRESSURE CONTROL	LH	102466-5	UNKNOWN	12/01/1984	0.0 hrs	0.0	11196.3
21		ABSOLUTE PRESSURE CONTROL	RH	102466-5	UNKNOWN	12/01/1984	0 ldg	0	9615
21		ABSOLUTE PRESSURE CONTROL	RH	102466-5	UNKNOWN	12/01/1984	0.0 hrs	0.0	11196.3
21		AIR JET PUMP		131150-1-1	UNKNOWN	12/01/1984	0 ldg	0	9615
21		AIR JET PUMP		131150-1-1	UNKNOWN	12/01/1984	0.0 hrs	0.0	11196.3
21		APU SUPPLY CHECK VALVE		109812-9	P3630	9/21/2009	8564 ldg	0	1051
21		APU SUPPLY CHECK VALVE		109812-9	P3630	9/21/2009	9827.1 hrs	0.0	1369.2
21		AUXILIARY HEATING VALVE		104568-3	UNKNOWN	12/01/1984	0 ldg	0	9615
21		AUXILIARY HEATING VALVE		104568-3	UNKNOWN	12/01/1984	0.0 hrs	0.0	11196.3
21		BLEED AIR MIXING VALVE	LH	3213788-1-1	UNKNOWN	12/01/1984	0 ldg	0	9615
21		BLEED AIR MIXING VALVE	LH	3213788-1-1	UNKNOWN	12/01/1984	0.0 hrs	0.0	11196.3
21		BLEED AIR NON RETURN VALVE	LH	HTE4168	UNKNOWN	12/01/1984	0 ldg	0	9615
21		BLEED AIR NON RETURN VALVE	LH	HTE4168	UNKNOWN	12/01/1984	0.0 hrs	0.0	11196.3
21		BLEED AIR NON RETURN VALVE	RH	HTE4168	UNKNOWN	12/01/1984	0 ldg	0	9615
21		BLEED AIR NON RETURN VALVE	RH	HTE4168	UNKNOWN	12/01/1984	0.0 hrs	0.0	11196.3
21		CABIN ALTIMETER		PW73AM4	UNKNOWN	12/01/1984	0 ldg	0	9615
21		CABIN ALTIMETER		PW73AM4	UNKNOWN	12/01/1984	0.0 hrs	0.0	11196.3
21		CABIN DIFFERENTIAL PRESS INDICATOR		PW1491PG	UNKNOWN	12/01/1984	0 ldg	0	9615
21		CABIN DIFFERENTIAL PRESS INDICATOR		PW1491PG	UNKNOWN	12/01/1984	0.0 hrs	0.0	11196.3
21		CABIN RATE OF CLIMB INDICATOR		720-15900-901	UNKNOWN	12/01/1984	0 ldg	0	9615
21		CABIN RATE OF CLIMB INDICATOR		720-15900-901	UNKNOWN	12/01/1984	0.0 hrs	0.0	11196.3
21		CABIN RECIRCULATING FAN		45C3-111	443786S	5/03/2002	7233 ldg	0	2382
21		CABIN RECIRCULATING FAN		45C3-111	443786S	5/03/2002	8541.4 hrs	0.0	2654.9
21		CABIN TEMP CONTROL SENSOR		25-6-MC-415	062C-413	9/21/2009	8564 ldg	0	1051
21		CABIN TEMP CONTROL SENSOR		25-6-MC-415	062C-413	9/21/2009	9827.1 hrs	0.0	1369.2
21		CABIN TEMP CONTROLLER (THERMAL SWT)		617452-3	072C-318	2/15/1985	31.4 hrs	0.0	11164.9
21		CABIN TEMP SENSOR FAN		19A2323	UNKNOWN	1/30/2003	7383 ldg	0	2232
21		CABIN TEMP SENSOR FAN		19A2323	UNKNOWN	1/30/2003	8675.0 hrs	0.0	2521.3
21		CABIN TEMPERATURE INDICATOR		51-2004	81R118	7/06/2001	7086 ldg	0	2529
21		CABIN TEMPERATURE INDICATOR		51-2004	81R118	7/06/2001	8350.8 hrs	0.0	2845.5
21		COOLING TURBINE		203880-2-2	UNKNOWN	12/01/1984	0 ldg	0	9615
21		COOLING TURBINE		203880-2-2	UNKNOWN	12/01/1984	0.0 hrs	0.0	11196.3
21		DEPRESS ALTITUDE WARNING SWITCH		214C40-2-57	W48995	11/06/1999	6649 ldg	0	2966
21		DEPRESS ALTITUDE WARNING SWITCH		214C40-2-57	W48995	11/06/1999	7749.1 hrs	0.0	3447.2
21		DUCT OVERHEAT TEMP WARNING SWITCH	LH	156D/05	D2448	9/15/2014	9097 ldg	0	518
21		DUCT OVERHEAT TEMP WARNING SWITCH	LH	156D/05	D2448	9/15/2014	10286.8 hrs	0.0	909.5
21		DUCT OVERHEAT TEMP WARNING SWITCH	RH	150D01-100	D2448	9/15/2014	9097 ldg	0	518
21		DUCT OVERHEAT TEMP WARNING SWITCH	RH	150D01-100	D2448	9/15/2014	10286.8 hrs	0.0	909.5
21		DUCT TEMPERATURE SWITCH		21346-5	4016	11/22/1992	4234 ldg	0	5381
21		DUCT TEMPERATURE SWITCH		21346-5	4016	11/22/1992	4765.5 hrs	0.0	6430.8
21		ENG HIGH PRESSURE BLEED AIR SWITCH	LH	HE12394	UNKNOWN	12/01/1984	0 ldg	0	9615
21		ENG HIGH PRESSURE BLEED AIR SWITCH	LH	HE12394	UNKNOWN	12/01/1984	0.0 hrs	0.0	11196.3

COMPONENT INVENTORY REPORT
HS-125 257208

4/25/2024
N2787

A T A	O C	D E S C R I P T I O N	L O C A T I O N	P A R T N U M B E R	S E R I A L N U M B E R	I N S T A L L A T I O N			C U R R E N T T I M E
						D A T E	T I M E	T S O	
21		ENG HIGH PRESSURE BLEED AIR SWITCH	RH	HE12394	UNKNOWN	12/01/1984	0 ldg	0	9615
21		ENG HIGH PRESSURE BLEED AIR SWITCH	RH	HE12394	UNKNOWN	12/01/1984	0.0 hrs	0.0	11196.3
21		ENG HP BLEED AIR SHUT OFF VALVE	LH	BOIA2-14128A	UNKNOWN	12/01/1984	0 ldg	0	9615
21		ENG HP BLEED AIR SHUT OFF VALVE	LH	BOIA2-14128A	UNKNOWN	12/01/1984	0.0 hrs	0.0	11196.3
21		ENG HP BLEED AIR SHUT OFF VALVE	RH	BOIA2-14128A	UNKNOWN	12/01/1984	0 ldg	0	9615
21		ENG HP BLEED AIR SHUT OFF VALVE	RH	BOIA2-14128A	UNKNOWN	12/01/1984	0.0 hrs	0.0	11196.3
21		FAN OPERATED VENTURI		132322-2	41-1739	9/15/2014	9097 ldg	0	518
21		FAN OPERATED VENTURI		132322-2	41-1739	9/15/2014	10286.8 hrs	0.0	909.5
21		FLOW CONTROL VALVE		106884-3-1	1186	12/19/2008	8480 ldg	0	1135
21		FLOW CONTROL VALVE		106884-3-1	1186	12/19/2008	9749.3 hrs	0.0	1447.0
21		GROUND PRESSURE CONNECTOR		133-2A	UNKNOWN	12/01/1984	0 ldg	0	9615
21		GROUND PRESSURE CONNECTOR		133-2A	UNKNOWN	12/01/1984	0.0 hrs	0.0	11196.3
21		HEAT EXCHANGER		178092-1	UNKNOWN	12/01/1984	0 ldg	0	9615
21		HEAT EXCHANGER		178092-1	UNKNOWN	12/01/1984	0.0 hrs	0.0	11196.3
21		HP/LP AIR MIXER VALVE	RH	3213788-1-1	UNKNOWN	12/01/1984	0 ldg	0	9615
21		HP/LP AIR MIXER VALVE	RH	3213788-1-1	UNKNOWN	12/01/1984	0.0 hrs	0.0	11196.3
21		INITIATION AIR VALVE	RH	321292-1	UNKNOWN	12/01/1984	0 ldg	0	9615
21		INITIATION AIR VALVE	RH	321292-1	UNKNOWN	12/01/1984	0.0 hrs	0.0	11196.3
21		INLET DUCT TEMPERATURE INDICATOR		51B-2232-2	617	11/09/2012	9017 ldg	0	598
21		INLET DUCT TEMPERATURE INDICATOR		51B-2232-2	617	11/09/2012	10216.8 hrs	0.0	979.5
21		MAIN SUPPLY CABIN NON RETURN VALVE		AWE124-51A	8910025	11/30/1994	4975 ldg	4975	9615
21		MANUAL CABIN ALTITUDE CONTROL VALVE		131004-2	UNKNOWN	12/01/1984	0 ldg	0	9615
21		MANUAL CABIN ALTITUDE CONTROL VALVE		131004-2	UNKNOWN	12/01/1984	0.0 hrs	0.0	11196.3
21		MECHANICAL DUMP VALVE CONTROLLER		AWE113-13A	8610003	10/22/1989	0 ldg	0	9615
21		MECHANICAL DUMP VALVE CONTROLLER		AWE113-13A	8610003	10/22/1989	0.0 hrs	0.0	11196.3
21		OUTFLOW/SAFETY VALVE	LH	103278-9-1	UNKNOWN	12/01/1984	0 ldg	0	9615
21		OUTFLOW/SAFETY VALVE	LH	103278-9-1	UNKNOWN	12/01/1984	0.0 hrs	0.0	11196.3
21		OUTFLOW/SAFETY VALVE	RH	103278-9-1	UNKNOWN	12/01/1984	0 ldg	0	9615
21		OUTFLOW/SAFETY VALVE	RH	103278-9-1	UNKNOWN	12/01/1984	0.0 hrs	0.0	11196.3
21		OUTFLOW/SAFETY VALVE CONTROLLER		102464-29	UNKNOWN	12/01/1984	0 ldg	0	9615
21		OUTFLOW/SAFETY VALVE CONTROLLER		102464-29	UNKNOWN	12/01/1984	0.0 hrs	0.0	11196.3
21		PNEUMATIC VALVE	LH	107312-4-1	UNKNOWN	12/01/1984	0 ldg	0	9615
21		PNEUMATIC VALVE	LH	107312-4-1	UNKNOWN	12/01/1984	0.0 hrs	0.0	11196.3
21		PNEUMATIC VALVE	RH	107312-4-1	UNKNOWN	12/01/1984	0 ldg	0	9615
21		PNEUMATIC VALVE	RH	107312-4-1	UNKNOWN	12/01/1984	0.0 hrs	0.0	11196.3
21		PUNKAH LOUVRE	LH	25-6VF107	UNKNOWN	12/01/1984	0 ldg	0	9615
21		PUNKAH LOUVRE	LH	25-6VF107	UNKNOWN	12/01/1984	0.0 hrs	0.0	11196.3
21		PUNKAH LOUVRE	RH	25-6VF107	UNKNOWN	12/01/1984	0 ldg	0	9615
21		PUNKAH LOUVRE	RH	25-6VF107	UNKNOWN	12/01/1984	0.0 hrs	0.0	11196.3
21		RAM AIR SHUT OFF VALVE		321262-1	UNKNOWN	12/01/1984	0 ldg	0	9615
21		RAM AIR SHUT OFF VALVE		321262-1	UNKNOWN	12/01/1984	0.0 hrs	0.0	11196.3
21		RAM AIR SUPPLY CHECK VALVE		123190-1-1	UNKNOWN	12/01/1984	0 ldg	0	9615
21		RAM AIR SUPPLY CHECK VALVE		123190-1-1	UNKNOWN	12/01/1984	0.0 hrs	0.0	11196.3
21		REFRIGERATION UNIT		682540-3-1	UNKNOWN	12/01/1984	0 ldg	0	9615

COMPONENT INVENTORY REPORT
HS-125 257208

4/25/2024
N2787

A T A	O C	D E S C R I P T I O N	L O C A T I O N	P A R T N U M B E R	S E R I A L N U M B E R	I N S T A L L A T I O N			C U R R E N T T I M E
						D A T E	T I M E	T S O	
21		REFRIGERATION UNIT		682540-3-1	UNKNOWN	12/01/1984	0.0 hrs	0.0	11196.3
21		REFRIGERATION UNIT BY-PASS VALVE		104968	UNKNOWN	12/01/1984	0 ldg	0	9615
21		REFRIGERATION UNIT BY-PASS VALVE		104968	UNKNOWN	12/01/1984	0.0 hrs	0.0	11196.3
21		TURBINE BY-PASS VALVE		321776-1-1	UNKNOWN	12/01/1984	0 ldg	0	9615
21		TURBINE BY-PASS VALVE		321776-1-1	UNKNOWN	12/01/1984	0.0 hrs	0.0	11196.3
21		VENTILATION FAN	RH	UNKNOWN	UNKNOWN	12/01/1984	0 ldg	0	9615
21		VENTILATION FAN	RH	UNKNOWN	UNKNOWN	12/01/1984	0.0 hrs	0.0	11196.3
21		VENTURI		131052-1	UNKNOWN	12/01/1984	0 ldg	0	9615
21		VENTURI		131052-1	UNKNOWN	12/01/1984	0.0 hrs	0.0	11196.3
21		VENTURI ISOLATION CHECK VALVE	LH	130156-1	UNKNOWN	12/01/1984	0 ldg	0	9615
21		VENTURI ISOLATION CHECK VALVE	LH	130156-1	UNKNOWN	12/01/1984	0.0 hrs	0.0	11196.3
21		VENTURI ISOLATION CHECK VALVE	RH	130156-1	UNKNOWN	12/01/1984	0 ldg	0	9615
21		VENTURI ISOLATION CHECK VALVE	RH	130156-1	UNKNOWN	12/01/1984	0.0 hrs	0.0	11196.3
21		WATER SEPARATOR		175050	UNKNOWN	12/01/1984	0 ldg	0	9615
21		WATER SEPARATOR		175050	UNKNOWN	12/01/1984	0.0 hrs	0.0	11196.3
21		WATER SEPARATOR BY-PASS VALVE		171019	UNKNOWN	12/01/1984	0 ldg	0	9615
21		WATER SEPARATOR BY-PASS VALVE		171019	UNKNOWN	12/01/1984	0.0 hrs	0.0	11196.3
22		AUTOPILOT AILERON SERVO		622-3016-001	1356	11/22/1992	4234 ldg	0	5381
22		AUTOPILOT AILERON SERVO		622-3016-001	1356	11/22/1992	4765.5 hrs	0.0	6430.8
22		AUTOPILOT AIRSPEED SENSOR		8059-2B	7390	9/13/2012	8987 ldg	0	628
22		AUTOPILOT AIRSPEED SENSOR		8059-2B	7390	9/13/2012	10184.6 hrs	0.0	1011.7
22		AUTOPILOT AMPLIFIER		622-2263-002	UNKNOWN	12/01/1984	0 ldg	0	9615
22		AUTOPILOT AMPLIFIER		622-2263-002	UNKNOWN	12/01/1984	0.0 hrs	0.0	11196.3
22		AUTOPILOT CONTROL PANEL		622-3109-009	UNKNOWN	12/01/1984	0 ldg	0	9615
22		AUTOPILOT CONTROL PANEL		622-3109-009	UNKNOWN	12/01/1984	0.0 hrs	0.0	11196.3
22		AUTOPILOT ELEVATOR SERVO		622-3016-001	1357	11/22/1992	4234 ldg	0	5381
22		AUTOPILOT ELEVATOR SERVO		622-3016-001	1357	11/22/1992	4765.5 hrs	0.0	6430.8
22		AUTOPILOT FLIGHT COMPUTER		522-2901-002	2602	9/13/2011	8826 ldg	0	789
22		AUTOPILOT FLIGHT COMPUTER		522-2901-002	2602	9/13/2011	10047.9 hrs	0.0	1148.4
22		AUTOPILOT RUDDER SERVO		792-6781-001	1966	11/22/1992	4234 ldg	0	5381
22		AUTOPILOT RUDDER SERVO		792-6781-001	1966	11/22/1992	4765.5 hrs	0.0	6430.8
22		YAW DAMPER COMPUTER		622-3167-099	1300	9/26/2008	8421 ldg	0	1194
22		YAW DAMPER COMPUTER		622-3167-099	1300	9/26/2008	9696.1 hrs	0.0	1500.2
23		COCKPIT VOICE RECORDER		1603-02-03	1279	2/09/2016	10342.2 hrs	55.4	909.5
23		AUDIO CONTROL UNIT	#1	M1045-F254-ALR1	840862	4/30/2002	7232 ldg	0	2383
23		AUDIO CONTROL UNIT	#1	M1045-F254-ALR1	840862	4/30/2002	8539.0 hrs	0.0	2657.3
23		AUDIO CONTROL UNIT	#2	M1045-F254-ALR1	8701123	4/30/2002	7232 ldg	0	2383
23		AUDIO CONTROL UNIT	#2	M1045-F254-ALR1	8701123	4/30/2002	8539.0 hrs	0.0	2657.3
23		AUDIO SPEAKER AMPLIFIER	#1	A693/1	UNKNOWN	12/01/1984	0 ldg	0	9615
23		AUDIO SPEAKER AMPLIFIER	#1	A693/1	UNKNOWN	12/01/1984	0.0 hrs	0.0	11196.3
23		AUDIO SPEAKER AMPLIFIER	#2	A693/1	UNKNOWN	12/01/1984	0 ldg	0	9615
23		AUDIO SPEAKER AMPLIFIER	#2	A693/1	UNKNOWN	12/01/1984	0.0 hrs	0.0	11196.3
23		COCKPIT VOICE RECORDER		1603-02-03	1279	2/09/2016	9131 ldg	34	518
23		HF ANTENNA COUPLER		787-6781-004	UNKNOWN	12/01/1984	0 ldg	0	9615

COMPONENT INVENTORY REPORT
HS-125 257208

4/25/2024
N2787

A T A	O C	D E S C R I P T I O N	L O C A T I O N	P A R T N U M B E R	S E R I A L N U M B E R	I N S T A L L A T I O N			C U R R E N T T I M E
						D A T E	T I M E	T S O	
23		HF ANTENNA COUPLER		787-6781-004	UNKNOWN	12/01/1984	0.0 hrs	0.0	11196.3
23		HF CONTROLLER	#1	792-6122-017	5767	6/10/2016	0 ldg	0	9615
23		HF CONTROLLER	#1	792-6122-017	5767	6/10/2016	0.0 hrs	0.0	11196.3
23		HF RECEIVER EXCITER		787-6934-011	5680	6/07/2016	0 ldg	0	9615
23		HF RECEIVER EXCITER		787-6934-011	5680	6/07/2016	0.0 hrs	0.0	11196.3
23		UNDERWATER LOCATOR BEACON BATT-CVR		266-E0305-00	ST11432	9/25/2023	9581 ldg	0	34
23		UNDERWATER LOCATOR BEACON BATT-CVR		266-E0305-00	ST11432	9/25/2023	11156.2 hrs	0.0	40.1
23		VHF ANTENNA	#1	16-21-1T	UNKNOWN	12/01/1984	0 ldg	0	9615
23		VHF ANTENNA	#1	16-21-1T	UNKNOWN	12/01/1984	0.0 hrs	0.0	11196.3
23		VHF ANTENNA	#2	16-21-1T	UNKNOWN	12/01/1984	0 ldg	0	9615
23		VHF ANTENNA	#2	16-21-1T	UNKNOWN	12/01/1984	0.0 hrs	0.0	11196.3
23		VHF CONTROL UNIT	#1	822-1120-005	18626	6/18/1999	0 ldg	0	9615
23		VHF CONTROL UNIT	#1	822-1120-005	18626	6/18/1999	0.0 hrs	0.0	11196.3
23		VHF CONTROL UNIT	#2	822-1120-005	18631	6/18/1999	0 ldg	0	9615
23		VHF CONTROL UNIT	#2	822-1120-005	18631	6/18/1999	0.0 hrs	0.0	11196.3
23		VHF TRANSCEIVER	#1	622-1879-001	23546	6/07/2016	0 ldg	0	9615
23		VHF TRANSCEIVER	#1	622-1879-001	23546	6/07/2016	0.0 hrs	0.0	11196.3
23		VHF TRANSCEIVER	#2	622-1879-001	6993	9/13/2012	8987 ldg	0	628
23		VHF TRANSCEIVER	#2	822-1111-001	6993	9/13/2012	8987 ldg	0	628
23		VHF TRANSCEIVER	#2	622-1879-001	6993	9/13/2012	10184.6 hrs	0.0	1011.7
23		VHF TRANSCEIVER	#2	822-1111-001	6993	9/13/2012	10184.6 hrs	0.0	1011.7
24		BUS TIE CONTACTOR		LDA15088C	P36443	1/25/1996	6109.1 hrs	0.0	5087.2
24		GROUND SUPPLY START CONTACTOR		LDG150-Y4	1445	11/30/1995	6048.1 hrs	0.0	5148.2
24		INVERTER SUPPLY CONTACTOR	#1	LDA200-B18C	Y3261	2/11/2011	9976.5 hrs	0.0	1219.8
24		INVERTER SUPPLY CONTACTOR	#2	LDA200B-18C	084348	5/09/1993	4980.0 hrs	0.0	6216.3
24		STARTER GENERATOR	LH	23080-005	1763	2/11/2011	9976.5 hrs	0.0	1219.8
24		STARTER GENERATOR	RH	23080-005	Y0571	2/11/2011	9976.5 hrs	0.0	1219.8
24		AC GENERATOR	LH	UNKNOWN	UNKNOWN	7/10/2016	9139 ldg	0	476
24		AC GENERATOR	RH	BA00501-1	0076	1/06/2014	9086 ldg	0	529
24		AC GENERATOR CONTROL UNIT	LH	CB005-01C01	UNKNOWN	12/01/1984	0 ldg	0	9615
24		AC GENERATOR CONTROL UNIT	LH	CB005-01C01	UNKNOWN	12/01/1984	0.0 hrs	0.0	11196.3
24		AC GENERATOR CONTROL UNIT	RH	CB005-01C01	UNKNOWN	12/01/1984	0 ldg	0	9615
24		AC GENERATOR CONTROL UNIT	RH	CB005-01C01	UNKNOWN	12/01/1984	0.0 hrs	0.0	11196.3
24		BUS TIE CONTACTOR		LDA15088C	P36443	1/25/1996	5376 ldg	0	4239
24		GROUND SUPPLY START CONTACTOR		LDG150-Y4	1445	11/30/1995	5320 ldg	0	4295
24		INVERTER	#1	501-1235-01	1207	5/23/1994	0 ldg	0	9615
24		INVERTER	#1	501-1235-01	1207	5/23/1994	0.0 hrs	0.0	11196.3
24		INVERTER	#2	501-1235-01	UNKNOWN	12/01/1984	0 ldg	0	9615
24		INVERTER	#2	501-1235-01	UNKNOWN	12/01/1984	0.0 hrs	0.0	11196.3
24		INVERTER AC VOLTMETER		51-2001	5457	11/22/1992	4234 ldg	0	5381
24		INVERTER AC VOLTMETER		51-2001	5457	11/22/1992	4765.5 hrs	0.0	6430.8
24		INVERTER FREQUENCY METER		51-2003	7214	11/22/1992	4234 ldg	0	5381
24		INVERTER FREQUENCY METER		51-2003	7214	11/22/1992	4765.5 hrs	0.0	6430.8
24		INVERTER STANDBY	#3	T1-1200	M13-10467	9/09/2014	9097 ldg	0	518

COMPONENT INVENTORY REPORT
HS-125 257208

4/25/2024
N2787

A T A	O C	D E S C R I P T I O N	L O C A T I O N	P A R T N U M B E R	S E R I A L N U M B E R	I N S T A L L A T I O N			C U R R E N T T I M E
						D A T E	T I M E	T S O	
24		INVERTER STANDBY	#3	T1-1200	M13-10467	9/09/2014	10286.0 hrs	0.0	910.3
24		INVERTER SUPPLY CONTACTOR	#1	LDA200-B18C	Y3261	2/11/2011	8745 ldg	0	870
24		INVERTER SUPPLY CONTACTOR	#2	LDA200B-18C	084348	5/09/1993	4415 ldg	0	5200
24		INVERTER VOLT PROTECTION UNIT	#1	B00-E600443A	UNKNOWN	12/01/1984	0 ldg	0	9615
24		INVERTER VOLT PROTECTION UNIT	#1	B00-E600443A	UNKNOWN	12/01/1984	0.0 hrs	0.0	11196.3
24		INVERTER VOLT PROTECTION UNIT	#2	B00-E600443A	UNKNOWN	12/01/1984	0 ldg	0	9615
24		INVERTER VOLT PROTECTION UNIT	#2	B00-E600443A	UNKNOWN	12/01/1984	0.0 hrs	0.0	11196.3
24		STARTER GENERATOR	LH	23080-005	1763	2/11/2011	8745 ldg	0	870
24		STARTER GENERATOR	RH	23080-005	Y0571	2/11/2011	8745 ldg	0	870
24		STARTER GENERATOR START CONTACTOR	LH	A703S	UNKNOWN	12/01/1984	0 ldg	0	9615
24		STARTER GENERATOR START CONTACTOR	LH	A703S	UNKNOWN	12/01/1984	0.0 hrs	0.0	11196.3
25		ELT BATTERY REPLACE		452-0133	361351-039	8/01/2022	11156.2 hrs	0.0	40.1
25		LIFE RAFT RECERTIFICATION	#1	N/A	N/A	9/25/2023	9581 ldg	0	34
25		LIFE RAFT RECERTIFICATION	#1	N/A	N/A	9/25/2023	11156.2 hrs	0.0	40.1
25		LIFE RAFT RECERTIFICATION	#2	N/A	N/A	9/25/2023	9581 ldg	0	34
25		LIFE RAFT RECERTIFICATION	#2	N/A	N/A	9/25/2023	11156.2 hrs	0.0	40.1
25		LIFE VEST RECERTIFICATION		ALL	UNKNOWN	12/01/1984	0 ldg	0	9615
25		LIFE VEST RECERTIFICATION		ALL	UNKNOWN	12/01/1984	0.0 hrs	0.0	11196.3
25		TOILET		4620-4HS	086	9/13/2012	8987 ldg	0	628
25		TOILET		4620-4HS	086	9/13/2012	10184.6 hrs	0.0	1011.7
26		APU FIRE EXT CARTRIDGE	FWD	UNKNOWN	UNKNOWN	9/25/2023	9581 ldg	0	34
26		APU FIRE EXT CARTRIDGE	FWD	UNKNOWN	UNKNOWN	9/25/2023	11156.2 hrs	0.0	40.1
26		APU FIRE EXT CARTRIDGE MANUF DATE	FWD	UNKNOWN	UNKNOWN	9/25/2023	9581 ldg	0	34
26		APU FIRE EXT CARTRIDGE MANUF DATE	FWD	UNKNOWN	UNKNOWN	9/25/2023	11156.2 hrs	0.0	40.1
26		APU FIRE EXTING OPERATING HEAD		182A	CR8071M	2/09/2016	9132 ldg	0	483
26		APU FIRE EXTING OPERATING HEAD		182A	CR8071M	2/09/2016	10343.8 hrs	0.0	852.5
26		APU FIRE EXTING PRESS RELIEF PLUG		182A	CR8071M	8/20/2021	9221 ldg	0	394
26		APU FIRE EXTING PRESS RELIEF PLUG		182A	CR8071M	8/20/2021	10559.0 hrs	0.0	637.3
26		APU FIRE EXTINGUISHER		182A	CR8071M	8/20/2021	9221 ldg	0	394
26		APU FIRE EXTINGUISHER		182A	CR8071M	8/20/2021	10559.0 hrs	0.0	637.3
26		CABIN FIRE EXTINGUISHER		N/A	N/A	8/20/2021	9221 ldg	0	394
26		CABIN FIRE EXTINGUISHER		N/A	N/A	8/20/2021	10559.0 hrs	0.0	637.3
26		COCKPIT FIRE EXTINGUISHER		N/A	N/A	8/20/2021	9221 ldg	0	394
26		COCKPIT FIRE EXTINGUISHER		N/A	N/A	8/20/2021	10559.0 hrs	0.0	637.3
26		ENGINE FIRE EXTINGUISHER	LH (AFT)	33200002-3	16224C1	8/20/2021	9221 ldg	0	394
26		ENGINE FIRE EXTINGUISHER	LH (AFT)	33200002-3	16224C1	8/20/2021	10559.0 hrs	0.0	637.3
26		ENGINE FIRE EXTINGUISHER	RH (FWD)	33200002-3	16223C1	8/20/2021	9221 ldg	0	394
26		ENGINE FIRE EXTINGUISHER	RH (FWD)	33200002-3	16223C1	8/20/2021	10559.0 hrs	0.0	637.3
26		ENGINE FIRE EXTINGUISHER CARTRIDGE	AFT HEAD A	UNKNOWN	0806KL	1/18/2010	8617 ldg	0	998
26		ENGINE FIRE EXTINGUISHER CARTRIDGE	AFT HEAD A	UNKNOWN	0806KL	1/18/2010	9865.9 hrs	0.0	1330.4
26		ENGINE FIRE EXTINGUISHER CARTRIDGE	AFT HEAD B	UNKNOWN	0789KL	1/18/2010	8617 ldg	0	998
26		ENGINE FIRE EXTINGUISHER CARTRIDGE	AFT HEAD B	UNKNOWN	0789KL	1/18/2010	9865.9 hrs	0.0	1330.4
26		ENGINE FIRE EXTINGUISHER CARTRIDGE	FWD HEAD A	UNKNOWN	809KL	1/18/2010	8617 ldg	0	998
26		ENGINE FIRE EXTINGUISHER CARTRIDGE	FWD HEAD A	UNKNOWN	809KL	1/18/2010	9865.9 hrs	0.0	1330.4

COMPONENT INVENTORY REPORT
HS-125 257208

4/25/2024
N2787

A T A	O C	D E S C R I P T I O N	L O C A T I O N	P A R T N U M B E R	S E R I A L N U M B E R	I N S T A L L A T I O N			C U R R E N T T I M E
						D A T E	T I M E	T S O	
26		ENGINE FIRE EXTINGUISHER CARTRIDGE	FWD HEAD B	UNKNOWN	0801KL	1/18/2010	8617 ldg	0	998
26		ENGINE FIRE EXTINGUISHER CARTRIDGE	FWD HEAD B	UNKNOWN	0801KL	1/18/2010	9865.9 hrs	0.0	1330.4
26		FIRE EXTINGUISHER FIRED FUSE	#1	A1003 (1)	N/A	9/15/2014	9097 ldg	0	518
26		FIRE EXTINGUISHER FIRED FUSE	#1	A1003 (1)	N/A	9/15/2014	10286.8 hrs	0.0	909.5
26		FIRE EXTINGUISHER FIRED FUSE	#2	A1003 (1)	N/A	9/15/2014	9097 ldg	0	518
26		FIRE EXTINGUISHER FIRED FUSE	#2	A1003 (1)	N/A	9/15/2014	10286.8 hrs	0.0	909.5
27		AIRBRAKE JACK	LH	AIR46520-2	APB3277	2/04/2012	10126.5 hrs	0.0	1069.8
27		AIRBRAKE JACK	RH	AIR46521-1	LK0053	10/21/2005	9284.7 hrs	0.0	1911.6
27		AIRBRAKE JACK BODY	LH	AIR111462	UNKNOWN	12/01/1984	0 ldg	0	9615
27		AIRBRAKE JACK BODY	RH	AIR111463	UNKNOWN	12/01/1984	0 ldg	0	9615
27		FLAP CONTROL UNIT		614MK2	614-E-535	7/14/2006	8105 ldg	0	1510
27		FLAP SCREWJACK & REDUCTION GEARBOX	LH	25-8CW-159AB	MEC/DHB/244	1/20/2006	8013 ldg	0	1602
27		FLAP SCREWJACK & REDUCTION GEARBOX	RH	25-8CW-161AB	MEC/DHB/240	1/20/2006	8013 ldg	0	1602
27		FLAP SYNCHRO CABLE ASSY (INNER)	LH AFT	25CF3225-19	UNKNOWN	11/26/1993	4642 ldg	0	4973
27		FLAP SYNCHRO CABLE ASSY (INNER)	LH FORWARD	25CF3225-17	UNKNOWN	11/26/1993	4642 ldg	0	4973
27		FLAP SYNCHRO CABLE ASSY (INNER)	RH AFT	25CF3225-9	UNKNOWN	11/26/1993	4642 ldg	0	4973
27		FLAP SYNCHRO CABLE ASSY (INNER)	RH FORWARD	25CF3225-9	UNKNOWN	11/26/1993	4642 ldg	0	4973
27		FLAP SYNCHRO CABLE ASSY (OUTER)	LH AFT	25CF3225-15	UNKNOWN	11/26/1993	4642 ldg	0	4973
27		FLAP SYNCHRO CABLE ASSY (OUTER)	LH FORWARD	25CF3225-3	UNKNOWN	11/26/1993	4642 ldg	0	4973
27		FLAP SYNCHRO CABLE ASSY (OUTER)	RH AFT	25CF3225-15	UNKNOWN	11/26/1993	4642 ldg	0	4973
27		FLAP SYNCHRO CABLE ASSY (OUTER)	RH FORWARD	25CF3225-13	UNKNOWN	11/30/1994	4975 ldg	0	4640
27		FLAP SYNCHRONIZ SYS RECEIVER UNIT		617 MK4	M764	8/29/2008	8411 ldg	0	1204
27		AIRBRAKE JACK	LH	AIR46520-2	APB3277	2/04/2012	8923 ldg	0	692
27		AIRBRAKE JACK	RH	AIR46521-1	LK0053	10/21/2005	7971 ldg	0	1644
27		AIRBRAKE JACK BODY	LH	AIR111462	UNKNOWN	12/01/1984	0.0 hrs	0.0	11196.3
27		AIRBRAKE JACK BODY	RH	AIR111463	UNKNOWN	12/01/1984	0.0 hrs	0.0	11196.3
27		FLAP CONTROL UNIT		614MK2	614-E-535	7/14/2006	9404.8 hrs	0.0	1791.5
27		FLAP SCREWJACK & REDUCTION GEARBOX	LH	25-8CW-159AB	MEC/DHB/244	1/20/2006	9322.0 hrs	0.0	1874.3
27		FLAP SCREWJACK & REDUCTION GEARBOX	RH	25-8CW-161AB	MEC/DHB/240	1/20/2006	9322.0 hrs	0.0	1874.3
27		FLAP SYNCHRO CABLE ASSY (INNER)	LH AFT	25CF3225-19	UNKNOWN	11/26/1993	5246.1 hrs	0.0	5950.2
27		FLAP SYNCHRO CABLE ASSY (INNER)	LH FORWARD	25CF3225-17	UNKNOWN	11/26/1993	5246.1 hrs	0.0	5950.2
27		FLAP SYNCHRO CABLE ASSY (INNER)	RH AFT	25CF3225-9	UNKNOWN	11/26/1993	5246.1 hrs	0.0	5950.2
27		FLAP SYNCHRO CABLE ASSY (INNER)	RH FORWARD	25CF3225-9	UNKNOWN	11/26/1993	5246.1 hrs	0.0	5950.2
27		FLAP SYNCHRO CABLE ASSY (OUTER)	LH AFT	25CF3225-15	UNKNOWN	11/26/1993	5246.1 hrs	0.0	5950.2
27		FLAP SYNCHRO CABLE ASSY (OUTER)	LH FORWARD	25CF3225-3	UNKNOWN	11/26/1993	5246.1 hrs	0.0	5950.2
27		FLAP SYNCHRO CABLE ASSY (OUTER)	RH AFT	25CF3225-15	UNKNOWN	11/26/1993	5246.1 hrs	0.0	5950.2
27		FLAP SYNCHRO CABLE ASSY (OUTER)	RH FORWARD	25CF3225-13	UNKNOWN	11/30/1994	5631.6 hrs	0.0	5564.7
27		FLAP SYNCHRONIZ SYS RECEIVER UNIT		617 MK4	M764	8/29/2008	9680.0 hrs	0.0	1516.3
27		STALL DETECTOR	AFT	0222KSB/1	GE23	1/28/2015	9113 ldg	0	502
27		STALL DETECTOR	AFT	0222KSB/1	GE23	1/28/2015	10309.8 hrs	0.0	886.5
28		FUEL BOOST PUMP	LH	2070C-11	164	12/05/2000	8188.7 hrs	0.0	3007.6
28	#	FUEL BOOST PUMP	RH	2C40-2	GAR92	3/28/2014	10273.1 hrs	0.0	923.2
28		VENTRAL TANK PICK-UP LINK BOLT	REAR	25FT373	UNKNOWN	12/01/1984	0 ldg	0	9615
28		FUEL BOOST PUMP	LH	2070C-11	164	12/05/2000	6944 ldg	0	2671

COMPONENT INVENTORY REPORT
HS-125 257208

4/25/2024
N2787

A T A	O C	D E S C R I P T I O N	L O C A T I O N	P A R T N U M B E R	S E R I A L N U M B E R	I N S T A L L A T I O N			C U R R E N T T I M E
						D A T E	T I M E	T S O	
28	#	FUEL BOOST PUMP	RH	2C40-2	GAR92	3/28/2014	9086 ldg	0	529
28		FUEL SIGNAL CONDITIONER		SCF1788	908093	1/31/2015	9113 ldg	0	502
28		FUEL SIGNAL CONDITIONER		SCF1788	908093	1/31/2015	10309.8 hrs	0.0	886.5
28		SINGLE POINT FUELING PRU		1159000-1	FRTR1051R	10/07/2010	8696 ldg	0	919
28		SINGLE POINT FUELING PRU		1159000-1	FRTR1051R	10/07/2010	9940.3 hrs	0.0	1256.0
28		VENTRAL TANK PICK-UP LINK BOLT	REAR	25FT373	UNKNOWN	12/01/1984	0.0 hrs	0.0	11196.3
28		WING REFUEL ACTUATOR VALVE	RH	HTE9044-001	192GB304	6/03/2011	8783 ldg	0	832
28		WING REFUEL ACTUATOR VALVE	RH	HTE9044-001	192GB304	6/03/2011	10006.6 hrs	0.0	1189.7
29		EMER BRAKE ACC LOW PRES WARN SWITCH		TP42001	240	9/21/1992	4693.2 hrs	0.0	6503.1
29		ENGINE HYDRAULIC PUMP	LH	65WE01030-3-6	AO-72-03-D3	8/29/2008	9680.0 hrs	0.0	1516.3
29		ENGINE HYDRAULIC PUMP	RH	65WE01030-3-6	A2-245-B3-C3-D3	6/07/2013	10274.0 hrs	0.0	922.3
29		FULL FLOW RELIEF VALVE	#1	AIR45394-0	LK8601709	7/17/2012	8971 ldg	0	644
29		FULL FLOW RELIEF VALVE	#2	AIR45394-0	LK8601710	7/17/2012	8971 ldg	0	644
29		PRESSURE MAINTAINING VALVE		AIR45474-0	APB981228	9/02/2003	7520 ldg	0	2095
29		EMER BRAKE ACC LOW PRES WARN SWITCH		TP42001	240	9/21/1992	4166 ldg	0	5449
29		ENGINE HYDRAULIC PUMP	LH	65WE01030-3-6	AO-72-03-D3	8/29/2008	8411 ldg	0	1204
29		ENGINE HYDRAULIC PUMP	RH	65WE01030-3-6	A2-245-B3-C3-D3	6/07/2013	9083 ldg	0	532
29		FULL FLOW RELIEF VALVE	#1	AIR45394-0	LK8601709	7/17/2012	10170.0 hrs	0.0	1026.3
29		FULL FLOW RELIEF VALVE	#2	AIR45394-0	LK8601710	7/17/2012	10170.0 hrs	0.0	1026.3
29		HYDRAULIC TEMP SWITCH (OVERHEAT)		150T283	1072	9/13/2012	8987 ldg	0	628
29		HYDRAULIC TEMP SWITCH (OVERHEAT)		150T283	1072	9/13/2012	10184.6 hrs	0.0	1011.7
29		PRESSURE MAINTAINING VALVE		AIR45474-0	APB981228	9/02/2003	8822.0 hrs	0.0	2374.3
30		AIRFRAME DE-ICE SYS CHECK VALVE		WGE150/9	UNKNOWN	9/13/2012	8987 ldg	0	628
30		AIRFRAME DE-ICE SYS RESTRICTOR VAL		150-10B	8004098	9/13/2012	8987 ldg	0	628
30		WINDSHIELD DE-ICE NON RETURN VALVE		150-9A	7812105	9/13/2012	8987 ldg	0	628
32		BRAKE CONTROL VALVE KNIFE EDGE	INNER	ACO25106	UNKNOWN	6/28/1999	6509 ldg	0	3106
32		BRAKE CONTROL VALVE KNIFE EDGE	LH OUTER	ACO25103	UNKNOWN	6/28/1999	6509 ldg	0	3106
32		BRAKE CONTROL VALVE KNIFE EDGE	RH OUTER	ACO25104	UNKNOWN	6/28/1999	6509 ldg	0	3106
32		BRAKE EMER REDUCING VALVE KNIFE EDG	LH	ACO34629	UNKNOWN	8/29/2008	8411 ldg	0	1204
32		BRAKE EMER REDUCING VALVE KNIFE EDG	RH	ACO34630	UNKNOWN	8/29/2008	8411 ldg	0	1204
32		BRAKE EMERGENCY SYS PRESSURE SWITCH	LH	TP42000	1146	9/13/2012	10184.6 hrs	0.0	1011.7
32		BRAKE EMERGENCY SYS PRESSURE SWITCH	RH	TP42000	1211	9/13/2012	10184.6 hrs	0.0	1011.7
32		BRAKE MAXARET	LH INBD	AC65216	02012	12/28/1999	6688 ldg	0	2927
32		BRAKE MAXARET	LH OTBD	AC65218	VP036	9/13/2012	8987 ldg	0	628
32		BRAKE MAXARET	RH INBD	AC65218	NM435	4/04/2012	8923 ldg	0	692
32		BRAKE MAXARET	RH OTBD	AC65216	ZJ120	8/06/2010	8671 ldg	0	944
32		DRAG STRUT PICK UP		25UN9A	UNKNOWN	12/01/1984	0 ldg	0	9615
32		MAIN GEAR DOOR JACK	LH	AIR48485-3	LK8205648	11/26/1993	4642 ldg	0	4973
32		MAIN GEAR DOOR JACK	RH	AIR48484-3	APB971635	8/29/2008	8411 ldg	0	1204
32		MAIN GEAR JACK CYLINDER HEAD	LH	AIR127866	UNKNOWN	11/26/1993	4642 ldg	0	4973
32		MAIN GEAR JACK CYLINDER HEAD	RH	UNKNOWN	UNKNOWN	7/01/2005	7901 ldg	3259	4973
32		MAIN GEAR JACK EYE END	LH	AIR158922	UNKNOWN	12/01/1984	0 ldg	-6944	2671
32		MAIN GEAR JACK EYE END	RH	UNKNOWN	UNKNOWN	12/01/1984	0 ldg	-6944	2671
32	#	MAIN GEAR JACK PIVOT	LH	25UM1199A	UNKNOWN	12/01/1984	0 ldg	0	9615

COMPONENT INVENTORY REPORT
HS-125 257208

4/25/2024
N2787

A T A	O C	D E S C R I P T I O N	L O C A T I O N	P A R T N U M B E R	S E R I A L N U M B E R	I N S T A L L A T I O N			C U R R E N T T I M E
						D A T E	T I M E	T S O	
32	#	MAIN GEAR JACK PIVOT	RH	UNKNOWN	UNKNOWN	12/01/1984	0 ldg	0	9615
32		MAIN GEAR JACK PIVOT BOLT	LH	25UM153A	UNKNOWN	12/01/1984	0 ldg	-7901	1714
32		MAIN GEAR JACK PIVOT BOLT	RH	UNKNOWN	UNKNOWN	12/01/1984	0 ldg	0	9615
32		MAIN GEAR PLUNGER TUBE	LH	25-8UM-6	UNKNOWN	12/01/1984	0 ldg	0	9615
32		MAIN GEAR PLUNGER TUBE	RH	25-8UM-6	UNKNOWN	12/01/1984	0 ldg	0	9615
32		MAIN GEAR RETRACT JACK	LH	AIR48502-4	LK0166	11/26/1993	4642 ldg	0	4973
32		MAIN GEAR RETRACT JACK	RH	AIR48503-4	LK0087	6/07/2013	9083 ldg	0	532
32		MAIN GEAR RETRACTION ARM	LH	UNKNOWN	UNKNOWN	12/01/1984	0 ldg	0	9615
32		MAIN GEAR RETRACTION ARM	RH	UNKNOWN	UNKNOWN	12/01/1984	0 ldg	0	9615
32		MAIN GEAR RETRACTION ARM PIN	LH	UNKNOWN	UNKNOWN	12/01/1984	0 ldg	0	9615
32		MAIN GEAR RETRACTION ARM PIN	RH	UNKNOWN	UNKNOWN	12/01/1984	0 ldg	0	9615
32		MAIN GEAR SIDESTAY LOWER ARM	LH	25-8UM31-1A	UNKNOWN	12/01/1984	0 ldg	0	9615
32		MAIN GEAR SIDESTAY LOWER ARM	RH	UNKNOWN	UNKNOWN	12/01/1984	0 ldg	0	9615
32		MAIN GEAR SIDESTAY UPPER ARM	LH	25-6UM35A/	DHL/DHI069	12/01/1984	0 ldg	0	9615
32		MAIN GEAR SIDESTAY UPPER ARM	RH	UNKNOWN	UNKNOWN	12/01/1984	0 ldg	0	9615
32		MAIN GEAR TORQUE LINK PIN	LH LOWER	25UM99A	UNKNOWN	12/01/1984	0 ldg	0	9615
32		MAIN GEAR TORQUE LINK PIN	LH UPPER	25UM99A	UNKNOWN	12/01/1984	0 ldg	0	9615
32		MAIN GEAR TORQUE LINK PIN	RH LOWER	25UM99A	UNKNOWN	12/01/1984	0 ldg	0	9615
32		MAIN GEAR TORQUE LINK PIN	RH UPPER	25UM99A	UNKNOWN	12/01/1984	0 ldg	0	9615
32		MAIN GEAR UPPER CASING	LH	UNKNOWN	UNKNOWN	12/01/1984	0 ldg	0	9615
32		MAIN GEAR UPPER CASING	RH	UNKNOWN	UNKNOWN	12/01/1984	0 ldg	0	9615
32		MAIN LANDING GEAR JACK DISTANCE PIN	LH	25UM423	UNKNOWN	12/01/1984	0 ldg	-7901	1714
32		MAIN LANDING GEAR JACK DISTANCE PIN	RH	25UM423	UNKNOWN	12/01/1984	0 ldg	0	9615
32		NOSE GEAR AXLE BARREL		25-8UN257-27A	UNKNOWN	4/24/2006	8062 ldg	7706	9259
32		NOSE GEAR CONNECTING ROD		UNKNOWN	UNKNOWN	12/01/1984	0 ldg	0	9615
32		NOSE GEAR DRAG STAY BRIDGE CASTING		25UN671-1A	BA326	11/30/1994	4975 ldg	0	4640
32		NOSE GEAR JACK LOWER PIVOT PIN		25UN597	UNKNOWN	4/24/2006	8062 ldg	0	1553
32		NOSE GEAR MAIN CASING BOLT		25UN603	UNKNOWN	4/24/2006	8062 ldg	0	1553
32		NOSE GEAR PICK-UP TRUNNION BOLTS		A102-28J	UNKNOWN	4/24/2006	8062 ldg	0	1553
32		NOSE GEAR PLUNGER TUBE		25UN649	UNKNOWN	4/24/2006	8062 ldg	0	1553
32		NOSE GEAR RADIUS ROD PICK-UP BOLTS		A102-21J	UNKNOWN	4/24/2006	8062 ldg	0	1553
32		NOSE GEAR RETRACT JACK		AIR45404-1	LK8200318	11/26/1993	4642 ldg	0	4973
32		NOSE GEAR STEERING JACK EYE END		AIR110646	24252	6/07/2013	9083 ldg	1500	2032
32		NOSE GEAR TORQUE LINK	LOWER	UNKNOWN	UNKNOWN	12/01/1984	0 ldg	0	9615
32		NOSE GEAR TORQUE LINK	UPPER	UNKNOWN	UNKNOWN	12/01/1984	0 ldg	0	9615
32		NOSE LANDING GEAR PIVOT PIN		25UN645A	UNKNOWN	4/24/2006	8062 ldg	7706	9259
32		NOSE STEERING JACK PICK UP		25UN7A/B	UNKNOWN	12/01/1984	0 ldg	0	9615
32		NOSE STEERING MAIN MEMBER	LOWER	UNKNOWN	UNKNOWN	12/01/1984	0 ldg	0	9615
32		NOSE STEERING MAIN MEMBER	UPPER	UNKNOWN	UNKNOWN	12/01/1984	0 ldg	0	9615
32		NOSE STEERING PIN		25UN605		4/24/2006	8062 ldg	0	1553
32		NOSE STEERING SLEEVE		UNKNOWN	UNKNOWN	12/01/1984	0 ldg	0	9615
32		BRAKE ASSEMBLY	LH INBD	AH52787	10290	9/13/2012	8987 ldg	0	628
32		BRAKE ASSEMBLY	LH INBD	AH52787	10290	9/13/2012	10184.6 hrs	0.0	1011.7
32		BRAKE ASSEMBLY	LH OTBD	AH52787	AS12848	9/13/2012	8987 ldg	0	628

COMPONENT INVENTORY REPORT
HS-125 257208

4/25/2024
N2787

A T A	O C	D E S C R I P T I O N	L O C A T I O N	P A R T N U M B E R	S E R I A L N U M B E R	I N S T A L L A T I O N			C U R R E N T T I M E
						D A T E	T I M E	T S O	
32		BRAKE ASSEMBLY	LH OTBD	AH52787	AS12848	9/13/2012	10184.6 hrs	0.0	1011.7
32		BRAKE CONTROL VALVE KNIFE EDGE	INNER	ACO25106	UNKNOWN	6/28/1999	7489.4 hrs	0.0	3706.9
32		BRAKE CONTROL VALVE KNIFE EDGE	LH OUTER	ACO25103	UNKNOWN	6/28/1999	7489.4 hrs	0.0	3706.9
32		BRAKE CONTROL VALVE KNIFE EDGE	RH OUTER	ACO25104	UNKNOWN	6/28/1999	7489.4 hrs	0.0	3706.9
32		BRAKE EMER REDUCING VALVE KNIFE EDG	LH	ACO34629	UNKNOWN	8/29/2008	9680.0 hrs	0.0	1516.3
32		BRAKE EMER REDUCING VALVE KNIFE EDG	RH	ACO34630	UNKNOWN	8/29/2008	9680.0 hrs	0.0	1516.3
32		BRAKE EMERGENCY SYS PRESSURE SWITCH	LH	TP42000	1146	9/13/2012	8987 ldg	0	628
32		BRAKE EMERGENCY SYS PRESSURE SWITCH	RH	TP42000	1211	9/13/2012	8987 ldg	0	628
32		BRAKE MAXARET	LH INBD	AC65216	02012	12/28/1999	7781.0 hrs	0.0	3415.3
32		BRAKE MAXARET	LH OTBD	AC65218	VP036	9/13/2012	10184.6 hrs	0.0	1011.7
32		BRAKE MAXARET	RH INBD	AC65218	NM435	4/04/2012	10126.5 hrs	0.0	1069.8
32		BRAKE MAXARET	RH OTBD	AC65216	ZJ120	8/06/2010	9912.6 hrs	0.0	1283.7
32		DRAG STRUT PICK UP		25UN9A	UNKNOWN	12/01/1984	0.0 hrs	0.0	11196.3
32		MAIN GEAR DOOR JACK	LH	AIR48485-3	LK8205648	11/26/1993	5646.0 hrs	0.0	5550.3
32		MAIN GEAR DOOR JACK	RH	AIR48484-3	APB971635	8/29/2008	9680.0 hrs	0.0	1516.3
32		MAIN GEAR JACK CYLINDER HEAD	LH	AIR127866	UNKNOWN	11/26/1993	5246.1 hrs	0.0	5950.2
32		MAIN GEAR JACK EYE END	LH	AIR158922	UNKNOWN	12/01/1984	0.0 hrs	0.0	11196.3
32		MAIN GEAR JACK EYE END	RH	UNKNOWN	UNKNOWN	12/01/1984	0.0 hrs	0.0	11196.3
32	#	MAIN GEAR JACK PIVOT	LH	25UM1199A	UNKNOWN	12/01/1984	0.0 hrs	0.0	11196.3
32	#	MAIN GEAR JACK PIVOT	RH	UNKNOWN	UNKNOWN	12/01/1984	0.0 hrs	0.0	11196.3
32		MAIN GEAR JACK PIVOT BOLT	LH	25UM153A	UNKNOWN	12/01/1984	0.0 hrs	0.0	11196.3
32		MAIN GEAR JACK PIVOT BOLT	RH	UNKNOWN	UNKNOWN	12/01/1984	0.0 hrs	0.0	11196.3
32		MAIN GEAR PLUNGER TUBE	LH	25-8UM-6	UNKNOWN	12/01/1984	0.0 hrs	0.0	11196.3
32		MAIN GEAR PLUNGER TUBE	RH	25-8UM-6	UNKNOWN	12/01/1984	0.0 hrs	0.0	11196.3
32		MAIN GEAR RETRACT JACK	LH	AIR48502-4	LK0166	11/26/1993	5246.1 hrs	0.0	5950.2
32		MAIN GEAR RETRACT JACK	RH	AIR48503-4	LK0087	6/07/2013	10274.0 hrs	0.0	922.3
32		MAIN GEAR RETRACTION ARM	LH	UNKNOWN	UNKNOWN	12/01/1984	0.0 hrs	0.0	11196.3
32		MAIN GEAR RETRACTION ARM	RH	UNKNOWN	UNKNOWN	12/01/1984	0.0 hrs	0.0	11196.3
32		MAIN GEAR RETRACTION ARM PIN	LH	UNKNOWN	UNKNOWN	12/01/1984	0.0 hrs	0.0	11196.3
32		MAIN GEAR RETRACTION ARM PIN	RH	UNKNOWN	UNKNOWN	12/01/1984	0.0 hrs	0.0	11196.3
32		MAIN GEAR REVERSING VALVE	LH	AIR48542/1	APB012087	1/20/2006	9322.0 hrs	0.0	1874.3
32		MAIN GEAR SEQUENCE VALVE	LH	AIR48540/1	LK0582	1/20/2006	9322.0 hrs	0.0	1874.3
32		MAIN GEAR SEQUENCE VALVE	RH	AIR48540/1	LK0587	1/20/2006	9322.0 hrs	0.0	1874.3
32		MAIN GEAR SIDESTAY LOWER ARM	LH	25-8UM31-1A	UNKNOWN	12/01/1984	0.0 hrs	0.0	11196.3
32		MAIN GEAR SIDESTAY LOWER ARM	RH	UNKNOWN	UNKNOWN	12/01/1984	0.0 hrs	0.0	11196.3
32		MAIN GEAR SIDESTAY UPPER ARM	LH	25-6UM35A/	DHL/DHI069	12/01/1984	0.0 hrs	0.0	11196.3
32		MAIN GEAR SIDESTAY UPPER ARM	RH	UNKNOWN	UNKNOWN	12/01/1984	0.0 hrs	0.0	11196.3
32		MAIN GEAR TIRE	LH INBD	237K23-2	11392951	2/18/2013	9075 ldg	0	540
32		MAIN GEAR TIRE	LH INBD	237K23-2	11392951	2/18/2013	10265.0 hrs	0.0	931.3
32		MAIN GEAR TIRE	LH OTBD	237K23-2	11822124	2/18/2013	9075 ldg	0	540
32		MAIN GEAR TIRE	LH OTBD	237K23-2	11822124	2/18/2013	10265.0 hrs	0.0	931.3
32		MAIN GEAR TIRE	RH INBD	237K23-2	11392959	2/05/2013	9064 ldg	0	551
32		MAIN GEAR TIRE	RH INBD	237K23-2	11392959	2/05/2013	10257.0 hrs	0.0	939.3
32		MAIN GEAR TIRE	RH OTBD	237K23-2	11382965	2/05/2013	9064 ldg	0	551

COMPONENT INVENTORY REPORT
HS-125 257208

4/25/2024
N2787

A T A	O C	D E S C R I P T I O N	L O C A T I O N	P A R T N U M B E R	S E R I A L N U M B E R	I N S T A L L A T I O N			C U R R E N T T I M E
						D A T E	T I M E	T S O	
32		MAIN GEAR TIRE	RH OTBD	237K23-2	11382965	2/05/2013	10257.0 hrs	0.0	939.3
32		MAIN GEAR TORQUE LINK PIN	LH LOWER	25UM99A	UNKNOWN	12/01/1984	0.0 hrs	0.0	11196.3
32		MAIN GEAR TORQUE LINK PIN	LH UPPER	25UM99A	UNKNOWN	12/01/1984	0.0 hrs	0.0	11196.3
32		MAIN GEAR TORQUE LINK PIN	RH LOWER	25UM99A	UNKNOWN	12/01/1984	0.0 hrs	0.0	11196.3
32		MAIN GEAR TORQUE LINK PIN	RH UPPER	25UM99A	UNKNOWN	12/01/1984	0.0 hrs	0.0	11196.3
32		MAIN GEAR UPPER CASING	LH	UNKNOWN	UNKNOWN	12/01/1984	0.0 hrs	0.0	11196.3
32		MAIN GEAR UPPER CASING	RH	UNKNOWN	UNKNOWN	12/01/1984	0.0 hrs	0.0	11196.3
32		MAIN GEAR WHEEL ASSEMBLY	LH INBD	AH52786	AH52786	2/18/2013	9075 ldg	0	540
32		MAIN GEAR WHEEL ASSEMBLY	LH INBD	AH52786	AH52786	2/18/2013	10265.0 hrs	0.0	931.3
32		MAIN GEAR WHEEL ASSEMBLY	LH OTBD	AH52786	LHR292	2/18/2013	9075 ldg	0	540
32		MAIN GEAR WHEEL ASSEMBLY	LH OTBD	AH52786	LHR292	2/18/2013	10265.0 hrs	0.0	931.3
32		MAIN GEAR WHEEL ASSEMBLY	RH INBD	AH52786	EJC620	2/05/2013	9064 ldg	0	551
32		MAIN GEAR WHEEL ASSEMBLY	RH INBD	AH52786	EJC620	2/05/2013	10257.0 hrs	0.0	939.3
32		MAIN GEAR WHEEL ASSEMBLY	RH OTBD	AH52786	EJC751	2/05/2013	9064 ldg	0	551
32		MAIN GEAR WHEEL ASSEMBLY	RH OTBD	AH52786	EJC751	2/05/2013	10257.0 hrs	0.0	939.3
32		MAIN LANDING GEAR JACK DISTANCE PIN	LH	25UM423	UNKNOWN	12/01/1984	0.0 hrs	0.0	11196.3
32		MAIN LANDING GEAR JACK DISTANCE PIN	RH	25UM423	UNKNOWN	12/01/1984	0.0 hrs	0.0	11196.3
32		NOSE GEAR AXLE BARREL		25-8UN257-27A	UNKNOWN	4/24/2006	9368.5 hrs	7706.0	9533.8
32		NOSE GEAR CONNECTING ROD		UNKNOWN	UNKNOWN	12/01/1984	0.0 hrs	0.0	11196.3
32		NOSE GEAR DRAG STAY BRIDGE CASTING		25UN671-1A	BA326	11/30/1994	5631.6 hrs	0.0	5564.7
32		NOSE GEAR JACK LOWER PIVOT PIN		25UN597	UNKNOWN	4/24/2006	9368.5 hrs	0.0	1827.8
32		NOSE GEAR LEG ASSEMBLY		25-UN1AZ	DHL/DH/727	4/24/2006	9368.5 hrs	0.0	1827.8
32		NOSE GEAR MAIN CASING BOLT		25UN603	UNKNOWN	4/24/2006	9368.5 hrs	0.0	1827.8
32		NOSE GEAR PICK-UP TRUNNION BOLTS		A102-28J	UNKNOWN	4/24/2006	9368.5 hrs	0.0	1827.8
32		NOSE GEAR PLUNGER TUBE		25UN649	UNKNOWN	4/24/2006	9368.5 hrs	0.0	1827.8
32		NOSE GEAR RADIUS ROD PICK-UP BOLTS		A102-21J	UNKNOWN	4/24/2006	9368.5 hrs	0.0	1827.8
32		NOSE GEAR RETRACT JACK		AIR45404-1	LK8200318	11/26/1993	5646.0 hrs	0.0	5550.3
32		NOSE GEAR STEERING JACK		AIR45396/7	APB000764	6/07/2013	9083 ldg	0	532
32		NOSE GEAR STEERING JACK		AIR45396/7	APB000764	6/07/2013	10274.0 hrs	0.0	922.3
32		NOSE GEAR STEERING JACK EYE END		AIR110646	24252	6/07/2013	10274.0 hrs	1500.0	2422.3
32		NOSE GEAR TIRE	LH	181K63-2	20662913	8/07/2015	9118 ldg	0	497
32		NOSE GEAR TIRE	LH	181K63-2	20662913	8/07/2015	10316.0 hrs	0.0	880.3
32		NOSE GEAR TIRE	RH	181K63-2	20672396	8/07/2015	9118 ldg	0	497
32		NOSE GEAR TIRE	RH	181K63-2	20672396	8/07/2015	10316.0 hrs	0.0	880.3
32		NOSE GEAR TORQUE LINK	LOWER	UNKNOWN	UNKNOWN	12/01/1984	0.0 hrs	0.0	11196.3
32		NOSE GEAR TORQUE LINK	UPPER	UNKNOWN	UNKNOWN	12/01/1984	0.0 hrs	0.0	11196.3
32		NOSE GEAR WHEEL ASSEMBLY	LH	AH52339	LX112 NDT	8/07/2015	9118 ldg	0	497
32		NOSE GEAR WHEEL ASSEMBLY	LH	AH52339	LX112 NDT	8/07/2015	10316.0 hrs	0.0	880.3
32		NOSE GEAR WHEEL ASSEMBLY	RH	AH52339	1163 NDT	8/07/2015	9118 ldg	0	497
32		NOSE GEAR WHEEL ASSEMBLY	RH	AH52339	1163 NDT	8/07/2015	10316.0 hrs	0.0	880.3
32		NOSE LANDING GEAR PIVOT PIN		25UN645A	UNKNOWN	4/24/2006	9368.5 hrs	7706.0	9533.8
32		NOSE STEERING JACK PICK UP		25UN7A/B	UNKNOWN	12/01/1984	0.0 hrs	0.0	11196.3
32		NOSE STEERING MAIN MEMBER	LOWER	UNKNOWN	UNKNOWN	12/01/1984	0.0 hrs	0.0	11196.3
32		NOSE STEERING MAIN MEMBER	UPPER	UNKNOWN	UNKNOWN	12/01/1984	0.0 hrs	0.0	11196.3

COMPONENT INVENTORY REPORT
HS-125 257208

4/25/2024
N2787

A T A	O C	D E S C R I P T I O N	L O C A T I O N	P A R T N U M B E R	S E R I A L N U M B E R	I N S T A L L A T I O N			C U R R E N T T I M E
						D A T E	T I M E	T S O	
32		NOSE STEERING PIN		25UN605		4/24/2006	9368.5 hrs	0.0	1827.8
32		NOSE STEERING SLEEVE		UNKNOWN	UNKNOWN	12/01/1984	0.0 hrs	0.0	11196.3
33		ANTI-COLLISION BEACON	BOTTOM	01-0790088-17	00128	6/07/2013	9083 ldg	0	532
33		ANTI-COLLISION BEACON	BOTTOM	01-0790088-17	00128	6/07/2013	10274.0 hrs	0.0	922.3
33		EMERGENCY EXIT LIGHT UNIT		N/A	N/A	2/09/2016	9131 ldg	0	484
33		EMERGENCY EXIT LIGHT UNIT		N/A	N/A	2/09/2016	10342.2 hrs	0.0	854.1
33	R	EMERGENCY LIGHT FILAMENT		N/A	N/A	9/25/2023	9581 ldg	0	34
33	R	EMERGENCY LIGHT FILAMENT		N/A	N/A	9/25/2023	11156.2 hrs	0.0	40.1
33		INERTIA SWITCH, EMERG LIGHTING		18C-2-1-5G	AT9938	2/09/2016	9131 ldg	0	484
33		INERTIA SWITCH, EMERG LIGHTING		18C-2-1-5G	AT9938	2/09/2016	10342.2 hrs	0.0	854.1
34		ELEVATOR TRIM SERVO/MOTOR		622-3260-001	480	11/30/1994	5631.6 hrs	0.0	5564.7
34		AIR DATA COMPUTER	#1	622-5465-651	2233 INSTL?	2/03/2021	9221 ldg	0	394
34		AIR DATA COMPUTER	#1	622-5465-651	2233 INSTL?	2/03/2021	10559.0 hrs	0.0	637.3
34		AIR DATA COMPUTER	#2	622-5465-651	158	2/09/2016	9131 ldg	0	484
34		AIR DATA COMPUTER	#2	622-5465-651	158	2/09/2016	10342.2 hrs	0.0	854.1
34		AIRSPEED INDICATOR	STANDBY	8059-2B	7390	9/13/2012	8987 ldg	0	628
34		AIRSPEED INDICATOR	STANDBY	8059-2B	7390	9/13/2012	10184.6 hrs	0.0	1011.7
34		ALTIMETER	STANDBY	8047/10	06125433B INSTL?	2/03/2021	9221 ldg	0	394
34		ALTIMETER	STANDBY	8047/10	06125433B INSTL?	2/03/2021	10559.0 hrs	0.0	637.3
34		ALTITUDE PRESELECT (PRE-80)		622-7648-006	2176	11/19/2012	9026 ldg	0	589
34		ALTITUDE PRESELECT (PRE-80)		622-7648-006	2176	11/19/2012	10226.7 hrs	0.0	969.6
34		CVR CONTROL HEAD		1634-02	332	6/16/2016	9139 ldg	0	476
34		CVR CONTROL HEAD		1634-02	332	6/16/2016	10361.0 hrs	0.0	835.3
34		DME INDICATOR	#2	622-3918-001	35069	6/07/2013	9083 ldg	0	532
34		DME INDICATOR	#2	622-3918-001	35069	6/07/2013	10274.0 hrs	0.0	922.3
34		EFIS HSI INDICATOR	#1	622-6020-011	988	6/11/2013	9083 ldg	0	532
34		EFIS HSI INDICATOR	#1	622-6020-011	988	6/11/2013	10274.0 hrs	0.0	922.3
34		EFIS HSI INDICATOR	#2	622-6020-011	UNKNOWN	1/06/2014	9086 ldg	0	529
34		EFIS HSI INDICATOR	#2	622-6020-011	UNKNOWN	1/06/2014	10275.1 hrs	0.0	921.2
34		ELEVATOR TRIM SERVO/MOTOR		622-3260-001	480	11/30/1994	4975 ldg	0	4640
34		GPS RECEIVER		81440-02-241P	8030011	9/15/2014	9097 ldg	0	518
34		GPS RECEIVER		81440-02-241P	8030011	9/15/2014	10286.8 hrs	0.0	909.5
34		MULTI FUNCTION DISPLAY	#1	622-7236-001	333	2/09/2016	9131 ldg	0	484
34		MULTI FUNCTION DISPLAY	#1	622-7236-001	333	2/09/2016	10342.2 hrs	0.0	854.1
34		PITOT HEAD	RH	853JF	6495E	6/07/2013	9083 ldg	0	532
34		PITOT HEAD	RH	853JF	6495E	6/07/2013	10274.0 hrs	0.0	922.3
34		RADIO ALTIMETER ANTENNA	LH	DMPN3-3	47999	6/03/2011	8783 ldg	0	832
34		RADIO ALTIMETER ANTENNA	LH	DMPN3-3	47999	6/03/2011	10006.6 hrs	0.0	1189.7
34		RADIO ALTIMETER ANTENNA	RH	DMPN3-3	47911	6/03/2011	8783 ldg	0	832
34		RADIO ALTIMETER ANTENNA	RH	DMPN3-3	47911	6/03/2011	10006.6 hrs	0.0	1189.7
34		RADIO ALTIMETER TRANSCEIVER	#1	622-3890-002	4499	6/03/2011	8783 ldg	0	832
34		RADIO ALTIMETER TRANSCEIVER	#1	622-3890-002	4499	6/03/2011	10006.6 hrs	0.0	1189.7
34		TRANSPONDER	#1	011-03303-00	3EH026439	2/03/2021	9221 ldg	0	394
34		TRANSPONDER	#1	011-03303-00	3EH026439	2/03/2021	10559.0 hrs	0.0	637.3

COMPONENT INVENTORY REPORT
HS-125 257208

4/25/2024
N2787

A T A	O C	D E S C R I P T I O N	L O C A T I O N	P A R T N U M B E R	S E R I A L N U M B E R	I N S T A L L A T I O N			C U R R E N T T I M E
						D A T E	T I M E	T S O	
34		TRANSPONDER	#2	011-03303-00	3EH026856 INSTL?	2/03/2021	9221 ldg	0	394
34		TRANSPONDER	#2	011-03303-00	3EH026856 INSTL?	2/03/2021	10559.0 hrs	0.0	637.3
35		OXYGEN CONTAINER (750 LITRE) HYDRO	LH	UNKNOWN	UNKNOWN	8/20/2021	9221 ldg	0	394
35		OXYGEN CONTAINER (750 LITRE) HYDRO	LH	UNKNOWN	UNKNOWN	8/20/2021	10559.0 hrs	0.0	637.3
35		OXYGEN CONTAINER (750 LITRE) HYDRO	RH	UNKNOWN	UNKNOWN	8/20/2021	9221 ldg	0	394
35		OXYGEN CONTAINER (750 LITRE) HYDRO	RH	UNKNOWN	UNKNOWN	8/20/2021	10559.0 hrs	0.0	637.3
35		OXYGEN CONTAINER HYDRO	#3	UNKNOWN	UNKNOWN	8/20/2021	9221 ldg	0	394
35		OXYGEN CONTAINER HYDRO	#3	UNKNOWN	UNKNOWN	8/20/2021	10559.0 hrs	0.0	637.3
35		OXYGEN MASK	COPILOT	UNKNOWN	UNKNOWN	8/20/2021	9221 ldg	0	394
35		OXYGEN MASK	COPILOT	UNKNOWN	UNKNOWN	8/20/2021	10559.0 hrs	0.0	637.3
35		OXYGEN MASK	PILOT	MC10-14-01	60862	2/09/2016	9131 ldg	0	484
35		OXYGEN MASK	PILOT	MC10-14-01	60862	2/09/2016	10342.2 hrs	0.0	854.1
35		PROTECTIVE BREATHING EQUIPMENT		E28180-20-0001	BEEB-0405	2/27/2013	9086 ldg	0	529
35		PROTECTIVE BREATHING EQUIPMENT		E28180-20-0001	BEEB-0405	2/27/2013	10275.1 hrs	0.0	921.2
49		APU STARTER/GENERATOR		23080-005	3477	9/13/2012	3414.8 hrs	0.0	417.0
57		AIRBRAKE INBD ATTACH PIVOT BOLT	LH TOP	25WB171	UNKNOWN	12/15/1983	0 ldg	0	9615
57		AIRBRAKE INBD ATTACH PIVOT BOLT	RH TOP	25WB171	UNKNOWN	12/15/1983	0 ldg	0	9615
57		FLAP HINGE ATTACH ANGLE BOLTS	LH INNER	25WB297	UNKNOWN	12/15/1983	0 ldg	0	9615
57		FLAP HINGE ATTACH ANGLE BOLTS	RH INNER	25WB297	UNKNOWN	12/15/1983	0 ldg	0	9615
57	#	MAIN GEAR FORWARD DOOR HINGE FITTNG	LH	POST MOD 3176	UNKNOWN	12/01/1984	0 ldg	0	9615
57	#	MAIN GEAR FORWARD DOOR HINGE FITTNG	RH	POST MOD 3176	UNKNOWN	12/01/1984	0 ldg	0	9615
57		AIRBRAKE INBD ATTACH PIVOT BOLT	LH TOP	25WB171	UNKNOWN	12/15/1983	0.0 hrs	0.0	11196.3
57		AIRBRAKE INBD ATTACH PIVOT BOLT	RH TOP	25WB171	UNKNOWN	12/15/1983	0.0 hrs	0.0	11196.3
57		FLAP HINGE ATTACH ANGLE BOLTS	LH INNER	25WB297	UNKNOWN	12/15/1983	0.0 hrs	0.0	11196.3
57		FLAP HINGE ATTACH ANGLE BOLTS	RH INNER	25WB297	UNKNOWN	12/15/1983	0.0 hrs	0.0	11196.3
57	#	MAIN GEAR FORWARD DOOR HINGE FITTNG	LH	POST MOD 3176	UNKNOWN	12/01/1984	0.0 hrs	0.0	11196.3
57	#	MAIN GEAR FORWARD DOOR HINGE FITTNG	RH	POST MOD 3176	UNKNOWN	12/01/1984	0.0 hrs	0.0	11196.3
71		ENGINE REAR MOUNT ATTACH BOLT	RH	3073361-1	N/A	6/07/2013	10274.0 hrs	0.0	922.3
71		ENGINE COWLING	LH	N/A	N/A	7/10/2016	10361.8 hrs	0.0	834.5
71		ENGINE COWLING	RH	N/A	N/A	7/10/2016	10352.3 hrs	0.0	844.0
71		ENGINE COWLING	LH	N/A	N/A	7/10/2016	9139 ldg	0	476
71		ENGINE COWLING	RH	N/A	N/A	7/10/2016	9136 ldg	0	479
71		ENGINE REAR MOUNT ATTACH BOLT	RH	3073361-1	N/A	6/07/2013	9083 ldg	0	532
72		FAN ROTOR DISC & HUB	LH	3073563-2	5-03229-2571	11/23/1995	4919 cyc	0	4132
72		FAN ROTOR DISC & HUB	RH	3073563-2	5-03229-502	6/19/1995	4761 cyc	0	4288
72		HP COMPRESSOR RADIAL IMPELLER	LH	3075765-1	000322902584	12/14/2000	6414 cyc	0	2637
72		HP COMPRESSOR RADIAL IMPELLER	RH	3073394-1	9-23365-1736	6/04/2013	8517 cyc	4857	5389
72		HP ROTOR SEAL PLATE	LH	3072411-1	1-18040-0307	7/31/1997	5388 cyc	4171	7834
72		HP ROTOR SEAL PLATE	RH	3072411-1	2-18040-3339	4/07/1983	0 cyc	0	9049
72		HP SHOULDERED SHAFT	LH	3072545-1	00P24042	12/14/2000	6414 cyc	0	2637
72		HP SHOULDERED SHAFT	RH	3072545-1	3P-5547	4/07/1983	0 cyc	0	9049
72		HP TURBINE WHEEL ROTOR	LH	3072316-3	000322900544	12/14/2000	6414 cyc	0	2637
72		HP TURBINE WHEEL ROTOR	RH	3072316-3	980322902885	1/11/2000	6190 cyc	0	2859
72		LP 1ST STAGE AXIAL COMPRESSOR DISC	LH	3072395-1	2-03501-5687	7/20/1983	0 cyc	0	9051

COMPONENT INVENTORY REPORT
HS-125 257208

4/25/2024
N2787

A T A	O C	D E S C R I P T I O N	L O C A T I O N	P A R T N U M B E R	S E R I A L N U M B E R	I N S T A L L A T I O N			C U R R E N T T I M E
						D A T E	T I M E	T S O	
72		LP 1ST STAGE AXIAL COMPRESSOR DISC	RH	3072395-1	2-03501-01433	4/07/1983	0 cyc	0	9049
72		LP 2ND STAGE AXIAL COMPRESSOR DISC	LH	3072396-1	2-12112-842	7/20/1983	0 cyc	0	9051
72		LP 2ND STAGE AXIAL COMPRESSOR DISC	RH	3075839-1	12-16204-2164	6/04/2013	8517 cyc	0	532
72		LP 2ND STAGE AXIAL COMPRESSOR DISC	RH	3072396-1	2-12112-1080	9/27/1996	5179 cyc	5179	9049
72		LP 2ND STAGE TURBINE ROTOR DISC	LH	3072542-5	060322905473	8/02/2007	7748 cyc	0	1303
72		LP 2ND STAGE TURBINE ROTOR DISC	RH	3072542-5	040322901958	2/08/2005	7264 cyc	0	1785
72		LP 3RD STAGE AXIAL COMPRESSOR DISC	LH	3072397-1	2-12112-1372	7/20/1983	0 cyc	0	9051
72		LP 3RD STAGE AXIAL COMPRESSOR DISC	RH	3072397-1	1-03160-1549	6/04/2013	8517 cyc	4166	4698
72		LP 3RD STAGE TURBINE ROTOR DISC	LH	3074096-2	965332201051	7/31/1997	5388 cyc	0	3663
72		LP 3RD STAGE TURBINE ROTOR DISC	RH	3074096-2	995332200279	1/11/2000	6190 cyc	0	2859
72		LP 4TH STAGE AXIAL COMPRESSOR DISC	LH	3072398-1	2-03160-2714	7/20/1983	0 cyc	0	9051
72		LP 4TH STAGE AXIAL COMPRESSOR DISC	RH	3072398-1	2-03160-2561	4/07/1983	0 cyc	0	9049
72		ACCESSORY GEARBOX	LH	3070003-26	P3421	12/14/2000	6414 cyc	6414	9051
72		ACCESSORY GEARBOX	LH	3070003-26	P3421	12/14/2000	7400.2 eng	7400.2	10382.9
72		ACCESSORY GEARBOX	RH	3070003-26	P-3323	9/27/1996	5179 cyc	5179	9049
72		ACCESSORY GEARBOX	RH	3070003-26	P-3323	9/27/1996	5849.9 eng	5849.9	10529.4
72		AIR SEAL	LH	3073765-1	00P13551	12/14/2000	6414 cyc	0	2637
72		AIR SEAL	LH	3073765-1	00P13551	12/14/2000	7400.2 eng	0.0	2982.7
72		AIR SEAL	RH	3073765-5	04P24850	6/04/2013	8517 cyc	1253	1785
72		AIR SEAL	RH	3073765-5	04P24850	6/04/2013	9607.1 eng	1144.8	2067.1
72		AIR SEAL SUPPORT	LH	30737641-3	00P11386	12/14/2000	6414 cyc	0	2637
72		AIR SEAL SUPPORT	LH	30737641-3	00P11386	12/14/2000	7400.2 eng	0.0	2982.7
72		AIR SEAL SUPPORT	RH	3073764-3	04P24854	6/04/2013	8517 cyc	1253	1785
72		AIR SEAL SUPPORT	RH	3073764-3	04P24854	6/04/2013	9607.1 eng	1144.8	2067.1
72		COMBUSTION CHAMBER PLENUM CASE	LH	3072443+4	9P-27563	7/31/1997	5388 cyc	6440	10103
72		COMBUSTION CHAMBER PLENUM CASE	LH	3072443+4	9P-27563	7/31/1997	5958.7 eng	6440.1	10864.3
72		COMBUSTION CHAMBER PLENUM CASE	RH	3072443-4	3P4090	6/04/2013	8517 cyc	7350	7882
72		COMBUSTION CHAMBER PLENUM CASE	RH	3072443-4	3P4090	6/04/2013	9607.1 eng	7350.6	8272.9
72		FAN DRIVE SHAFT	LH	3071955-5	3P5781	11/10/1993	4243 cyc	1060	5868
72		FAN DRIVE SHAFT	LH	3071955-5	3P5781	11/10/1993	4611.1 eng	1170.3	6942.1
72		FAN DRIVE SHAFT	RH	3071955-5-22242	39-5766	9/27/1996	5179 cyc	4937	8807
72		FAN DRIVE SHAFT	RH	3071955-5-22242	39-5766	9/27/1996	5849.9 eng	4813.4	9492.9
72		FAN ROTOR DISC & HUB	LH	3073563-2	5-03229-2571	11/23/1995	5413.1 eng	0.0	4969.8
72		FAN ROTOR DISC & HUB	RH	3073563-2	5-03229-502	6/19/1995	5346.6 eng	0.0	5182.8
72		FUEL PUMP	LH	3070850-57	MX413448	9/18/2004	7185 cyc	0	1866
72		FUEL PUMP	LH	3070850-57	MX413448	9/18/2004	8234.7 eng	0.0	2148.2
72		FUEL PUMP	RH	3070850-44	MX-371822	9/27/1996	5179 cyc	0	3870
72		FUEL PUMP	RH	3070850-44	MX-371822	9/27/1996	5849.9 eng	0.0	4679.5
72		HP COMPRESSOR RADIAL IMPELLER	LH	3075765-1	000322902584	12/14/2000	7400.2 eng	0.0	2982.7
72		HP COMPRESSOR RADIAL IMPELLER	RH	3073394-1	9-23365-1736	6/04/2013	9607.1 eng	7349.6	8271.9
72		HP ROTOR SEAL PLATE	LH	3072411-1	1-18040-0307	7/31/1997	5958.7 eng	0.0	4424.2
72		HP ROTOR SEAL PLATE	RH	3072411-1	2-18040-3339	4/07/1983	0.0 eng	0.0	10529.4
72		HP SHOULDERED SHAFT	LH	3072545-1	00P24042	12/14/2000	7400.2 eng	0.0	2982.7
72		HP SHOULDERED SHAFT	RH	3072545-1	3P-5547	4/07/1983	0.0 eng	0.0	10529.4

COMPONENT INVENTORY REPORT
HS-125 257208

4/25/2024
N2787

A T A	O C	D E S C R I P T I O N	L O C A T I O N	P A R T N U M B E R	S E R I A L N U M B E R	I N S T A L L A T I O N			C U R R E N T T I M E
						D A T E	T I M E	T S O	
72		HP TURBINE WHEEL ROTOR	LH	3072316-3	000322900544	12/14/2000	7400.2 eng	0.0	2982.7
72		HP TURBINE WHEEL ROTOR	RH	3072316-3	980322902885	1/11/2000	7164.6 eng	0.0	3364.8
72		LP 1ST STAGE AXIAL COMPRESSOR DISC	LH	3072395-1	2-03501-5687	7/20/1983	0.0 eng	0.0	10382.9
72		LP 1ST STAGE AXIAL COMPRESSOR DISC	RH	3072395-1	2-03501-01433	4/07/1983	0.0 eng	0.0	10529.4
72		LP 2ND STAGE AXIAL COMPRESSOR DISC	LH	3072396-1	2-12112-842	7/20/1983	0.0 eng	0.0	10382.9
72		LP 2ND STAGE AXIAL COMPRESSOR DISC	RH	3075839-1	12-16204-2164	6/04/2013	9607.1 eng	0.0	922.3
72		LP 2ND STAGE AXIAL COMPRESSOR DISC	RH	3072396-1	2-12112-1080	9/27/1996	5849.9 eng	5849.9	10529.4
72		LP 2ND STAGE TURBINE ROTOR DISC	LH	3072542-5	060322905473	8/02/2007	8770.1 eng	0.0	1612.8
72		LP 2ND STAGE TURBINE ROTOR DISC	RH	3072542-5	040322901958	2/08/2005	8462.3 eng	0.0	2067.1
72		LP 3RD STAGE AXIAL COMPRESSOR DISC	LH	3072397-1	2-12112-1372	7/20/1983	0.0 eng	0.0	10382.9
72		LP 3RD STAGE AXIAL COMPRESSOR DISC	RH	3072397-1	1-03160-1549	6/04/2013	9607.1 eng	6647.4	7569.7
72		LP 3RD STAGE TURBINE ROTOR DISC	LH	3074096-2	965332201051	7/31/1997	5958.7 eng	0.0	4424.2
72		LP 3RD STAGE TURBINE ROTOR DISC	RH	3074096-2	995332200279	1/11/2000	7164.6 eng	0.0	3364.8
72		LP 4TH STAGE AXIAL COMPRESSOR DISC	LH	3072398-1	2-03160-2714	7/20/1983	0.0 eng	0.0	10382.9
72		LP 4TH STAGE AXIAL COMPRESSOR DISC	RH	3072398-1	2-03160-2561	4/07/1983	0.0 eng	0.0	10529.4
72		LP FIRST STAGE NOZZLE ASSEMBLY	LH	3072319-11	5-08378-1022	7/31/1997	5388 cyc	0	3663
72		LP FIRST STAGE NOZZLE ASSEMBLY	LH	3072319-11	5-08378-1022	7/31/1997	5958.7 eng	0.0	4424.2
72		LP FIRST STAGE NOZZLE ASSEMBLY	RH	3072319-11	04P25823	6/04/2013	8517 cyc	1253	1785
72		LP FIRST STAGE NOZZLE ASSEMBLY	RH	3072319-11	04P25823	6/04/2013	9607.1 eng	1144.8	2067.1
72		ROTATING SEAL	LH	3072729-1	9-23151-3171	8/19/1993	4243 cyc	2747	7555
72		ROTATING SEAL	LH	3072729-1	9-23151-3171	8/19/1993	4611.1 eng	3991.6	9763.4
72		ROTATING SEAL	RH	3072729-1	8P-29644	8/26/1986	822 cyc	665	8892
72		ROTATING SEAL	RH	3072729-1	8P-29644	8/26/1986	916.1 eng	800.1	10413.4
72		TIE ROD	LH	3073049-1	9P-18194	8/02/2007	7748 cyc	5265	6568
72		TIE ROD	LH	3073049-1	9P-18194	8/02/2007	8770.1 eng	5462.4	7075.2
72		TIE ROD	RH	3073049-1	2P11790	1/11/2000	6190 cyc	6022	8881
72		TIE ROD	RH	3073049-1	2P11790	1/11/2000	7164.6 eng	8133.7	11498.5
72		TRANSFER GEARBOX	LH	3070093-12	P4705	7/31/1997	5388 cyc	5388	9051
72		TRANSFER GEARBOX	LH	3070093-12	P4705	7/31/1997	5958.7 eng	5958.7	10382.9
72		TRANSFER GEARBOX	RH	3070093-12	P-4632	9/27/1996	5179 cyc	5179	9049
72		TRANSFER GEARBOX	RH	3070093-12	P-4632	9/27/1996	5849.9 eng	5849.9	10529.4
72		TURBINE INTERSTAGE TRANSITION DUCT	LH	3072318-3	1P-2553	8/02/2007	7748 cyc	6581	7884
72		TURBINE INTERSTAGE TRANSITION DUCT	LH	3072318-3	1P-2553	8/02/2007	8770.1 eng	6581.3	8194.1
72		TURBINE INTERSTAGE TRANSITION DUCT	RH	3072318-3	1P-9103	2/08/2005	7264 cyc	1946	3731
72		TURBINE INTERSTAGE TRANSITION DUCT	RH	3072318-3	1P-9103	2/08/2005	8462.3 eng	2983.5	5050.6
73		FUEL FILTER ELEMENT	LH	897830-1	N/A	7/17/2012	9356.6 eng	0.0	1026.3
73		FUEL FILTER ELEMENT	RH	UNKNOWN	N/A	6/04/2013	9607.1 eng	0.0	922.3
73		FUEL COMPUTER	LH	2119020-3	50-BB0062	3/17/2003	6869 cyc	0	2182
73		FUEL COMPUTER	LH	2119020-3	50-BB0062	3/17/2003	7903.6 eng	0.0	2479.3
73		FUEL COMPUTER	RH	2119020-3001	82-BB0182	3/17/2003	8081.3 eng	0.0	2448.1
73		FUEL CONTROL ASSEMBLY	LH	3070800-22	A8808C	3/09/2003	6865 cyc	0	2186
73		FUEL CONTROL ASSEMBLY	LH	3070800-22	A8808C	3/09/2003	7899.5 eng	0.0	2483.4
73		FUEL CONTROL ASSEMBLY	RH	3070800-22	A6629CT	12/13/2001	6682 cyc	621	2988
73		FUEL CONTROL ASSEMBLY	RH	3070800-22	A6629CT	12/13/2001	7844.5 eng	621.2	3306.1

COMPONENT INVENTORY REPORT
HS-125 257208

4/25/2024
N2787

A T A	O C	D E S C R I P T I O N	L O C A T I O N	P A R T N U M B E R	S E R I A L N U M B E R	I N S T A L L A T I O N			C U R R E N T T I M E
						D A T E	T I M E	T S O	
73		FUEL FILTER ELEMENT	LH	897830-1	N/A	7/17/2012	8407 cyc	0	644
73		FUEL FILTER ELEMENT	RH	UNKNOWN	N/A	6/04/2013	8517 cyc	0	532
73		FUEL MANIFOLD	LH	3073591-2	9-739C	8/02/2007	7748 cyc	0	1303
73		FUEL MANIFOLD	LH	3073591-2	9-739C	8/02/2007	8770.1 eng	0.0	1612.8
75		IGNITION EXCITER	RH	10-617050-4	49R006	6/26/2001	6565 cyc	0	2484
75		IGNITION EXCITER	RH	10-617050-4	49R006	6/26/2001	7710.0 eng	0.0	2819.4
75		IGNITOR	LH AFT	3074541-4	N/A	8/02/2007	7748 cyc	0	1303
75		IGNITOR	LH AFT	3074541-4	N/A	8/02/2007	8770.1 eng	0.0	1612.8
75		IGNITOR	LH FWD	3074541-4	N/A	8/02/2007	7748 cyc	0	1303
75		IGNITOR	LH FWD	3074541-4	N/A	8/02/2007	8770.1 eng	0.0	1612.8
75		IGNITOR	RH AFT	3074541-4	N/A	6/04/2013	8517 cyc	0	532
75		IGNITOR	RH AFT	3074541-4	N/A	6/04/2013	9607.1 eng	0.0	922.3
75		IGNITOR	RH FWD	3074541-4	N/A	6/04/2013	8517 cyc	0	532
75		IGNITOR	RH FWD	3074541-4	N/A	6/04/2013	9607.1 eng	0.0	922.3
77		HP (N2) TRANSDUCER	LH	3070722-3	14910300017	9/27/2014	8537 ldg	0	1078
77		HP (N2) TRANSDUCER	LH	3070722-3	14910300017	9/27/2014	9480.5 hrs	0.0	1715.8
77		ITT INDICATOR	LH	H900K-243	608J	9/18/2014	9098 ldg	0	517
77		ITT INDICATOR	LH	H900K-243	608J	9/18/2014	10287.8 hrs	0.0	908.5
77		ITT INDICATOR	RH	H900K-243	5509G	9/15/2014	9097 ldg	0	518
77		ITT INDICATOR	RH	H900K-243	5509G	9/15/2014	10286.8 hrs	0.0	909.5
79		ENGINE OIL CHANGE	LH	MOBIL 254	N/A	7/17/2012	9356.6 eng	0.0	1026.3
79		ENGINE OIL CHANGE	RH	N/A	N/A	6/04/2013	9607.1 eng	0.0	922.3
79		ENGINE OIL CHANGE	LH	MOBIL 254	N/A	7/17/2012	8407 cyc	0	644
79		ENGINE OIL CHANGE	RH	N/A	N/A	6/04/2013	8517 cyc	0	532
79		ENGINE OIL PUMP	RH	3060785-2	041405700870	2/14/2005	7264 cyc	0	1785
79		ENGINE OIL PUMP	RH	3060785-2	041405700870	2/14/2005	8462.3 eng	0.0	2067.1
79		OIL FILTER	LH	3070945-1	N/A	7/17/2012	8407 ldg	0	1208
79		OIL FILTER	LH	3070945-1	N/A	7/17/2012	9356.6 hrs	0.0	1839.7
79		OIL TANK	LH	3071845-5	1-01599-3792	1/02/2001	6964 ldg	0	2651
79		OIL TANK	LH	3071845-5	1-01599-3792	1/02/2001	8213.3 hrs	0.0	2983.0

NOTE: # INDICATES ITEM HAS BEEN CHANGED TO AN ON CONDITION STATUS.

AIRFRAME AIRWORTHINESS DIRECTIVE
HS-125 257208

4/25/2024
N2787

DIRECTIVE NUMBER	REVISION	DESCRIPTION	VENDER	COMPLIANCE	NEXT DUE
LOCATION	RECURRS		METHOD		
EFFECTIVE DATE					
AD 2000-02-35		TO PREVENT FLAKING OF CADMIUM FROM CERTAIN OXYGEN SYS PLUMBING FITTINGS & CONE CAPS FROM BLOCKING	RAYTHEON AIRCRAFT	DATE: 12/10/1998	DATE:
3/13/2000	ONE TIME		35-3169,-3034,-3170,-3167,-3168		TIME:
				LD/CY:	LD/CY:
AD 2000-22-03		TO PREVENT ERRONEOUS ALTIMETER & AIRSPEED INDICATIONS DUE TO PLUGGED OR TAPED VENT DRAIN VALVES	RAYTHEON	DATE: 7/01/2016	DATE:
12/04/2000	ONE TIME		C/W SB 34-3207		TIME: 9136.0
				LD/CY: 9136	LD/CY:
AD 2001-17-26		EDDY CURRENT INSPECTION OF MLG ACTUATOR CYLINDER HEAD LUGS FOR CRACKING OR SUPERSEDED BY AD 2003-04-20	RAYTHEON AIRCRAFT	DATE: 1/10/2016	DATE:
10/03/2001	ONE TIME		N/A BY AIRCRAFT MODEL		TIME: 9136.0
				LD/CY: 9136	LD/CY:
AD 2003-04-20		EDDY CURRENT INSPECTION OF MLG ACTUATOR CYLINDER HEAD LUGS FOR CRACKING OR CORROSION	RAYTHEON AIRCRAFT	DATE: 11/30/2004	DATE:
4/04/2003	ONE TIME		SB 32-3391		TIME:
				LD/CY:	LD/CY:
AD 2003-07-07		INSPECTION AND REPLACEMENT OF MLG WHEEL TIE-BOLT NUTS P/N NAS1804	RAYTHEON AIRCRAFT	DATE: 7/01/2016	DATE:
5/08/2003	ONE TIME		N/A BY AIRCRAFT MODEL		TIME: 9136.0
				LD/CY: 9136	LD/CY:
AD 2003-26-14		REPLACEMENT OF HAND HELD FAULTY FIRE EXTINGUISHERS WHICH DO NOT FULLY DISCHARGE	WATER KIDDE	DATE: 7/01/2016	DATE:
2/20/2004	ONE TIME		N/A BY PART NUMBER INSTALLED		TIME: 9136.0
				LD/CY: 9136	LD/CY:
AD 2005-03-16		INSTALL INSULATING BLANKETS ON THE ENGINE COMPARTMENT FIREWALL & WIRE HARNESS	RAYTHEON AIRCRAFT	DATE: 6/28/2005	DATE:
RH	ONE TIME		C/W SB 26-3496		TIME: 9136.0
3/21/2005				LD/CY: 9136	LD/CY:
AD 2005-03-16	1	INSTALL INSULATING BLANKETS ON THE ENGINE COMPARTMENT FIREWALL & WIRE HARNESS	RAYTHEON AIRCRAFT	DATE: 6/28/2005	DATE:
LH	ONE TIME		C/W SB 26-3496		TIME: 9136.0
3/21/2005				LD/CY: 9136	LD/CY:
AD 2005-16-02		INSPECT TO DETERMINE THE CURRENT RATING OF THE CIRCUIT BREAKERS OF CERTAIN COCKPIT VENT & AVIONICS COOLING BLOWERS	RAYTHEON AIRCRAFT	DATE: 7/01/2006	DATE:
9/06/2005	ONE TIME		N/A EQUIPMENT NOT INSTALLED		TIME:
				LD/CY:	LD/CY:
AD 2006-01-04		PREVENT SMOKE OR FIRE IN THE CABIN WHILE THE ACFT IS IN FLIGHT;CLEARANCE BETWEEN THE FAN VENTURI MOTOR CASING & ADJ EQUIP	RAYTHEON	DATE: 7/01/2006	DATE:
2/22/2006	ONE TIME		N/A BY PART NUMBER INSTALLED		TIME:
				LD/CY:	LD/CY:
AD 2006-12-20		PERFORM A RESISTANCE MEASUREMENT TEST & REPLACEMENT IF NECESSARY ON THE PE, PS1 & PS2 BUSSES CURRENT LIMITERS	RAYTHEON	DATE: 7/01/2006	DATE:
7/03/2006	ONE TIME		NOT APPLICABLE		TIME:
				LD/CY:	LD/CY:
AD 2006-16-18	R1	MODIFY & PERFORM SOFTWARE UPGRADE FOR AIRCRAFT EQUIPPED WITH A SANDEL ST3400 TAWS	SANDEL AVIONICS	DATE: 7/10/2016	DATE:
9/25/2006	ONE TIME		COMPLIED WITH		TIME: 10328.0
				LD/CY: 9136	LD/CY:
AD 2006-16-18		PLACARD & REVISE AIRCRAFT FLIGHT MANUAL (AFM) FOR AIRCRAFT EQUIPPED WITH A SANDEL ST3400 TAWS	SANDEL AVIONICS	DATE: 9/11/2006	DATE:
9/25/2006	ONE TIME		COMPLIED WITH		TIME: 9438.3
				LD/CY: 8142	LD/CY:
AD 2009-08-04		INSPECT & REWORK AS NECESSARY THE COCKPIT BLOWER WIRING CONFIGURATION	RAYTHEON	DATE: 6/10/2016	DATE:
5/14/2009	ONE TIME		N/A BY PART S/N INSTALLED		TIME: 10352.0
				LD/CY:	LD/CY:

AIRFRAME AIRWORTHINESS DIRECTIVE
HS-125 257208

4/25/2024
N2787

DIRECTIVE NUMBER	REVISION	DESCRIPTION	VENDER	COMPLIANCE	NEXT DUE
LOCATION	RECURRS		METHOD		
EFFECTIVE DATE					
AD 2010-01-03		INSPECT PROTABLE HALON FIRE EXTINGUISGER FOR EFFECTIVE P/N AND SERIAL NUMBER	FIRE FIGHT ENT	DATE: 6/10/2016	DATE:
1/20/2010	ONE TIME	SEE SB 26-115	FOUND P/C/W	TIME: 10352.0	TIME:
				LD/CY:	LD/CY:
AD 2011-14-08		DO A RECORD CHECK OR VISUAL INSPECTION FOR EFFECTED PASSENGER OXY MASKS LISTED IN BE AEROSPACE SB 174080-35-04	BE AEROSPACE	DATE: 9/13/2012	DATE:
8/09/2011	ONE TIME		N/A BY MANUFACTURE	TIME: 10184.6	TIME:
				LD/CY:	LD/CY:
AD 2012-02-08		UPGRADE SOFTWARE FOR AVIATION COMMUNICATION & SURVELLANCE SYSTEMS (ACSS) TCAS	ACSS	DATE: 9/13/2012	DATE:
3/13/2012	ONE TIME		N/A EQUIPMENT NOT INSTALLED	TIME: 10184.6	TIME:
				LD/CY: 8987	LD/CY:
AD 2015-08-07		INSPECT INFLATABLE HARNESS FITTED TO EACH FLIGHTCREW OXYGEN MASK REGULATOR TO SEE IF EFFECTIVE P/N INSTALLED	ZODIAC AERO	DATE:	DATE: 6/16/2017
6/16/2015	ONE TIME			TIME:	TIME:
				LD/CY:	LD/CY:
AD 2015-10-51E		INCORPORATE THE OPERATIONAL LIMITATIONS LISTED IN PARA (G)(1)(I) & (II)OF THIS AD INTO AFM OR AFMS AS APPLICABLE	AVIDYNE AEROSPACE	DATE: 2/09/2016	DATE:
5/20/2015	ONE TIME		N/A EQUIPMENT NOT INSTALLED	TIME: 10342.2	TIME:
				LD/CY: 9131	LD/CY:
AD 2016-11-20 (H)		REPLACEMENT OF PBE DUE TO FIRE UPON ACTIVATION BY CREWMEMBER P/N 119003-11 SUPERSEDED BY AD 2017-18-12	B/E AEROPSACE	DATE: 7/01/2016	DATE:
7/15/2016	ONE TIME		N/A EQUIPMENT NOT INSTALLED	TIME: 9136.0	TIME:
				LD/CY: 9136	LD/CY:
AD 71-16-02		PREVENT A HAZARDOUS DRIFT IN THE ROTAX VOLTAGE SENSING UNIT	BRITISH AEROSPACE	DATE: 6/10/2016	DATE:
11/05/1971	ONE TIME		N/A BY AIRCRAFT SERIAL NUMBER	TIME:	TIME:
				LD/CY:	LD/CY:
AD 73-18-02		PREVENT POSSIBLE BURST FAILURE OF OVERHAULD O2 CYLINDERS, P/N WKA31394, WKA29396/GR14, WKA39396/GR22,WKA31393	BRITISH AEROSPACE	DATE: 7/01/2016	DATE:
LH			COMPLIED WITH	TIME: 9136.0	TIME:
8/28/1973	ONE TIME			LD/CY:	LD/CY:
AD 74-08-09	R3	INSPECT LAVATORY WASTE RECEPTACLE: TO PREVENT POSSIBLE FIRES THAT COULD RESULT FROM SMOKING MATERIALS DROPPED IN RECEPT	T-CATEGORY	DATE: 6/06/2011	DATE:
3/28/2012	RECURRS		INSPECTED LAV RECEPTICLE & PLACARD	TIME: 10006.6	TIME:
				LD/CY:	LD/CY:
AD 75-17-21		PREVENT POSSIBLE RAPID LOSS OF CABIN PRESSURIZATION	BRITISH AEROSPACE	DATE: 6/10/2016	DATE:
8/19/1975	ONE TIME		COMPLIED WITH	TIME: 10352.0	TIME:
				LD/CY:	LD/CY:
AD 76-06-08		TO PREVENT POSSIBLE FAILURE OF THE ORIGINAL BOLTS ATTACHING THE OTBD HINGE BRACKET TO THE UPPER AIRBRAKE ASSY	BRITISH AEROSPACE	DATE: 6/10/2016	DATE:
LH/RH			FOUND P/C/W	TIME: 10352.0	TIME:
2/09/1976	ONE TIME			LD/CY:	LD/CY:
AD 77-13-02		TO PREVENT THE FAILURE OF THE KNIFE EDGE OF THE BRAKE CONTROL VALVE, P/N AC.61520 & THE LOSS OF BRAKING ON ONE SIDE	BRITISH AEROSPACE	DATE: 6/28/1999	DATE:
LH/RH			C/W SB 32-166	TIME: 7489.4	TIME:
7/20/1977	RECURRS			LD/CY: 6509	LD/CY: 11009
AD 77-13-11		TO PREVENT POSSIBLE FAILURE OF THE KNIFE EDGES OF THE EMERG BRAKE REDUCING VALVE P/N AC.61516 WHICH RESULTS IN LOSS BRAKE	BRITISH AEROSPACE	DATE: 8/29/2008	DATE:
LH/RH			C/W SB 32-167	TIME: 9680.0	TIME:
7/25/1977	RECURRS			LD/CY: 8411	LD/CY: 12911
AD 78-07-02		TO DETECT CRACKING & POSSIBLE FAILURE OF THE ATTACHING LUGS OF THE TEE PIECES, PN 25-7PA41, MOUNTED ON MASTER REFUEL VALVE	BRITISH AEROSPACE	DATE: 6/10/2016	DATE:
4/14/1978	ONE TIME		SB 28-065A	TIME: 10352.0	TIME:
				LD/CY:	LD/CY:

AIRFRAME AIRWORTHINESS DIRECTIVE
HS-125 257208

4/25/2024
N2787

DIRECTIVE NUMBER	REVISION	DESCRIPTION	VENDER	COMPLIANCE	NEXT DUE
LOCATION	RECURRS		METHOD		
EFFECTIVE DATE					
AD 78-07-07		TO PREVENT POSSIBLE LIGHTNING STRIKE DAMAGE TO THE RADOME WHICH COULD RESULT IN LOSS OF THE RADOME	BRITISH AEROSPACE	DATE: 12/01/1984 TIME: 0.0 LD/CY: 0	DATE: TIME: LD/CY:
5/03/1978	ONE TIME		COMPLIED WITH AT MANUFACTURE		
AD 78-12-11		TO PREVENT ELECTRICAL OVERLOAD AND POSSIBLE FIRE	BRITISH AEROSPACE	DATE: 6/10/2016 TIME: 10352.0 LD/CY:	DATE: TIME: LD/CY:
7/26/1978	ONE TIME		N/A BY AIRCRAFT SERIAL NUMBER		
AD 78-13-02		TO PREVENT FAILURE OF THE RESTRAINT PROVISIONS FOR THE WEATHER RADAR RECEIVER/TRANSMITTER	BRITISH AEROSPACE	DATE: 6/10/2016 TIME: 10352.0 LD/CY:	DATE: TIME: LD/CY:
7/05/1978	ONE TIME		N/A BY AIRCRAFT SERIAL NUMBER		
AD 80-02-07		TO PREVENT THE FAILURE OF THE ALUMINUM HTE "V" CLAMPS INSTALLED IN THE PRESSURE REFUEL AND DEFUEL SYSTEM	BRITISH AEROSPACE	DATE: 6/10/2016 TIME: 10352.0 LD/CY:	DATE: TIME: LD/CY:
1/24/1980	ONE TIME		COMPLIED WITH		
AD 80-12-05		TO DETECT & CORRECT CRACKS IN THE BRIDGE CASTING OF THE NOSE LANDING GEAR DRAG STAY ASSY & PREVENT POSSIBLE COLLAPSE	BRITISH AEROSPACE	DATE: 8/20/2021 TIME: 10559.0 LD/CY: 9221	DATE: 8/20/2023 TIME: LD/CY: 10121
3/16/1983	RECURRS		COMPLIED WITH		
AD 80-12-10		INSPECTION OF THE FLAP OUTER HINGE ASSY SUPERSEDES AD 78-03-03	BRITISH AEROSPACE	DATE: 6/10/2016 TIME: 10352.0 LD/CY:	DATE: TIME: LD/CY:
1/03/1983	ONE TIME		P/C/W AT MFG		
AD 80-12-10	R1	INSPECTION OF THE FLAP OUTER HINGE ASSY SUPERSEDES AD 78-03-03	BRITISH AEROSPACE	DATE: 6/10/2016 TIME: 10352.0 LD/CY:	DATE: TIME: LD/CY:
1/03/1983	ONE TIME		P/C/W AT MFG		
AD 80-12-13		TO PREVENT FAILURE OF THE MAIN ENGINE MOUNT BEAM	BRITISH AEROSPACE	DATE: 6/10/2016 TIME: 10352.0 LD/CY:	DATE: TIME: LD/CY:
7/14/1980	ONE TIME		N/A BY AIRCRAFT SERIAL NUMBER		
AD 82-11-03	R1	TO PREVENT IMPROPER OPERATION OF THE ELEVATOR PITCH TRIM SWITCH LOCATED IN THE CONTROL COLUMN HANDWHEEL	BRITISH AEROSPACE	DATE: 12/01/1984 TIME: 0.0 LD/CY: 0	DATE: TIME: LD/CY:
10/12/1982	ONE TIME		COMPLIED WITH AT MANUFACTURE		
AD 82-12-01		TO PREVENT BLOCKING OF THE MAIN LANDING GEAR RESTRICTOR VALVES	BRITISH AEROSPACE	DATE: 6/10/2016 TIME: 10352.0 LD/CY:	DATE: TIME: LD/CY:
6/08/1982	ONE TIME		C/W SB 32-190 MOD 2252837		
AD 82-12-02	R1	TO PREVENT STRUCTURAL FAILURE OF THE FLAP	BRITISH AEROSPACE	DATE: 6/10/2016 TIME: 10352.0 LD/CY:	DATE: TIME: LD/CY:
6/17/1985	ONE TIME		C/W SB 57-058 MOD 252659		
AD 83-02-04		TO PREVENT POSSIBLE FAILURE OF WINDSHIELD HEAT FROM EXTERNAL HIGH VOLTAGE STATIC CHARGE & GEN TRIPPING	BRITISH AEROSPACE	DATE: 2/07/1985 TIME: LD/CY:	DATE: TIME: LD/CY:
6/22/1983	ONE TIME		COMPLIED WITH AT MANUFACTURE		
AD 83-22-09		TO PROTECT THE MAIN ENGINE BEAM FROM A BURST FAILURE OF THE COLD AIR UNIT FAN (PRE MOD 1600)	BRITISH AEROSPACE	DATE: 6/10/2016 TIME: 10352.0 LD/CY:	DATE: TIME: LD/CY:
12/01/1983	ONE TIME		N/A BY AIRCRAFT SERIAL NUMBER		
AD 84-03-03		TO PREVENT LOSS OF POWER TO BOTH ENGINE FUEL COMPUTERS BY A SINGLE FUSE FAILURE	BRITISH AEROSPACE	DATE: 6/10/2016 TIME: 10352.0 LD/CY:	DATE: TIME: LD/CY:
3/22/1984	ONE TIME		SB 24-225, MOD 2747		

AIRFRAME AIRWORTHINESS DIRECTIVE
HS-125 257208

4/25/2024
N2787

DIRECTIVE NUMBER LOCATION	REVISION RECURRS	DESCRIPTION	VENDER METHOD	COMPLIANCE	NEXT DUE
AD 84-20-05 C 10/14/1984	ONE TIME	TO PREVENT LANDING GEAR AND BRAKE FAILURE - INSPECTION OF MAIN LANDING GEAR JACKS FOR CRACKS.	BRITISH AEROSPACE C/W SB 32-A197	DATE: 6/10/2016 TIME: 10352.0 LD/CY:	DATE: TIME: LD/CY:
AD 84-21-01 11/14/1984	R1 ONE TIME	TO PREVENT ELECTRICAL FAILURES IN THE "ZL" PANEL	BRITISH AEROSPACE COMPLIED WITH AT MANUFACTURE	DATE: 1/15/1985 LD/CY:	DATE: TIME: LD/CY:
AD 86-21-05 RH 10/20/1986	ONE TIME	TO PREVENT THE FAILURE OF THE FORWARD ENGINE MOUNTS ON A/C EQUIPPED WITH TFE 731-3R-1H	BRITISH AEROSPACE C/W SB 71-038 R1	DATE: 10/20/1985 TIME: LD/CY:	DATE: TIME: LD/CY:
AD 86-21-05 LH 10/20/1986	ONE TIME	TO PREVENT THE FAILURE OF THE FORWARD ENGINE MOUNTS ON A/C EQUIPPED WITH TFE 731-3R-1H	BRITISH AEROSPACE C/W SB 71-038 R1	DATE: 10/20/1985 TIME: LD/CY:	DATE: TIME: LD/CY:
AD 87-04-14 3/09/1987	ONE TIME	APU FUEL LEAKAGE IN REAR COMPARTMENT & ELECTRICAL BONDING OF STARTER/GENERATOR	BRITISH AEROSPACE SB 49-31-9286A & SB 49-32-9210A	DATE: 3/21/2002 TIME: LD/CY:	DATE: TIME: LD/CY:
AD 88-05-02 B 4/06/1988	ONE TIME	TO DETECT FATIGUE CRACKING IN AIRCRAFT STRUCTURE WHICH COULD RESULT IN THE INABILITY OF THE STRUCTURE TO MEET LOADS	BRITISH AEROSPACE N/A BY AIRCRAFT MODEL	DATE: 6/10/2016 TIME: 10352.0 LD/CY:	DATE: TIME: LD/CY:
AD 88-07-03 4/25/1988	ONE TIME	TO PREVENT DISPLACEMENT OF THE AILERON MASS BALANCE SIDE PLATE, & POSSIBLE CONTROL SURFACE INTERFERENCE	BRITISH AEROSPACE C/W 25WG/R143	DATE: 9/15/2014 TIME: 10286.8 LD/CY: 9097	DATE: TIME: LD/CY:
AD 89-17-06 9/15/1989	ONE TIME	TO PREVENT AN ELECTRICAL FIRE CAUSED BY GROUNDING OF CERTAIN ELECTRICAL CONTRACTORS	BRITISH AEROSPACE C/W SB 24-268/MOD 3223 A&B	DATE: 4/08/1989 TIME: LD/CY:	DATE: TIME: LD/CY:
AD 89-18-07 12/18/1998	ONE TIME	INSPECTION OF ELEVATOR MASS BALANCE WEIGHT SIDE PLATE ASSEMBLY AND BALANCE WEIGHT SPIGOT FOR CORROSION.	BRITISH AEROSPACE C/W SB 27-142 REV 2	DATE: 12/05/2000 TIME: LD/CY:	DATE: TIME: LD/CY:
AD 89-18-13 9/28/1989	ONE TIME	PLACARD TO PROHIBIT USE OF SUNDSTRAND TURBOMACH TITAN APU DURING FLIGHT	BRITISH AEROSPACE COMPLIED WITH	DATE: 12/05/2000 TIME: LD/CY:	DATE: TIME: LD/CY:
AD 90-08-07 4/10/1990	ONE TIME	LOSS OF AILERON CONTROL. AIRCRAFT EQUIPPED WITH CABIN INTERIOR & AFT LAVATORY WATER SYSTEM PER STC SA2271SW	BRITISH AEROSPACE N/A BY AIRCRAFT SERIAL NUMBER	DATE: 3/21/2002 TIME: LD/CY:	DATE: TIME: LD/CY:
AD 90-17-11 9/17/1990	ONE TIME	TO ENSURE CREWMEMBERS PULL THE CORRECT CB TO ELECTRICAL/ELECTRONIC EQUIPMENT - INSTALL CB ID LABELS IN PANEL DA-A.	BRITISH AEROSPACE C/W SB 24-263-9486A REV 1	DATE: 3/08/1988 TIME: LD/CY:	DATE: TIME: LD/CY:
AD 91-03-06 2/11/1991	ONE TIME	TO PREVENT OVERHEATING OF THE BATTERY VISUAL INSPECTION OF THE GENERATOR CONTROL UNIT EARTH WIRE	BRITISH AEROSPACE CW SB24-A278	DATE: 8/10/1990 TIME: LD/CY:	DATE: TIME: LD/CY:
AD 91-03-18 3/11/1991	ONE TIME	TO PREVENT A WARMING OVEN FIRE ON APC WARMING OVENS P/N 255B-LH-28/115 OR 255B-RH-28/115 OR 255-362	BRITISH AEROSPACE N/A EQUIPMENT NOT INSTALLED	DATE: 3/26/2002 TIME: LD/CY:	DATE: TIME: LD/CY:

AIRFRAME AIRWORTHINESS DIRECTIVE
HS-125 257208

4/25/2024
N2787

DIRECTIVE NUMBER	REVISION	DESCRIPTION	VENDER	COMPLIANCE	NEXT DUE
LOCATION	RECURRS		METHOD		
EFFECTIVE DATE					
AD 91-07-12		REPLACEMENT OF MAIN LANDING GEAR DOOR HINGES	BRITISH AEROSPACE	DATE: 12/05/2000	DATE:
4/29/1991	ONE TIME	SUPERSEDES AD 90-23-01	C/W SB 32-220, MOD 3176B	TIME: 8188.7	TIME:
				LD/CY: 6944	LD/CY:
AD 91-14-12		INSTALLATION OF A PARTIAL COVER ABOVE THE STANDBY INVERTER "TZ" LOCATED BETWEEN FRAMES 22 & 23 LH	BRITISH AEROSPACE	DATE: 8/08/1991	DATE:
8/06/1991	ONE TIME		COMPLIED WITH	TIME: 3805.0	TIME:
				LD/CY:	LD/CY:
AD 91-19-05		PREVENT LOSS OF FIRE EXTINGUISHMENT CAPABILITY	BRITISH AEROSPACE	DATE: 3/31/1991	DATE:
9/26/1991	ONE TIME		C/W SB 26-31	TIME:	TIME:
				LD/CY:	LD/CY:
AD 92-01-09		PREVENT AN IN-FLIGHT FIRE HAZARD IN THE REAR EQUIPMENT BAY	BRITISH AEROSPACE	DATE: 9/20/1991	DATE:
1/24/1992	ONE TIME		C/W SB 28-086	TIME:	TIME:
				LD/CY:	LD/CY:
AD 92-06-05	R1	PREVENT REDUCED STRUCTURAL INTEGRITY OF THE FUSELAGE & SUBSEQUENT DECOMPRESSION OF THE AIRCRAFT	BRITISH AEROSPACE	DATE: 10/27/1991	DATE:
4/21/1992	ONE TIME		C/W SB 53-73	TIME:	TIME:
				LD/CY:	LD/CY:
AD 92-16-12	R1	PREVENT FIRE IN THE TAIL CONE AIRCRAFT POST MOD 5640/2906; PRE MOD 3193B; PRE MOD 5640	BRITISH AEROSPACE	DATE: 8/09/1992	DATE:
9/28/1992	ONE TIME		COMPLIED WITH	TIME:	TIME:
				LD/CY:	LD/CY:
AD 92-17-12		PREVENT ELECTRICAL ARCING & A RESULTANT FIRE	BRITISH AEROSPACE	DATE: 8/09/1992	DATE:
9/28/1992	ONE TIME		C/W SB 33-45-25A027A&B	TIME:	TIME:
				LD/CY:	LD/CY:
AD 92-25-11		PREVENT RUPTURE OF THE HYDRAULIC ACCUMULATOR	BRITISH AEROSPACE	DATE: 11/22/1992	DATE:
1/12/1993	ONE TIME		C/W SB 29-089, MOD 3269A	TIME:	TIME:
				LD/CY:	LD/CY:
AD 92-27-09		TO ENSURE CONTINUED STRUCTURAL INTEGRITY OF THE MAIN LANDING GEAR SIDESTAY UPPER ARM ASSEMBLY	BRITISH AEROSPACE	DATE: 6/22/2016	DATE:
1/27/1993	ONE TIME		COMPLIED WITH	TIME: 10352.0	TIME:
				LD/CY: 9135	LD/CY:
AD 93-01-10		PREVENT BATTERY OVERHEATING AND/OR DAMAGE OF THE VOLTAGE SENSITIVE AVIONICS EQUIPMENT	BRITISH AEROSPACE	DATE: 5/09/1992	DATE:
3/02/1993	ONE TIME		C/W SB 24-289, MOD 3267	TIME:	TIME:
				LD/CY:	LD/CY:
AD 93-02-10		INSPECTION OF BATTERY CABLES FOR CHAFING SUPERSEDES AD 87-12-08	BRITISH AEROSPACE	DATE: 7/01/2016	DATE:
3/26/1993	ONE TIME		N/A BY AIRCRAFT SERIAL NUMBER	TIME:	TIME:
				LD/CY: 9136	LD/CY:
AD 93-02-11		PREVENT REDUCED STRUCTURAL INTEGRITY OF THE WINGS	BRITISH AEROSPACE	DATE: 6/07/1993	DATE:
3/26/1993	ONE TIME		C/W SB 57-073	TIME: 5029.0	TIME:
				LD/CY: 4450	LD/CY:
AD 93-04-02		PREVENT A MID AIR COLLISION OR NEAR MISS SITUATION CAUSED BY FAILURE OF MODE S TRANSPONDERS P/N CPN 622-9210-002	ROCKWELL	DATE: 3/28/2002	DATE:
3/26/1993	ONE TIME		NOT APPLICABLE	TIME:	TIME:
				LD/CY:	LD/CY:
AD 93-23-08		PREVENT OVERHEATING OF THE BATTERY CONTACTORS & EMERG CONTACTORS	CORPORATE JETS	DATE: 6/07/1993	DATE:
12/29/1993	ONE TIME		C/W SB 24-293, MOD 3501	TIME: 5029.0	TIME:
				LD/CY: 4450	LD/CY:

AIRFRAME AIRWORTHINESS DIRECTIVE
HS-125 257208

4/25/2024
N2787

DIRECTIVE NUMBER	REVISION	DESCRIPTION	VENDER	COMPLIANCE	NEXT DUE
LOCATION	RECURRS		METHOD		
EFFECTIVE DATE					
AD 93-24-07		PREVENT FAILURE OF THE SEALANT AROUND THE OVER TEMP SENSOR IN THE FUEL CONTROL ENCLOSURE BOX OF APU	CORPORATE JETS	DATE: 6/10/2016 TIME: 10352.0	DATE: TIME:
12/23/1993	ONE TIME		N/A EQUIPMENT NOT INSTALLED		LD/CY:
AD 93-24-08		PREVENT FAILURE OF THE ENGINE FIRE EXTINGUISHER SYSTEMS	CORPORATE JETS	DATE: 1/21/2003 TIME: 10352.0	DATE: TIME:
1/18/1994	ONE TIME		FOUND P/C/W		LD/CY:
AD 94-01-04		PREVENT COLLISIONS CAUSED BY INCOMPATIBILITY BETWEEN TCAS II & TRAFFIC CONTROL; P/N 4066010-901,-902,-903	HONEYWELL	DATE: 3/28/2002 TIME:	DATE: TIME:
2/04/1994	ONE TIME		NOT APPLICABLE		LD/CY:
AD 94-01-05		PREVENT COLLISIONS CAUSED BY INCOMPATIBILITY BETWEEN TCAS II & TRAFFIC CONTROL	ALLIED SIGNAL	DATE: 3/28/2002 TIME:	DATE: TIME:
2/04/1994	ONE TIME		NOT APPLICABLE		LD/CY:
AD 94-01-06		PREVENT COLLISIONS CAUSED BY INCOMPATIBILITY BETWEEN TCAS II & TRAFFIC CONTROL	ROCKWELL	DATE: 3/28/2002 TIME:	DATE: TIME:
2/04/1994	ONE TIME		NOT APPLICABLE		LD/CY:
AD 94-11-03		PREVENT SMOKE OR FIRE IN THE CABIN WHILE THE ACFT IS IN FLIGHT; CLEARANCE BETWEEN SUPERSEDED BY AD 2006-01-04	RAYTHEON	DATE: 6/10/2016 TIME: 10352.0	DATE: TIME:
5/18/1994	ONE TIME		COMPLIED WITH		LD/CY:
AD 94-19-06		PREVENT FLIGHT CREW FROM EXPERIENCING DIFFICULTY IN EXHALING INTO CREW OXYGEN MASKS	PURITAN BENNETT	DATE: 6/30/2016 TIME:	DATE: TIME:
9/14/1994	ONE TIME		N/A EQUIPMENT NOT INSTALLED		LD/CY:
AD 94-21-06		PREVENT THE INABILITY OF PASSENGERS OR CREW TO EGRESS FROM THEIR SEATS DURING EMERGENCY SITUATION	PACIFIC SCIENTIFIC	DATE: 3/28/2002 TIME:	DATE: TIME:
11/25/1994	ONE TIME		NOT APPLICABLE		LD/CY:
AD 94-24-06		PREVENT SMOKE OR FIRE IN THE FLIGHT DECK DUE TO SHORT CIRCUITING OF THE FLIGHT DECK LIGHTING TRANSFORMERS 6V OUTPUT	RAYTHEON	DATE: 11/30/2006 TIME:	DATE: TIME:
1/04/1995	ONE TIME		SB 24-310, MOD 3544A&B		LD/CY:
AD 95-08-06		TO PREVENT AN ELECTRICAL SHORT IN THE STANDBY STATIC INVERTER DUE TO THE PCB BEING EXPOSED TO MOISTURE	RAYTHEON	DATE: 11/30/1994 TIME:	DATE: TIME:
5/18/1995	ONE TIME		SB 24-308, MOD 7673A		LD/CY:
AD 95-22-01		TO PREVENT SMOKE, FIRE, ELECTRICAL SHOCK & POSSIBLE ELECTROMAGNETIC INTERFERENCE SUPERSEDES AD 90-14-06	AEROSPACE LIGHTING	DATE: 3/03/1996 TIME: 6070.0	DATE: TIME:
12/04/1995	ONE TIME		N/A EQUIPMENT NOT INSTALLED		LD/CY:
AD 97-03-07 (a) RH		INSPECT OF MLG SIDESTAYS POST MOD 2091 (STEEL JACK PIVOTS) FOR CRACKS USING 10X MAGNIFIER; SUPERSEDES AD 94-26-12	RAYTHEON	DATE: 11/30/1994 TIME:	DATE: TIME:
3/11/1997	ONE TIME		COMPLIED WITH		LD/CY:
AD 97-03-07 (a) LH		INSPECT OF MLG SIDESTAYS POST MOD 2091 (STEEL JACK PIVOTS) FOR CRACKS USING 10X MAGNIFIER; SUPERSEDES AD 94-26-12	RAYTHEON	DATE: 11/30/1994 TIME:	DATE: TIME:
3/11/1997	ONE TIME		COMPLIED WITH		LD/CY:
AD 97-05-03		TO PREVENT DEVIATION OF THE INTENDED FLIGHT PATH DURING A NON-PRECISION APPROACHES	ALLIED SIGNAL	DATE: 3/28/2002 TIME:	DATE: TIME:
4/20/1999	ONE TIME		NOT APPLICABLE		LD/CY:

AIRFRAME AIRWORTHINESS DIRECTIVE
HS-125 257208

4/25/2024
N2787

DIRECTIVE NUMBER	REVISION	DESCRIPTION	VENDER	COMPLIANCE	NEXT DUE
LOCATION	RECURRS		METHOD		
EFFECTIVE DATE					
AD 97-11-10		TO PREVENT RESTRICTED OXYGEN FLOW	PURITAN BENNETT	DATE: 3/28/2002	DATE:
		MASKS P/N 174290-14, 174290-24		TIME:	TIME:
6/23/1997	ONE TIME	174290-34,174290-44,174290-54	NOT APPLICABLE	LD/CY:	LD/CY:
AD 97-18-03		PREVENT FAILURE OF THE ULTRASONIC WELD	PURITAN BENNETT	DATE: 3/28/2002	DATE:
		ON THE CONE & SEAL ASSY OF OXYGEN MASK		TIME:	TIME:
9/22/1997	ONE TIME	P/N 210543 & 210543-01	NOT APPLICABLE	LD/CY:	LD/CY:
AD 97-21-05		TO PREVENT LEAKS IN HIGH PRESSURE OXYGEN	RAYTHEON AIRCRAFT	DATE: 12/26/1996	DATE:
		HOSE ASSY		TIME:	TIME:
11/24/1997	ONE TIME		SB 35-046	LD/CY:	LD/CY:
AD 98-25-02		TO PREVENT THE DISPLAY OF TARGET	BFGOODRICH AVIONICS	DATE: 3/28/2002	DATE:
		INDICATORS ON THE WRONG SIDE OF THE		TIME:	TIME:
12/22/1998	ONE TIME	AIRCRAFT	NOT APPLICABLE	LD/CY:	LD/CY:
AD 99-08-21		TO PREVENT REDUCED OXYGEN CONSUMPTION	PURITAN BENNETT	DATE: 5/13/1999	DATE:
		WHEN PASSENGERS ARE REQUIRED TO USE		TIME:	TIME:
6/02/1999	ONE TIME	DEFECTIVE MASKS	NOT APPLICABLE	LD/CY:	LD/CY:

**LH ENGINE AIRWORTHINESS DIRECTIVE
GARRETT P84484**

**4/25/2024
N2787**

DIRECTIVE NUMBER	REVISION	DESCRIPTION	VENDER	COMPLIANCE	NEXT DUE
LOCATION	RECURRS		METHOD		
EFFECTIVE DATE					
AD 2000-15-09 LH 10/10/2000	RECURRS	TO PREVENT FAILURE OF THE HPC IMPELLER P/N 3073393-1,3073394-1,3073433-1, 3073434-1,3073398-ALL,3073435-ALL	GARRETT SB A72-3641 R1	DATE: 12/14/2000 TIME: 7400.2 LD/CY: 6414	DATE: TIME: 11600.2 LD/CY:
AD 2001-23-09 LH 12/21/2001	ONE TIME	TO PREVENT FAILURE OF THE FAN ROTOR DISK DUE TO FATIGUE CRACKING; SUPERSEDS AD 86-11-05 & AD 96-18-13	GARRETT N/A BY PART NUMBER INSTALLED	DATE: 5/15/2013 TIME: 9460.6 LD/CY: 8519	DATE: TIME: LD/CY:
AD 2005-05-15 LH 4/18/2005	ONE TIME	INSPECTION OR REPLACEMENT OF DEFECTIVE LOW PRESSURE TURBINE (LPT) STAGE 1 DISKS	GARRETT N/A P/N 3075830-1 INSTALLED	DATE: 8/02/2007 TIME: 8770.1 LD/CY: 7748	DATE: TIME: LD/CY:
AD 2005-13-07 LH 7/27/2005	ONE TIME	REMOVAL FROM SERVICE OF LP 1ST & 2ND STAGE TURBINE ROTOR DISCS	GARRETT NOT APPLICABLE	DATE: 5/15/2013 TIME: 9460.6 LD/CY: 8519	DATE: TIME: LD/CY:
AD 2010-06-11 LH 4/21/2010	ONE TIME	TO PREVENT UNCONTAINED FAILURE OF THE 2ND & 3RD LPCR DISCS, 3072396-1 OR 3075190-1 OR 3072397-1 OR 3075192-1	GARRETT N/A BY PART S/N INSTALLED	DATE: 5/15/2013 TIME: 9460.6 LD/CY: 8519	DATE: TIME: LD/CY:
AD 75-07-10 LH 5/01/1975	ONE TIME	TO DETECT, PREVENT & CORRECT WEAR OF THE TRANSFER GEARBOX VERTICAL BEVEL GEAR BEARING SUPPORT	GARRETT N/A PER SB 72-3019	DATE: 5/15/2013 TIME: 9460.6 LD/CY: 8519	DATE: TIME: LD/CY:
AD 78-22-10 LH 11/13/1978	ONE TIME	TO PREVENT FAILURE OF THE LOW PRESSURE ROTOR THRUST BALL BEARING WHICH COULD RESULT IN AN IMMEDIATE INFLITE SHUTDOWN	GARRETT N/A PER SB	DATE: 5/15/2013 TIME: 9460.6 LD/CY: 8519	DATE: TIME: LD/CY:
AD 80-16-04 LH 8/07/1980	ONE TIME	TO PREVENT SEPARATION OF TIE ROD AND POTENTIAL MASSIVE ENGINE FAILURE P/N 3070065-1	GARRETT N/A PER SB	DATE: 5/15/2013 TIME: 9460.6 LD/CY: 8519	DATE: TIME: LD/CY:
AD 81-24-08 e(1) LH 1/06/1982	ONE TIME	TO PREVENT SEPARATION OF THE ENGINE REAR MOUNT FROM THE DUCT	GARRETT N/A PER SB	DATE: 5/15/2013 TIME: 9460.6 LD/CY: 8519	DATE: TIME: LD/CY:
AD 82-23-03 B LH 12/09/1983	R1 ONE TIME	TO PREVENT CRACKING AND POSSIBLE FAILURE OF FAN DISC PART NUMBER 3072162	GARRETT N/A PER SB	DATE: 5/15/2013 TIME: 9460.6 LD/CY: 8519	DATE: TIME: LD/CY:
AD 86-03-01 LH 2/24/1986	ONE TIME	INTERSTAGE TRANSITION DUCTS - INSPECTION TO PREVENT SEPARATION OF ENGINE REAR MOUNT FROM THE DUCT	GARRETT N/A PER SB	DATE: 5/15/2013 TIME: 9460.6 LD/CY: 8519	DATE: TIME: LD/CY:
AD 88-18-03 LH 8/30/1988	ONE TIME	TO PREVENT UNCONTAINED ENGINE FAILURES APPLIES TO HP TURBINE ROTOR DISC P/N 3072316-2, -3 OR 3073110-1, -2	GARRETT N/A PER SB	DATE: 5/15/2013 TIME: 9460.6 LD/CY: 8519	DATE: TIME: LD/CY:
AD 90-24-06 LH 11/13/1990	ONE TIME	INSPECTION TO DETECT DEFECTIVE THERMOCOUPLE LEAD ASSY P/N 3073950-1,-2, -7,-15, 3074175-1,RWK 3077031-1,-2	GARRETT N/A PER SB	DATE: 5/15/2013 TIME: 9460.6 LD/CY: 8519	DATE: TIME: LD/CY:
AD 92-21-06 LH 11/27/1992	ONE TIME	TO PREVENT AN UNCONTAINED ENGINE FAILURE P/N 3072068-X, 3072544-X,3073015-X, OR 3073115-X LP TURBINE ROTOR DISKS	GARRETT N/A PER SB	DATE: 5/15/2013 TIME: 9460.6 LD/CY: 8519	DATE: TIME: LD/CY:

**LH ENGINE AIRWORTHINESS DIRECTIVE
GARRETT P84484**

**4/25/2024
N2787**

DIRECTIVE NUMBER	REVISION	DESCRIPTION	VENDER	COMPLIANCE	NEXT DUE
LOCATION	RECURRS		METHOD		
EFFECTIVE DATE					
AD 94-07-03		PREVENT UNCONTAINED FAILURE OF THE FIRST STAGE LP TURBINE DISK; LP TURBINE NOZZLE P/N 3072842-1 OR 3072319-1 THRU -8	GARRETT	DATE: 5/15/2013	DATE:
LH	ONE TIME		FOUND P/C/W	TIME: 9460.6	TIME:
6/06/1994				LD/CY: 8519	LD/CY:
AD 95-07-02		TO PREVENT A LOW PRESSURE TURBINE DISK WEB SEPARATION	GARRETT	DATE: 5/15/2013	DATE:
LH	ONE TIME		FOUND P/C/W	TIME: 9460.6	TIME:
6/19/1995				LD/CY: 8519	LD/CY:
AD 96-04-01		UNCONTAIN FAN DISK FAILURE P/N 3072162,3073436,3073539,3074529 SUPERSEDES AD 93-25-16,AD 92-26-09	GARRETT	DATE: 5/15/2013	DATE:
LH	ONE TIME		N/A BY PART NUMBER INSTALLED	TIME: 9460.6	TIME:
3/15/1996				LD/CY: 8519	LD/CY:
AD 96-05-03		EDDY-CURRENT INSPECTION OF FAN ROTOR DISC P/N 3072162-1 THRU -4, 3073436-1 THRU -4;SUPERSEDES AD 91-08-13	GARRETT	DATE: 5/15/2013	DATE:
LH	ONE TIME		N/A BY PART NUMBER INSTALLED	TIME: 9460.6	TIME:
4/02/1996				LD/CY: 8519	LD/CY:
AD 98-17-01		TO PREVENT CRACKED FUEL TUBES SUPERSEDES AD 93-10-10	GARRETT	DATE: 5/15/2013	DATE:
LH	ONE TIME		NOT APPLICABLE	TIME: 9460.6	TIME:
11/29/1999				LD/CY: 8519	LD/CY:

**RH ENGINE AIRWORTHINESS DIRECTIVE
GARRETT P84497**

**4/25/2024
N2787**

DIRECTIVE NUMBER	REVISION	DESCRIPTION	VENDER	COMPLIANCE	NEXT DUE
LOCATION	RECURRS		METHOD		
EFFECTIVE DATE					
AD 2000-15-09		TO PREVENT FAILURE OF THE HPC IMPELLER	GARRETT	DATE: 1/11/2000	DATE:
RH		P/N 3073393-1,3073394-1,3073433-1,		TIME: 7164.6	TIME: 11364.6
10/10/2000	RECURRS	3073434-1,3073398-ALL,3073435-ALL	SB A72-3641 R1	LD/CY: 6190	LD/CY:
AD 2001-23-09		TO PREVENT FAILURE OF THE FAN ROTOR DISK	GARRETT	DATE: 6/04/2013	DATE:
RH		DUE TO FATIGUE CRACKING;		TIME: 9607.1	TIME:
12/21/2001	ONE TIME	SUPERSEDS AD 86-11-05 & AD 96-18-13	N/A BY PART NUMBER INSTALLED	LD/CY: 8517	LD/CY:
AD 2005-05-15		INSPECTION OR REPLACEMENT OF DEFECTIVE	GARRETT	DATE: 2/08/2005	DATE:
RH		LOW PRESSURE TURBINE (LPT) STAGE 1 DISKS		TIME: 8462.3	TIME:
4/18/2005	ONE TIME		N/A 3075830-1 INSTALLED	LD/CY: 7264	LD/CY:
AD 2005-13-07		REMOVAL FROM SERVICE OF LP 1ST & 2ND	GARRETT	DATE: 6/04/2013	DATE:
RH		STAGE TURBINE ROTOR DISCS		TIME: 9607.1	TIME:
7/27/2005	ONE TIME		N/A PER SB SB 72-3682	LD/CY: 8517	LD/CY:
AD 2010-06-11		TO PREVENT UNCONTAINED FAILURE OF THE	GARRETT	DATE: 6/04/2013	DATE:
RH		2ND & 3RD LPCR DISCS, 3072396-1 OR		TIME: 9607.1	TIME:
4/21/2010	ONE TIME	3075190-1 OR 3072397-1 OR 3075192-1	N/A BY PART NUMBER INSTALLED	LD/CY: 8517	LD/CY:
AD 2017-20-01		REPLACEMENT OF FAN DISK P/N 3060287-2	GARRETT	DATE: 9/27/1996	DATE:
RH		WITH S/N LISTED IN TABLE 9 OF HONEYWELL		TIME: 5849.9	TIME:
11/02/2017	ONE TIME	SUPERSEDED BY AD 2019-05-07	N/A FAN P/N 3073563-2 INSTALLED	LD/CY: 5179	LD/CY:
AD 75-07-10		TO DETECT, PREVENT & CORRECT WEAR OF THE	GARRETT	DATE: 6/04/2013	DATE:
RH		TRANSFER GEARBOX VERTICAL BEVEL GEAR		TIME: 9607.1	TIME:
5/01/1975	ONE TIME	BEARING SUPPORT	NOT APPLICABLE PER SB 72-3019	LD/CY: 8517	LD/CY:
AD 78-22-10		TO PREVENT FAILURE OF THE LOW PRESSURE	GARRETT	DATE: 6/04/2013	DATE:
RH		ROTOR THRUST BALL BEARING WHICH COULD		TIME: 9607.1	TIME:
11/13/1978	ONE TIME	RESULT IN AN IMMEDIATE INFLITE SHUTDOWN	NOT APPLICABLE PER SB	LD/CY: 8517	LD/CY:
AD 80-16-04		TO PREVENT SEPARATION OF TIE ROD AND	GARRETT	DATE: 6/04/2013	DATE:
RH		POTENTIAL MASSIVE ENGINE FAILURE		TIME: 9607.1	TIME:
8/07/1980	ONE TIME	P/N 3070065-1	NOT APPLICABLE PER SB	LD/CY: 8517	LD/CY:
AD 81-24-08 e(1)		TO PREVENT SEPARATION OF THE ENGINE REAR	GARRETT	DATE: 6/04/2013	DATE:
RH		MOUNT FROM THE DUCT		TIME: 9607.1	TIME:
1/06/1982	ONE TIME		NOT APPLICABLE PER SB	LD/CY: 8517	LD/CY:
AD 82-23-03 B	R1	TO PREVENT CRACKING AND POSSIBLE FAILURE	GARRETT	DATE: 9/27/1996	DATE:
RH		OF FAN DISC PART NUMBER 3072162		TIME: 5849.9	TIME:
12/09/1983	ONE TIME		N/A FAN P/N 3073563-2 INSTALLED	LD/CY: 5179	LD/CY:
AD 86-03-01		INTERSTAGE TRANSITION DUCTS - INSPECTION	GARRETT	DATE: 6/04/2013	DATE:
RH		TO PREVENT SEPARATION OF ENGINE REAR		TIME: 9607.1	TIME:
2/24/1986	ONE TIME	MOUNT FROM THE DUCT	NOT APPLICABLE PER SB	LD/CY: 8517	LD/CY:
AD 86-11-05		FAILURE OF FAN ROTOR DISCS	GARRETT	DATE: 9/27/1996	DATE:
RH		PART NUMBER 3073436 AND 3072162		TIME: 5849.9	TIME:
6/16/1986	ONE TIME	SUPERSEDED BY AD 2001-23-09	N/A FAN P/N 3073563-2 INSTALLED	LD/CY: 5179	LD/CY:
AD 88-18-03		TO PREVENT UNCONTAINED ENGINE FAILURES	GARRETT	DATE: 6/04/2013	DATE:
RH		APPLIES TO HP TURBINE ROTOR DISC P/N		TIME: 9607.1	TIME:
8/30/1988	ONE TIME	3072316-2, -3 OR 3073110-1, -2	NOT APPLICABLE PER SB	LD/CY: 8517	LD/CY:

**RH ENGINE AIRWORTHINESS DIRECTIVE
GARRETT P84497**

**4/25/2024
N2787**

DIRECTIVE NUMBER	REVISION	DESCRIPTION	VENDER	COMPLIANCE	NEXT DUE
LOCATION	RECURRS		METHOD		
EFFECTIVE DATE					
AD 90-03-04		REMOVAL AND REPLACEMENT OF HIGH PRESSURE TURBINE ROTOR DISCS P/N 3072316-2 ,-3 AND 3073110-1 ,-2	GARRETT	DATE: 2/08/2005	DATE:
RH			NOT APPLICABLE PER SB	TIME: 8462.3	TIME:
2/22/1990	ONE TIME			LD/CY: 7264	LD/CY:
AD 90-24-06		INSPECTION TO DETECT DEFECTIVE THERMOCOUPLE LEAD ASSY P/N 3073950-1,-2, -7,-15, 3074175-1,RWK 3077031-1,-2	GARRETT	DATE: 6/04/2013	DATE:
RH			NOT APPLICABLE PER SB	TIME: 9607.1	TIME:
11/13/1990	ONE TIME			LD/CY: 8517	LD/CY:
AD 91-08-13		FLUORESCENT PENETRANT INSPECTION OF THE FAN ROTOR DISC P/N 3072162, 3073436 SUPERSEDED BY AD 96-05-03	GARRETT	DATE: 9/27/1996	DATE:
RH			N/A FAN P/N 3073563-2 INSTALLED	TIME: 5849.9	TIME:
8/16/1993	ONE TIME			LD/CY: 5179	LD/CY:
AD 92-21-06		TO PREVENT AN UNCONTAINED ENGINE FAILURE P/N 3072068-X, 3072544-X,3073015-X, OR 3073115-X LP TURBINE ROTOR DISKS	GARRETT	DATE: 6/04/2013	DATE:
RH			NOT APPLICABLE PER SB	TIME: 9607.1	TIME:
11/27/1992	ONE TIME			LD/CY: 8517	LD/CY:
AD 93-25-16 (B)		UNCONTAIN FAN DISK FAILURE P/N 3073539-2 OR 3072162-2 SUPERSEDED BY AD 96-04-01	GARRETT	DATE: 9/27/1996	DATE:
RH			N/A FAN P/N 3073563-2 INSTALLED	TIME: 5849.9	TIME:
1/18/1994	ONE TIME			LD/CY: 5179	LD/CY:
AD 93-25-16 (C)		UNCONTAIN FAN DISK FAILURE P/N 3072162,3073436,3073539,3074529 SUPERSEDED BY AD 96-04-01	GARRETT	DATE: 9/27/1996	DATE:
RH			N/A FAN P/N 3073563-2 INSTALLED	TIME: 5849.9	TIME:
1/18/1994	ONE TIME			LD/CY: 5179	LD/CY:
AD 94-07-03		PREVENT UNCONTAINED FAILURE OF THE FIRST STAGE LP TURBINE DISK; LP TURBINE NOZZLE P/N 3072842-1 OR 3072319-1 THRU -8	GARRETT	DATE: 6/04/2013	DATE:
RH			NOT APPLICABLE PER SB 72-3502	TIME: 9607.1	TIME:
6/06/1994	ONE TIME			LD/CY: 8517	LD/CY:
AD 95-07-02		TO PREVENT A LOW PRESSURE TURBINE DISK WEB SEPARATION	GARRETT	DATE: 6/04/2013	DATE:
RH			NOT APPLICABLE PER SB	TIME: 9607.1	TIME:
6/19/1995	ONE TIME			LD/CY: 8517	LD/CY:
AD 96-04-01		UNCONTAIN FAN DISK FAILURE P/N 3072162,3073436,3073539,3074529 SUPERSEDES AD 93-25-16,AD 92-26-09	GARRETT	DATE: 9/27/1996	DATE:
RH			N/A FAN P/N 3073563-2 INSTALLED	TIME: 5849.9	TIME:
3/15/1996	ONE TIME			LD/CY: 5179	LD/CY:
AD 96-05-03		EDDY-CURRENT INSPECTION OF FAN ROTOR DISC P/N 3072162-1 THRU -4, 3073436-1 THRU -4;SUPERSEDES AD 91-08-13	GARRETT	DATE: 9/27/1996	DATE:
RH			N/A FAN P/N 3073563-2 INSTALLED	TIME: 5849.9	TIME:
4/02/1996	ONE TIME			LD/CY: 5179	LD/CY:
AD 96-18-13		TO PREVENT FAILURE OF THE FAN ROTOR DISK DUE TO FATIGUE CRACKING; SUPERSEDED BY AD 2001-23-09	GARRETT	DATE: 9/27/1996	DATE:
RH			N/A FAN P/N 3073563-2 INSTALLED	TIME: 5849.9	TIME:
11/12/1996	ONE TIME			LD/CY: 5179	LD/CY:
AD 98-17-01	R1	TO PREVENT CRACKED FUEL TUBES SUPERSEDES AD 93-10-10	GARRETT	DATE: 6/04/2013	DATE:
RH			NOT APPLICABLE PER SB	TIME: 9607.1	TIME:
11/29/1999	ONE TIME			LD/CY: 8517	LD/CY:

AIRFRAME & APPLIANCE SB REPORT

HS-125 257208

4/25/2024
N2787

DIRECTIVE NUMBER	REVISION	DESCRIPTION	VENDER	COMPLIANCE	NEXT DUE
LOCATION	RECURRS		METHOD		
EFFECTIVE DATE					
MOD 3176A		MAIN GEAR - INTRODUCTION OF STEEL WING ATTACHMENT CASTING FOR LEFT & RIGHT MAIN GEAR DOOR JACK	BRITISH AEROSPACE	DATE: 12/05/2000	DATE:
9/02/1988	ONE TIME		SB 32-220	TIME: 8188.7	TIME:
				LD/CY: 6944	LD/CY:
SB 21-3669		AIR CONDITIONING-FAN VENTURI MOTOR REPLACEMENT	RAYTHEON AIRCRAFT Mandatory	DATE: 7/01/2006	DATE:
12/01/2004	ONE TIME		N/A BY PART NUMBER INSTALLED	TIME:	TIME:
				LD/CY:	LD/CY:
SB 24-261A	R1	ELECTRICAL POWER-CABLE INSTALLATION-CHAFING OF WIRE AT PANEL ZL	BRITISH AEROSPACE Mandatory	DATE: 7/01/2016	DATE:
8/17/1987	ONE TIME		C/W	TIME: 9136.0	TIME:
				LD/CY: 9136	LD/CY:
SB 24-3793		ELECTRICAL POWER - INSPECTION AND REPLACEMENT OF UAM100 LIMITERS	RAYTHEON AIRCRAFT Mandatory	DATE: 5/23/2006	DATE:
5/01/2006	ONE TIME		NOT APPLICABLE	TIME: 9387.9	TIME:
				LD/CY: 8078	LD/CY:
SB 24-3850	R1	CIRCUIT PROTECTION FOR COCKPIT FAN BLOWERS	RAYTHEON AIRCRAFT Mandatory	DATE: 6/16/2016	DATE:
11/01/2008	ONE TIME		N/A BY PART S/N INSTALLED	TIME: 10361.0	TIME:
				LD/CY: 9139	LD/CY:
SB 26-3496		INTRODUCTION OF ELECTRICAL WIRE PROTECTION KIT	BRITISH AEROSPACE Mandatory	DATE: 6/28/2005	DATE:
11/01/2003	ONE TIME		COMPLIED WITH	TIME: 9136.0	TIME:
				LD/CY: 9136	LD/CY:
SB 26-4013		HALON 1211 PORTABLE FIRE EXTINGUISHER INSPECTION/ REPLENISHMENT/REPLACEMENT	BRITISH AEROSPACE Mandatory	DATE: 6/10/2016	DATE:
1/01/2010	ONE TIME		FOUND P/C/W	TIME: 10352.0	TIME:
				LD/CY:	LD/CY:
SB 27-142	R3	ELEVATOR MASS BALANCE-POSSIBLE CORROSION OF BALANCE WEIGHT SIDE-PLATE ASSEMBLY AND SPIGOT	BRITISH AEROSPACE Mandatory	DATE: 12/05/2000	DATE:
11/13/1989	ONE TIME		COMPLIED WITH	TIME:	TIME:
				LD/CY:	LD/CY:
SB 32-167		DUNLOP EMERGENCY BRAKE REDUCING VALVE - FAILURE OF KNIFE EDGES	BRITISH AEROSPACE Mandatory	DATE: 8/29/2008	DATE:
1/27/1976	RECURRS		C/W	TIME: 9680.0	TIME:
				LD/CY: 8411	LD/CY: 12911
SB 32-184		NOSE LEG DRAG STAY ASSY - INSPECTION OF NOSE BRIDGE CASTING FOR CRACKS	BRITISH AEROSPACE Mandatory	DATE: 8/20/2021	DATE: 8/20/2023
2/18/1992	RECURRS		C/W	TIME: 10559.0	TIME:
				LD/CY: 9221	LD/CY: 10121
SB 32-220		MAIN GEAR - INTRODUCTION OF STEEL WING ATTACHMENT CASTING FOR LEFT & RIGHT MAIN GEAR DOOR JACK	BRITISH AEROSPACE	DATE: 12/05/2000	DATE:
9/02/1988	ONE TIME		MOD 3176A	TIME: 8188.7	TIME:
				LD/CY: 6944	LD/CY:
SB 32-3391		LANDING GEAR-MAIN LANDING GEAR (MLG) ACTUATOR CYLINDER HEAD INSPECTION	BRITISH AEROSPACE Mandatory	DATE: 11/30/2004	DATE:
8/01/2000	ONE TIME		COMPLIED WITH	TIME:	TIME:
				LD/CY:	LD/CY:
SB 32-3522		DUNLOP WHEEL TIE-BOLT NUTS INSPECTION / REPLACEMENT	BRITISH AEROSPACE Mandatory	DATE: 7/01/2016	DATE:
9/01/2002	ONE TIME		N/A BY AIRCRAFT MODEL	TIME: 9136.0	TIME:
				LD/CY: 9136	LD/CY:
SB 32-3604	R2	NOSE STEERING JACK RIVET INSPECTION	BRITISH AEROSPACE Recommended	DATE: 7/31/1997	DATE:
8/01/2003	ONE TIME		COMPLIED WITH	TIME: 5958.7	TIME:
				LD/CY: 5388	LD/CY:

AIRFRAME & APPLIANCE SB REPORT
HS-125 257208

4/25/2024
N2787

DIRECTIVE NUMBER	REVISION	DESCRIPTION	VENDER		COMPLIANCE	NEXT DUE
LOCATION	RECURRS		METHOD			
EFFECTIVE DATE						
SB 34-3207		NAVIGATION-INSPECTION OF PITOT/STATIC AND STALL VENT DRAIN VALVES	RAYTHEON AIRCRAFT	Mandatory	DATE: 7/01/2016	DATE:
8/01/1999	ONE TIME		COMPLIED WITH		TIME: 9136.0	TIME:
					LD/CY: 9136	LD/CY:
SB 35-3169		OXYGEN-TO INTRODUCE REPLACEMENT OXYGEN FITTINGS IN LIEU OF FITTINGS INCOMPATIBLE WITH THE OXYGEN SYSTEM	RAYTHEON AIRCRAFT	Mandatory	DATE: 12/10/1998	DATE:
9/01/1998	ONE TIME		COMPLIED WITH		TIME:	TIME:
					LD/CY:	LD/CY:
SB 71-036		POSSIBLE DAMAGE TO NACELLE INLET COWLS	BRITISH AEROSPACE		DATE: 7/10/2016	DATE:
LH			COMPLIED WITH		TIME: 10352.3	TIME: 10502.3
	RECURRS			LD/CY: 9136	LD/CY:	
SB 71-036		POSSIBLE DAMAGE TO NACELLE INLET COWLS	BRITISH AEROSPACE		DATE: 7/10/2016	DATE:
RH			C/W		TIME: 10352.3	TIME: 10502.3
	RECURRS			LD/CY: 9136	LD/CY:	

**LEFT ENGINE SERVICE BULLETINS
GARRETT P84484**

**4/25/2024
N2787**

DIRECTIVE NUMBER	REVISION	DESCRIPTION	VENDER	COMPLIANCE	NEXT DUE	
LOCATION	RECURRS		METHOD			
EFFECTIVE DATE						
SB 72-3001	R56	ENGINE - SERVICE LIFE - SERVICE LIFE LIMITS OF CRITICAL LIFE LIMITED COMPONENTS	GARRETT	Mandatory	DATE: 5/15/2013 TIME: 9460.6 LD/CY: 8519	DATE: TIME: LD/CY:
LH	ONE TIME		COMPLIED WITH			
6/29/2011						
SB 72-3042	R8	REPLACE COMBUSTION LINER P/N 3072448-4 WITH IMPROVED COMBUSTION LINER INACTIVE	GARRETT	Optional	DATE: 5/15/2013 TIME: 9460.6 LD/CY: 8519	DATE: TIME: LD/CY:
LH	ONE TIME		NOT APPLICABLE			
12/12/2001						
SB 72-3078	R1	POWER SECTION - INSTALL NEW BOLTS WITH LOCKWIRE FEATURE THAT ATTACH TRANSFER TUBES TO INTERMEDIATE CASE ASSEMBLY	GARRETT	Recommended	DATE: 5/15/2013 TIME: 9460.6 LD/CY: 8519	DATE: TIME: LD/CY:
LH	ONE TIME		FOUND P/C/W			
5/30/1986						
SB 72-3085	R11	ENGINE - FAN SPINNER - REPLACE FAN SPINNER & RELATED ANTI-ICE COMPONENTS: REDUCES ODOR & SMOKE IN ACFT CABIN	GARRETT	Recommended	DATE: 5/15/2013 TIME: 9460.6 LD/CY: 8519	DATE: TIME: LD/CY:
LH	ONE TIME		NOT APPLICABLE			
9/10/1985						
SB 72-3086	R3	INTERSTAGE & HP TURBINE ROTOR INSTALL 1ST STG TURBINE NOZZLE ASSY REPLACEMENT OF P/N 3072319-1 W/3072319-4 INACTIVE	GARRETT		DATE: 5/15/2013 TIME: 9460.6 LD/CY: 8519	DATE: TIME: LD/CY:
LH	ONE TIME		NOT APPLICABLE			
12/12/2001						
SB 72-3106	R15	ENGINE - INSPECTION INTERVALS - ESTABLISHING PERIODIC INSPECTION INTERVALS	GARRETT	Mandatory	DATE: 5/15/2013 TIME: 9460.6 LD/CY: 8519	DATE: TIME: LD/CY:
LH	ONE TIME		FOUND P/C/W			
4/30/1991						
SB 72-3111	R3	ENGINE - ACCESSORY DRIVE GEARBOX ASSEMBLY, INSTALL ELASTOMERIC MOUNTS FOR FIELD EVALUATION	GARRETT	Optional	DATE: 5/15/2013 TIME: 9460.6 LD/CY: 8519	DATE: TIME: LD/CY:
LH	ONE TIME		NOT APPLICABLE			
7/06/1979						
SB 72-3113		ENGINE- SUPPORT HOUSING- REPLACE SUPPORT HOUSING: TO PROVIDE TRACEABILITY FOR CHANGES IN THE MANUFACTUR PROCESS	GARRETT	Optional	DATE: 5/15/2013 TIME: 9460.6 LD/CY: 8519	DATE: TIME: LD/CY:
LH	ONE TIME		COMPLIED WITH			
8/29/1979						
SB 72-3124	R8	ACCESSORY DRIVES - MODIFY STARTER/GEN DRIVE SPUR GEARSHAFT:REPLACE OF GEARSHAF SPLINE ADAPTER ELIMINATES SPLINE WEAR	GARRETT	Recommended	DATE: 7/31/1997 TIME: 5958.7 LD/CY: 5388	DATE: TIME: LD/CY:
LH	ONE TIME		COMPLIED WITH			
6/24/1996						
SB 72-3126	R13	ENGINE- PLANET GEAR INSTALLATION-REPLACE /REWORK PLANET GEARSHAFT ASSY: USES OPTIMIZED DIAMETER & BALANCE CLAMP NUTS	GARRETT	Recommended	DATE: 5/15/2013 TIME: 9460.6 LD/CY: 8519	DATE: TIME: LD/CY:
LH	ONE TIME		NOT APPLICABLE			
9/22/1989						
SB 72-3128	R9	ACCESSORY DRIVES - MODIFY ALTERNATOR DRIVE SPUR GEARSHAFT	GARRETT	Recommended	DATE: 5/15/2013 TIME: 9460.6 LD/CY: 8519	DATE: TIME: LD/CY:
LH	ONE TIME		FOUND P/C/W			
2/18/2003						
SB 72-3133	R1	ENGINE - FAN BYPASS STATOR INSTALLATION INSPECT AND REPLACE FAN BYPASS STATOR ALIGNMENT PINS	GARRETT	Recommended	DATE: 5/15/2013 TIME: 9460.6 LD/CY: 8519	DATE: TIME: LD/CY:
LH	ONE TIME		FOUND P/C/W			
5/04/1981						
SB 72-3136	R1	ENGINE- ACCESSORY DRIVE GEARBOX- REPLACE ANNULAR BALL BEARINGS, P/N 358206: TO PREVENT ROTATION OF THE INNER RACE	GARRETT	Optional	DATE: 5/15/2013 TIME: 9460.6 LD/CY: 8519	DATE: TIME: LD/CY:
LH	ONE TIME		FOUND P/C/W			
7/28/1980						
SB 72-3145	R2	ENGINE - CONICAL FAN SPINNER INTERNAL CORROSION PREVENTION	GARRETT	Recommended	DATE: 5/15/2013 TIME: 9460.6 LD/CY: 8519	DATE: TIME: LD/CY:
LH	ONE TIME		FOUND P/C/W			
5/25/1983						

**LEFT ENGINE SERVICE BULLETINS
GARRETT P84484**

**4/25/2024
N2787**

DIRECTIVE NUMBER	REVISION	DESCRIPTION	VENDER	COMPLIANCE	NEXT DUE
LOCATION	RECURRS		METHOD		
EFFECTIVE DATE					
SB 72-3159	R7	ENGINE - INSPECT AND/OR REPLACE TURBINE INTERSTAGE TRANSITION DUCT: WILL REVEAL INADEQUATE WELD PENETRATION	GARRETT Recommended	DATE: 5/15/2013 TIME: 9460.6 LD/CY: 8519	DATE: TIME: LD/CY:
LH	ONE TIME		FOUND P/C/W		
1/08/1988					
SB 72-3164	R2	ENGINE - LOW PRESSURE COMPRESSOR ASSY - INTERCHANGE OF 4TH STAGE AXIAL FLOW COMPRESSOR ROTOR ASSY., PN 3071652-7,-9	GARRETT Optional	DATE: 5/15/2013 TIME: 9460.6 LD/CY: 8519	DATE: TIME: LD/CY:
LH	ONE TIME		FOUND P/C/W		
8/19/1988					
SB 72-3167	R3	FAN SUPPORT SHAFT & HOUSING ASSY - REPLACE GASKET, P/N 3071968-1/-2 WITH SEAL PLATE, P/N 3073213-1 INACTIVE	GARRETT Optional	DATE: 5/15/2013 TIME: 9460.6 LD/CY: 8519	DATE: TIME: LD/CY:
LH	ONE TIME		NOT APPLICABLE		
9/12/2001					
SB 72-3169	R2	ENGINE - COMPRESSOR INSTALLATION - REPLACE IDENTIFIED HP ROTOR THRUST (NO. 5) BEARING	GARRETT Recommended	DATE: 5/15/2013 TIME: 9460.6 LD/CY: 8519	DATE: TIME: LD/CY:
LH	ONE TIME		NOT APPLICABLE		
3/19/1982					
SB 72-3170	R2	ENGINE - TURBINE INTERSTAGE TRANSITION DUCT - INSTALL AFT MOUNT AUXILIARY BRACKET	GARRETT Optional	DATE: 5/15/2013 TIME: 9460.6 LD/CY: 8519	DATE: TIME: LD/CY:
LH	ONE TIME		NOT APPLICABLE		
3/07/1985					
SB 72-3174	R4	ENGINE - COMPRESSOR INSTALLATION-INSTALL NEW OR REWORKED HIGH PRESSURE DIFFUSER: REDUCES EXCITATION LEVELS	GARRETT Recommended	DATE: 5/15/2013 TIME: 9460.6 LD/CY: 8519	DATE: TIME: LD/CY:
LH	ONE TIME		NOT APPLICABLE		
6/24/2010					
SB 72-3177	R1	ENGINE - COMBUSTION SECTION - REPLACE SHIPPING GASKET UNDER HIGH PRESSURE BLEED AIR PORT COVER	GARRETT Recommended	DATE: 5/15/2013 TIME: 9460.6 LD/CY: 8519	DATE: TIME: LD/CY:
LH	ONE TIME		FOUND P/C/W		
7/08/1982					
SB 72-3190	R2	ENGINE - FAN SHAFT AND HOUSING ASSEMBLY - INSTALL REWORKED SPUR RING GEAR, P/N 3077000-1 OR 3077000-2	GARRETT	DATE: 5/15/2013 TIME: 9460.6 LD/CY: 8519	DATE: TIME: LD/CY:
LH	ONE TIME		FOUND P/C/W		
4/12/1982					
SB 72-3197		ENGINE - FAN INLET HOUSING REPLACEMENT: INSTALL IMPROVED FAN INLET HOUSING	GARRETT Optional	DATE: 5/15/2013 TIME: 9460.6 LD/CY: 8519	DATE: TIME: LD/CY:
LH	ONE TIME		FOUND P/C/W		
12/04/1981					
SB 72-3202	R7	ENGINE - FUEL - MODIFY ENGINE TO PERMIT USE OF JP-4 FUEL WITH THE AIRCRAFT FUEL SUPPLY SYSTEM	GARRETT	DATE: 5/15/2013 TIME: 9460.6 LD/CY: 8519	DATE: TIME: LD/CY:
LH	ONE TIME		FOUND P/C/W		
12/12/2001					
SB 72-3224		ENGINE - COMBUSTION SECTION - INSPECT COMBUSTION CHAMBER LINER, P/N 3072674-3 FOR DISTRESS IN REGION OF IGNITOR PLUGS	GARRETT Recommended	DATE: 5/15/2013 TIME: 9460.6 LD/CY: 8519	DATE: TIME: LD/CY:
LH	ONE TIME		FOUND P/C/W		
8/12/1982					
SB 72-3225	R1	ENGINE - TURBINE SECTION - REMOVE FROM SERVICE ALL FIRST STAGE LP TURBINE BLADE P/N 3072311-2: LOT # IN SPEC ROTOR ASSY	GARRETT Mandatory	DATE: 5/15/2013 TIME: 9460.6 LD/CY: 8519	DATE: TIME: LD/CY:
LH	ONE TIME		FOUND P/C/W		
4/19/1984					
SB 72-3227		ENGINE - COMPRESSOR SECTION - REPLACE LP COMPRESSOR BEARING HOUSING: HAVE BEEN SUBJECT TO FRETTING, FATIGUE & FRACTURE	GARRETT Recommended	DATE: 5/15/2013 TIME: 9460.6 LD/CY: 8519	DATE: TIME: LD/CY:
LH	ONE TIME		FOUND P/C/W		
9/17/1982					
SB 72-3237	R3	ENGINE - COMPRESSOR SECTION - INSTALL HP COMPRESSOR IMPELLER, P/N 3073393-1, 3073394-1 AND 3073398-1	GARRETT Mandatory	DATE: 5/15/2013 TIME: 9460.6 LD/CY: 8519	DATE: TIME: LD/CY:
LH	ONE TIME		FOUND P/C/W		
12/15/1989					

**LEFT ENGINE SERVICE BULLETINS
GARRETT P84484**

**4/25/2024
N2787**

DIRECTIVE NUMBER	REVISION	DESCRIPTION	VENDER		COMPLIANCE	NEXT DUE
LOCATION	RECURRS		METHOD			
EFFECTIVE DATE						
SB 72-3239RWK LH 12/10/1982	R2 ONE TIME	REWORK HP COMPRESSOR RADIAL IMPELLER, P/N 3070274-1, TO 3073393-1 OR 3072639-1 TO 3073394-1	GARRETT NOT APPLICABLE		DATE: 5/15/2013 TIME: 9460.6 LD/CY: 8519	DATE: TIME: LD/CY:
SB 72-3252 LH 7/19/1984	R2 ONE TIME	ENGINE - TURBINE SECTION - INSPECTION OF 2ND STAGE LP TURBINE DISK: INSUFFICIENT WEB THICKNESS RESULTS IN REDUCED LIFE	GARRETT NOT APPLICABLE	Mandatory	DATE: 5/15/2013 TIME: 9460.6 LD/CY: 8519	DATE: TIME: LD/CY:
SB 72-3272 LH 12/12/2001	R4 ONE TIME	INSPECTION OF LP TURBINE ROTOR ASSEMBLY DISCS & REWORK OF 1ST STAGE LP TURBINE NOZZLE ASSY INACTIVE	GARRETT NOT APPLICABLE	Recommended	DATE: 5/15/2013 TIME: 9460.6 LD/CY: 8519	DATE: TIME: LD/CY:
SB 72-3274 LH 9/10/1985	R1 ONE TIME	REPLACE RING GEAR WITH 3072511-3	GARRETT FOUND P/C/W	Optional	DATE: 5/15/2013 TIME: 9460.6 LD/CY: 8519	DATE: TIME: LD/CY:
SB 72-3280 LH 3/14/1986	R1 ONE TIME	ENGINE - COMPRESSOR SECTION - REPLACE/ REWORK COMPRESSOR INTERSTAGE DIFFUSER, P/N 3071722-1/-3/-5 WITH/TO -4	GARRETT FOUND P/C/W	Recommended	DATE: 5/15/2013 TIME: 9460.6 LD/CY: 8519	DATE: TIME: LD/CY:
SB 72-3281 LH 2/07/1986	R1 ONE TIME	ENGINE - TURBINE SECTION - REPLACEMENT OF LP 1ST STAGE TURBINE DISCS/ROTOR ASSY : IMPROVED HEAT TREATMENT	GARRETT FOUND P/C/W	Optional	DATE: 5/15/2013 TIME: 9460.6 LD/CY: 8519	DATE: TIME: LD/CY:
SB 72-3283 LH 3/07/1986	R1 ONE TIME	ENGINE - TURBINE SECTION - REPLACEMENT OF LP 2ND STAGE TURBINE DISCS/ROTOR ASSY : IMPROVED HEAT TREATMENT	GARRETT COMPLIED WITH	Optional	DATE: 5/15/2013 TIME: 9460.6 LD/CY: 8519	DATE: TIME: LD/CY:
SB 72-3287 LH 3/25/1985	 ONE TIME	ENGINE - ACCESSORY DRIVES - REWORK OR REPLACE ACCESSORY DRIVE GEARBOX HOUSING ASSEMBLY P/N 3071321-3 TO -4	GARRETT COMPLIED WITH	Recommended	DATE: 5/15/2013 TIME: 9460.6 LD/CY: 8519	DATE: TIME: LD/CY:
SB 72-3288 LH 9/11/1984	 ONE TIME	ENGINE - MODIFICATION TO PROVIDE POSITIV RETENTION OF ENGINE NAMEPLATE	GARRETT COMPLIED WITH	Recommended	DATE: 5/15/2013 TIME: 9460.6 LD/CY: 8519	DATE: TIME: LD/CY:
SB 72-3290 LH 2/18/1994	R3 ONE TIME	ACCESSORY DRIVE GEARBOX- INCORPORATE IMPROVE ALTERNATOR GEARSHAFT SEAL: IMPROVED SEALING THAT REDUCES OIL LEAK	GARRETT NOT APPLICABLE	Optional	DATE: 5/15/2013 TIME: 9460.6 LD/CY: 8519	DATE: TIME: LD/CY:
SB 72-3293 LH 5/31/1985	R1 ONE TIME	ENGINE - ACCESSORY DRIVES - REPLACE SHIM P/N 3070379-1/-2/-3 WITH SHIM (INTERGRAL SEAL) P/N 3073493-1/-2/-3: STOP OIL LEAK	GARRETT FOUND P/C/W	Recommended	DATE: 5/15/2013 TIME: 9460.6 LD/CY: 8519	DATE: TIME: LD/CY:
SB 72-3298 LH 12/12/2001	R3 ONE TIME	REPLACE/REWORK OUTER TRANSITION LINER REPLACE P/N 3072327-2/-3/-4/-5/-6/-7 OR REWORK -6/-7 INACTIVE	GARRETT FOUND P/C/W	Recommended	DATE: 5/15/2013 TIME: 9460.6 LD/CY: 8519	DATE: TIME: LD/CY:
SB 72-3299 LH 9/13/1991	R3 ONE TIME	REPLACE/REWORK SECOND STAGE LP TURBINE NOZZLE, P/N 3072340-1 TO 3072340-4	GARRETT FOUND P/C/W	Recommended	DATE: 5/15/2013 TIME: 9460.6 LD/CY: 8519	DATE: TIME: LD/CY:
SB 72-3304 LH 5/24/1985	 ONE TIME	ENGINE - BYPASS SECTION - REPLACE/REWORK FAN DISC NUT, P/N 3071981-1: WILL PROVIDE COMMONALITY OF PARTS	GARRETT FOUND P/C/W	Recommended	DATE: 5/15/2013 TIME: 9460.6 LD/CY: 8519	DATE: TIME: LD/CY:

**LEFT ENGINE SERVICE BULLETINS
GARRETT P84484**

**4/25/2024
N2787**

DIRECTIVE NUMBER	REVISION	DESCRIPTION	VENDER	COMPLIANCE	NEXT DUE
LOCATION	RECURRS		METHOD		
EFFECTIVE DATE					
SB 72-3306		ENGINE - TURBINE SECTION - REMOVE FROM SERVICE 1ST STAGE LP TURBINE DISC IDENTIFIED BY SN 2-18040-XXXX	GARRETT FOUND P/C/W	Recommended DATE: 5/15/2013 TIME: 9460.6 LD/CY: 8519	DATE: TIME: LD/CY:
LH	ONE TIME				
2/01/1985					
SB 72-3309	R5	ENGINE - TURBINE SECTION - INSPECT AND/OR REPAIR/REPLACE SPECIFIC IDENTIFIED TURBINE INTERSTAGE TRANSITION DUCTS	GARRETT NOT APPLICABLE	Recommended DATE: 5/15/2013 TIME: 9460.6 LD/CY: 8519	DATE: TIME: LD/CY:
LH	ONE TIME				
10/20/2004					
SB 72-3322	R1	ENGINE - PERMANENTLY PLUG COMPRESSOR INTERSTAGE DIFFUSER BOROSCOPE PORT: REPLACE SEALED PLUG TO STOP OIL LEAK	GARRETT FOUND P/C/W	Recommended DATE: 5/15/2013 TIME: 9460.6 LD/CY: 8519	DATE: TIME: LD/CY:
LH	ONE TIME				
4/04/1986					
SB 72-3346	1	WELD TITANIUM STRIPS TO ENDS OF ALL VANES AT INNER & OUTER SHROUD LOCATIONS ON FAN BY-PASS STATORS P/N3071965-1,	GARRETT NOT APPLICABLE	Optional DATE: 5/15/2013 TIME: 9460.6 LD/CY: 8519	DATE: TIME: LD/CY:
LH	ONE TIME				
1/12/2007					
SB 72-3367	R3	ENGINE - TURBINE SECTION - PERFORM ONE TIME INSPECTION OF NOZZLE THROAT (A5) OPENING FOR PROPER DIMENSION	GARRETT FOUND P/C/W	Recommended DATE: 5/15/2013 TIME: 9460.6 LD/CY: 8519	DATE: TIME: LD/CY:
LH	ONE TIME				
9/02/1994					
SB 72-3369	R6	ENGINE - TURBINE SECTION - ADJUST NOZZLE THROAT (A5) OPENING(S) EFFECTIVE (AE) FLOW AREA	GARRETT FOUND P/C/W	DATE: 5/15/2013 TIME: 9460.6 LD/CY: 8519	DATE: TIME: LD/CY:
LH	ONE TIME				
6/26/2002					
SB 72-3370	R1	ENGINE - TURBINE SECTION - INSPECT AND REWORK TURBINE INTERSTAGE TRANSITION DUCTS P/N 3071486-X,3072318-X,3072726-X	GARRETT FOUND P/C/W	Recommended DATE: 5/15/2013 TIME: 9460.6 LD/CY: 8519	DATE: TIME: LD/CY:
LH	ONE TIME				
6/15/1990					
SB 72-3380		ENGINE - COMBUSTION SECTION - INSTALL OUTER TRANSITION LINER WITH THERMAL BARRIER COATING (TBC) APPLIED	GARRETT FOUND P/C/W	Recommended DATE: 5/15/2013 TIME: 9460.6 LD/CY: 8519	DATE: TIME: LD/CY:
LH	ONE TIME				
8/25/1989					
SB 72-3381	R1	ENGINE - INSTALL REDESIGNED COMBUSTION SYSTEM (LOW SMOKE)	GARRETT NOT APPLICABLE	Optional DATE: 5/15/2013 TIME: 9460.6 LD/CY: 8519	DATE: TIME: LD/CY:
LH	ONE TIME				
10/30/1992					
SB 72-3384	R2	ENGINE - BY-PASS SECTION - REPLACE OIL DEFLECTOR OR REWORK EXISTING OIL DEFLECTOR	GARRETT FOUND P/C/W	Optional DATE: 5/15/2013 TIME: 9460.6 LD/CY: 8519	DATE: TIME: LD/CY:
LH	ONE TIME				
3/06/2001					
SB 72-3393	R1	ENGINE - BY-PASS SECTION - REPLACE/REWORK FAN SUPPORT SHAFT & HOUSING INACTIVE FOR FURTHER ACCOMPLISHMENT	GARRETT NOT APPLICABLE	Optional DATE: 5/15/2013 TIME: 9460.6 LD/CY: 8519	DATE: TIME: LD/CY:
LH	ONE TIME				
12/17/2001					
SB 72-3397	R4	ENGINE - INITIATE COMPONENT MAINTENANCE/MODIFICATION RECORD CARD (CARD-LOG BOOK) (CMMC)	GARRETT FOUND P/C/W	Mandatory DATE: 5/15/2013 TIME: 9460.6 LD/CY: 8519	DATE: TIME: LD/CY:
LH	ONE TIME				
11/14/2012					
SB 72-3405	R4	REPLACE SHROUD RETAINING SLEEVE, P/N 3070023-1 WITH P/N 3070023-3 OR 3070023-4	GARRETT FOUND P/C/W	Optional DATE: 5/15/2013 TIME: 9460.6 LD/CY: 8519	DATE: TIME: LD/CY:
LH	ONE TIME				
11/26/2002					
SB 72-3408		COMPRESSOR SECTION - REPLACE SPRING TENSION WASHER, P/N 3000005-2/-56 WITH P/N 3000005-64	GARRETT FOUND P/C/W	Recommended DATE: 5/15/2013 TIME: 9460.6 LD/CY: 8519	DATE: TIME: LD/CY:
LH	ONE TIME				
2/19/1990					

**LEFT ENGINE SERVICE BULLETINS
GARRETT P84484**

**4/25/2024
N2787**

DIRECTIVE NUMBER	REVISION	DESCRIPTION	VENDER	COMPLIANCE	NEXT DUE
LOCATION	RECURRS		METHOD		
EFFECTIVE DATE					
SB 72-3409 LH 8/10/1990	R1 ONE TIME	COMPRESSOR SECTION - INSTALL FIRST STAGE COMPRESSOR WHEEL ASSEMBLY BLADE P/N 3075358-1	GARRETT FOUND P/C/W	Recommended DATE: 5/15/2013 TIME: 9460.6 LD/CY: 8519	DATE: TIME: LD/CY:
SB 72-3410 LH 8/10/1990	R1 ONE TIME	COMPRESSOR SECTION - INSTALL SECOND STAGE COMPRESSOR ROTOR ASSEMBLY BLADE RETAINER, P/N 3075357-2	GARRETT FOUND P/C/W	Recommended DATE: 5/15/2013 TIME: 9460.6 LD/CY: 8519	DATE: TIME: LD/CY:
SB 72-3411 LH 8/10/1990	R1 ONE TIME	COMPRESSOR SECTION - INSTALL THIRD STAGE COMPRESSOR ROTOR ASSEMBLY BLADE RETAINER, P/N 3075357-3	GARRETT FOUND P/C/W	Recommended DATE: 5/15/2013 TIME: 9460.6 LD/CY: 8519	DATE: TIME: LD/CY:
SB 72-3416 LH 1/22/2001	R6 ONE TIME	HP IMPELLER SHROUD WITH IMPROVED COATING	GARRETT FOUND P/C/W	Recommended DATE: 5/15/2013 TIME: 9460.6 LD/CY: 8519	DATE: TIME: LD/CY:
SB 72-3421 LH 5/24/1991	ONE TIME	ENGINE - COMPRESSOR SECTINO - INSTALL LP COMPRESSOR BEARING HOUSING, P/N 3071691-7 OR 3077043-3	GARRETT FOUND P/C/W	Recommended DATE: 5/15/2013 TIME: 9460.6 LD/CY: 8519	DATE: TIME: LD/CY:
SB 72-3422 LH 1/03/1991	ONE TIME	INSPECTION OF THE PINION GEAR RETAINER PLATE ASSEMBLY	GARRETT FOUND P/C/W	Recommended DATE: 5/15/2013 TIME: 9460.6 LD/CY: 8519	DATE: TIME: LD/CY:
SB 72-3424 LH 12/20/1990	R1 ONE TIME	BY-PASS SECTION - REPLACEMENT OF FAN ROTOR ASSY WITH SPECIFIC S/N DISC & HUB MADE FROM THE SAME MATERIAL HEAT CODE	GARRETT NOT APPLICABLE	Recommended DATE: 5/15/2013 TIME: 9460.6 LD/CY: 8519	DATE: TIME: LD/CY:
SB 72-3426 LH 5/08/1996	R2 ONE TIME	ENG.-TURBINE SECTION-REPLACE/REWORK 3RD STAGE LP TURBINE NOZZLE, P/N 3072342-2 TO 3072342-4 OR 3070014-3 TO 3070014-5	GARRETT FOUND P/C/W	Recommended DATE: 5/15/2013 TIME: 9460.6 LD/CY: 8519	DATE: TIME: LD/CY:
SB 72-3427 LH 5/01/1992	R1 ONE TIME	COMPRESSOR SECTION - INSTALL HP COMPRESS DIFFUSER INCORPORATING A HONEYCOMB SEAL & AN IMPROVED SURFACE FINISH	GARRETT FOUND P/C/W	Recommended DATE: 5/15/2013 TIME: 9460.6 LD/CY: 8519	DATE: TIME: LD/CY:
SB 72-3429 LH 4/03/1992	R1 ONE TIME	COMPRESSOR SECTION - REPLACE TIE BOLT, P/N 3070065-1/-4 WITH P/N 3070065-3 OR 3073049-1	GARRETT NOT APPLICABLE	Recommended DATE: 5/15/2013 TIME: 9460.6 LD/CY: 8519	DATE: TIME: LD/CY:
SB 72-3449 LH 2/07/1992	ONE TIME	ENGINE-COMPRESSOR SECTION-INSTALL WASHER P/N S8154-2P025, ON BOLTS THAT SECURE HP SHROUD TO HP COMPRESSOR DIFFUSER	GARRETT FOUND P/C/W	Recommended DATE: 5/15/2013 TIME: 9460.6 LD/CY: 8519	DATE: TIME: LD/CY:
SB 72-3451 LH 10/14/1991	ONE TIME	REPLACE SPECIFIC S/N 3072542-5 2ND LPT DISC	GARRETT NOT APPLICABLE	DATE: 5/15/2013 TIME: 9460.6 LD/CY: 8519	DATE: TIME: LD/CY:
SB 72-3455 LH 9/24/1996	R3 ONE TIME	INSTALL PACKINGS, P/N S9413-036 AND SEAL P/N 3075506-2, ON TOWER SHAFT OIL TRANSFER TUBE	GARRETT FOUND P/C/W	Recommended DATE: 5/15/2013 TIME: 9460.6 LD/CY: 8519	DATE: TIME: LD/CY:
SB 72-3458 LH 6/23/2008	R4 ONE TIME	ENGINE-BYPASS SECTION-PROVIDE EDDY CURRENT INSPECTION INSTRUCTIONS FOR FAN ROTOR ASSY DISC	GARRETT COMPLIED WITH	DATE: 7/31/1997 TIME: 5958.7 LD/CY: 5388	DATE: TIME: LD/CY:

**LEFT ENGINE SERVICE BULLETINS
GARRETT P84484**

**4/25/2024
N2787**

DIRECTIVE NUMBER	REVISION	DESCRIPTION	VENDER	COMPLIANCE	NEXT DUE
LOCATION	RECURRS		METHOD		
EFFECTIVE DATE					
SB 72-3459 LH 3/18/1994	ONE TIME	REFERENCE MAINTENANCE INSTRUCTION TO FOR ENG MODELS TFE731-5AR-3C/-4C/TFE731-5BR-1C/-2C/-3C;INACTIVE FOR FURTHER ACC.	GARRETT COMPLIED WITH	Optional DATE: 7/31/1997 TIME: 5958.7 LD/CY: 5388	DATE: TIME: LD/CY:
SB 72-3469 LH 9/14/2001	R3 ONE TIME	ENGINE - COMPRESSOR SECTION - REPLACE NO. 3 CARBON FACE SEAL AND SEAL ROTOR INACTIVE	GARRETT FOUND P/C/W	Recommended DATE: 5/15/2013 TIME: 9460.6 LD/CY: 8519	DATE: TIME: LD/CY:
SB 72-3471 LH 9/02/1994	R2 ONE TIME	ENGINE - TURBINE SECTION - REPLACE SUPPORT & SEAL ASSY IN HP TURBINE NOZZLE ASSY	GARRETT FOUND P/C/W	Recommended DATE: 5/15/2013 TIME: 9460.6 LD/CY: 8519	DATE: TIME: LD/CY:
SB 72-3473 LH 4/03/1992	ONE TIME	ENGINE BY-PASS SECTION - ADDITIONAL SOAP SAMPLING REQUIREMENT	GARRETT NOT APPLICABLE	Recommended DATE: 5/15/2013 TIME: 9460.6 LD/CY: 8519	DATE: TIME: LD/CY:
SB 72-3475 LH 9/14/2001	R1 ONE TIME	ENGINE - BY-PASS SECTION - REPLACE NO. 1 CARBON FACE SEAL AND SEAL ROTOR. INACTIVE	GARRETT NOT APPLICABLE	Optional DATE: 5/15/2013 TIME: 9460.6 LD/CY: 8519	DATE: TIME: LD/CY:
SB 72-3476 LH 10/16/1992	R1 ONE TIME	TURBINE SECTION - INSTALL HP TURBINE PISTON RING SEAL, P/N 3000002-10	GARRETT FOUND P/C/W	Recommended DATE: 5/15/2013 TIME: 9460.6 LD/CY: 8519	DATE: TIME: LD/CY:
SB 72-3477 LH 4/08/1992	ONE TIME	ACCESSORY DRIVES - REPLACE ACCESSORY DRIVE GEARBOX GASKET	GARRETT FOUND P/C/W	Recommended DATE: 5/15/2013 TIME: 9460.6 LD/CY: 8519	DATE: TIME: LD/CY:
SB 72-3480 LH 5/29/1992	ONE TIME	INCORPORATION OF NEW ENGINE LOG BOOK	GARRETT FOUND P/C/W	DATE: 5/15/2013 TIME: 9460.6 LD/CY: 8519	DATE: TIME: LD/CY:
SB 72-3482 LH 6/24/2003	R7 ONE TIME	TURBINE SECTION-INSTALL LP TURBINE THIRD STAGE ROTOR ASSEMBLY, P/N 3072848-3/-4 OR 3074097-1 & ASSOCIATED PARTS	GARRETT FOUND P/C/W	Optional DATE: 5/15/2013 TIME: 9460.6 LD/CY: 8519	DATE: TIME: LD/CY:
SB 72-3483 LH 11/08/1996	R2 ONE TIME	COMPRESSOR SECTION - INSTALL LP COMPRESSOR FOURTH STAGE STATOR	GARRETT FOUND P/C/W	Recommended DATE: 5/15/2013 TIME: 9460.6 LD/CY: 8519	DATE: TIME: LD/CY:
SB 72-3487 LH 6/20/2003	R3 ONE TIME	ENGINE-BYPASS SECTION-INSPECT/REWORK FAN BLADE MIDSPAN DAMPER	GARRETT FOUND P/C/W	Recommended DATE: 5/15/2013 TIME: 9460.6 LD/CY: 8519	DATE: TIME: LD/CY:
SB 72-3488 LH 10/02/1998	R3 ONE TIME	TURBINE SECTION - PROVIDE AUTHORITY FOR INSTALLATION OF ALTERNATE PART NUMBERED HP TURBINE SHROUD SEGMENTS	GARRETT FOUND P/C/W	Recommended DATE: 5/15/2013 TIME: 9460.6 LD/CY: 8519	DATE: TIME: LD/CY:
SB 72-3492 LH 7/30/1993	ONE TIME	BYPASS SECTION - INSTALL O-RING PACKING, P/N S9873-001, BETWEEN SPINNER SUPPORT AND FAN BLADES	GARRETT FOUND P/C/W	Optional DATE: 5/15/2013 TIME: 9460.6 LD/CY: 8519	DATE: TIME: LD/CY:
SB 72-3494 LH 8/06/2015	R2 RECURRS	TURBINE SECTION-HIGH PRESSURE & LOW PRESSURE TURBINE BLADE HOUR TRACKING	GARRETT COMPLIED WITH	Recommended DATE: 8/02/2007 TIME: 8770.1 LD/CY: 7748	DATE: TIME: LD/CY: 10170.1

**LEFT ENGINE SERVICE BULLETINS
GARRETT P84484**

**4/25/2024
N2787**

DIRECTIVE NUMBER	REVISION	DESCRIPTION	VENDER	COMPLIANCE	NEXT DUE	
LOCATION	RECURRS		METHOD			
EFFECTIVE DATE						
SB 72-3498	R1	BYPASS SECTION - INSTALL FAN SHAFT & RING GEAR WITH NEW RETAINING RING	GARRETT	Recommended	DATE: 5/15/2013 TIME: 9460.6 LD/CY: 8519	DATE: TIME: LD/CY:
LH	ONE TIME		FOUND P/C/W			
5/07/1993						
SB 72-3499	R6	ENGINE - BY-PASS SECTION - INSTALL COMPONENT PARTS TO PREVENT OIL LEAKAGE IN #1 OIL SEAL REGION. INACTIVE	GARRETT	Recommended	DATE: 5/15/2013 TIME: 9460.6 LD/CY: 8519	DATE: TIME: LD/CY:
LH	ONE TIME		NOT APPLICABLE			
12/14/2001						
SB 72-3502	R4	INSTALL/REWORK LOW PRESSURE 1ST STAGE TURBINE NOZZLE WITH AN IMPROVED AIR (A5) SEAL INSTALLED	GARRETT	Recommended	DATE: 5/15/2013 TIME: 9460.6 LD/CY: 8519	DATE: TIME: LD/CY:
LH	ONE TIME		FOUND P/C/W			
6/10/2003						
SB 72-3507	R1	REWORK FAN SHAFT HOUSING 3072160-1/-2 TO 3077082-1/-2	GARRETT		DATE: 5/15/2013 TIME: 9460.6 LD/CY: 8519	DATE: TIME: LD/CY:
LH	ONE TIME		FOUND P/C/W			
SB 72-3520	R3	TURBINE SECTION - INSTALL LP THIRD STAGE TURBINE ROTOR ASSEMBLY INCORPORATING A NEWLY DESIGNED SEAL ROTOR	GARRETT	Optional	DATE: 5/15/2013 TIME: 9460.6 LD/CY: 8519	DATE: TIME: LD/CY:
LH	ONE TIME		NOT APPLICABLE			
10/15/1999						
SB 72-3524		BYPASS SECTION - INSTALL RETAINING (DAMPER) RING, P/N 3072463-2	GARRETT	Recommended	DATE: 5/15/2013 TIME: 9460.6 LD/CY: 8519	DATE: TIME: LD/CY:
LH	ONE TIME		FOUND P/C/W			
6/04/1993						
SB 72-3529	R2	BYPASS SECTION - REDESIGNED FAN DISC	GARRETT	Optional	DATE: 5/15/2013 TIME: 9460.6 LD/CY: 8519	DATE: TIME: LD/CY:
LH	ONE TIME		FOUND P/C/W			
10/25/2000						
SB 72-3530	R1	TURBINE SECTION - INSTALL AN LP SECOND STAGE TURBINE NOZZLE THAT INCORPORATES A HONEYCOMB AIR SEAL	GARRETT	Recommended	DATE: 5/15/2013 TIME: 9460.6 LD/CY: 8519	DATE: TIME: LD/CY:
LH	ONE TIME		FOUND P/C/W			
10/08/1993						
SB 72-3531	R4	BYPASS SECTION-INSTALLATION OF FAN BLADES & IDENTIFICATION OF FAN ROTOR ASSEMBLIES	GARRETT	Recommended	DATE: 5/15/2013 TIME: 9460.6 LD/CY: 8519	DATE: TIME: LD/CY:
LH	ONE TIME		FOUND P/C/W			
1/28/2003						
SB 72-3532		REWORK COMPRESSOR INTERSTAGE DIFFUSER	GARRETT		DATE: 5/15/2013 TIME: 9460.6 LD/CY: 8519	DATE: TIME: LD/CY:
LH	ONE TIME		FOUND P/C/W			
SB 72-3536	R3	COMBUSTION SECTION - INSTALL COMBUSTION CHAMBER & INNER TRANSITION LINER (CONTROLLED FIT/LOW SMOKE)	GARRETT	Optional	DATE: 5/15/2013 TIME: 9460.6 LD/CY: 8519	DATE: TIME: LD/CY:
LH	ONE TIME		FOUND P/C/W			
1/24/2002						
SB 72-3540	R3	COMPRESSOR SECTION - IMPROVED NO.4 & 5 BEARING SUMP SCAVENGE	GARRETT	Recommended	DATE: 5/15/2013 TIME: 9460.6 LD/CY: 8519	DATE: TIME: LD/CY:
LH	ONE TIME		NOT APPLICABLE			
9/14/2001						
SB 72-3542	R3	COMPRESSOR SECTION - INSTALL LP SECOND STAGE COMPRESSOR ROTOR ASSY WITH FREQUENCY INSPECTED ROTOR BLADES	GARRETT	Recommended	DATE: 5/15/2013 TIME: 9460.6 LD/CY: 8519	DATE: TIME: LD/CY:
LH	ONE TIME		COMPLIED WITH			
3/28/2007						
SB 72-3549		TURBINE SECTION-INSPECT FWD & AFT WELDS FOR MACHINING ON LP FIRST STAGE TURBINE NOZZLE ASSY, AIR SEAL P/N 3073765-3	GARRETT	Recommended	DATE: 5/15/2013 TIME: 9460.6 LD/CY: 8519	DATE: TIME: LD/CY:
LH	ONE TIME		FOUND P/C/W			
4/04/1994						

**LEFT ENGINE SERVICE BULLETINS
GARRETT P84484**

**4/25/2024
N2787**

DIRECTIVE NUMBER	REVISION	DESCRIPTION	VENDER	COMPLIANCE	NEXT DUE
LOCATION	RECURRS		METHOD		
EFFECTIVE DATE					
SB 72-3556 LH 5/06/1994	ONE TIME	TURBINE SECTION-REPLACE LP SECOND STAGE TURBINE BLADES, P/N 3072012-1/-2	GARRETT FOUND P/C/W	Optional DATE: 5/15/2013 TIME: 9460.6 LD/CY: 8519	DATE: TIME: LD/CY:
SB 72-3560 LH 3/26/1996	R1 ONE TIME	COMPRESSOR SECTION-LP FIRST STAGE COMPRESSOR ROTOR ASSEMBLY BLADES	GARRETT FOUND P/C/W	DATE: 5/15/2013 TIME: 9460.6 LD/CY: 8519	DATE: TIME: LD/CY:
SB 72-3561 LH 5/05/2005	R2 ONE TIME	COMPRESSOR SECTION-LP SECOND STAGE COMPRESSOR ROTOR ASSEMBLY BLADES	GARRETT FOUND P/C/W	DATE: 5/15/2013 TIME: 9460.6 LD/CY: 8519	DATE: TIME: LD/CY:
SB 72-3562 LH 3/26/1996	R1 ONE TIME	COMPRESSOR SECTION-LP THIRD STAGE COMPRESSOR ROTOR ASSEMBLY BLADES	GARRETT FOUND P/C/W	DATE: 5/15/2013 TIME: 9460.6 LD/CY: 8519	DATE: TIME: LD/CY:
SB 72-3563 LH 3/26/1996	R1 ONE TIME	COMPRESSOR SECTION-LP FOURTH STAGE COMPRESSOR ROTOR ASSEMBLY BLADES	GARRETT FOUND P/C/W	DATE: 5/15/2013 TIME: 9460.6 LD/CY: 8519	DATE: TIME: LD/CY:
SB 72-3564 LH 1/07/2003	R7 ONE TIME	ENGINE - BANK/SPARE ENGINE CONVERSIONS-	GARRETT NOT APPLICABLE	DATE: 5/15/2013 TIME: 9460.6 LD/CY: 8519	DATE: TIME: LD/CY:
SB 72-3566 LH 10/29/2002	R4 ONE TIME	ENGINE-INSTALL ALTERNATE FITTINGS WITH A RING SEAL	GARRETT NOT APPLICABLE	DATE: 5/15/2013 TIME: 9460.6 LD/CY: 8519	DATE: TIME: LD/CY:
SB 72-3568 LH 8/15/2008	R5 ONE TIME	CONVERT ENGINE MODELS TFE731-3 TO TFE731-3D AND TFE731-3R TO TFE731-3DR	GARRETT FOUND P/C/W	DATE: 5/15/2013 TIME: 9460.6 LD/CY: 8519	DATE: TIME: LD/CY:
SB 72-3591 LH 2/01/1996	ONE TIME	TURBINE SECTION-PROVIDE FOR INSTALLATION OF HP TURBINE BLADES, P/N 3072450-1/-2	GARRETT FOUND P/C/W	Recommended DATE: 5/15/2013 TIME: 9460.6 LD/CY: 8519	DATE: TIME: LD/CY:
SB 72-3596 LH 9/14/2001	R8 ONE TIME	ENGINE - REPLACE MAINSHAFT CARBON RING SEALS AND ASSOCIATED VENT/OIL SYSTEM COMPONENTS INACTIVE	GARRETT FOUND P/C/W	Optional DATE: 5/15/2013 TIME: 9460.6 LD/CY: 8519	DATE: TIME: LD/CY:
SB 72-3600 LH 1/13/1997	ONE TIME	ENGINE-COMPRESSOR SECTION-INSTALL LP COMPRESSOR STATOR SHIM, P/N 3060360-1 THRU -11	GARRETT FOUND P/C/W	DATE: 5/15/2013 TIME: 9460.6 LD/CY: 8519	DATE: TIME: LD/CY:
SB 72-3603RWK LH 5/22/1996	R1 ONE TIME	REWORK COMPRESSOR INTERSTAGE DIFFUSER TO INCORPORATE/ENLARGE OIL SCAVENGE SLOTS	GARRETT FOUND P/C/W	DATE: 5/15/2013 TIME: 9460.6 LD/CY: 8519	DATE: TIME: LD/CY:
SB 72-3604 LH 3/20/2015	R5 ONE TIME	ENGINE-ACCESSORY DRIVES-REWORK TRANSFER GEARBOX ASSEMBLY, P/N 3070093-X TO P/N 3070093-12	GARRETT FOUND P/C/W	DATE: 5/15/2013 TIME: 9460.6 LD/CY: 8519	DATE: TIME: LD/CY:
SB 72-3605 LH 6/16/2004	R4 ONE TIME	INSTALL/REWORK ACCESSORY DRIVE GEARBOX ASSY W/ AN IMPROVED AIR OIL SEPARATOR & A NEW AIR BREATHER VALVE ASSY	GARRETT FOUND P/C/W	DATE: 5/15/2013 TIME: 9460.6 LD/CY: 8519	DATE: TIME: LD/CY:

**LEFT ENGINE SERVICE BULLETINS
GARRETT P84484**

**4/25/2024
N2787**

DIRECTIVE NUMBER	REVISION	DESCRIPTION	VENDER	COMPLIANCE	NEXT DUE
LOCATION	RECURRS		METHOD		
EFFECTIVE DATE					
SB 72-3613 LH 1/23/2009	R8 ONE TIME	ENGINE-REPLACE NO.1 & NO.3 CARBON RING SEALS & ASSOCIATED VENT/OIL SYSTEM COMPONENTS	GARRETT FOUND P/C/W	Recommended DATE: 5/15/2013 TIME: 9460.6 LD/CY: 8519	DATE: TIME: LD/CY:
SB 72-3614RWK LH 2/06/1997	R4 ONE TIME	BYPASS SECTION-REWORK NO.1 SEAL & SEAL HOUSING TO PART NO. 3071966-5 OR 3077122-1/-2/-3	GARRETT FOUND P/C/W	DATE: 5/15/2013 TIME: 9460.6 LD/CY: 8519	DATE: TIME: LD/CY:
SB 72-3615 LH 2/06/1997	ONE TIME	REWORK AIR BREATHER VALVE, P/N 3071564-7 /-8 TO P/N 3071564-9,USED IN AIR BREATHR VALVE P/N 3075323-3	GARRETT FOUND P/C/W	DATE: 5/15/2013 TIME: 9460.6 LD/CY: 8519	DATE: TIME: LD/CY:
SB 72-3635 LH 11/16/1998	ONE TIME	INSPECT/REWORK/INSTALL OIL FILTER COVER P/N 3072231-1 TO P/N 3072231-4	GARRETT FOUND P/C/W	DATE: 5/15/2013 TIME: 9460.6 LD/CY: 8519	DATE: TIME: LD/CY:
SB 72-3640 LH 11/10/2000	R4 ONE TIME	ENGINE-SERVICING WITH MOBIL 254 OIL OR EXXON 2197 OIL INACTIVE	GARRETT FOUND P/C/W	Recommended DATE: 5/15/2013 TIME: 9460.6 LD/CY: 8519	DATE: TIME: LD/CY:
SB 72-3661 LH 1/24/2000	ONE TIME	INSPECT SPECIFIC IDENTIFIED LP 3RD STAGE TURB ROTOR ASSY INCORP. LPT3 BLADE P/N 3072845-1 WITH MFG CODE OF 24217	GARRETT FOUND P/C/W	Recommended DATE: 5/15/2013 TIME: 9460.6 LD/CY: 8519	DATE: TIME: LD/CY:
SB 72-3662 LH 4/12/2012	R8 ONE TIME	REPLACE NO. 4 AND NO. 5 CARBON RING SEALS AND ASSOCIATED VENT/OIL SYSTEM COMPONENTS	GARRETT FOUND P/C/W	Recommended DATE: 5/15/2013 TIME: 9460.6 LD/CY: 8519	DATE: TIME: LD/CY:
SB 72-3664 LH 5/05/2000	ONE TIME	INSPECTION/REPLACEMENT OF THREADED ENDS TIE ROD, (LP TIE ROD), P/N 3073049-1 & 3074744-1	GARRETT NOT APPLICABLE	Recommended DATE: 5/15/2013 TIME: 9460.6 LD/CY: 8519	DATE: TIME: LD/CY:
SB 72-3674 LH 9/16/2003	R2 ONE TIME	INSPECTION OF SPECIFIC IDENTIFIED MAIN SUPPORT FRAME ASSEMBLIES	GARRETT NOT APPLICABLE	Recommended DATE: 5/15/2013 TIME: 9460.6 LD/CY: 8519	DATE: TIME: LD/CY:
SB 72-3675 LH 1/13/2010	R5 ONE TIME	INSPECT FAN BLADES FOR UNAUTHORIZED MARKINGS ON THE FAN BLADE DOVETAIL AFT REGION	GARRETT FOUND P/C/W	Recommended DATE: 5/15/2013 TIME: 9460.6 LD/CY: 8519	DATE: TIME: LD/CY:
SB 72-3676 LH 7/12/2001	ONE TIME	REPLACE THE HOISTING BRACKET ON THE FAN DUCT SET, P/N 3072420-7(UPPER HALF) ON SPECIFIC IDENTIFIED ENGINES	GARRETT COMPLIED WITH	Recommended DATE: 5/15/2013 TIME: 9460.6 LD/CY: 8519	DATE: TIME: LD/CY:
SB 72-3682 LH 11/26/2002	ONE TIME	REMOVE SPECIFIC IDENTIFIED LP COMPRESSOR 2ND STAGE (LPC2) DISCS	GARRETT NOT APPLICABLE	Recommended DATE: 5/15/2013 TIME: 9460.6 LD/CY: 8519	DATE: TIME: LD/CY:
SB 72-3685 LH 3/08/2002	ONE TIME	REPLACE SPECIFIC INDENTIFIED LP SECOND STAGE TURBINE BLADES, P/N 3072012-2 AND P/N 3074099-1	GARRETT NOT APPLICABLE	Recommended DATE: 5/15/2013 TIME: 9460.6 LD/CY: 8519	DATE: TIME: LD/CY:
SB 72-3687 LH 11/11/2002	ONE TIME	REMOVE SPECIFIC IDENTIFIED LP COMPRESSOR 2ND STAGE (LPC2) DISCS	GARRETT NOT APPLICABLE	Recommended DATE: 5/15/2013 TIME: 9460.6 LD/CY: 8519	DATE: TIME: LD/CY:

**LEFT ENGINE SERVICE BULLETINS
GARRETT P84484**

4/25/2024

N2787

DIRECTIVE NUMBER	REVISION	DESCRIPTION	VENDER	COMPLIANCE	NEXT DUE	
LOCATION	RECURRS		METHOD			
EFFECTIVE DATE						
SB 72-3693	R1	REPLACE SPECIFIC IDENTIFIED HIGH PRESSURE TURBINE (HPT) TIE SHAFT PLAIN ROUND NUTS, P/N 3070151-4	GARRETT	Recommended	DATE: 5/15/2013	DATE:
LH	ONE TIME		FOUND P/C/W		TIME: 9460.6	TIME:
6/28/2004					LD/CY: 8519	LD/CY:
SB 72-3705	R2	INSTALL A LOW PRESSURE FIRST STAGE TURBINE (LPT1) ROTOR ASSEMBLY WITH AN IMPROVED LPT1 ROTOR DISC	GARRETT	Recommended	DATE: 5/15/2013	DATE:
LH	ONE TIME		FOUND P/C/W		TIME: 9460.6	TIME:
11/09/2005					LD/CY: 8519	LD/CY:
SB 72-3741		INSTALL IMPROVED NO. 4 SEG CARBON SEAL, P/N 3060437-1 AND NO. 5 SEG CARBON SEAL P/N 3060436-1	GARRETT		DATE: 5/15/2013	DATE:
LH	ONE TIME		COMPLIED WITH		TIME: 9460.6	TIME:
4/21/2008					LD/CY: 8519	LD/CY:
SB 72-3758		INSPECT SUSPECT HIGH PRESSURE TURBINE (HPT) ROTOR ASSEMBLIES, PN 3072314-2, -3	GARRETT		DATE: 5/15/2013	DATE:
LH	ONE TIME		NOT APPLICABLE		TIME: 9460.6	TIME:
1/19/2010					LD/CY: 8519	LD/CY:
SB 72-3759 I	R1	INSTALL IMPROVED PLAIN ENCASED SEAL, P/N 3020052-26	GARRETT		DATE: 5/15/2013	DATE:
LH	ONE TIME		COMPLIED WITH		TIME: 9460.6	TIME:
10/28/2011					LD/CY: 8519	LD/CY:
SB 72-3764 1		REMOVE SPECIFIC IDENTIFIED THIRD STAGE AXIAL COMPRESSOR DISKS, PN 3072397-3	GARRETT		DATE: 5/15/2013	DATE:
LH	ONE TIME		NOT APPLICABLE		TIME: 9460.6	TIME:
6/14/2011					LD/CY: 8519	LD/CY:
SB 72-3773		INTRODUCTION OF IMPROVED STAGE 4 CASE AND VANE ASSEMBLIES, PN 3074555-10, -11	GARRETT	Recommended	DATE: 5/15/2013	DATE:
LH	ONE TIME		COMPLIED WITH		TIME: 9460.6	TIME:
7/08/2011					LD/CY: 8519	LD/CY:
SB 72-3777	R2	INSTALL IMPROVED LOW PRESSURE SECOND STAGE (LPC2) SHROUD, PN 3072403-6	GARRETT		DATE: 5/15/2013	DATE:
LH	ONE TIME		COMPLIED WITH		TIME: 9460.6	TIME:
8/17/2012					LD/CY: 8519	LD/CY:
SB 73-3028		FUEL - REPLACE FLOW DIVIDER AND DRAIN VALVE WITH NEW FLOW DIVIDER VALVE WITHOUT DRAIN FUNCTION	GARRETT	Optional	DATE: 5/15/2013	DATE:
LH	ONE TIME		FOUND P/C/W		TIME: 9460.6	TIME:
7/05/1979					LD/CY: 8519	LD/CY:
SB 73-3049	R1	ENGINE FUEL AND CONTROL - CONTROLLING - INSTALL REWORKED FUEL CONTROL ASSEMBLY: INCREASES SERVICE LIFE	GARRETT	Recommended	DATE: 5/15/2013	DATE:
LH	ONE TIME		FOUND P/C/W		TIME: 9460.6	TIME:
10/05/1984					LD/CY: 8519	LD/CY:
SB 73-3062	R3	ENGINE FUEL AND CONTROL - ADJUST FUEL PUMP ANTI-ICING VALVE	GARRETT		DATE: 5/15/2013	DATE:
LH	ONE TIME		FOUND P/C/W		TIME: 9460.6	TIME:
5/23/1994					LD/CY: 8519	LD/CY:
SB 73-3064		ENGINE FUEL AND CONTROL - INSTALL LEAF SPRING BETWEEN VARIABLE RESISTOR & SPUR GEAR: MINIMIZES WEAR	GARRETT	Recommended	DATE: 5/15/2013	DATE:
LH	ONE TIME		FOUND P/C/W		TIME: 9460.6	TIME:
7/19/1983					LD/CY: 8519	LD/CY:
SB 73-3067	R3	REWORK FUEL CONTROL P/N 3070800-8 TO P/N 3070800-11 OR P/N 3070800-11 TO P/N 3070800-8	GARRETT	Recommended	DATE: 5/15/2013	DATE:
LH	ONE TIME		FOUND P/C/W		TIME: 9460.6	TIME:
2/24/1995					LD/CY: 8519	LD/CY:
SB 73-3075	R6	ENGINE FUEL & CONTROL - REPLACE FUEL PUMP DIFFERENTIAL PRESSURE INDICATOR: INCORP. A DIAPHRAGM OPERATED PISTON	GARRETT	Recommended	DATE: 5/15/2013	DATE:
LH	ONE TIME		FOUND P/C/W		TIME: 9460.6	TIME:
6/13/2003					LD/CY: 8519	LD/CY:

**LEFT ENGINE SERVICE BULLETINS
GARRETT P84484**

**4/25/2024
N2787**

DIRECTIVE NUMBER	REVISION	DESCRIPTION	VENDER	COMPLIANCE	NEXT DUE
LOCATION	RECURRS		METHOD		
EFFECTIVE DATE					
SB 73-3078		ENGINE FUEL & CONTROL - INSTALLATION OF FUEL PUMP UPDATE RECORD PLATE: PROVIDES BETTER RECORD OF PRODUCT IMPROVEMENT	GARRETT Optional	DATE: 5/15/2013 TIME: 9460.6 LD/CY: 8519	DATE: TIME: LD/CY:
LH	ONE TIME		FOUND P/C/W		
5/08/1984					
SB 73-3083	R1	ENGINE - FUEL AND CONTROL - REPLACE FUEL PUMP ANTI-ICING VALVE WITH UNIT CONTAINING AN IMPROVED THERMOSTAT	GARRETT Recommended	DATE: 5/15/2013 TIME: 9460.6 LD/CY: 8519	DATE: TIME: LD/CY:
LH	ONE TIME		NOT APPLICABLE		
10/20/1989					
SB 73-3107	R4	INSTALL SUPPORT CLAMP, P/N 211-501-9114, ON FUEL LINE, P/N 3071051-1	GARRETT Recommended	DATE: 5/15/2013 TIME: 9460.6 LD/CY: 8519	DATE: TIME: LD/CY:
LH	ONE TIME		FOUND P/C/W		
4/20/1994					
SB 73-3108	R1	ENGINE FUEL AND CONTROL - DISTRIBUTION INSTALL FUEL CONTROL P3 SENSE LINE, GASKET, P/N 3075481-1	GARRETT Recommended	DATE: 5/15/2013 TIME: 9460.6 LD/CY: 8519	DATE: TIME: LD/CY:
LH	ONE TIME		FOUND P/C/W		
10/09/1995					
SB 73-3109	R1	ENGINE FUEL & CONTROL-DISTRIBUTION-MAIN-TENANCE OF ENGINES WITH SERVICE TUBE CLAMPS P/N 3073542-1 & 3073543-91 INSTLD	GARRETT Recommended	DATE: 5/15/2013 TIME: 9460.6 LD/CY: 8519	DATE: TIME: LD/CY:
LH	ONE TIME		COMPLIED WITH		
3/12/1993					
SB 73-3110	R1	ENG FUEL & CONTROL - DIST.-REPLACE SEC-ONDARY FLEXIBLE HOSE ASSY (AS REQUIRED) ON SPEC IDENTIFIED FUEL MANIFOLD ASSYS	GARRETT Recommended	DATE: 5/15/2013 TIME: 9460.6 LD/CY: 8519	DATE: TIME: LD/CY:
LH	ONE TIME		NOT APPLICABLE		
4/03/1992					
SB 73-3112		ENG FUEL & CONT-CONTROLLING-INSP & REPL IDENT FUEL CONT VAR RESIS (PWR LEV POT) AS REQ AT COMPONENT OVHL/REPAIR FACILITY	GARRETT Recommended	DATE: 5/15/2013 TIME: 9460.6 LD/CY: 8519	DATE: TIME: LD/CY:
LH	ONE TIME		FOUND P/C/W		
2/14/1992					
SB 73-3113		ENGINE FUEL AND CONTROL - DISTRIBUTION - REPLACE FUEL HEATER OUTLET ADAPTER AND OIL TRANSFER TUBE	GARRETT Recommended	DATE: 5/15/2013 TIME: 9460.6 LD/CY: 8519	DATE: TIME: LD/CY:
LH	ONE TIME		FOUND P/C/W		
3/10/1992					
SB 73-3114		FUEL AND CONTROL-CONTROLLING-REPLACE METERING VALVE ADJUSTMENT SHAFT AND THREADED RESTRICTOR AT COMPONENT O/H	GARRETT Recommended	DATE: 5/15/2013 TIME: 9460.6 LD/CY: 8519	DATE: TIME: LD/CY:
LH	ONE TIME		FOUND P/C/W		
5/29/1992					
SB 73-3115	R1	INSTALL AN IMPROVED FUEL CONTROL INCORPORATING A MINIMUM MOD CONFIGURATION STANDARD	GARRETT Recommended	DATE: 5/15/2013 TIME: 9460.6 LD/CY: 8519	DATE: TIME: LD/CY:
LH	ONE TIME		FOUND P/C/W		
3/18/1994					
SB 73-3119		CONTROLLING - REPLACE/REWORK GOVERNOR FLYWEIGHT ASSEMBLY AT COMPONENT REPAIR FACILITY	GARRETT Recommended	DATE: 5/15/2013 TIME: 9460.6 LD/CY: 8519	DATE: TIME: LD/CY:
LH	ONE TIME		FOUND P/C/W		
5/07/1993					
SB 73-3120		REPLACE / REWORK FUEL MANIFOLD ASSY	GARRETT Recommended	DATE: 5/15/2013 TIME: 9460.6 LD/CY: 8519	DATE: TIME: LD/CY:
LH	ONE TIME		NOT APPLICABLE		
SB 73-3121		DISTRIBUTION -REPLACE SECONDARY FLEXIBLE HOSE ASSY (AS REQUIRED) ON SPECIFIC IDENTIFIED FUEL MANIFOLD ASSEMBLIES	GARRETT Recommended	DATE: 5/15/2013 TIME: 9460.6 LD/CY: 8519	DATE: TIME: LD/CY:
LH	ONE TIME		FOUND P/C/W		
11/03/1993					
SB 73-3131	R2	ONE TIME INSPECTION FOR SPECIFIC ID FUEL CONTROL COMPRESSOR DISCHARGE SENSOR BELLOWS P/N 3074139-2	GARRETT Recommended	DATE: 5/15/2013 TIME: 9460.6 LD/CY: 8519	DATE: TIME: LD/CY:
LH	ONE TIME		FOUND P/C/W		
6/16/2004					

**LEFT ENGINE SERVICE BULLETINS
GARRETT P84484**

**4/25/2024
N2787**

DIRECTIVE NUMBER	REVISION	DESCRIPTION	VENDER	COMPLIANCE	NEXT DUE
LOCATION	RECURRS		METHOD		
EFFECTIVE DATE					
SB 73-3134	R2	REPLACE SPECIFIC IDENTIFIED FUEL CONTROL ASSEMBLIES HAVING SUSPECT TORQUE MOTORS	GARRETT	DATE: 5/15/2013 TIME: 9460.6 LD/CY: 8519	DATE: TIME: LD/CY:
LH	ONE TIME		NOT APPLICABLE		
4/30/1999					
SB 73-3135		DISTRIBUTION-INSPECT/REPLACE FLEX TUBE ASSY, P/N 3074376-1 (399-5500-0003) OR 3074376-2 (AS APPLICABLE)	GARRETT	DATE: 5/15/2013 TIME: 9460.6 LD/CY: 8519	DATE: TIME: LD/CY:
LH	ONE TIME		FOUND P/C/W		
8/17/2000					
SB 73-3136	R3	DISTRIBUTION-INCORP. IMPROVED PRIMARY & SECONDARY MANIFOLD FUEL FEEDER TUBE ASSEMBLIES	GARRETT	DATE: 5/15/2013 TIME: 9460.6 LD/CY: 8519	DATE: TIME: LD/CY:
LH	ONE TIME		Optional FOUND P/C/W		
9/10/2002					
SB 73-3137		REPLACE THE FUEL HEATER CHECK VALVE, P/N 3073932-5 WITH P/N 3073932-6 AND CONNECTING METAL TUBE ASSEMBLIES	GARRETT	DATE: 5/15/2013 TIME: 9460.6 LD/CY: 8519	DATE: TIME: LD/CY:
LH	ONE TIME		Recommended NOT APPLICABLE		
11/03/2000					
SB 73-3142		REPLACE SPECIFIC IDENTIFIED FUEL CONTROL ASSYS HAVING A SUSPECT OVERSPEED AND/OR MANUAL MODE SOLENOID VALVE INSTALLED	GARRETT	DATE: 5/15/2013 TIME: 9460.6 LD/CY: 8519	DATE: TIME: LD/CY:
LH	ONE TIME		Recommended NOT APPLICABLE		
10/07/2002					
SB 73-3147		REPLACE SPECIFIC IDENTIFIED MAIN TURBINE ENGINE FUEL CONTROLS WITH A SUSPECT OVER SPEED GOVERNOR ASSEMBLY INSTALLED	GARRETT	DATE: 5/15/2013 TIME: 9460.6 LD/CY: 8519	DATE: TIME: LD/CY:
LH	ONE TIME		NOT APPLICABLE		
3/29/2005					
SB 73-3149		CONTROLLING - REPLACE MAIN TURBINE ENGINE FUEL PUMP FUEL FILTER ELEMENT WITH FUEL FILTER ELEMENT,P/N 897830-1	GARRETT	DATE: 5/15/2013 TIME: 9460.6 LD/CY: 8519	DATE: TIME: LD/CY:
LH	ONE TIME		Recommended FOUND P/C/W		
9/12/2005					
SB 74-3003	R5	ENGINE - INSTALL IGNITION UNIT WITH REDUNDANT FIRING CIRCUITS: ALLOWS EACH IGNITOR PLUG TO FIRE ASYNCHRONOUSLY	GARRETT	DATE: 5/15/2013 TIME: 9460.6 LD/CY: 8519	DATE: TIME: LD/CY:
LH	ONE TIME		Optional FOUND P/C/W		
9/21/2001					
SB 74-3006	R1	IGNITION - GENERAL - INSTALL IGNITION IGNITOR PLUG P/N 3074541-1	GARRETT	DATE: 5/15/2013 TIME: 9460.6 LD/CY: 8519	DATE: TIME: LD/CY:
LH	ONE TIME		Optional FOUND P/C/W		
4/20/1990					
SB 74-3007	R1	GENERAL - INSPECT IRIIDIUM IGNITER PLUGS, P/N 3074541-1 (CHAMPION CH31815) FOR LOOSE CENTER FIRING TIP ELECTRODE	GARRETT	DATE: 5/15/2013 TIME: 9460.6 LD/CY: 8519	DATE: TIME: LD/CY:
LH	ONE TIME		Recommended FOUND P/C/W		
11/11/1993					
SB 76-3014		ENGINE - CONTROL - CONVERSION OF ELECTRONIC COMPUTER P/N 2101144-1 TO P/N 2101144-2 BY ADJUSTING ITT LIMITER	GARRETT	DATE: 5/15/2013 TIME: 9460.6 LD/CY: 8519	DATE: TIME: LD/CY:
LH	ONE TIME		Recommended NOT APPLICABLE		
8/09/1979					
SB 76-3017		ENGINE - CONTROLS - ONE TIME INSPECTION OF ELECTRONIC COMPUTER P/N 2101144-1/-2	GARRETT	DATE: 5/15/2013 TIME: 9460.6 LD/CY: 8519	DATE: TIME: LD/CY:
LH	ONE TIME		Recommended NOT APPLICABLE		
4/17/1980					
SB 76-3018	R1	ENGINE - CONTROLS - INSTALL COMPUTER ASSEMBLY P/N 2101144-5: IMPROVED FEATURES	GARRETT	DATE: 5/15/2013 TIME: 9460.6 LD/CY: 8519	DATE: TIME: LD/CY:
LH	ONE TIME		Recommended NOT APPLICABLE		
9/23/1982					
SB 76-3022		ENGINE CONTROLS - POWER CONTROL - INSP AND, IF REQUIRED, REPLACE CAPACITORS ON A9 AND A10 POWER SUPPLY BOARD	GARRETT	DATE: 5/15/2013 TIME: 9460.6 LD/CY: 8519	DATE: TIME: LD/CY:
LH	ONE TIME		Recommended NOT APPLICABLE		
6/01/1982					

**LEFT ENGINE SERVICE BULLETINS
GARRETT P84484**

4/25/2024

N2787

DIRECTIVE NUMBER	REVISION	DESCRIPTION	VENDER	COMPLIANCE	NEXT DUE	
LOCATION	RECURRS		METHOD			
EFFECTIVE DATE						
SB 76-3038	R1	ENGINE POWER CONTROLS - REWORK	GARRETT	Recommended	DATE: 5/15/2013	DATE:
LH		P/N 2101144-5, SERIES 1 TO SERIES 3:			TIME: 9460.6	TIME:
8/01/1983	ONE TIME	IMPROVES UNIT	NOT APPLICABLE		LD/CY: 8519	LD/CY:
SB 76-3054	R1	ENGINE CONTROLS - POWER CONTROL	GARRETT	Recommended	DATE: 5/15/2013	DATE:
LH		INSTALL SURGE CONTROL GASKET, P/N			TIME: 9460.6	TIME:
10/06/1995	ONE TIME	3075481-1/-3.	FOUND P/C/W		LD/CY: 8519	LD/CY:
SB 76-3067	R19	POWER CONTROL - INSTALL DIGITAL	GARRETT	Optional	DATE: 5/15/2013	DATE:
LH		ELECTRONIC ENGINE CONTROL (N1 DEEC)			TIME: 9460.6	TIME:
12/05/2005	ONE TIME		FOUND P/C/W		LD/CY: 8519	LD/CY:
SB 76-3073	R1	POWER CONTROL - REWORK N1 DIGITAL	GARRETT	Optional	DATE: 5/15/2013	DATE:
LH		ELECTRONIC ENGINE CONTROL (DEEC), P/N			TIME: 9460.6	TIME:
6/27/2002	ONE TIME	2119020-3 TO P/N 2119020-3001	FOUND P/C/W		LD/CY: 8519	LD/CY:
SB 76-3075		REPLACE SPECIFIC ID N1 DEEC	GARRETT		DATE: 5/15/2013	DATE:
LH					TIME: 9460.6	TIME:
	ONE TIME		NOT APPLICABLE		LD/CY: 8519	LD/CY:
SB 77-3001	R1	N1 MOTIONAL PICKUP- INSTALL N1 TRANSDUCR	GARRETT	Recommended	DATE: 5/15/2013	DATE:
LH		WITH CHANGE IN DESIGN & FUNCT REQUIREMNT			TIME: 9460.6	TIME:
7/05/1979	ONE TIME	NEW WELD TECHNIQUE TO PREVENT POROSITY	FOUND P/C/W		LD/CY: 8519	LD/CY:
SB 77-3002	R2	ENGINE - N2 MOTIONAL PICKUP - INSTALL N2	GARRETT	Recommended	DATE: 5/15/2013	DATE:
LH		TRANSDUCER INCORPORATING IMPROVED			TIME: 9460.6	TIME:
5/18/1981	ONE TIME	SEALANT	FOUND P/C/W		LD/CY: 8519	LD/CY:
SB 77-3007FE		ENGINE - N2 MOTIONAL PICKUP -	GARRETT	Optional	DATE: 5/15/2013	DATE:
LH		INSTALLATION OF N2 TRANSDUCER FOR FIELD			TIME: 9460.6	TIME:
9/03/1981	ONE TIME	EVALUATION	FOUND P/C/W		LD/CY: 8519	LD/CY:
SB 77-3008		ENGINE - REPLACE THERMOCOUPLE HARNESS	GARRETT	Optional	DATE: 5/15/2013	DATE:
LH		MOUNTING BOLTS: MADE OF IMPROVED MATERIA			TIME: 9460.6	TIME:
12/01/1981	ONE TIME	TO PREVENT BREAKAGE DURING REMOVAL	FOUND P/C/W		LD/CY: 8519	LD/CY:
SB 77-3019	R2	ENGINE INDICATING - TEMPERATURE -	GARRETT	Recommended	DATE: 5/15/2013	DATE:
LH		INSTALL THERMOCLOUPLE HARNESS, P/N			TIME: 9460.6	TIME:
6/19/1990	ONE TIME	3073595-1	FOUND P/C/W		LD/CY: 8519	LD/CY:
SB 79-3025	R4	ENGINE - REPLACE OR REWORK OIL LUBRICATE	GARRETT	Recommended	DATE: 5/15/2013	DATE:
LH		NOZZLE: PROVIDES FOR INSTALLATION OF			TIME: 9460.6	TIME:
11/11/2002	ONE TIME	LOCKING WASHERS TO PREVENT BOLTS LOOSEN	COMPLIED WITH		LD/CY: 8519	LD/CY:
SB 79-3031	R1	OIL - DISTRIBUTION - REPLACE/REWORK #6	GARRETT	Recommended	DATE: 5/15/2013	DATE:
LH		BEARING LUBRICATION TUBE ASSY P/N			TIME: 9460.6	TIME:
7/21/1983	ONE TIME	3071841-3 TO -4: ELIMINATES TUBE CORROS	NOT APPLICABLE		LD/CY: 8519	LD/CY:
SB 79-3032	R2	OIL - REWORK/REPLACE #6 BEARING LUBRICAT	GARRETT	Recommended	DATE: 5/15/2013	DATE:
LH		TUBE ASSY P/N 3073418-1 TO 3073418-2			TIME: 9460.6	TIME:
12/22/1989	ONE TIME	ELIMINATES SOURCE OF TUBE CORROSION	FOUND P/C/W		LD/CY: 8519	LD/CY:
SB 79-3034	R3	OIL - REPLACEMENT/REWORK OF PLUG (CHIP	GARRETT	Recommended	DATE: 5/15/2013	DATE:
LH		DETECTOR): VALVE HOUSING MADE OF STEEL			TIME: 9460.6	TIME:
1/28/2000	ONE TIME	TO REDUCE POSSIBILITY OF CRACKING	FOUND P/C/W		LD/CY: 8519	LD/CY:

**LEFT ENGINE SERVICE BULLETINS
GARRETT P84484**

**4/25/2024
N2787**

DIRECTIVE NUMBER	REVISION	DESCRIPTION	VENDER	COMPLIANCE	NEXT DUE
LOCATION	RECURRS		METHOD		
EFFECTIVE DATE					
SB 79-3051 LH 2/18/1994	ONE TIME	OIL-DISTRIBUTION-INSTALL METAL GASKET, P/N 3075481-2	GARRETT FOUND P/C/W	Optional DATE: 5/15/2013 TIME: 9460.6 LD/CY: 8519	DATE: TIME: LD/CY:
SB 79-3053 LH 4/01/1994	ONE TIME	OIL-DISTRIBUTION-REPLACE REAR TURBINE BEARING OIL-OUT TUBE AND GASKET	GARRETT COMPLIED WITH	Optional DATE: 5/15/2013 TIME: 9460.6 LD/CY: 8519	DATE: TIME: LD/CY:
SB 79-3054 LH 7/29/1997	R1 ONE TIME	OIL-DISTRIBUTION-INSTALL/REWORK OIL LUBE & SCAVENGE PUMP (OIL PUMP) THAT INCORP. AN IMPROVED REGULATOR SECTION	GARRETT FOUND P/C/W	Optional DATE: 5/15/2013 TIME: 9460.6 LD/CY: 8519	DATE: TIME: LD/CY:
SB 79-3055 LH 3/30/1995	R2 ONE TIME	REPLACE SEAL P/N 3020052-5/-16/-21 WITH P/N 3020052-24, IN AIR BREATHER VALVE ASSY P/N 3072119-1	GARRETT NOT APPLICABLE	Optional DATE: 5/15/2013 TIME: 9460.6 LD/CY: 8519	DATE: TIME: LD/CY:
SB 79-3058 LH 12/12/2001	R1 ONE TIME	OIL - DISTRIBUTION - INSTALL OIL JET STRAINER, P/N 891764-11 INACTIVE	GARRETT NOT APPLICABLE	DATE: 5/15/2013 TIME: 9460.6 LD/CY: 8519	DATE: TIME: LD/CY:
SB 79-3059 LH 11/01/1996	R1 ONE TIME	OIL - DISTRIBUTION - INSTALL/REWORK OIL LUBE AND SCAVENGE PUMP WITH IMPROVED SCAVENGE CAPABILITIES	GARRETT FOUND P/C/W	Recommended DATE: 5/15/2013 TIME: 9460.6 LD/CY: 8519	DATE: TIME: LD/CY:
SB 79-3062 LH 6/19/1998	ONE TIME	OIL-DISTRIBUTION-REPLACE DE-OIL VALVE (CHECK VALVE), P/N 3074372-1 WITH P/N 3074372-2	GARRETT NOT APPLICABLE	DATE: 5/15/2013 TIME: 9460.6 LD/CY: 8519	DATE: TIME: LD/CY:
SB 79-3066 LH 4/12/2012	R2 ONE TIME	INSTALL LUBE WITH REGULATOR AND SCAVENGE PUMP (OIL LUBE PUMP), P/N 3060785-2	GARRETT COMPLIED WITH	Recommended DATE: 5/15/2013 TIME: 9460.6 LD/CY: 8519	DATE: TIME: LD/CY:
SB 79-3070 LH 5/09/2018	R2 ONE TIME	INSTALL IMPROVED OIL TANK INSTRUCTION PLATE TO PREVENT OIL TANK OVERSERVICING	GARRETT COMPLIED WITH	Recommended DATE: 5/15/2013 TIME: 9460.6 LD/CY: 8519	DATE: TIME: LD/CY:
SB A72-3328 LH 5/31/1995	R5 ONE TIME	REPLACEMENT OF FAN ROTOR DISC, P/N 3072162-ALL, OR 3073436-ALL WITH MORE THAN 4000 OPERATING CYCLES	GARRETT N/A BY PART NUMBER INSTALLED	Recommended DATE: 7/31/1997 TIME: 5958.7 LD/CY: 5388	DATE: TIME: LD/CY:
SB A72-3432 LH 5/31/1995	R5 ONE TIME	INSPECTION OF FAN ROTOR ASSY P/N 3072162-ALL/3073436-ALL/3073539-ALL OR 3074529-ALL	GARRETT N/A BY PART NUMBER INSTALLED	Recommended DATE: 7/31/1997 TIME: 5958.7 LD/CY: 5388	DATE: TIME: LD/CY:
SB A72-3557 LH 5/12/1994	ONE TIME	TURBINE SECTION-REPLACEMENT OF SPECIFIC SERIAL NO. FIRST & SECOND LP TURBINE DISCS WITH SUSPECT MATERIAL PROPERTIES	GARRETT N/A BY PART NUMBER INSTALLED	Mandatory DATE: 7/31/1997 TIME: 5958.7 LD/CY: 5388	DATE: TIME: LD/CY:
SB A72-3578 LH 5/23/2007	ONE TIME	ENGINE-BYPASS SECTION-INSPECT SPECIFIC S/N FAN ROTOR DISCS INACTIVE FOR FURTHER ACCOMPLISHMENT	GARRETT N/A BY PART NUMBER INSTALLED	DATE: 7/31/1997 TIME: 5958.7 LD/CY: 5388	DATE: TIME: LD/CY:
SB A72-3641 LH 7/06/2010	RECURRS	PERFORM EDDY CURRENT INSPECTION OF HP IMPELLER P/N 3073393-1,3073394-1, 3073433-1,3073434-1,3073398-ALL	GARRETT C/W	Recommended DATE: 12/14/2000 TIME: 7400.2 LD/CY: 6414	DATE: TIME: LD/CY: 11600.2

**LEFT ENGINE SERVICE BULLETINS
GARRETT P84484**

4/25/2024
N2787

DIRECTIVE NUMBER	REVISION	DESCRIPTION	VENDER	COMPLIANCE	NEXT DUE
LOCATION	RECURRS		METHOD		
SB A73-3128		DISTRIBUTION-INSTALL FLEX TUBE ASSY	GARRETT	DATE: 7/31/1997	DATE:
LH		P/N 399-5500-0003 OR 3074376-1		TIME: 5958.7	TIME:
8/17/2000	ONE TIME		COMPLIED WITH	LD/CY: 5388	LD/CY:

**RIGHT ENGINE SERVICE BULLETINS
GARRETT P84497**

**4/25/2024
N2787**

DIRECTIVE NUMBER	REVISION	DESCRIPTION	VENDER	COMPLIANCE	NEXT DUE
LOCATION	RECURRS		METHOD		
EFFECTIVE DATE					
SB 72-3001 RH 6/29/2011	R56 ONE TIME	ENGINE - SERVICE LIFE - SERVICE LIFE LIMITS OF CRITICAL LIFE LIMITED COMPONENTS	GARRETT N/A BY MOD STATUS	Mandatory 	DATE: 6/04/2013 TIME: 9607.1 LD/CY: 8517 DATE: TIME: LD/CY:
SB 72-3042 RH 12/12/2001	R8 ONE TIME	REPLACE COMBUSTION LINER P/N 3072448-4 WITH IMPROVED COMBUSTION LINER INACTIVE	GARRETT FOUND P/C/W	Optional 	DATE: 6/04/2013 TIME: 9607.1 LD/CY: 8517 DATE: TIME: LD/CY:
SB 72-3053 RH 10/13/1982	R3 ONE TIME	ENGINE - LOW PRESSURE TURBINE ROTOR ASSY INSTALL IMPROVED LP THIRD STAGE TURBINE BLADE, P/N 3072014-2	GARRETT FOUND P/C/W	Optional 	DATE: 6/04/2013 TIME: 9607.1 LD/CY: 8517 DATE: TIME: LD/CY:
SB 72-3057 RH 7/12/1979	R2 ONE TIME	ENGINE - LOW PRESSURE TURBINE ASSEMBLY - INSTALL IMPROVED LOW PRESSURE TURBINE ROTATING SEAL	GARRETT FOUND P/C/W	Recommended 	DATE: 6/04/2013 TIME: 9607.1 LD/CY: 8517 DATE: TIME: LD/CY:
SB 72-3078 RH 5/30/1986	R1 ONE TIME	POWER SECTION - INSTALL NEW BOLTS WITH LOCKWIRE FEATURE THAT ATTACH TRANSFER TUBES TO INTERMEDIATE CASE ASSEMBLY	GARRETT FOUND P/C/W	Recommended 	DATE: 6/04/2013 TIME: 9607.1 LD/CY: 8517 DATE: TIME: LD/CY:
SB 72-3085 RH 9/10/1985	R11 ONE TIME	ENGINE - FAN SPINNER - REPLACE FAN SPINNER & RELATED ANTI-ICE COMPONENTS: REDUCES ODOR & SMOKE IN ACFT CABIN	GARRETT FOUND P/C/W	Recommended 	DATE: 6/04/2013 TIME: 9607.1 LD/CY: 8517 DATE: TIME: LD/CY:
SB 72-3086 RH 12/12/2001	R3 ONE TIME	INTERSTAGE & HP TURBINE ROTOR INSTALL 1ST STG TURBINE NOZZLE ASSY REPLACEMENT OF P/N 3072319-1 W/3072319-4 INACTIVE	GARRETT FOUND P/C/W	Recommended 	DATE: 6/04/2013 TIME: 9607.1 LD/CY: 8517 DATE: TIME: LD/CY:
SB 72-3087 RH 1/31/1984	R1 ONE TIME	ENGINE - LOW PRESSURE TURBINE ASSEMBLY - INCORPORATE REPLACEMENT TIE SHAFT: IMPRV COOLING AIR FLOW TO LP TURBINE ASSEMBLY	GARRETT FOUND P/C/W	Recommended 	DATE: 6/04/2013 TIME: 9607.1 LD/CY: 8517 DATE: TIME: LD/CY:
SB 72-3096 RH 1/31/1984	R1 ONE TIME	ENGINE - LOW PRESSURE TURBINE ASSEMBLY - INCORPORATE REPLACEMENT LP SHAFT & SEAL ASSY TO IMPROVE COOLING AIR FLOW	GARRETT FOUND P/C/W	Recommended 	DATE: 6/04/2013 TIME: 9607.1 LD/CY: 8517 DATE: TIME: LD/CY:
SB 72-3106 RH 4/30/1991	 ONE TIME	ENGINE - INSPECTION INTERVALS - ESTABLISHING PERIODIC INSPECTION INTERVALS	GARRETT FOUND P/C/W	Mandatory 	DATE: 6/04/2013 TIME: 9607.1 LD/CY: 8517 DATE: TIME: LD/CY:
SB 72-3113 RH 8/29/1979	 ONE TIME	ENGINE- SUPPORT HOUSING- REPLACE SUPPORT HOUSING: TO PROVIDE TRACEABILITY FOR CHANGES IN THE MANUFACTUR PROCESS	GARRETT FOUND P/C/W	Optional 	DATE: 6/04/2013 TIME: 9607.1 LD/CY: 8517 DATE: TIME: LD/CY:
SB 72-3119 RH 3/27/1980	 ONE TIME	ENGINE - TURBINE SECTION - DECREASE TURBINE END SHAFT STRETCH DIMENSION ON LOW PRESSURE TIE ROD	GARRETT FOUND P/C/W	Recommended 	DATE: 6/04/2013 TIME: 9607.1 LD/CY: 8517 DATE: TIME: LD/CY:
SB 72-3124 RH 6/24/1996	R8 ONE TIME	ACCESSORY DRIVES - MODIFY STARTER/GEN DRIVE SPUR GEARSHAFT:REPLACE OF GEARSHAF SPLINE ADAPTER ELIMINATES SPLINE WEAR	GARRETT FOUND P/C/W	Recommended 	DATE: 6/04/2013 TIME: 9607.1 LD/CY: 8517 DATE: TIME: LD/CY:
SB 72-3126 RH 9/22/1989	R13 ONE TIME	ENGINE- PLANET GEAR INSTALLATION-REPLACE /REWORK PLANET GEARSHAFT ASSY: USES OPTIMIZED DIAMETER & BALANCE CLAMP NUTS	GARRETT FOUND P/C/W	Recommended 	DATE: 6/04/2013 TIME: 9607.1 LD/CY: 8517 DATE: TIME: LD/CY:

**RIGHT ENGINE SERVICE BULLETINS
GARRETT P84497**

**4/25/2024
N2787**

DIRECTIVE NUMBER	REVISION	DESCRIPTION	VENDER	COMPLIANCE	NEXT DUE	
LOCATION	RECURRS		METHOD			
EFFECTIVE DATE						
SB 72-3128	R9	ACCESSORY DRIVES - MODIFY ALTERNATOR DRIVE SPUR GEARSHAFT	GARRETT	Recommended	DATE: 6/04/2013 TIME: 9607.1 LD/CY: 8517	DATE: TIME: LD/CY:
RH	ONE TIME		FOUND P/C/W			
2/18/2003						
SB 72-3129	R7	ENGINE - TRANSFER GEARBOX TUBE INSTALLATION - INCORPORATE IMPROVED BREATHER SYSTEM FOR NO. 4 AND 5 BEARING	GARRETT	Optional	DATE: 6/04/2013 TIME: 9607.1 LD/CY: 8517	DATE: TIME: LD/CY:
RH	ONE TIME		FOUND P/C/W			
3/21/1986						
SB 72-3133	R1	ENGINE - FAN BYPASS STATOR INSTALLATION INSPECT AND REPLACE FAN BYPASS STATOR ALIGNMENT PINS	GARRETT	Recommended	DATE: 6/04/2013 TIME: 9607.1 LD/CY: 8517	DATE: TIME: LD/CY:
RH	ONE TIME		FOUND P/C/W			
5/04/1981						
SB 72-3136	R1	ENGINE- ACCESSORY DRIVE GEARBOX- REPLACE ANNULAR BALL BEARINGS, P/N 358206: TO PREVENT ROTATION OF THE INNER RACE	GARRETT	Optional	DATE: 6/04/2013 TIME: 9607.1 LD/CY: 8517	DATE: TIME: LD/CY:
RH	ONE TIME		FOUND P/C/W			
7/28/1980						
SB 72-3143	R1	ENGINE - CONICAL FAN SPINNER - REWORK CONICAL FAN SPINNER, P/N 3072867-1/-2 TO -3 OR P/N 3072867-4/-5 TO P/N 3072867-6	GARRETT	Optional	DATE: 6/04/2013 TIME: 9607.1 LD/CY: 8517	DATE: TIME: LD/CY:
RH	ONE TIME		FOUND P/C/W			
8/04/1981						
SB 72-3145	R2	ENGINE - CONICAL FAN SPINNER INTERNAL CORROSION PREVENTION	GARRETT	Recommended	DATE: 6/04/2013 TIME: 9607.1 LD/CY: 8517	DATE: TIME: LD/CY:
RH	ONE TIME		FOUND P/C/W			
5/25/1983						
SB 72-3159	R7	ENGINE - INSPECT AND/OR REPLACE TURBINE INTERSTAGE TRANSITION DUCT: WILL REVEAL INADEQUATE WELD PENETRATION	GARRETT	Recommended	DATE: 6/04/2013 TIME: 9607.1 LD/CY: 8517	DATE: TIME: LD/CY:
RH	ONE TIME		FOUND P/C/W			
1/08/1988						
SB 72-3164	R2	ENGINE - LOW PRESSURE COMPRESSOR ASSY - INTERCHANGE OF 4TH STAGE AXIAL FLOW COMPRESSOR ROTOR ASSY., PN 3071652-7,-9	GARRETT	Optional	DATE: 6/04/2013 TIME: 9607.1 LD/CY: 8517	DATE: TIME: LD/CY:
RH	ONE TIME		FOUND P/C/W			
8/19/1988						
SB 72-3167	R3	FAN SUPPORT SHAFT & HOUSING ASSY - REPLACE GASKET, P/N 3071968-1/-2 WITH SEAL PLATE, P/N 3073213-1 INACTIVE	GARRETT	Optional	DATE: 6/04/2013 TIME: 9607.1 LD/CY: 8517	DATE: TIME: LD/CY:
RH	ONE TIME		FOUND P/C/W			
9/12/2001						
SB 72-3169	R2	ENGINE - COMPRESSOR INSTALLATION - REPLACE IDENTIFIED HP ROTOR THRUST (NO. 5) BEARING	GARRETT	Recommended	DATE: 6/04/2013 TIME: 9607.1 LD/CY: 8517	DATE: TIME: LD/CY:
RH	ONE TIME		NOT APPLICABLE			
3/19/1982						
SB 72-3174	R7	ENGINE - COMPRESSOR INSTALLATION-INSTALL NEW OR REWORKED HIGH PRESSURE DIFFUSER: REDUCES EXCITATION LEVELS	GARRETT	Recommended	DATE: 6/04/2013 TIME: 9607.1 LD/CY: 8517	DATE: TIME: LD/CY:
RH	ONE TIME		FOUND P/C/W			
6/24/2010						
SB 72-3177	R1	ENGINE - COMBUSTION SECTION - REPLACE SHIPPING GASKET UNDER HIGH PRESSURE BLEED AIR PORT COVER	GARRETT	Recommended	DATE: 6/04/2013 TIME: 9607.1 LD/CY: 8517	DATE: TIME: LD/CY:
RH	ONE TIME		FOUND P/C/W			
7/08/1982						
SB 72-3190	R2	ENGINE - FAN SHAFT AND HOUSING ASSEMBLY - INSTALL REWORKED SPUR RING GEAR, P/N 3077000-1 OR 3077000-2	GARRETT		DATE: 6/04/2013 TIME: 9607.1 LD/CY: 8517	DATE: TIME: LD/CY:
RH	ONE TIME		FOUND P/C/W			
4/12/1982						
SB 72-3202	R7	ENGINE - FUEL - MODIFY ENGINE TO PERMIT USE OF JP-4 FUEL WITH THE AIRCRAFT FUEL SUPPLY SYSTEM	GARRETT		DATE: 6/04/2013 TIME: 9607.1 LD/CY: 8517	DATE: TIME: LD/CY:
RH	ONE TIME		FOUND P/C/W			
12/12/2001						

**RIGHT ENGINE SERVICE BULLETINS
GARRETT P84497**

**4/25/2024
N2787**

DIRECTIVE NUMBER	REVISION	DESCRIPTION	VENDER	COMPLIANCE	NEXT DUE
LOCATION	RECURRS		METHOD		
EFFECTIVE DATE					
SB 72-3208 RH 5/01/1989	R1 ONE TIME	ENGINE - COMPRESSOR INLET STATOR - REPLACE OR REWORK COMPRESSOR INLET STATOR, P/N 3072429-1 TO P/N 3072429-2	GARRETT FOUND P/C/W	Optional DATE: 6/04/2013 TIME: 9607.1 LD/CY: 8517	DATE: TIME: LD/CY:
SB 72-3224 RH 8/12/1982	ONE TIME	ENGINE - COMBUSTION SECTION - INSPECT COMBUSTION CHAMBER LINER, P/N 3072674-3 FOR DISTRESS IN REGION OF IGNITOR PLUGS	GARRETT FOUND P/C/W	Recommended DATE: 6/04/2013 TIME: 9607.1 LD/CY: 8517	DATE: TIME: LD/CY:
SB 72-3225 RH 4/19/1984	R1 ONE TIME	ENGINE - TURBINE SECTION - REMOVE FROM SERVICE ALL FIRST STAGE LP TURBINE BLADE P/N 3072311-2: LOT # IN SPEC ROTOR ASSY	GARRETT NOT APPLICABLE	Mandatory DATE: 6/04/2013 TIME: 9607.1 LD/CY: 8517	DATE: TIME: LD/CY:
SB 72-3227 RH 9/17/1982	ONE TIME	ENGINE - COMPRESSOR SECTION - REPLACE LP COMPRESSOR BEARING HOUSING: HAVE BEEN SUBJECT TO FRETTING, FATIGUE & FRACTURE	GARRETT FOUND P/C/W	Recommended DATE: 6/04/2013 TIME: 9607.1 LD/CY: 8517	DATE: TIME: LD/CY:
SB 72-3237 RH 12/15/1989	R3 ONE TIME	ENGINE - COMPRESSOR SECTION - INSTALL HP COMPRESSOR IMPELLER, P/N 3073393-1, 3073394-1 AND 3073398-1	GARRETT FOUND P/C/W	Mandatory DATE: 6/04/2013 TIME: 9607.1 LD/CY: 8517	DATE: TIME: LD/CY:
SB 72-3239RWK RH 12/10/1982	R3 ONE TIME	REWORK HP COMPRESSOR RADIAL IMPELLER, P/N 3070274-1, TO 3073393-1 OR 3072639-1 TO 3073394-1	GARRETT NOT APPLICABLE	DATE: 6/04/2013 TIME: 9607.1 LD/CY: 8517	DATE: TIME: LD/CY:
SB 72-3252 RH 7/19/1984	R2 ONE TIME	ENGINE - TURBINE SECTION - INSPECTION OF 2ND STAGE LP TURBINE DISK: INSUFFICIENT WEB THICKNESS RESULTS IN REDUCED LIFE	GARRETT NOT APPLICABLE	Mandatory DATE: 6/04/2013 TIME: 9607.1 LD/CY: 8517	DATE: TIME: LD/CY:
SB 72-3272 RH 12/12/2001	R4 ONE TIME	INSPECTION OF LP TURBINE ROTOR ASSEMBLY DISCS & REWORK OF 1ST STAGE LP TURBINE NOZZLE ASSY INACTIVE	GARRETT NOT APPLICABLE	Recommended DATE: 6/04/2013 TIME: 9607.1 LD/CY: 8517	DATE: TIME: LD/CY:
SB 72-3280 RH 3/14/1986	R1 ONE TIME	ENGINE - COMPRESSOR SECTION - REPLACE/REWORK COMPRESSOR INTERSTAGE DIFFUSER, P/N 3071722-1/-3/-5 WITH/TO -4	GARRETT FOUND P/C/W	Recommended DATE: 6/04/2013 TIME: 9607.1 LD/CY: 8517	DATE: TIME: LD/CY:
SB 72-3281 RH 2/07/1986	R1 ONE TIME	ENGINE - TURBINE SECTION - REPLACEMENT OF LP 1ST STAGE TURBINE DISCS/ROTOR ASSY : IMPROVED HEAT TREATMENT	GARRETT NOT APPLICABLE	Optional DATE: 6/04/2013 TIME: 9607.1 LD/CY: 8517	DATE: TIME: LD/CY:
SB 72-3283 RH 3/07/1986	R1 ONE TIME	ENGINE - TURBINE SECTION - REPLACEMENT OF LP 2ND STAGE TURBINE DISCS/ROTOR ASSY : IMPROVED HEAT TREATMENT	GARRETT NOT APPLICABLE	Optional DATE: 6/04/2013 TIME: 9607.1 LD/CY: 8517	DATE: TIME: LD/CY:
SB 72-3288 RH 9/11/1984	ONE TIME	ENGINE - MODIFICATION TO PROVIDE POSITIV RETENTION OF ENGINE NAMEPLATE	GARRETT FOUND P/C/W	Recommended DATE: 6/04/2013 TIME: 9607.1 LD/CY: 8517	DATE: TIME: LD/CY:
SB 72-3290 RH 2/18/1994	R3 ONE TIME	ACCESSORY DRIVE GEARBOX- INCORPORATE IMPROVE ALTERNATOR GEARSHAFT SEAL: IMPROVED SEALING THAT REDUCES OIL LEAK	GARRETT NOT APPLICABLE	Optional DATE: 6/04/2013 TIME: 9607.1 LD/CY: 8517	DATE: TIME: LD/CY:
SB 72-3293 RH 5/31/1985	R1 ONE TIME	ENGINE - ACCESSORY DRIVES - REPLACE SHIM P/N 3070379-1/-2/-3 WITH SHIM (INTERGRAL SEAL) P/N 3073493-1/-2/-3: STOP OIL LEAK	GARRETT FOUND P/C/W	Recommended DATE: 6/04/2013 TIME: 9607.1 LD/CY: 8517	DATE: TIME: LD/CY:

**RIGHT ENGINE SERVICE BULLETINS
GARRETT P84497**

**4/25/2024
N2787**

DIRECTIVE NUMBER	REVISION	DESCRIPTION	VENDER	COMPLIANCE	NEXT DUE
LOCATION	RECURRS		METHOD		
EFFECTIVE DATE					
SB 72-3298	R3	REPLACE/REWORK OUTER TRANSITION LINER	GARRETT	Recommended	DATE: 6/04/2013
RH		REPLACE P/N 3072327-2/-3/-4/-5/-6/-7 OR			TIME: 9607.1
12/12/2001	ONE TIME	REWORK -6/-7 INACTIVE	FOUND P/C/W		LD/CY: 8517
SB 72-3299	R3	REPLACE/REWORK SECOND STAGE LP TURBINE	GARRETT	Recommended	DATE: 6/04/2013
RH		NOZZLE, P/N 3072340-1 TO 3072340-4			TIME: 9607.1
9/13/1991	ONE TIME		FOUND P/C/W		LD/CY: 8517
SB 72-3306		ENGINE - TURBINE SECTION - REMOVE FROM	GARRETT	Recommended	DATE: 6/04/2013
RH		SERVICE 1ST STAGE LP TURBINE DISC			TIME: 9607.1
2/01/1985	ONE TIME	IDENTIFIED BY SN 2-18040-XXXX	FOUND P/C/W		LD/CY: 8517
SB 72-3309	R5	ENGINE - TURBINE SECTION - INSPECT AND/ OR REPAIR/REPLACE SPECIFIC IDENTIFIED	GARRETT	Recommended	DATE: 6/04/2013
RH		TURBINE INTERSTAGE TRANSITION DUCTS			TIME: 9607.1
10/20/2004	ONE TIME		NOT APPLICABLE		LD/CY: 8517
SB 72-3322	R1	ENGINE - PERMANENTLY PLUG COMPRESSOR	GARRETT	Recommended	DATE: 6/04/2013
RH		INTERSTAGE DIFFUSER BOROSCOPE PORT:			TIME: 9607.1
4/04/1986	ONE TIME	REPLACE SEALED PLUG TO STOP OIL LEAK	FOUND P/C/W		LD/CY: 8517
SB 72-3367	R3	ENGINE - TURBINE SECTION - PERFORM ONE	GARRETT	Recommended	DATE: 6/04/2013
RH		TIME INSPECTION OF NOZZLE THROAT (A5)			TIME: 9607.1
9/02/1994	ONE TIME	OPENING FOR PROPER DIMENSION	COMPLIED WITH		LD/CY: 8517
SB 72-3370	R1	ENGINE - TURBINE SECTION - INSPECT AND	GARRETT	Recommended	DATE: 6/04/2013
RH		REWORK TURBINE INTERSTAGE TRANSITION			TIME: 9607.1
6/15/1990	ONE TIME	DUCTS P/N 3071486-X,3072318-X,3072726-X	FOUND P/C/W		LD/CY: 8517
SB 72-3380		ENGINE - COMBUSTION SECTION - INSTALL	GARRETT	Recommended	DATE: 6/04/2013
RH		OUTER TRANSITION LINER WITH THERMAL			TIME: 9607.1
8/25/1989	ONE TIME	BARRIER COATING (TBC) APPLIED	FOUND P/C/W		LD/CY: 8517
SB 72-3384	R2	ENGINE - BY-PASS SECTION - REPLACE OIL	GARRETT	Optional	DATE: 6/04/2013
RH		DEFLECTOR OR REWORK EXISTING OIL			TIME: 9607.1
3/06/2001	ONE TIME	DEFLECTOR	FOUND P/C/W		LD/CY: 8517
SB 72-3393	R1	ENGINE - BY-PASS SECTION - REPLACE/ REWORK FAN SUPPORT SHAFT & HOUSING	GARRETT	Optional	DATE: 6/04/2013
RH		INACTIVE FOR FURTHER ACCOMPLISHMENT			TIME: 9607.1
12/17/2001	ONE TIME		NOT APPLICABLE		LD/CY: 8517
SB 72-3397	R4	ENGINE - INITIATE COMPONENT MAINTENANCE/ MODIFICATION RECORD CARD (CARD-LOG BOOK)	GARRETT	Mandatory	DATE: 6/04/2013
RH		(CMMC)			TIME: 9607.1
11/14/2012	ONE TIME		FOUND P/C/W		LD/CY: 8517
SB 72-3405	R4	REPLACE SHROUD RETAINING SLEEVE, P/N	GARRETT	Optional	DATE: 6/04/2013
RH		3070023-1 WITH P/N 3070023-3			TIME: 9607.1
11/26/2002	ONE TIME	OR 3070023-4	FOUND P/C/W		LD/CY: 8517
SB 72-3408		COMPRESSOR SECTION - REPLACE SPRING	GARRETT	Recommended	DATE: 6/04/2013
RH		TENSION WASHER, P/N 3000005-2/-56			TIME: 9607.1
2/19/1990	ONE TIME	WITH P/N 3000005-64	FOUND P/C/W		LD/CY: 8517
SB 72-3409	R1	COMPRESSOR SECTION - INSTALL FIRST STAGE	GARRETT	Recommended	DATE: 6/04/2013
RH		COMPRESSOR WHEEL ASSEMBLY BLADE			TIME: 9607.1
8/10/1990	ONE TIME	P/N 3075358-1	FOUND P/C/W		LD/CY: 8517

**RIGHT ENGINE SERVICE BULLETINS
GARRETT P84497**

**4/25/2024
N2787**

DIRECTIVE NUMBER	REVISION	DESCRIPTION	VENDER	COMPLIANCE	NEXT DUE
LOCATION	RECURRS		METHOD		
EFFECTIVE DATE					
SB 72-3410 RH 8/10/1990	R1 ONE TIME	COMPRESSOR SECTION - INSTALL SECOND STAGE COMPRESSOR ROTOR ASSEMBLY BLADE RETAINER, P/N 3075357-2	GARRETT FOUND P/C/W	Recommended DATE: 6/04/2013 TIME: 9607.1 LD/CY: 8517	DATE: TIME: LD/CY:
SB 72-3411 RH 8/10/1990	R1 ONE TIME	COMPRESSOR SECTION - INSTALL THIRD STAGE COMPRESSOR ROTOR ASSEMBLY BLADE RETAINER, P/N 3075357-3	GARRETT FOUND P/C/W	Recommended DATE: 6/04/2013 TIME: 9607.1 LD/CY: 8517	DATE: TIME: LD/CY:
SB 72-3416 RH 1/22/2001	R6 ONE TIME	HP IMPELLER SHROUD WITH IMPROVED COATING	GARRETT FOUND P/C/W	Recommended DATE: 6/04/2013 TIME: 9607.1 LD/CY: 8517	DATE: TIME: LD/CY:
SB 72-3421 RH 5/24/1991	ONE TIME	ENGINE - COMPRESSOR SECTION - INSTALL LP COMPRESSOR BEARING HOUSING, P/N 3071691-7 OR 3077043-3	GARRETT FOUND P/C/W	Recommended DATE: 6/04/2013 TIME: 9607.1 LD/CY: 8517	DATE: TIME: LD/CY:
SB 72-3422 RH 1/03/1991	ONE TIME	INSPECTION OF THE PINION GEAR RETAINER PLATE ASSEMBLY	GARRETT NOT APPLICABLE	Recommended DATE: 6/04/2013 TIME: 9607.1 LD/CY: 8517	DATE: TIME: LD/CY:
SB 72-3424 RH 12/20/1990	ONE TIME	BY-PASS SECTION - REPLACEMENT OF FAN ROTOR ASSY WITH SPECIFIC S/N DISC & HUB MADE FROM THE SAME MATERIAL HEAT CODE	GARRETT NOT APPLICABLE	Recommended DATE: 6/04/2013 TIME: 9607.1 LD/CY: 8517	DATE: TIME: LD/CY:
SB 72-3426 RH 5/08/1996	R2 ONE TIME	ENG.-TURBINE SECTION-REPLACE/REWORK 3RD STAGE LP TURBINE NOZZLE, P/N 3072342-2 TO 3072342-4 OR 3070014-3 TO 3070014-5	GARRETT FOUND P/C/W	Recommended DATE: 6/04/2013 TIME: 9607.1 LD/CY: 8517	DATE: TIME: LD/CY:
SB 72-3427 RH 5/01/1992	R1 ONE TIME	COMPRESSOR SECTION - INSTALL HP COMPRESSOR DIFFUSER INCORPORATING A HONEYCOMB SEAL & AN IMPROVED SURFACE FINISH	GARRETT COMPLIED WITH	Recommended DATE: 6/04/2013 TIME: 9607.1 LD/CY: 8517	DATE: TIME: LD/CY:
SB 72-3429 RH 4/03/1992	R1 ONE TIME	COMPRESSOR SECTION - REPLACE TIE BOLT, P/N 3070065-1/-4 WITH P/N 3070065-3 OR 3073049-1	GARRETT COMPLIED WITH	Recommended DATE: 6/04/2013 TIME: 9607.1 LD/CY: 8517	DATE: TIME: LD/CY:
SB 72-3449 RH 2/07/1992	ONE TIME	ENGINE-COMPRESSOR SECTION-INSTALL WASHER P/N S8154-2P025, ON BOLTS THAT SECURE HP SHROUD TO HP COMPRESSOR DIFFUSER	GARRETT FOUND P/C/W	Recommended DATE: 6/04/2013 TIME: 9607.1 LD/CY: 8517	DATE: TIME: LD/CY:
SB 72-3451 RH 10/14/1991	ONE TIME	REPLACE SPECIFIC S/N 3072542-5 2ND LPT DISC	GARRETT NOT APPLICABLE	DATE: 6/04/2013 TIME: 9607.1 LD/CY: 8517	DATE: TIME: LD/CY:
SB 72-3455 RH 9/24/1996	R3 ONE TIME	INSTALL PACKINGS, P/N S9413-036 AND SEAL P/N 3075506-2, ON TOWER SHAFT OIL TRANSFER TUBE	GARRETT FOUND P/C/W	Recommended DATE: 6/04/2013 TIME: 9607.1 LD/CY: 8517	DATE: TIME: LD/CY:
SB 72-3458 RH 6/23/2008	R12 ONE TIME	ENGINE-BYPASS SECTION-PROVIDE EDDY CURRENT INSPECTION INSTRUCTIONS FOR FAN ROTOR ASSY DISC	GARRETT COMPLIED WITH	DATE: 6/04/2013 TIME: 9607.1 LD/CY: 8517	DATE: TIME: LD/CY:
SB 72-3469 RH 9/14/2001	R3 ONE TIME	ENGINE - COMPRESSOR SECTION - REPLACE NO. 3 CARBON FACE SEAL AND SEAL ROTOR INACTIVE	GARRETT FOUND P/C/W	Recommended DATE: 6/04/2013 TIME: 9607.1 LD/CY: 8517	DATE: TIME: LD/CY:

**RIGHT ENGINE SERVICE BULLETINS
GARRETT P84497**

**4/25/2024
N2787**

DIRECTIVE NUMBER	REVISION	DESCRIPTION	VENDER	COMPLIANCE	NEXT DUE
LOCATION	RECURRS		METHOD		
EFFECTIVE DATE					
SB 72-3471	R2	ENGINE - TURBINE SECTION - REPLACE SUPPORT & SEAL ASSY IN HP TURBINE NOZZLE ASSY	GARRETT FOUND P/C/W	Recommended DATE: 6/04/2013 TIME: 9607.1 LD/CY: 8517	DATE: TIME: LD/CY:
RH	ONE TIME				
9/02/1994					
SB 72-3473		ENGINE BY-PASS SECTION - ADDITIONAL SOAP SAMPLING REQUIREMENT	GARRETT NOT APPLICABLE	Recommended DATE: 6/04/2013 TIME: 9607.1 LD/CY: 8517	DATE: TIME: LD/CY:
RH	ONE TIME				
4/03/1992					
SB 72-3475	R1	ENGINE - BY-PASS SECTION - REPLACE NO. 1 CARBON FACE SEAL AND SEAL ROTOR. INACTIVE	GARRETT FOUND P/C/W	Optional DATE: 6/04/2013 TIME: 9607.1 LD/CY: 8517	DATE: TIME: LD/CY:
RH	ONE TIME				
9/14/2001					
SB 72-3476	R1	TURBINE SECTION - INSTALL HP TURBINE PISTON RING SEAL, P/N 3000002-10	GARRETT FOUND P/C/W	Recommended DATE: 6/04/2013 TIME: 9607.1 LD/CY: 8517	DATE: TIME: LD/CY:
RH	ONE TIME				
10/16/1992					
SB 72-3477		ACCESSORY DRIVES - REPLACE ACCESSORY DRIVE GEARBOX GASKET	GARRETT FOUND P/C/W	Recommended DATE: 6/04/2013 TIME: 9607.1 LD/CY: 8517	DATE: TIME: LD/CY:
RH	ONE TIME				
4/08/1992					
SB 72-3480		INCORPORATION OF NEW ENGINE LOG BOOK	GARRETT FOUND P/C/W	DATE: 6/04/2013 TIME: 9607.1 LD/CY: 8517	DATE: TIME: LD/CY:
RH	ONE TIME				
5/29/1992					
SB 72-3482	R7	TURBINE SECTION-INSTALL LP TURBINE THIRD STAGE ROTOR ASSEMBLY, P/N 3072848-3/-4 OR 3074097-1 & ASSOCIATED PARTS	GARRETT FOUND P/C/W	Optional DATE: 6/04/2013 TIME: 9607.1 LD/CY: 8517	DATE: TIME: LD/CY:
RH	ONE TIME				
6/24/2003					
SB 72-3483	R2	COMPRESSOR SECTION - INSTALL LP COMPRESSOR FOURTH STAGE STATOR	GARRETT FOUND P/C/W	Recommended DATE: 6/04/2013 TIME: 9607.1 LD/CY: 8517	DATE: TIME: LD/CY:
RH	ONE TIME				
11/08/1996					
SB 72-3487	R3	ENGINE-BYPASS SECTION-INSPECT/REWORK FAN BLADE MIDSPAN DAMPER	GARRETT FOUND P/C/W	Recommended DATE: 6/04/2013 TIME: 9607.1 LD/CY: 8517	DATE: TIME: LD/CY:
RH	ONE TIME				
6/20/2003					
SB 72-3492		BYPASS SECTION - INSTALL O-RING PACKING, P/N S9873-001, BETWEEN SPINNER SUPPORT AND FAN BLADES	GARRETT FOUND P/C/W	Optional DATE: 6/04/2013 TIME: 9607.1 LD/CY: 8517	DATE: TIME: LD/CY:
RH	ONE TIME				
7/30/1993					
SB 72-3494	R11	TURBINE SECTION-HIGH PRESSURE & LOW PRESSURE TURBINE BLADE HOUR TRACKING	GARRETT COMPLIED WITH	Recommended DATE: 6/04/2013 TIME: 9607.1 LD/CY: 8517	DATE: TIME: LD/CY: 11007.1
RH	RECURRS				
8/06/2015					
SB 72-3498	R1	BYPASS SECTION - INSTALL FAN SHAFT & RING GEAR WITH NEW RETAINING RING	GARRETT FOUND P/C/W	Recommended DATE: 6/04/2013 TIME: 9607.1 LD/CY: 8517	DATE: TIME: LD/CY:
RH	ONE TIME				
5/07/1993					
SB 72-3499	R6	ENGINE - BY-PASS SECTION - INSTALL COMPONENT PARTS TO PREVENT OIL LEAKAGE IN #1 OIL SEAL REGION. INACTIVE	GARRETT NOT APPLICABLE	Recommended DATE: 6/04/2013 TIME: 9607.1 LD/CY: 8517	DATE: TIME: LD/CY:
RH	ONE TIME				
12/14/2001					
SB 72-3502	R4	INSTALL/REWORK LOW PRESSURE 1ST STAGE TURBINE NOZZLE WITH AN IMPROVED AIR (A5) SEAL INSTALLED	GARRETT FOUND P/C/W	Recommended DATE: 6/04/2013 TIME: 9607.1 LD/CY: 8517	DATE: TIME: LD/CY:
RH	ONE TIME				
6/10/2003					

**RIGHT ENGINE SERVICE BULLETINS
GARRETT P84497**

**4/25/2024
N2787**

DIRECTIVE NUMBER	REVISION	DESCRIPTION	VENDER	COMPLIANCE	NEXT DUE
LOCATION	RECURRS		METHOD		
EFFECTIVE DATE					
SB 72-3507 RH	R1 ONE TIME	REWORK FAN SHAFT HOUSING 3072160-1/-2 TO 3077082-1/-2	GARRETT FOUND P/C/W	DATE: 6/04/2013 TIME: 9607.1 LD/CY: 8517	DATE: TIME: LD/CY:
SB 72-3520 RH 10/15/1999	R3 ONE TIME	TURBINE SECTION - INSTALL LP THIRD STAGE TURBINE ROTOR ASSEMBLY INCORPORATING A NEWLY DESIGNED SEAL ROTOR	GARRETT Optional NOT APPLICABLE	DATE: 6/04/2013 TIME: 9607.1 LD/CY: 8517	DATE: TIME: LD/CY:
SB 72-3523 RH 6/17/2003	R2 ONE TIME	INSTALL LP 4TH STAGE COMPRESSOR ROTOR ASSY INCORPORATING A SHOULDERED SHAFT WITH AN INTERFERENCE FIT	GARRETT Optional FOUND P/C/W	DATE: 6/04/2013 TIME: 9607.1 LD/CY: 8517	DATE: TIME: LD/CY:
SB 72-3524 RH 6/04/1993	ONE TIME	BYPASS SECTION - INSTALL RETAINING (DAMPER) RING, P/N 3072463-2	GARRETT Recommended FOUND P/C/W	DATE: 6/04/2013 TIME: 9607.1 LD/CY: 8517	DATE: TIME: LD/CY:
SB 72-3529 RH 10/25/2000	R2 ONE TIME	BYPASS SECTION - REDESIGNED FAN DISC	GARRETT Optional FOUND P/C/W	DATE: 6/04/2013 TIME: 9607.1 LD/CY: 8517	DATE: TIME: LD/CY:
SB 72-3530 RH 10/08/1993	R1 ONE TIME	TURBINE SECTION - INSTALL AN LP SECOND STAGE TURBINE NOZZLE THAT INCORPORATES A HONEYCOMB AIR SEAL	GARRETT Recommended FOUND P/C/W	DATE: 6/04/2013 TIME: 9607.1 LD/CY: 8517	DATE: TIME: LD/CY:
SB 72-3531 RH 1/28/2003	R4 ONE TIME	BYPASS SECTION-INSTALLATION OF FAN BLADES & IDENTIFICATION OF FAN ROTOR ASSEMBLIES	GARRETT Recommended FOUND P/C/W	DATE: 6/04/2013 TIME: 9607.1 LD/CY: 8517	DATE: TIME: LD/CY:
SB 72-3532 RH	ONE TIME	REWORK COMPRESSOR INTERSTAGE DIFFUSER	GARRETT NOT APPLICABLE	DATE: 6/04/2013 TIME: 9607.1 LD/CY: 8517	DATE: TIME: LD/CY:
SB 72-3536 RH 1/24/2002	R3 ONE TIME	COMBUSTION SECTION - INSTALL COMBUSTION CHAMBER & INNER TRANSITION LINER (CONTROLLED FIT/LOW SMOKE)	GARRETT Optional FOUND P/C/W	DATE: 6/04/2013 TIME: 9607.1 LD/CY: 8517	DATE: TIME: LD/CY:
SB 72-3540 RH 9/14/2001	R3 ONE TIME	COMPRESSOR SECTION - IMPROVED NO.4 & 5 BEARING SUMP SCAVENGE INACTIVE	GARRETT Recommended COMPLIED WITH	DATE: 6/04/2013 TIME: 9607.1 LD/CY: 8517	DATE: TIME: LD/CY:
SB 72-3542 RH 3/28/2007	R3 ONE TIME	COMPRESSOR SECTION - INSTALL LP SECOND STAGE COMPRESSOR ROTOR ASSY WITH FREQUENCY INSPECTED ROTOR BLADES	GARRETT Recommended COMPLIED WITH	DATE: 6/04/2013 TIME: 9607.1 LD/CY: 8517	DATE: TIME: LD/CY:
SB 72-3549 RH 4/04/1994	ONE TIME	TURBINE SECTION-INSPECT FWD & AFT WELDS FOR MACHINING ON LP FIRST STAGE TURBINE NOZZLE ASSY, AIR SEAL P/N 3073765-3	GARRETT Recommended FOUND P/C/W	DATE: 6/04/2013 TIME: 9607.1 LD/CY: 8517	DATE: TIME: LD/CY:
SB 72-3556 RH 5/06/1994	ONE TIME	TURBINE SECTION-REPLACE LP SECOND STAGE TURBINE BLADES, P/N 3072012-1/-2	GARRETT Optional FOUND P/C/W	DATE: 6/04/2013 TIME: 9607.1 LD/CY: 8517	DATE: TIME: LD/CY:
SB 72-3560 RH 3/26/1996	R1 ONE TIME	COMPRESSOR SECTION-LP FIRST STAGE COMPRESSOR ROTOR ASSEMBLY BLADES	GARRETT FOUND P/C/W	DATE: 6/04/2013 TIME: 9607.1 LD/CY: 8517	DATE: TIME: LD/CY:

**RIGHT ENGINE SERVICE BULLETINS
GARRETT P84497**

**4/25/2024
N2787**

DIRECTIVE NUMBER	REVISION	DESCRIPTION	VENDER	COMPLIANCE	NEXT DUE
LOCATION	RECURRS		METHOD		
EFFECTIVE DATE					
SB 72-3561 RH 5/05/2005	R2 ONE TIME	COMPRESSOR SECTION-LP SECOND STAGE COMPRESSOR ROTOR ASSEMBLY BLADES	GARRETT FOUND P/C/W	DATE: 6/04/2013 TIME: 9607.1 LD/CY: 8517	DATE: TIME: LD/CY:
SB 72-3562 RH 3/26/1996	R1 ONE TIME	COMPRESSOR SECTION-LP THIRD STAGE COMPRESSOR ROTOR ASSEMBLY BLADES	GARRETT FOUND P/C/W	DATE: 6/04/2013 TIME: 9607.1 LD/CY: 8517	DATE: TIME: LD/CY:
SB 72-3563 RH 3/26/1996	R1 ONE TIME	COMPRESSOR SECTION-LP FOURTH STAGE COMPRESSOR ROTOR ASSEMBLY BLADES	GARRETT FOUND P/C/W	DATE: 6/04/2013 TIME: 9607.1 LD/CY: 8517	DATE: TIME: LD/CY:
SB 72-3564 RH 1/07/2003	R7 ONE TIME	ENGINE - BANK/SPARE ENGINE CONVERSIONS-	GARRETT NOT APPLICABLE	DATE: 6/04/2013 TIME: 9607.1 LD/CY: 8517	DATE: TIME: LD/CY:
SB 72-3591 RH 2/01/1996	ONE TIME	TURBINE SECTION-PROVIDE FOR INSTALLATION OF HP TURBINE BLADES, P/N 3072450-1/-2	GARRETT Recommended FOUND P/C/W	DATE: 6/04/2013 TIME: 9607.1 LD/CY: 8517	DATE: TIME: LD/CY:
SB 72-3596 RH 9/14/2001	R8 ONE TIME	ENGINE - REPLACE MAINSHAFT CARBON RING SEALS AND ASSOCIATED VENT/OIL SYSTEM COMPONENTS INACTIVE	GARRETT Optional FOUND P/C/W	DATE: 6/04/2013 TIME: 9607.1 LD/CY: 8517	DATE: TIME: LD/CY:
SB 72-3600 RH 1/13/1997	ONE TIME	ENGINE-COMPRESSOR SECTION-INSTALL LP COMPRESSOR STATOR SHIM, P/N 3060360-1 THRU -11	GARRETT FOUND P/C/W	DATE: 6/04/2013 TIME: 9607.1 LD/CY: 8517	DATE: TIME: LD/CY:
SB 72-3603RWK RH 5/22/1996	R1 ONE TIME	REWORK COMPRESSOR INTERSTAGE DIFFUSER TO INCORPORATE/ENLARGE OIL SCAVENGE SLOTS	GARRETT FOUND P/C/W	DATE: 6/04/2013 TIME: 9607.1 LD/CY: 8517	DATE: TIME: LD/CY:
SB 72-3604 RH 3/20/2015	R5 ONE TIME	ENGINE-ACCESSORY DRIVES-REWORK TRANSFER GEARBOX ASSEMBLY,P/N 3070093-X TO P/N 3070093-12	GARRETT FOUND P/C/W	DATE: 6/04/2013 TIME: 9607.1 LD/CY: 8517	DATE: TIME: LD/CY:
SB 72-3605 RH 6/16/2004	R4 ONE TIME	INSTALL/REWORK ACCESSORY DRIVE GEARBOX ASSY W/ AN IMPROVED AIR OIL SEPARATOR & A NEW AIR BREATHER VALVE ASSY	GARRETT FOUND P/C/W	DATE: 6/04/2013 TIME: 9607.1 LD/CY: 8517	DATE: TIME: LD/CY:
SB 72-3613 RH 1/23/2009	R8 ONE TIME	ENGINE-REPLACE NO.1 & NO.3 CARBON RING SEALS & ASSOCIATED VENT/OIL SYSTEM COMPONENTS	GARRETT Recommended FOUND P/C/W	DATE: 6/04/2013 TIME: 9607.1 LD/CY: 8517	DATE: TIME: LD/CY:
SB 72-3614RWK RH 2/06/1997	ONE TIME	BYPASS SECTION-REWORK NO.1 SEAL & SEAL HOUSING TO PART NO. 3071966-5 OR 3077122-1/-2/-3	GARRETT FOUND P/C/W	DATE: 6/04/2013 TIME: 9607.1 LD/CY: 8517	DATE: TIME: LD/CY:
SB 72-3615 RH 2/06/1997	ONE TIME	REWORK AIR BREATHER VALVE, P/N 3071564-7 /-8 TO P/N 3071564-9, USED IN AIR BREATHR VALVE P/N 3075323-3	GARRETT FOUND P/C/W	DATE: 6/04/2013 TIME: 9607.1 LD/CY: 8517	DATE: TIME: LD/CY:
SB 72-3620 RH 3/19/2009	R3 ONE TIME	INSTALL LP TURBINE 1ST & 2ND STAGE TURB NOZZLE & ROTOR ASSEMBLIES FOR IMPROVED LP TURBINE EFFICIENCY	GARRETT Optional FOUND P/C/W	DATE: 6/04/2013 TIME: 9607.1 LD/CY: 8517	DATE: TIME: LD/CY:

**RIGHT ENGINE SERVICE BULLETINS
GARRETT P84497**

**4/25/2024
N2787**

DIRECTIVE NUMBER	REVISION	DESCRIPTION	VENDER	COMPLIANCE	NEXT DUE
LOCATION	RECURRS		METHOD		
EFFECTIVE DATE					
SB 72-3626 RH	R4 ONE TIME	1ST STAGE LPT ASSEMBLY, P/N 3072071-ALL, TO P/N 3073786-1	GARRETT COMPLIED WITH	DATE: 6/04/2013 TIME: 9607.1 LD/CY: 8517	DATE: TIME: LD/CY:
SB 72-3627 RH	R1 ONE TIME	2ND STAGE LPT ASSEMBLY, P/N 3072013-ALL, TO P/N 3073787-1	GARRETT COMPLIED WITH	DATE: 6/04/2013 TIME: 9607.1 LD/CY: 8517	DATE: TIME: LD/CY:
SB 72-3635 RH 11/16/1998	ONE TIME	INSPECT/REWORK/INSTALL OIL FILTER COVER P/N 3072231-1 TO P/N 3072231-4	GARRETT FOUND P/C/W	DATE: 6/04/2013 TIME: 9607.1 LD/CY: 8517	DATE: TIME: LD/CY:
SB 72-3640 RH 11/10/2000	R4 ONE TIME	ENGINE-SERVICING WITH MOBIL 254 OIL OR EXXON 2197 OIL INACTIVE	GARRETT Recommended FOUND P/C/W	DATE: 6/04/2013 TIME: 9607.1 LD/CY: 8517	DATE: TIME: LD/CY:
SB 72-3644 RH 1/10/2001	R2 ONE TIME	INSTALL HP IMPELLER SHROUD P/N 3074567-1/-2	GARRETT Optional FOUND P/C/W	DATE: 6/04/2013 TIME: 9607.1 LD/CY: 8517	DATE: TIME: LD/CY:
SB 72-3654 RH 12/10/2010	R1 ONE TIME	PREVENT LP THIRD STAGE TURBINE ROTOR DISC FROM RUBBING THE LP THIRD STAGE TURBINE NOZZLE	GARRETT Recommended COMPLIED WITH	DATE: 6/04/2013 TIME: 9607.1 LD/CY: 8517	DATE: TIME: LD/CY:
SB 72-3661 RH 1/24/2000	ONE TIME	INSPECT SPECIFIC IDENTIFIED LP 3RD STAGE TURB ROTOR ASSY INCORP. LPT3 BLADE P/N 3072845-1 WITH MFG CODE OF 24217	GARRETT Recommended NOT APPLICABLE	DATE: 6/04/2013 TIME: 9607.1 LD/CY: 8517	DATE: TIME: LD/CY:
SB 72-3662 RH 4/12/2012	R8 ONE TIME	REPLACE NO. 4 AND NO. 5 CARBON RING SEALS AND ASSOCIATED VENT/OIL SYSTEM COMPONENTS	GARRETT Recommended COMPLIED WITH	DATE: 6/04/2013 TIME: 9607.1 LD/CY: 8517	DATE: TIME: LD/CY:
SB 72-3664 RH 5/05/2000	ONE TIME	INSPECTION/REPLACEMENT OF THREADED ENDS TIE ROD, (LP TIE ROD), P/N 3073049-1 & 3074744-1	GARRETT Recommended NOT APPLICABLE	DATE: 6/04/2013 TIME: 9607.1 LD/CY: 8517	DATE: TIME: LD/CY:
SB 72-3672 RH 3/26/2004	ONE TIME	PROVIDE A LOW PRESSURE 1ST STAGE TURBINE (LPT1) NOZZLE WITHOUT THE AIR (A5) SEAL ASSEMBLY ATTACHED	GARRETT Optional COMPLIED WITH	DATE: 6/04/2013 TIME: 9607.1 LD/CY: 8517	DATE: TIME: LD/CY:
SB 72-3674 RH 9/16/2003	R2 ONE TIME	INSPECTION OF SPECIFIC IDENTIFIED MAIN SUPPORT FRAME ASSEMBLIES	GARRETT Recommended NOT APPLICABLE	DATE: 6/04/2013 TIME: 9607.1 LD/CY: 8517	DATE: TIME: LD/CY:
SB 72-3675 RH 1/13/2010	R5 ONE TIME	INSPECT FAN BLADES FOR UNAUTHORIZED MARKINGS ON THE FAN BLADE DOVETAIL AFT REGION	GARRETT Recommended FOUND P/C/W	DATE: 6/04/2013 TIME: 9607.1 LD/CY: 8517	DATE: TIME: LD/CY:
SB 72-3676 RH 7/12/2001	ONE TIME	REPLACE THE HOISTING BRACKET ON THE FAN DUCT SET, P/N 3072420-7(UPPER HALF) ON SPECIFIC IDENTIFIED ENGINES	GARRETT Recommended NOT APPLICABLE	DATE: 6/04/2013 TIME: 9607.1 LD/CY: 8517	DATE: TIME: LD/CY:
SB 72-3682 RH 11/26/2002	ONE TIME	REMOVE SPECIFIC IDENTIFIED LP COMPRESSOR 2ND STAGE (LPC2) DISCS	GARRETT Recommended NOT APPLICABLE	DATE: 6/04/2013 TIME: 9607.1 LD/CY: 8517	DATE: TIME: LD/CY:

**RIGHT ENGINE SERVICE BULLETINS
GARRETT P84497**

**4/25/2024
N2787**

DIRECTIVE NUMBER	REVISION	DESCRIPTION	VENDER	COMPLIANCE	NEXT DUE
LOCATION	RECURRS		METHOD		
EFFECTIVE DATE					
SB 72-3685		REPLACE SPECIFIC IDENTIFIED LP SECOND STAGE TURBINE BLADES, P/N 3072012-2 AND P/N 3074099-1	GARRETT	Recommended	DATE: 6/04/2013 TIME: 9607.1 LD/CY: 8517
RH	ONE TIME		NOT APPLICABLE		
3/08/2002					DATE: 6/04/2013 TIME: 9607.1 LD/CY: 8517
SB 72-3687		REMOVE SPECIFIC IDENTIFIED LP COMPRESSOR 2ND STAGE (LPC2) DISCS	GARRETT	Recommended	DATE: 6/04/2013 TIME: 9607.1 LD/CY: 8517
RH	ONE TIME		NOT APPLICABLE		
11/11/2002					DATE: 6/04/2013 TIME: 9607.1 LD/CY: 8517
SB 72-3693	R1	REPLACE SPECIFIC IDENTIFIED HIGH PRESSURE TURBINE (HPT) TIE SHAFT PLAIN ROUND NUTS, P/N 3070151-4	GARRETT	Recommended	DATE: 6/04/2013 TIME: 9607.1 LD/CY: 8517
RH	ONE TIME		NOT APPLICABLE		
6/28/2004					DATE: 6/04/2013 TIME: 9607.1 LD/CY: 8517
SB 72-3705	R2	INSTALL A LOW PRESSURE FIRST STAGE TURBINE (LPT1) ROTOR ASSEMBLY WITH AN IMPROVED LPT1 ROTOR DISC	GARRETT	Recommended	DATE: 6/04/2013 TIME: 9607.1 LD/CY: 8517
RH	ONE TIME		FOUND P/C/W		
11/09/2005					DATE: 6/04/2013 TIME: 9607.1 LD/CY: 8517
SB 72-3711	R4	INSTALL IMPROVED 2ND STAGE LOW PRESSURE COMPRESSOR (LPC2) ROTOR DISC	GARRETT	Recommended	DATE: 6/04/2013 TIME: 9607.1 LD/CY: 8517
RH	ONE TIME		COMPLIED WITH		
10/22/2015					DATE: 6/04/2013 TIME: 9607.1 LD/CY: 8517
SB 72-3739		INSTALL IMPROVED NO. 1 SEG CARBON SEAL, P/N 3060457-1 OR -2 (AS APPLICABLE) AND/OR NO. 3 SEG CARBON SEAL 3060458-1	GARRETT		DATE: 6/04/2013 TIME: 9607.1 LD/CY: 8517
RH	ONE TIME		COMPLIED WITH		
4/21/2008					DATE: 6/04/2013 TIME: 9607.1 LD/CY: 8517
SB 72-3741		INSTALL IMPROVED NO. 4 SEG CARBON SEAL, P/N 3060437-1 AND NO. 5 SEG CARBON SEAL P/N 3060436-1	GARRETT		DATE: 6/04/2013 TIME: 9607.1 LD/CY: 8517
RH	ONE TIME		COMPLIED WITH		
4/21/2008					DATE: 6/04/2013 TIME: 9607.1 LD/CY: 8517
SB 72-3758		INSPECT SUSPECT HIGH PRESSURE TURBINE (HPT) ROTOR ASSEMBLIES, PN 3072314-2, -3	GARRETT		DATE: 6/04/2013 TIME: 9607.1 LD/CY: 8517
RH	ONE TIME		NOT APPLICABLE		
1/19/2010					DATE: 6/04/2013 TIME: 9607.1 LD/CY: 8517
SB 72-3759 I	R1	INSTALL IMPROVED PLAIN ENCASED SEAL, P/N 3020052-26	GARRETT		DATE: 6/04/2013 TIME: 9607.1 LD/CY: 8517
RH	ONE TIME		COMPLIED WITH		
10/28/2011					DATE: 6/04/2013 TIME: 9607.1 LD/CY: 8517
SB 72-3764 1		REMOVE SPECIFIC IDENTIFIED THIRD STAGE AXIAL COMPRESSOR DISKS,PN 3072397-3	GARRETT		DATE: 6/04/2013 TIME: 9607.1 LD/CY: 8517
RH	ONE TIME		NOT APPLICABLE		
6/14/2011					DATE: 6/04/2013 TIME: 9607.1 LD/CY: 8517
SB 72-3773		INTRODUCTION OF IMPROVED STAGE 4 CASE AND VANE ASSEMBLIES, PN 3074555-10, -11	GARRETT	Recommended	DATE: 6/04/2013 TIME: 9607.1 LD/CY: 8517
RH	ONE TIME		COMPLIED WITH		
7/08/2011					DATE: 6/04/2013 TIME: 9607.1 LD/CY: 8517
SB 72-3777	R2	INSTALL IMPROVED LOW PRESSURE SECOND STAGE (LPC2) SHROUD, PN 3072403-6	GARRETT		DATE: 6/04/2013 TIME: 9607.1 LD/CY: 8517
RH	ONE TIME		COMPLIED WITH		
8/17/2012					DATE: 6/04/2013 TIME: 9607.1 LD/CY: 8517
SB 73-3027	R7	ENGINE - FUEL AND CONTROL - REPLACE FUEL PUMP ASSEMBLY WITH FUEL ASSEMBLY INCORPORATING FUEL INLET TEMP BOSS	GARRETT	Optional	DATE: 6/04/2013 TIME: 9607.1 LD/CY: 8517
RH	ONE TIME		FOUND P/C/W		
5/23/1986					DATE: 6/04/2013 TIME: 9607.1 LD/CY: 8517
SB 73-3028		FUEL - REPLACE FLOW DIVIDER AND DRAIN VALVE WITH NEW FLOW DIVIDER VALVE WITHOUT DRAIN FUNCTION	GARRETT	Optional	DATE: 6/04/2013 TIME: 9607.1 LD/CY: 8517
RH	ONE TIME		FOUND P/C/W		
7/05/1979					DATE: 6/04/2013 TIME: 9607.1 LD/CY: 8517

**RIGHT ENGINE SERVICE BULLETINS
GARRETT P84497**

**4/25/2024
N2787**

DIRECTIVE NUMBER	REVISION	DESCRIPTION	VENDER	COMPLIANCE	NEXT DUE	
LOCATION	RECURRS		METHOD			
EFFECTIVE DATE						
SB 73-3030 RH 7/31/1981	R2 ONE TIME	ENGINE- FUEL CONTROL - REIDENTIFY/REPLAC FUEL CONTROL: ADDS STRENGTH TO GOVERNOR SHAFT & REDUCE AXIAL SHAFT PLAY	GARRETT FOUND P/C/W	Optional	DATE: 6/04/2013 TIME: 9607.1 LD/CY: 8517	DATE: TIME: LD/CY:
SB 73-3049 RH 10/05/1984	R1 ONE TIME	ENGINE FUEL AND CONTROL - CONTROLLING - INSTALL REWORKED FUEL CONTROL ASSEMBLY: INCREASES SERVICE LIFE	GARRETT NOT APPLICABLE	Recommended	DATE: 6/04/2013 TIME: 9607.1 LD/CY: 8517	DATE: TIME: LD/CY:
SB 73-3062 RH 5/23/1994	R3 ONE TIME	ENGINE FUEL AND CONTROL - ADJUST FUEL PUMP ANTI-ICING VALVE	GARRETT FOUND P/C/W		DATE: 6/04/2013 TIME: 9607.1 LD/CY: 8517	DATE: TIME: LD/CY:
SB 73-3064 RH 7/19/1983	ONE TIME	ENGINE FUEL AND CONTROL - INSTALL LEAF SPRING BETWEEN VARIABLE RESISTOR & SPUR GEAR: MINIMIZES WEAR	GARRETT FOUND P/C/W	Recommended	DATE: 6/04/2013 TIME: 9607.1 LD/CY: 8517	DATE: TIME: LD/CY:
SB 73-3075 RH 6/13/2003	R6 ONE TIME	ENGINE FUEL & CONTROL - REPLACE FUEL PUMP DIFFERENTIAL PRESSURE INDICATOR: INCORP. A DIAPHRAGM OPERATED PISTON	GARRETT FOUND P/C/W	Recommended	DATE: 6/04/2013 TIME: 9607.1 LD/CY: 8517	DATE: TIME: LD/CY:
SB 73-3078 RH 5/08/1984	ONE TIME	ENGINE FUEL & CONTROL - INSTALLATION OF FUEL PUMP UPDATE RECORD PLATE: PROVIDES BETTER RECORD OF PRODUCT IMPROVEMENT	GARRETT FOUND P/C/W	Optional	DATE: 6/04/2013 TIME: 9607.1 LD/CY: 8517	DATE: TIME: LD/CY:
SB 73-3083 RH 10/20/1989	R1 ONE TIME	ENGINE - FUEL AND CONTROL - REPLACE FUEL PUMP ANTI-ICING VALVE WITH UNIT CONTAINING AN IMPROVED THERMOSTAT	GARRETT NOT APPLICABLE	Recommended	DATE: 6/04/2013 TIME: 9607.1 LD/CY: 8517	DATE: TIME: LD/CY:
SB 73-3107 RH 4/20/1994	R4 ONE TIME	INSTALL SUPPORT CLAMP, P/N 211-501-9114, ON FUEL LINE, P/N 3071051-1	GARRETT FOUND P/C/W	Recommended	DATE: 6/04/2013 TIME: 9607.1 LD/CY: 8517	DATE: TIME: LD/CY:
SB 73-3108 RH 10/09/1995	R1 ONE TIME	ENGINE FUEL AND CONTROL - DISTRIBUTION INSTALL FUEL CONTROL P3 SENSE LINE, GASKET, P/N 3075481-1	GARRETT FOUND P/C/W	Recommended	DATE: 6/04/2013 TIME: 9607.1 LD/CY: 8517	DATE: TIME: LD/CY:
SB 73-3109 RH 3/12/1993	R1 ONE TIME	ENGINE FUEL & CONTROL-DISTRIBUTION-MAIN-TENANCE OF ENGINES WITH SERVICE TUBE CLAMPS P/N 3073542-1 & 3073543-91 INSTLD	GARRETT COMPLIED WITH		DATE: 6/04/2013 TIME: 9607.1 LD/CY: 8517	DATE: TIME: LD/CY:
SB 73-3110 RH 4/03/1992	R1 ONE TIME	ENG FUEL & CONTROL - DIST.-REPLACE SEC-ONDARY FLEXIBLE HOSE ASSY (AS REQUIRED) ON SPEC IDENTIFIED FUEL MANIFOLD ASSYS	GARRETT NOT APPLICABLE	Recommended	DATE: 6/04/2013 TIME: 9607.1 LD/CY: 8517	DATE: TIME: LD/CY:
SB 73-3112 RH 2/14/1992	ONE TIME	ENG FUEL & CONT-CONTROLLING-INSP & REPL IDENT FUEL CONT VAR RESIS (PWR LEV POT) AS REQ AT COMPONENT OVHL/REPAIR FACILITY	GARRETT NOT APPLICABLE	Recommended	DATE: 6/04/2013 TIME: 9607.1 LD/CY: 8517	DATE: TIME: LD/CY:
SB 73-3113 RH 3/10/1992	ONE TIME	ENGINE FUEL AND CONTROL - DISTRIBUTION - REPLACE FUEL HEATER OUTLET ADAPTER AND OIL TRANSFER TUBE	GARRETT FOUND P/C/W	Recommended	DATE: 6/04/2013 TIME: 9607.1 LD/CY: 8517	DATE: TIME: LD/CY:
SB 73-3114 RH 5/29/1992	ONE TIME	FUEL AND CONTROL-CONTROLLING-REPLACE METERING VALVE ADJUSTMENT SHAFT AND THREADED RESTRICTOR AT COMPONENT O/H	GARRETT NOT APPLICABLE	Recommended	DATE: 6/04/2013 TIME: 9607.1 LD/CY: 8517	DATE: TIME: LD/CY:

**RIGHT ENGINE SERVICE BULLETINS
GARRETT P84497**

**4/25/2024
N2787**

DIRECTIVE NUMBER	REVISION	DESCRIPTION	VENDER	COMPLIANCE	NEXT DUE
LOCATION	RECURRS		METHOD		
EFFECTIVE DATE					
SB 73-3115	R1	INSTALL AN IMPROVED FUEL CONTROL INCORPORATING A MINIMUM MOD CONFIGURATION STANDARD	GARRETT	Recommended	DATE: 6/04/2013 TIME: 9607.1 LD/CY: 8517
RH	ONE TIME		FOUND P/C/W		
3/18/1994					
SB 73-3119		CONTROLLING - REPLACE/REWORK GOVERNOR FLYWEIGHT ASSEMBLY AT COMPONENT REPAIR FACILITY	GARRETT	Recommended	DATE: 6/04/2013 TIME: 9607.1 LD/CY: 8517
RH	ONE TIME		FOUND P/C/W		
5/07/1993					
SB 73-3120	R1	REPLACE / REWORK FUEL MANIFOLD ASSY	GARRETT		DATE: 6/04/2013 TIME: 9607.1 LD/CY: 8517
RH	ONE TIME		COMPLIED WITH		
SB 73-3121		DISTRIBUTION -REPLACE SECONDARY FLEXIBLE HOSE ASSY (AS REQUIRED) ON SPECIFIC IDENTIFIED FUEL MANIFOLD ASSEMBLIES	GARRETT	Recommended	DATE: 6/04/2013 TIME: 9607.1 LD/CY: 8517
RH	ONE TIME		FOUND P/C/W		
11/03/1993					
SB 73-3131	R2	ONE TIME INSPECTION FOR SPECIFIC ID FUEL CONTROL COMPRESSOR DISCHARGE SENSOR BELLOWS P/N 3074139-2	GARRETT	Recommended	DATE: 6/04/2013 TIME: 9607.1 LD/CY: 8517
RH	ONE TIME		FOUND P/C/W		
6/16/2004					
SB 73-3134	R2	REPLACE SPECIFIC IDENTIFIED FUEL CONTROL ASSEMBLIES HAVING SUSPECT TORQUE MOTORS	GARRETT		DATE: 6/04/2013 TIME: 9607.1 LD/CY: 8517
RH	ONE TIME		NOT APPLICABLE		
4/30/1999					
SB 73-3135		DISTRIBUTION-INSPECT/REPLACE FLEX TUBE ASSY, P/N 3074376-1 (399-5500-0003) OR 3074376-2 (AS APPLICABLE)	GARRETT		DATE: 6/04/2013 TIME: 9607.1 LD/CY: 8517
RH	ONE TIME		FOUND P/C/W		
8/17/2000					
SB 73-3137		REPLACE THE FUEL HEATER CHECK VALVE, P/N 3073932-5 WITH P/N 3073932-6 AND CONNECTING METAL TUBE ASSEMBLIES	GARRETT	Recommended	DATE: 6/04/2013 TIME: 9607.1 LD/CY: 8517
RH	ONE TIME		NOT APPLICABLE		
11/03/2000					
SB 73-3138		DISTRIBUTION-REPLACE FUEL NOZZLE GASKETS	GARRETT	Optional	DATE: 6/04/2013 TIME: 9607.1 LD/CY: 8517
RH	ONE TIME		FOUND P/C/W		
10/20/2000					
SB 73-3142		REPLACE SPECIFIC IDENTIFIED FUEL CONTROL ASSYS HAVING A SUSPECT OVERSPEED AND/OR MANUAL MODE SOLENOID VALVE INSTALLED	GARRETT	Recommended	DATE: 6/04/2013 TIME: 9607.1 LD/CY: 8517
RH	ONE TIME		NOT APPLICABLE		
10/07/2002					
SB 73-3147		REPLACE SPECIFIC IDENTIFIED MAIN TURBINE ENGINE FUEL CONTROLS WITH A SUSPECT OVER SPEED GOVERNOR ASSEMBLY INSTALLED	GARRETT		DATE: 6/04/2013 TIME: 9607.1 LD/CY: 8517
RH	ONE TIME		NOT APPLICABLE		
3/29/2005					
SB 73-3149	R1	CONTROLLING - REPLACE MAIN TURBINE ENGINE FUEL PUMP FUEL FILTER ELEMENT WITH FUEL FILTER ELEMENT,P/N 897830-1	GARRETT	Recommended	DATE: 6/04/2013 TIME: 9607.1 LD/CY: 8517
RH	ONE TIME		FOUND P/C/W		
9/12/2005					
SB 74-3006	R1	IGNITION - GENERAL - INSTALL IGNITION IGNITOR PLUG P/N 3074541-1	GARRETT	Optional	DATE: 6/04/2013 TIME: 9607.1 LD/CY: 8517
RH	ONE TIME		FOUND P/C/W		
4/20/1990					
SB 74-3007	R1	GENERAL - INSPECT IRIIDIUM IGNITER PLUGS, P/N 3074541-1 (CHAMPION CH31815) FOR LOOSE CENTER FIRING TIP ELECTRODE	GARRETT	Recommended	DATE: 6/04/2013 TIME: 9607.1 LD/CY: 8517
RH	ONE TIME		NOT APPLICABLE		
11/11/1993					

**RIGHT ENGINE SERVICE BULLETINS
GARRETT P84497**

**4/25/2024
N2787**

DIRECTIVE NUMBER	REVISION	DESCRIPTION	VENDER	COMPLIANCE	NEXT DUE
LOCATION	RECURRS		METHOD		
EFFECTIVE DATE					
SB 76-3017 RH 4/17/1980	ONE TIME	ENGINE - CONTROLS - ONE TIME INSPECTION OF ELECTRONIC COMPUTER P/N 2101144-1/-2	GARRETT NOT APPLICABLE	Recommended DATE: 6/04/2013 TIME: 9607.1 LD/CY: 8517	DATE: TIME: LD/CY:
SB 76-3018 RH 9/23/1982	R1 ONE TIME	ENGINE - CONTROLS - INSTALL COMPUTER ASSEMBLY P/N 2101144-5: IMPROVED FEATURES	GARRETT NOT APPLICABLE	Recommended DATE: 6/04/2013 TIME: 9607.1 LD/CY: 8517	DATE: TIME: LD/CY:
SB 76-3022 RH 6/01/1982	ONE TIME	ENGINE CONTROLS - POWER CONTROL - INSP AND, IF REQUIRED, REPLACE CAPACITORS ON A9 AND A10 POWER SUPPLY BOARD	GARRETT NOT APPLICABLE	Recommended DATE: 6/04/2013 TIME: 9607.1 LD/CY: 8517	DATE: TIME: LD/CY:
SB 76-3038 RH 8/01/1983	R1 ONE TIME	ENGINE POWER CONTROLS - REWORK P/N 2101144-5, SERIES 1 TO SERIES 3: IMPROVES UNIT	GARRETT NOT APPLICABLE	Recommended DATE: 6/04/2013 TIME: 9607.1 LD/CY: 8517	DATE: TIME: LD/CY:
SB 76-3051 RH 5/18/1990	ONE TIME	ENGINE CONTROL - POWER CONTROL - INSTALL ANTI-ICE AND SURGE SYSTEMS AIR LINE MANIFOLD, P/N 3071778-2	GARRETT NOT APPLICABLE	Optional DATE: 6/04/2013 TIME: 9607.1 LD/CY: 8517	DATE: TIME: LD/CY:
SB 76-3054 RH 10/06/1995	R1 ONE TIME	ENGINE CONTROLS - POWER CONTROL INSTALL SURGE CONTROL GASKET, P/N 3075481-1/-3.	GARRETT FOUND P/C/W	Recommended DATE: 6/04/2013 TIME: 9607.1 LD/CY: 8517	DATE: TIME: LD/CY:
SB 76-3067 RH 12/05/2005	R19 ONE TIME	POWER CONTROL - INSTALL DIGITAL ELECTRONIC ENGINE CONTROL (N1 DEEC)	GARRETT FOUND P/C/W	Optional DATE: 6/04/2013 TIME: 9607.1 LD/CY: 8517	DATE: TIME: LD/CY:
SB 76-3073 RH 6/27/2002	R1 ONE TIME	POWER CONTROL - REWORK N1 DIGITAL ELECTRONIC ENGINE CONTROL (DEEC), P/N 2119020-3 TO P/N 2119020-3001	GARRETT FOUND P/C/W	Optional DATE: 6/04/2013 TIME: 9607.1 LD/CY: 8517	DATE: TIME: LD/CY:
SB 76-3075 RH	ONE TIME	REPLACE SPECIFIC ID N1 DEEC	GARRETT NOT APPLICABLE	DATE: 6/04/2013 TIME: 9607.1 LD/CY: 8517	DATE: TIME: LD/CY:
SB 77-3001 RH 7/05/1979	R1 ONE TIME	N1 MOTIONAL PICKUP- INSTALL N1 TRANSDUCR WITH CHANGE IN DESIGN & FUNCT REQUIREMNT NEW WELD TECHNIQUE TO PREVENT POROSITY	GARRETT FOUND P/C/W	Recommended DATE: 6/04/2013 TIME: 9607.1 LD/CY: 8517	DATE: TIME: LD/CY:
SB 77-3002 RH 5/18/1981	R2 ONE TIME	ENGINE - N2 MOTIONAL PICKUP - INSTALL N2 TRANSDUCER INCORPORATING IMPROVED SEALANT	GARRETT FOUND P/C/W	Recommended DATE: 6/04/2013 TIME: 9607.1 LD/CY: 8517	DATE: TIME: LD/CY:
SB 77-3006 RH 10/10/1985	R4 ONE TIME	INDICATING - TEMPERATURE - INSTALL TWO PIECE INTERSTAGE TURBINE TEMPERATURE (ITT) HARNESS WITH MORE FLEXIBLE HARNESS	GARRETT FOUND P/C/W	Optional DATE: 6/04/2013 TIME: 9607.1 LD/CY: 8517	DATE: TIME: LD/CY:
SB 77-3019 RH 6/19/1990	R2 ONE TIME	ENGINE INDICATING - TEMPERATURE - INSTALL THERMOCLOUPLE HARNESS, P/N 3073595-1	GARRETT FOUND P/C/W	Recommended DATE: 6/04/2013 TIME: 9607.1 LD/CY: 8517	DATE: TIME: LD/CY:
SB 77-3021 RH 1/16/2006	R1 ONE TIME	ENGINE INDICATING-POWER - REPLACE N1 MOTIONAL PICKUP TRANSDUCER	GARRETT FOUND P/C/W	Recommended DATE: 6/04/2013 TIME: 9607.1 LD/CY: 8517	DATE: TIME: LD/CY:

**RIGHT ENGINE SERVICE BULLETINS
GARRETT P84497**

**4/25/2024
N2787**

DIRECTIVE NUMBER	REVISION	DESCRIPTION	VENDER	COMPLIANCE	NEXT DUE	
LOCATION	RECURRS		METHOD			
EFFECTIVE DATE						
SB 79-3017 RH 7/31/2006	R3 ONE TIME	DISTRIBUTION - REPLACE AIR/OIL COOLER & BYPASS VALVE TO PREVENT OIL LEAKGE BY REDUCING FRETTING AT FLOW CONNECTION	GARRETT FOUND P/C/W	Optional	DATE: 6/04/2013 TIME: 9607.1 LD/CY: 8517	DATE: TIME: LD/CY:
SB 79-3023 RH 11/30/2006	R1 ONE TIME	ENGINE OIL - DISTRIBUTION - INSTALLATION OF REDESIGNED OIL COOLER OIL TRANSFER TUBE: TO REDUCE FATIGUE CRACKING	GARRETT FOUND P/C/W	Recommended	DATE: 6/04/2013 TIME: 9607.1 LD/CY: 8517	DATE: TIME: LD/CY:
SB 79-3025 RH 11/11/2002	R4 ONE TIME	ENGINE - REPLACE OR REWORK OIL LUBRICATE NOZZLE: PROVIDES FOR INSTALLATION OF LOCKING WASHERS TO PREVENT BOLTS LOOSEN	GARRETT FOUND P/C/W	Recommended	DATE: 6/04/2013 TIME: 9607.1 LD/CY: 8517	DATE: TIME: LD/CY:
SB 79-3031 RH 7/21/1983	R1 ONE TIME	OIL - DISTRIBUTION - REPLACE/REWORK #6 BEARING LUBRICATION TUBE ASSY P/N 3071841-3 TO -4: ELIMINATES TUBE CORROS	GARRETT FOUND P/C/W	Recommended	DATE: 6/04/2013 TIME: 9607.1 LD/CY: 8517	DATE: TIME: LD/CY:
SB 79-3032 RH 12/22/1989	R2 ONE TIME	OIL - REWORK/REPLACE #6 BEARING LUBRICAT TUBE ASSY P/N 3073418-1 TO 3073418-2 ELIMINATES SOURCE OF TUBE CORROSION	GARRETT FOUND P/C/W	Recommended	DATE: 6/04/2013 TIME: 9607.1 LD/CY: 8517	DATE: TIME: LD/CY:
SB 79-3034 RH 1/28/2000	R3 ONE TIME	OIL - REPLACEMENT/REWORK OF PLUG (CHIP DETECTOR): VALVE HOUSING MADE OF STEEL TO REDUCE POSSIBILITY OF CRACKING	GARRETT FOUND P/C/W	Recommended	DATE: 6/04/2013 TIME: 9607.1 LD/CY: 8517	DATE: TIME: LD/CY:
SB 79-3051 RH 2/18/1994	ONE TIME	OIL-DISTRIBUTION-INSTALL METAL GASKET, P/N 3075481-2	GARRETT FOUND P/C/W	Optional	DATE: 6/04/2013 TIME: 9607.1 LD/CY: 8517	DATE: TIME: LD/CY:
SB 79-3053 RH 4/01/1994	ONE TIME	OIL-DISTRIBUTION-REPLACE REAR TURBINE BEARING OIL-OUT TUBE AND GASKET	GARRETT FOUND P/C/W	Optional	DATE: 6/04/2013 TIME: 9607.1 LD/CY: 8517	DATE: TIME: LD/CY:
SB 79-3054 RH 7/29/1997	R1 ONE TIME	OIL-DISTRIBUTION-INSTALL/REWORK OIL LUBE & SCAVENGE PUMP (OIL PUMP) THAT INCORP. AN IMPROVED REGULATOR SECTION	GARRETT FOUND P/C/W	Optional	DATE: 6/04/2013 TIME: 9607.1 LD/CY: 8517	DATE: TIME: LD/CY:
SB 79-3055 RH 3/30/1995	R2 ONE TIME	REPLACE SEAL P/N 3020052-5/-16/-21 WITH P/N 3020052-24, IN AIR BREATHER VALVE ASSY P/N 3072119-1	GARRETT FOUND P/C/W	Optional	DATE: 6/04/2013 TIME: 9607.1 LD/CY: 8517	DATE: TIME: LD/CY:
SB 79-3058 RH 12/12/2001	R1 ONE TIME	OIL - DISTRIBUTION - INSTALL OIL JET STRAINER, P/N 891764-11 INACTIVE	GARRETT NOT APPLICABLE		DATE: 6/04/2013 TIME: 9607.1 LD/CY: 8517	DATE: TIME: LD/CY:
SB 79-3059 RH 11/01/1996	R1 ONE TIME	OIL - DISTRIBUTION - INSTALL/REWORK OIL LUBE AND SCAVENGE PUMP WITH IMPROVED SCAVENGE CAPABILITIES	GARRETT FOUND P/C/W	Recommended	DATE: 6/04/2013 TIME: 9607.1 LD/CY: 8517	DATE: TIME: LD/CY:
SB 79-3062 RH 6/19/1998	ONE TIME	OIL-DISTRIBUTION-REPLACE DE-OIL VALVE (CHECK VALVE), P/N 3074372-1 WITH P/N 3074372-2	GARRETT NOT APPLICABLE		DATE: 6/04/2013 TIME: 9607.1 LD/CY: 8517	DATE: TIME: LD/CY:
SB 79-3063 RH 7/16/1999	ONE TIME	INSTALL #6 BEARING LUBE TUBE ASSY P/N 3073736-1 & ASSOCIATED BRACKET, P/N 3073788-1/3075507-1 (AS APPLICABLE)	GARRETT FOUND P/C/W		DATE: 6/04/2013 TIME: 9607.1 LD/CY: 8517	DATE: TIME: LD/CY:

**RIGHT ENGINE SERVICE BULLETINS
GARRETT P84497**

**4/25/2024
N2787**

DIRECTIVE NUMBER	REVISION	DESCRIPTION	VENDER	COMPLIANCE	NEXT DUE
LOCATION	RECURRS		METHOD		
EFFECTIVE DATE					
SB 79-3066	R2	INSTALL LUBE WITH REGULATOR AND SCAVENGE PUMP (OIL LUBE PUMP), P/N 3060785-2	GARRETT	Recommended	DATE: 6/04/2013 TIME: 9607.1 LD/CY: 8517
RH	ONE TIME		FOUND P/C/W		
4/12/2012					
SB 79-3070	R1	INSTALL IMPROVED OIL TANK INSTRUCTION PLATE TO PREVENT OIL TANK OVERSERVICING	GARRETT	Recommended	DATE: 6/04/2013 TIME: 9607.1 LD/CY: 8517
RH	ONE TIME		COMPLIED WITH		
5/09/2018					
SB A72-3641	R7	PERFORM EDDY CURRENT INSPECTION OF HP IMPELLER P/N 3073393-1,3073394-1, 3073433-1,3073434-1,3073398-ALL	GARRETT	Recommended	DATE: 1/11/2000 TIME: 7164.6 LD/CY: 6190
RH	RECURRS		COMPLIED WITH		
7/06/2010					DATE: 11364.6 TIME: LD/CY: