## Competency list taken from the 404D Industrial Painter Training Standard 21 Feb 2017

## ON-THE-JOB PERFORMANCE OBJECTIVES

5370.0	PROTECT SELF AND OTHERS
5370.1	Identify health and safety hazards in the workplace
5370.2	Select, wear, adjust, and maintain personal protective equipment
5370.3	Practice safe work habits
5370.4	Contain health, safety, and environmental hazards by erecting and
	maintaining containment structures and installing appropriate ventilation
	equipment,
5370.5	Follow site fire safety directives and procedures
5370.6	Practice industrial hygiene by wearing required clothing, personal
	protective equipment, and using eye wash or decontamination showers to
	avoid contamination or injury
5370.7	Practice good housekeeping in the workplace
5370.8	Conduct pre-operational check of equipment
5370.9	Follow emergency procedures for treating conditions
5370.10	Report injuries
5370.11	Lock and/or tag out all energy sources for repair or maintenance
5370.12	Handle designated substances using specified handling and storage
	procedures and equipment
5370.13	Operate and maintain lifting devices and material handling equipment
5370.14	Manage hazardous materials
5371.0	USE AND MAINTAIN ACCESS EQUIPMENT
5371.1	Assemble and operate access equipment,
5371.2	Erect scaffolds
5371.3	Operate lifting equipment
5371.4	Select and use ladders
5372.0	PREPARE FOR PRODUCT APPLICATION
5372.1	Read and apply information from material safety data sheets (MSDS),
	product data sheets, application instruction sheets, and project specifications to
	ensure the proper application of coatings and linings.
5372.2	Identify required types of resins and additives, curing agents and
	mechanisms, and thinners and solvents,
5372.3	Identify the condition and characteristics of pre-existing coatings by
	using visual inspection, and destructive and non-destructive testing
	procedures, in accordance with industry standards.
5372.4	Perform water and/or chemical cleaning of substrates
5372.5	Perform mechanical cleaning by using power tools
5372.6	Prepare substrates by using hand tools

5372.7 5372.8	Etch concrete with chemicals Perform abrasive blasting of structural steel
5372.9	Perform abrasive blasting of concrete substrates
5373.0	APPLY COATINGS AND LININGS
5373.0	<b>Apply coatings and linings</b> by selecting, using, and maintaining the conventional (pneumatic), High Volume Low Pressure (HVLP), airless (hydraulic) spray, Air Assisted (AA) airless spray, and/or electrostatic spray equipment appropriate for the job, in accordance with manufacturers' specifications and instructions, material safety data sheets, company policy, site specific guidelines, the <i>Occupational Health and Safety Act</i> , and all applicable legislation.

5374.0	PRACTICE QUALITY CONTROL
5374.1	Complete Quality Control and/or Quality Assurance (QC/QA)
	documentation
5374.2	Perform ambient atmospheric testing
5374.3	Manage material inventory and storage
5374.4	Perform application testing by using non-destructive methods, such as wet
	and dry film thickness gauges
5374.5	Inspect substrate conditions using visual comparators, in accordance
	with