




- 1. ANT SW
- 2. DIST.
- 3. LOC.
- 4. MYLAR
- 5. MICA
- 6. STYROL
- 7. OFF
- 8. POWER SW
- 9. ON
- 10. OFF

- 1. ANT SW
- 2. DIST.
- 3. LOC.
- 4. MYLAR
- 5. MICA
- 6. STYROL
- 7. OFF
- 8. POWER SW
- 9. ON
- 10. OFF

*Wired-in Fuse
CSA Approved equipment only Plug 6V01A

POWER ADJUSTMENT
117V 100V 117V 140V 220V

