



Product Overview

SCRUBrite AP-581

Acid Activated Pumice

Product Description

SCRUBrite AP-581 is an acid activated, 3F pumice that chemically removes copper oxidation and imparts anti-tarnish properties on the copper surface during the pumice scrubbing process. AP-581 can be used dry or mixed with water to form a slurry. AP-581 is designed specifically for hand scrubbing applications and should not be used in automatic scrubbing equipment.

Physical Properties

Specific gravity:	2.2
pH (1% slurry):	<5
Appearance:	white to gray free flowing powder

Storage

Store in original containers above 40 °F.

Safety

CAUTION! AP-581 contains acidic components. Avoid contact with eyes, skin and clothing. Wear chemical handler's gloves, goggles and protective clothing when handling. Read and understand Material Safety Data Sheet before using this product.

Notice

The information and recommendations, contained herein, regarding this product are, to the best of our knowledge, true and accurate. We make no guarantee of results because the conditions of actual use are beyond our control. We assume no liability for damages or penalties resulting from the use of this product or following our recommendations. Our recommendations and suggestions for use of this product are not intended to grant license to operate under or infringe any patent.