


WELL BUBBLER 10-120 PRESSURE SENSOR WIRING DIAGRAM



Transducers
Direct TDH-33

WIRING INSTRUCTIONS		
WIRE	COLOR	TERMINAL #
POSITIVE	RED	13
NEGATIVE	BLACK	11

DRAWING	Well Bubbler 10-120 Pressure Sensor Wiring Diagram		
VERSION	1.0	PAGE	1 OF 1
DATE	02/05/19		
DRAWN BY	A. BUGROV		