


## WELL BUBBLER 5-120 WIRING DIAGRAM: 0-5V OUTPUT



MAIN HARNESS WIRING		
Designation	Color	Wire To
0-5V OUT NEG-	BLACK	External 0-5V NEG-
0-5V OUT POS+	RED	External 0-5V POS+
4-20mA OUT NEG-	GREEN	
4-20mA OUT POS+	WHITE	
FLOW PULSE NEG -	GREY	
GROUND GND	BROWN	
12V OUT POS+	BLUE	
18-24V DC IN POS+	PURPLE	

<b>DRAWING</b>	Well Bubbler 5-120 Wiring Diagram 0-5V Output		
<b>VERSION</b>	1.0	<b>PAGE</b>	1 OF 1
<b>DATE</b>	02/20/19		
<b>DRAWN BY</b>	A. BUGROV		