


WELL BUBBLER 5-120 WIRING DIAGRAM: 4-20mA OUTPUT



MAIN HARNESS WIRING		
Designation	Color	Wire To
0-5V OUT NEG-	BLACK	
0-5V OUT POS+	RED	
4-20mA OUT NEG-	GREEN	External 4-20mA NEG-
4-20mA OUT POS+	WHITE	External 4-20mA POS+
FLOW PULSE NEG -	GREY	
GROUND GND	BROWN	
12V OUT POS+	BLUE	
18-24V DC IN POS+	PURPLE	

DRAWING	Well Bubbler 5-120 Wiring Diagram 4-20mA Output		
VERSION	1.0	PAGE	1 OF 1
DATE	02/20/19		
DRAWN BY	A. BUGROV		