



C&M Lighting - Leader in Temporary Lighting

**The best temporary lighting products
Offers a full line at best pricing and all listed under UL 1088**

Don't Be Fooled by 18-2 integrated stringers

- Listed under the wrong UL Code 153
- Overpriced - and indoor use only
- Not enough lumens at 10 feet in the air
- If one lamp stops working it is non replaceable



C&M - UL 1088	Others - UL 153
Job Site Use	Not Intended for Job Sites - Household Only
Durable for Construction	Light Duty Only
Wet/Damp Rated	Indoor Only
Construction / Industrial Use	May violate code and compromise safety!

