



# CARE INSTRUCTIONS

Keep Your Magnetic Geode Prestine!

## Carrying + Handling

- Lift your geode from the edges giving your best effort to not leave finger prints on the piece. Finger prints can be removed but the less, the better!

## ⚠️ Cleaning + Dusting

- Some geodes will have acrylic (water-based) geode lines on the top surface to give them a "pop" look. **These lines CAN BE EASILY WIPED OFF.**
- Never spray and wipe the geode down. You will remove the "pop" lines and leave water marks.
- The *best practice* is to dry polish using a microfiber cloth or a dry paper towel. If truly needed, spray a cloth first then wipe and polish with intention.
- Do not wipe the acrylic geode lines. Work around them.
- A feather duster can be used to remove dust.

## Hanging

- Most Geodes are on premium plywood 3/4 inch thick. This is perfect for a D-ring hook to be drilled in the back of the art for hanging on a wall.
- Please make sure your wall can support the weight and that proper anchors are used in the wall. Geodes range from 15-30 lbs for most 3'x4' slabs.
- Use two D-ring hooks per piece.
- Make sure your screw for the d-ring is not longer than the 3/4 inch plywood.



D-ring hangers