## **WoodCove HOA Annual Meeting Agenda 9/25/25**

- 1.Call Meeting to order
- 2.Review last minutes Teri
- 3. Review Budget- Cindy
- 4.3: AA landscaping: Explanation Of projects
- .Unexpected repairs to water infrastructure:



Exhibits of A park #2-

A- Park #2 Main line brake. Replaced parts grass removed to complete work and Re-Sodded B-Home owner near Shack. The pump motor was very loud, water was coming into the homeowners back yard. Causing us to replace the motor with the spare we had.

C- Home owner- Line break in back yard water coming up into 2 home wonders. Replaced Because of the problems we have run into this year we have spent over 19,000.00 dollars. Now we'll have to replace the spare pump motor.

## Exhibits of A park #2-











Exhibits of C- on Pump Line brake behind home ower on 7840w now compleated





Tree Trim in Park#3 Compleat









## Resulting

A: An increase in HOA fees to buy a new motor for the pump house, prepared for possible line breaks, and all landscaping needs.


Forecasting a 15% increase in homeowner fees (from \$56.03 to \$64.43 per month).

<u>Use of Reserves explanation:</u> <u>woodcovehoa.com</u> >Governing Documents > Current Amendment and Restatement of Declaration of Covenants, Conditions and Restrictions. Current Bylaws

## Possible Project at a glance

Replacement \$19,513.98 + safety regulations and permit requirements.

Potential dues increase of \$12.81 per month to fund a playground project or special assessment



Part Number	Description	Qtv	Weight	Volume	Unit Price	Total	
200203668	Hypersonic Slide 8'	1	425.00	112.00	6,638.00	6,638.00	
Additional	Items						
Part Number	Description	Qty	Weight	Volume	Unit Price	Total	
105295	BAG ZIPLOCK 12" X 14"	1	0.00	0.00	0.00	0.00	
200111492	Label, Identification stamped w/rivets	1	0.00	0.00	0.00	0.00	
925960	THUMB DRIVE 2GB - PPLT	1	0.00	0.00	0.00	0.00	
INSTALL BK	INSTALL BOOK FOR PP ORDERS	1	0.00	0.00	0.00	0.00	
Parts By O	ther						
Part Number	Description	Qty	Weight	Volume	Unit Price	Total	
2by2412	4'x12" Containment Border/Steel Spike Combo Plastic Border panels	6	0.00	0.00	29.00	174.00	
2by2steel20	20" steel spike	1	0.00	0.00	13.00	13.00	
EWF	Engineered Wood Fiber Per a Cubic Yard / IPEMA Certified per cubic yard enough for 2357 sq ft of existing play area adding 7" depth	77	0.00	0.00	95.00	7,315.00	
2/6/2025					Page 1 of 4		

EWF	Delivered and blown in Engineered Wood Fiber Per a Cubic Yard / Certified per cubic yard		16	0.00	0.00	95.00	1,520.00
Filter Fab	enough for 319 sq ft of new additional play area adding depth Delivered and blown in Filter Fabric Material per sq ft. Filter Fabric for under new wood mulch area	12"	319	0.00	0.00	0.45	143.55
	Т	otals:					

Equipment Weight: 425.00 lbs
Equipment Volume: 12.00 ft
Equipment List: \$6,638.00
Discount Amount: \$-1,039.00
Products Subtotal: \$5,599.00
Products by Other: \$9,165.55
PBO Freight: \$179.00
Installation: \$3,500.00
Freight: \$0.00 Code: 200203668
Estimated Salos Tax": \$1,070.43
Grand Total: \$19,513.98

