

## IFS Kit HEUI Connection Points

Hi Folks,

A customer struggled connecting the 90 degree fitting to the HEUI output port due to secondary filter causing obstruction path coming out the top port of the HEUI and attempted to use the IFS straight fitting. The HEUI has TWO outlet ports. One is plugged with an internal hex, shown with the arrow, the other with the original FFS fitting.

The following photo shows an INCORRECT connection with the straight fitting connected to the TOP HEUI port rather the REAR port with the IFS hose 90 degree fitting. The REAR port is shown with an arrow. IF an obstruction creates an issue then simply move the original HEUI fitting to the REAR port and move the plug to the top port. These two ports are common to each other. However, the IFS 90 degree fitting connects to the HEUI outlet port, not the straight.



Once the customer sent me this photo I was able to advise on the port layout and the ability to use the rear port.

As always, we are a phone call away if any questions arise.  
Thank you,  
George