




# Discover the Oak's Manufacturing Difference



Cross-Sectional View  
Full 360° Supported Contact  
Ball — Solid one-piece  
construction with no welds  
that could chip, crack, or fail.



Aftermarket Friction Disk Jaw Plate,  
replaces Sandvik P/N BG00338144



Aftermarket Break Out Jaw, replaces  
Furukawa P/N E083402050240



Aftermarket Full Length Break Out Table Jaw,  
replaces Epiroc P/N 3222 3285 51 and spacer  
OEM P/N 3222 3113 62



Aftermarket Break Out Table Jaw, replaces  
Epiroc P/N 3222 3285 51

## Discover the Oak's Manufacturing Difference:

Our Generation 2 breakout table jaws are designed to exceed typical OEM performance standards:

- **Solid one-piece construction** — no welds to chip, crack, break, or cause part distortion.
- **Proprietary heat-treat process** — achieves higher Rockwell hardness than seen with most OEMs, without case hardening, ensuring consistent hardness throughout each contact “ball”.
- **Durable and reliable** — built to withstand the toughest conditions in the field!