




Discover the Oak's Manufacturing Difference



Aftermarket Market Friction Disk Jaw Plate, replaces Sandvik P/N BG00338144

Cross-Sectional View
Full 360° Supported Contact Ball — Solid one-piece construction with no welds that could chip, crack, or fail.



Aftermarket Full Length Break Out Table Jaw,
replaces Epiroc P/N 3222 3285 51 and spacer
OEM P/N 3222 3113 62



Aftermarket Market Break Out Jaw,
replaces Furukawa P/N E083402050240



Aftermarket Break Out Table Jaw, replaces
Epiroc P/N 3222 3285 51

Discover the Oak's Manufacturing Difference:

Our Generation 2 breakout table jaws are designed to exceed typical OEM performance standards:

- **Solid one-piece construction** — no welds to chip, crack, break, or cause part distortion.
- **Proprietary heat-treat process** — achieves higher Rockwell hardness than seen with most OEMs, without case hardening, ensuring consistent hardness throughout each contact “ball”.
- **Durable and reliable** — built to withstand the toughest conditions in the field since 2017!