

PISTON KIT CHART

PKCG-4001V
September 2018



WARNING

IT IS ESSENTIAL THAT INDOOR AND OUTDOOR UNITS BE PROPERLY MATCHED. FAILURE TO FOLLOW THESE INSTRUCTIONS OR TO PROPERLY MATCH EVAPORATORS AND CONDENSERS CAN RESULT IN UNIT DAMAGE, PROPERTY DAMAGE AND/OR PERSONAL INJURY. NO WARRANTY CLAIM WILL BE HONORED FOR MIX-MATCHED SYSTEMS THAT FAIL TO ADHERE TO THE SPECIFIED PISTON SIZE.

Outdoor Unit				Indoor Unit	Indoor Piston Size	Piston P/N	TXV Kit P/N (if used)	Note
GSX130181(B,C,D,E)*	VSX130181(A,B,D,E)*	ASX130181(B,C,D)*		All AHRI Matches	0.051	B1789851	TX2N4/TX2N4A	1,3
		ANX130181A*			0.051	B1789851	TX2N4/TX2N4A	1,3
		ANX130181B*			0.052	B1789852	TX2N4/TX2N4A	1,3
GSX130241(B,C,D)*	VSX130241(A,B,D)*	ASX130241(B,C)*		All other AHRI Matches	0.057	B1789857	TX2N4A	1,3
				CA*FA2418*6 & CA*FA24226	0.059	B1789859		
	VSX130241E*			All other AHRI Matches	0.055	B1789855	TX2N4A	1,3
				CA*FA2418*6 & CA*FA24226	0.057	B1789857		
		ANX130241A*			0.057	B1789857	TX2N4A	1,3
				All AHRI Matches	0.055	B1789855	TX2N4A	1,3
GSX130241E*		ASX130241B*		All other AHRI Matches	0.055	B1789855	TX3N4	1,3
				CA*FA2418*6 & CA*FA24226	0.057	B1789857		
GSX130242A*				A24-00-2R*	0.055	B1789855	TX2N4A	1,3
GSX130242XCA*				XRUF25B24A*	0.055	B1789855	TX2N4A	1,3
GSX130242XKA*				XRUF25B24A*	0.055	B1789855	TX2N4A	1,3
GSX130301(B,D)*	VSX130301(A,D)*	ASX130301(B,C)*		All other AHRI Matches	0.061	B1789861	TX3N4	1,3
				CA*FA3022*6	0.063	B1789865		
		ANX130301A*			0.061	B1789861	TX3N4	1,3
GSX130301L*	VSX130301L*	ANX130301B*		All other AHRI Matches	0.067	B1789867	TX3N4	1,3
				CA*FA3022*6	0.065	B1789865		
GSX130361(B,E)*	VSX130361(A,E)*	ASX130361(B,C,D)*		All AHRI Matches	0.070	B1789870	TX3N4	1,3
GSX130361D*	VSX130361D*			All AHRI Matches	0.067	B1789867	TX3N4	1,3
		ANX130361A*			0.070	B1789870	TX3N4	1,3
GSX130362A*				A36-00-2R*	0.065	B1789865	TX3N4	1,3
GSX130362XCA*				XRUF37C24A*	0.065	B1789865	TX3N4	1,3
GSX130362XKA*				XRUF37C24A*	0.072	B1789872	TX3N4	1,3
GSX130363A*				All AHRI Matches	0.070	B1789870	TX3N4	1,3
GSX130365A*				A36-00-2R*	0.065	B1789865	TX3N4	1,3
GSX130365XCA*				XRUF37C24A*	0.065	B1789865	TX3N4	1,3
GSX130365XKA*				XRUF37C24A*	0.072	B1789872	TX3N4	1,3
GSX130421B*	VSX130421(A,B)*	ASX130421(B,C)*		All AHRI Matches	0.076	B1789876	TX5N4	1,3
		ANX130421A*			0.076	B1789876	TX5N4	1,3

(*) SIGNIFIES UNIT REVISION.

(1) CORRECT PISTON IS SUPPLIED WITH THE OUTDOOR UNIT.

(2) CORRECT PISTON IS SUPPLIED IN THE HIGHEST SALES VOLUME TESTED COMBINATION INDOOR UNIT.

ALL OTHER INDOOR COMBINATIONS, PISTON MUST BE PURCHASED FROM DISTRIBUTOR.

(3) TXV MUST BE PURCHASED SEPARATELY.



PISTON KIT CHART

PKCG-4001V
September 2018



WARNING

IT IS ESSENTIAL THAT INDOOR AND OUTDOOR UNITS BE PROPERLY MATCHED. FAILURE TO FOLLOW THESE INSTRUCTIONS OR TO PROPERLY MATCH EVAPORATORS AND CONDENSERS CAN RESULT IN UNIT DAMAGE, PROPERTY DAMAGE AND/OR PERSONAL INJURY. NO WARRANTY CLAIM WILL BE HONORED FOR MIX-MATCHED SYSTEMS THAT FAIL TO ADHERE TO THE SPECIFIED PISTON SIZE.

Outdoor Unit				Indoor Unit	Indoor Piston Size	Piston P/N	TXV Kit P/N (if used)	Note
GSX130481B*	VSX130481A*	ASX130481(B,C)*		All AHRI Matches	0.080	B1789880	TX5N4	1,3
		ANX130481A*			0.080	B1789880	TX5N4	1,3
GSX130483A*				All AHRI Matches	0.080	B1789880	TX5N4	1,3
GSX130484A*				All AHRI Matches	0.080	B1789880	TX5N4	1,3
GSX130485A*				A48-00-2R* A50-00-2R	0.076	B1789876	TX5N4	1,3
GSX130485XCA*				XRUF49D24A*	0.076	B1789876	TX5N4	1,3
GSX130485XKA*				XRUF49D24A*	0.080	B1789880	TX5N4	1,3
GSX130601B*	VSX130601B*	ASX130601(B,C)*		All AHRI Matches	0.086	B1789886	TX5N4	1,3
		ANX130601A*			All AHRI Matches	0.086	B1789886	TX5N4
GSX130603A*				All AHRI Matches	0.086	B1789886	TX5N4	1,3
GSX130605A*				A60-00-2R	0.082	B1789882	TX5N4	1,3
GSX130605XCA*				XRUF61D24A*	0.082	B1789882	TX5N4	1,3
GSX130605XKA*				XRUF61D24A*	0.084	B1789884	TX5N4	1,3
GSX130611A*	VSX130611A*	ASX130611A*		ASUF49C14	0.086	B1789886	TX5N4	2,3
		ANX130611A*		All AHRI Matches	0.086	B1789886	TX5N4	1,3
					0.086	B1789886	TX5N4	1,3
GSX130613A*				ASUF49C14	0.086	B1789886	TX5N4	2,3
				All AHRI Matches	0.086	B1789886	TX5N4	1,3
GSX130604A*				All AHRI Matches	0.086	B1789886	TX5N4	1,3
GSX130605A*				A60-00-2R*	0.082	B1789882	TX5N4	1,3
GSX130614A*				ASUF49C14	0.086	B1789886	TX5N4	2,3
				All AHRI Matches	0.086	B1789886	TX5N4	1,3
GSX140181A*		ASX140181(B,C,D)*	SSX140181(A,B)*	AWUF31 & 32	0.051	B1789851	TX2N4/TX2N4A	2,3
				All other AHRI Matches	0.052	B1789852	TX2N4/TX2N4A	1,3
		ANX140191A*		AWUF 31 & 32	0.051	B1789851	TX2N4/TX2N4A	2,3
				All other AHRI Matches	0.053	B1789853	TX2N4/TX2N4A	1,3
GSX140241A*		ASX140241(B,C)*	SSX140241(A,B)*	AWUF 31	0.057	B1789857	TX2N4A	2,3
				All Other AHRI Matches	0.055	B1789855	TX2N4A	1,3
		ANX140241(A,B)*		All AHRI Matches	0.057	B1789857	TX2N4A	1,3
		ANX140251(A,B)*		All AHRI Matches	0.057	B1789857	TX2N4A	1,3
GSX140301A*		ASX140301(B,C)*	SSX140301(A,B)*	AWUF 31 & 32	0.061	B1789861	TX3N4	2,3
				All Other AHRI Matches	0.065	B1789865	TX3N4	1,3
		ANX140301A*		AWUF 31 & 32	0.061	B1789861	TX3N4	2,3
				All other AHRI Matches	0.065	B1789865	TX3N4	1,3

(*) SIGNIFIES UNIT REVISION.

(1) CORRECT PISTON IS SUPPLIED WITH THE OUTDOOR UNIT.

(2) CORRECT PISTON IS SUPPLIED IN THE HIGHEST SALES VOLUME TESTED COMBINATION INDOOR UNIT.

ALL OTHER INDOOR COMBINATIONS, PISTON MUST BE PURCHASED FROM DISTRIBUTOR.

(3) TXV MUST BE PURCHASED SEPARATELY.

PISTON KIT CHART

PKCG-4001V
September 2018



WARNING

IT IS ESSENTIAL THAT INDOOR AND OUTDOOR UNITS BE PROPERLY MATCHED. FAILURE TO FOLLOW THESE INSTRUCTIONS OR TO PROPERLY MATCH EVAPORATORS AND CONDENSERS CAN RESULT IN UNIT DAMAGE, PROPERTY DAMAGE AND/OR PERSONAL INJURY. NO WARRANTY CLAIM WILL BE HONORED FOR MIX-MATCHED SYSTEMS THAT FAIL TO ADHERE TO THE SPECIFIED PISTON SIZE.

Outdoor Unit				Indoor Unit	Indoor Piston Size	Piston P/N	TXV Kit P/N (if used)	Note
		ANX140311A*		AWUF 31 & 32 All other AHRI Matches CA*FA3022*6 & *FA3626*6	0.061 0.063 0.065	B1789861 B1789863 B1789865	TX3N4 TX3N4	2,3 1,3
GSX140361A*		ASX140361(B,C)*	SSX140361(A,B)*	All AHRI Matches	0.068	B1789868	TX3N4	1,3
		ANX140361A*		All AHRI Matches	0.068	B1789868	TX3N4	1,3
		ANX140371A*		All AHRI Matches	0.071	B1789871	TX3N4	1,3
GSX140421A*		ASX140421(C,D)*	SSX140421(B,C)*	All AHRI Matches	0.070	B1789870	TX5N4	1,3
		ANX140421A*		All AHRI Matches	0.074	B1789874	TX5N4	1,3
GSX140481A*		ASX140481C*	SSX140481B*	All AHRI Matches	0.078	B1789878	TX5N4	1,3
		ASX140481B*	SSX140481A*	All AHRI Matches	0.079	B1789879	TX5N4	1,3
		ANX140481A*		All AHRI Matches	0.078	B1789878	TX5N4	1,3
GSX140601A*		ASX140601(A,B)*	SSX140601A*	All AHRI Matches	0.088	B1789888	TX5N4	1,3
		ANX140601A*		All AHRI Matches	0.088	B1789888	TX5N4	1,3
GSX140181K*	VSX140181A*	ASX140181K*		AWUF19 AWUF 31 & 32 All other AHRI Matches	0.049 0.051 0.052	B1789849 B1789851 B1789852	TX2N4/TX2N4A TX2N4/TX2N4A TX2N4/TX2N4A	2,3 2,3 1,3
GSX140181L*	VSX140181B*			All other AHRI Matches	0.051	B1789851	TX2N4/TX2N4A	1,3
GSX140191K*	VSX140191A*	ASX140191K*		AWUF19 AWUF 31 & 32, ACNF25 All other AHRI Matches	0.049 0.051 0.053	B1789849 B1789851 B1789853	TX2N4/TX2N4A TX2N4/TX2N4A TX2N4/TX2N4A	2,3 2,3 1,3
GSX140241K*	VSX140241A*	ASX140241K*		AWUF25 All other AHRI Matches	0.055 0.057	B1789855 B1789857	TX2N4A TX2N4A	2,3 1,3
GSX140241L*	VSX140241B*	ANX140241(A,B)*		ACNF25 All other AHRI Matches	0.055 0.057	B1789855 B1789857	TX2N4 TX2N4	2,3 1,3
		ASX140241L*		CA*FA2418*6 & CA*FA2422*6 All other AHRI Matches	0.059 0.057	B1789859 B1789857	TX2N4A TX2N4A TX2N4	2,3 1,3
GSX140251K*	VSX140251A*	ASX140251K*		ACNF25 All other AHRI Matches	0.055 0.057	B1789855 B1789857	TX2N4A TX2N4A	2,3 1,3
GSX140251L*	VSX140251B*	ASX140251L* & ANX140251(A,B)*		ACNF25 All other AHRI Matches CA*FA2418*6 & CA*FA2422*6	0.055 0.057 0.059	B1789855 B1789857 B1789859	TX2N4A TX2N4A	2,3 1,3

(*) SIGNIFIES UNIT REVISION.

(1) CORRECT PISTON IS SUPPLIED WITH THE OUTDOOR UNIT.

(2) CORRECT PISTON IS SUPPLIED IN THE HIGHEST SALES VOLUME TESTED COMBINATION INDOOR UNIT.

ALL OTHER INDOOR COMBINATIONS, PISTON MUST BE PURCHASED FROM DISTRIBUTOR.

(3) TXV MUST BE PURCHASED SEPARATELY.

PISTON KIT CHART

PKCG-4001V
September 2018



WARNING

IT IS ESSENTIAL THAT INDOOR AND OUTDOOR UNITS BE PROPERLY MATCHED. FAILURE TO FOLLOW THESE INSTRUCTIONS OR TO PROPERLY MATCH EVAPORATORS AND CONDENSERS CAN RESULT IN UNIT DAMAGE, PROPERTY DAMAGE AND/OR PERSONAL INJURY. NO WARRANTY CLAIM WILL BE HONORED FOR MIX-MATCHED SYSTEMS THAT FAIL TO ADHERE TO THE SPECIFIED PISTON SIZE.

Outdoor Unit				Indoor Unit	Indoor Piston Size	Piston P/N	TXV Kit P/N (if used)	Note
GSX140301K*	VSX140301A*	ASX140301K*		AWUF 31 & 32	0.061	B1789861	TX3N4	2,3
				All other AHRI Matches	0.065	B1789865	TX3N4	1,3
	VSX140301B*			AWUF 31 & 32	0.061	B1789861	TX2N4A	2,3
				All other AHRI Matches	0.065	B1789865	TX2N4A	1,3
				CA*FA3022*6 & CA*FA3626*6	0.067	B1789867		
GSX140301L*		ANX140301B*		All other AHRI Matches	0.067	B1789867	TX3N4	1,3
				CA*FA3022*6 & CA*FA3626*6	0.065	B1789865		
GSX140311K*	VSX140311A*	ASX140311K*		AWUF 31 & 32	0.061	B1789861	TX3N4	2,3
				All other AHRI Matches	0.063	B1789863	TX3N4	1,3
				CA*FA3022*6 & CA*FA3626*6	0.065	B1789865		
GSX140361K*	VSX140361A*	ASX140361K*		All AHRI Matches	0.068	B1789868	TX3N4	1,3
GSX140371K*	VSX140371A*	ASX140371K*		All AHRI Matches	0.071	B1789871	TX3N4	1,3
GSX140421K*	VSX140421A*	ASX140421K*		All AHRI Matches	0.074	B1789874	TX5N4	1,3
GSX140481K*	VSX140481A*	ASX140481K*		All AHRI Matches	0.078	B1789878	TX5N4	1,3
GSX140601K*	VSX140601A*	ASX140601K*		All AHRI Matches	0.088	B1789888	TX5N4	1,3
GSX160181F*		ASX160181**		All AHRI Matches	0.049	B1789849	TXV-30	1,3
GSX16S181A*				All AHRI Matches	0.053	B1789853	TXV-30	1,3
GSX16A181A*				All AHRI Matches	0.049	B1789849	TXV-30	1,3
GSX160241F*		ASX160241**		ACNF30	0.059	B1789859	TXV-30	2,3
				All other AHRI Matches	0.057	B1789857	TXV-30	1,3
GSX16S241A*				All other AHRI Matches	0.06	B1789860	TXV-30	1,3
				CA*FA2418*6 & CA*FA2422*6	0.059	B1789859		
GSX16A241A*				ACNF30	0.059	B1789859	TXV-30	2,3
				All other AHRI Matches	0.057	B1789857	TXV-30	1,3
GSX160301F*		ASX160301**		ACNF30	0.063	B1789863	TXV-30	2,3
				All other AHRI Matches	0.065	B1789865	TXV-30	1,3
GSX16S301A*				ACNF30	0.063	B1789863	TXV-30	2,3
				All other AHRI Matches	0.065	B1789865	TXV-30	1,3
GSX160311A*		ASX160311A*		ACNF30	0.063	B1789863	TXV-30	2,3
				All other AHRI Matches	0.065	B1789865	TXV-30	1,3
GSX16A301A*				All AHRI Matches	0.063	B1789863	TXV-30	2,3
					0.065	B1789865	TXV-30	1,3

(*) SIGNIFIES UNIT REVISION.

(1) CORRECT PISTON IS SUPPLIED WITH THE OUTDOOR UNIT.

(2) CORRECT PISTON IS SUPPLIED IN THE HIGHEST SALES VOLUME TESTED COMBINATION INDOOR UNIT.

ALL OTHER INDOOR COMBINATIONS, PISTON MUST BE PURCHASED FROM DISTRIBUTOR.

(3) TXV MUST BE PURCHASED SEPARATELY.

PISTON KIT CHART

PKCG-4001V
September 2018



WARNING

IT IS ESSENTIAL THAT INDOOR AND OUTDOOR UNITS BE PROPERLY MATCHED. FAILURE TO FOLLOW THESE INSTRUCTIONS OR TO PROPERLY MATCH EVAPORATORS AND CONDENSERS CAN RESULT IN UNIT DAMAGE, PROPERTY DAMAGE AND/OR PERSONAL INJURY. NO WARRANTY CLAIM WILL BE HONORED FOR MIX-MATCHED SYSTEMS THAT FAIL TO ADHERE TO THE SPECIFIED PISTON SIZE.

Outdoor Unit				Indoor Unit	Indoor Piston Size	Piston P/N	TXV Kit P/N (if used)	Note
GSX160361F*		ASX160361**		All AHRI Matches	0.072	B1789872	TXV-42	1,3
GSX16S361A*				All AHRI Matches	0.072	B1789872	TXV-42	1,3
GSX160371A*		ASX160371A*		All AHRI Matches	0.072	B1789872	TXV-42	1,3
GSX16A361A*				All AHRI Matches	0.072	B1789872	TXV-42	1,3
GSX160421F*		ASX160421**		All AHRI Matches	0.074	B1789874	TXV-42	1,3
GSX16S421A*				All AHRI Matches	0.074	B1789874	TXV-42	1,3
GSX16A421A*				All AHRI Matches	0.074	B1789874	TXV-42	1,3
GSX160481F*		ASX160481**		All AHRI Matches	0.078	B1789878	TXV-48	1,3
GSX16S481A*				All AHRI Matches	0.078	B1789878	TXV-48	1,3
GSX16A481A*				All AHRI Matches	0.078	B1789878	TXV-48	1,3
GSX160601F*		ASX160601**		All AHRI Matches	0.086	B1789886	TXV-60	1,3
GSX160611F*		ASX160611F*		All AHRI Matches	0.088	B1789888	TXV-60	1,3
GSX16A601A*				All AHRI Matches	0.086	B1789886	TXV-60	1,3
GSX16A611A*				All AHRI Matches	0.088	B1789888	TXV-60	1,3
			SSX160241B*	All AHRI Matches	0.055	B1789855	TX2N4/TX2N4A	1,3
			SSX160301A*	All AHRI Matches	0.062	B1789862	TX3N4	1,3
			SSX160361(A,B)*	All AHRI Matches	0.068	B1789868	TX3N4	1,3
			SSX160421A*	All AHRI Matches	0.070	B1789870	TX5N4	1,3
			SSX160481(A,B)*	All AHRI Matches	0.078	B1789878	TX5N4	1,3
			SSX160591A*	All AHRI Matches	N/A	TXV only	TX5N4	3
			SSX160601(A,B)*	All AHRI Matches	N/A	TXV only	TX5N4	3
		ASXC160241B*	DSXC160241A*	All AHRI Matches	N/A	TXV only	TX2N4A	3
		ASXC160361B*	DSXC160361A*	All AHRI Matches	N/A	TXV only	TX3N4	3
		ASXC160481(A,B)*	DSXC160481(A,B)*	All AHRI Matches	N/A	TXV only	TX5N4	3
		ASXC160601(A,B)*	DSXC160601(A,B)*	All AHRI Matches	N/A	TXV only	TX5N4	3
		ASXC180361A*	DSXC180361A*	All AHRI Matches	N/A	TXV only	TX3N4	3
		ASXC180481A*	DSXC180481A*	All AHRI Matches	N/A	TXV only	TX5N4	3
		ASXC180601A*	DSXC180601A*	All AHRI Matches	N/A	TXV only	TX5N4	3
GSXC160241C*		ASXC160241C*		All AHRI Matches	N/A	TXV only	TX2N4A	3
GSXC160361C*		ASXC160361C*		All AHRI Matches	N/A	TXV only	TX3N4	3
GSXC160481C*		ASXC160481C*		All AHRI Matches	N/A	TXV only	TX5N4	3
GSXC160601C*		ASXC160601C*		All AHRI Matches	N/A	TXV only	TX5N4	3
GSXC180241B*		ASXC180241B*		All AHRI Matches	N/A	TXV only	TX2N4A	3
GSXC180361B*		ASXC180361B*		All AHRI Matches	N/A	TXV only	TX3N4	3
GSXC180481B*		ASXC180481B*		All AHRI Matches	N/A	TXV only	TX5N4	3

(*) SIGNIFIES UNIT REVISION.

(1) CORRECT PISTON IS SUPPLIED WITH THE OUTDOOR UNIT.

(2) CORRECT PISTON IS SUPPLIED IN THE HIGHEST SALES VOLUME TESTED COMBINATION INDOOR UNIT.

ALL OTHER INDOOR COMBINATIONS, PISTON MUST BE PURCHASED FROM DISTRIBUTOR.

(3) TXV MUST BE PURCHASED SEPARATELY.

PISTON KIT CHART

PKCG-4001V
September 2018



WARNING

IT IS ESSENTIAL THAT INDOOR AND OUTDOOR UNITS BE PROPERLY MATCHED. FAILURE TO FOLLOW THESE INSTRUCTIONS OR TO PROPERLY MATCH EVAPORATORS AND CONDENSERS CAN RESULT IN UNIT DAMAGE, PROPERTY DAMAGE AND/OR PERSONAL INJURY. NO WARRANTY CLAIM WILL BE HONORED FOR MIX-MATCHED SYSTEMS THAT FAIL TO ADHERE TO THE SPECIFIED PISTON SIZE.

Outdoor Unit			Indoor Unit	Indoor Piston Size	Piston P/N	TXV Kit P/N (if used)	Note
GSXC180601B*		ASXC180601B*	All AHRI Matches	N/A	TXV only	TX5N4	3
GSC130181(B,D,F,G,H)*			All AHRI Matches	0.055	B1789855	TX2N2	1,3
GSC130241(D,E)*			All AHRI Matches	0.059	B1789859	TX2N2	1,3
GSC130241F*			All AHRI Matches	0.061	B1789861	TX2N2	1,3
GSC130301E*			All AHRI Matches	0.065	B1789865	TX3N2	1,3
GSC130361(A*-F*/G*)			All AHRI Matches	0.074	B1789874	TX3N2	1,3
GSC130363(A*, BA, BB)			All AHRI Matches	0.074	B1789874	TX3N2	1,3
GSC130363B*			All AHRI Matches	0.071	B1789871	TX3N2	1,3
GSC130421C*			All AHRI Matches	0.076	B1789876	TX5N2	1,3
GSC130481(B,C)*			All AHRI Matches	0.082	B1789882	TX5N2	1,3
GSC130483(B,C)*			All AHRI Matches	0.082	B1789882	TX5N2	1,3
GSC130484(A,B)*			All AHRI Matches	0.082	B1789882	TX5N2	1,3
GSC130601C*			All AHRI Matches	0.093	B1789893	TX5N2	1,3
GSC130601D*			All AHRI Matches	0.090	B1789890	TX5N2	1,3
GSC130603B*			All AHRI Matches	0.093	B1789893	TX5N2	1,3
GSC130603C*			All AHRI Matches	0.090	B1789890	TX5N2	1,3
GSC130604(A*, BA, BB)			All AHRI Matches	0.093	B1789893	TX5N2	1,3
GSC130604B*			All AHRI Matches	0.090	B1789890	TX5N2	1,3
GSZ130181A*	VSZ130181A*	ASZ130181A*	All AHRI Matches	0.051	B1789851	TX2N4/TX2N4A	1,3
		ANZ130181A*		0.051	B1789851	TX2N4/TX2N4A	1,3
GSZ130241(A,B)*	VSZ130241B*	ASZ130241(A,B)*	All AHRI Matches	0.057	B1789857	TX2N4A	1,3
GSZ130242A*			A24-00-2R*	0.057	B1789857	TX2N4A	1,3
GSZ130242XCA*			XRUF25B24A*	0.057	B1789857	TX2N4A	1,3
		ANZ130241A*		0.057	B1789857	TX2N4A	1,3
GSZ130301A*	VSZ130301A*	ASZ130301A*	All AHRI Matches	0.065	B1789865	TX3N4	1,3
		ANZ130301A*		0.065	B1789865	TX3N4	1,3
GSZ130361B*	VSZ130361B*		ARUF36C	0.071	B1789871	TX3N4	2,3
			All AHRI Matches	0.071	B1789871	TX3N4	1,3
GSZ130361A*	VSZ130361A*	ASZ130361A*	ARUF36C	0.071	B1789871	TX3N4	2,3
			AR*F3636	0.070	B1789870	TX3N4	2,3
			All Other AHRI Matches	0.068	B1789868	TX3N4	1,3
		ANZ130361A*	ARUF36C	0.071	B1789871	TX3N4	2,3
			AR*F3636	0.070	B1789870	TX3N4	2,3
			All Other AHRI Matches	0.071	B1789871	TX3N4	1,3

(*) SIGNIFIES UNIT REVISION.

(1) CORRECT PISTON IS SUPPLIED WITH THE OUTDOOR UNIT.

(2) CORRECT PISTON IS SUPPLIED IN THE HIGHEST SALES VOLUME TESTED COMBINATION INDOOR UNIT.

ALL OTHER INDOOR COMBINATIONS, PISTON MUST BE PURCHASED FROM DISTRIBUTOR.

(3) TXV MUST BE PURCHASED SEPARATELY.

PISTON KIT CHART

PKCG-4001V
September 2018



WARNING

IT IS ESSENTIAL THAT INDOOR AND OUTDOOR UNITS BE PROPERLY MATCHED. FAILURE TO FOLLOW THESE INSTRUCTIONS OR TO PROPERLY MATCH EVAPORATORS AND CONDENSERS CAN RESULT IN UNIT DAMAGE, PROPERTY DAMAGE AND/OR PERSONAL INJURY. NO WARRANTY CLAIM WILL BE HONORED FOR MIX-MATCHED SYSTEMS THAT FAIL TO ADHERE TO THE SPECIFIED PISTON SIZE.

Outdoor Unit				Indoor Unit	Indoor Piston Size	Piston P/N	TXV Kit P/N (if used)	Note
GSZ130362A*				A36-00-2R*	0.071	B1789871	TX3N4	1,3
GSZ130362XCA*				XRUF37C24A*	0.071	B1789871	TX3N4	1,3
GSZ130363A*				AR*F3636	0.070	B1789870	TX3N4	2,3
				All Other AHRI Matches	0.068	B1789868	TX3N4	1,3
GSZ130365A*				A36-00-2R*	0.071	B1789871	TX3N4	1,3
GSZ130365XCA*				XRUF37C24A*	0.071	B1789871	TX3N4	1,3
GSZ130421A*	VSZ130421A*	ASZ130421A*		All AHRI Matches	0.072	B1789872	TX5N4	1,3
		ANZ130421A*			0.072	B1789872	TX5N4	1,3
GSZ130481A*	VSZ130481A*	ASZ130481A*		All AHRI Matches	0.078	B1789878	TX5N4	1,3
		ANZ130481A*			0.078	B1789878	TX5N4	1,3
GSZ130483A*				All AHRI Matches	0.078	B1789878	TX5N4	1,3
GSZ130484A*				All AHRI Matches	0.078	B1789878	TX5N4	1,3
GSZ130485A*				A48-00-2R*	0.078	B1789878	TX5N4	1,3
				A50-00-2R				
GSZ130485XCA*				XRUF49D24A	0.078	B1789878	TX5N4	1,3
GSZ130601A*	VSZ130601A*	ASZ130601A*		CHPF4860D6D*	0.086	B1789886	TX5N4	1,3
		ANZ130601A*		All Other AHRI Matches	0.088	B1789888	TX5N4	1,3
					0.088	B1789888	TX5N4	1,3
GSZ130603A*				CHPF4860D6D*	0.086	B1789886	TX5N4	1,3
				All Other AHRI Matches	0.088	B1789888	TX5N4	1,3
GSZ130604A*				CHPF4860D6D*	0.086	B1789886	TX5N4	1,3
				All Other AHRI Matches	0.088	B1789888	TX5N4	1,3
GSZ130605A*				A60-00-2R*	0.088	B1789888	TX5N4	1,3
GSZ130605XCA*				XRUF61D24A*	0.088	B1789888	TX5N4	1,3
GSH130181(B,C)*				All AHRI Matches	0.055	B1789855	TX2N2	1,3
GSH130241(B,C)*				All AHRI Matches	0.061	B1789861	TX2N2	1,3
GSH130301(B,C)*				All AHRI Matches	0.070	B1789870	TX3N2	1,3
GSH130361(A,B)*				All AHRI Matches	0.073	B1789873	TX3N2	1,3
GSH130361C*				All AHRI Matches	0.071	B1789871	TX3N2	1,3
GSH130363A*				All AHRI Matches	0.071	B1789871	TX5N2	1,3
GSH130421A*				All AHRI Matches	0.082	B1789882	TX5N2	1,3
GSH130421B*				All AHRI Matches	0.080	B1789880	TX5N2	1,3
GSH130481(A, B)*				All AHRI Matches	0.084	B1789884	TX5N2	1,3
GSH130483(A, B)*				All AHRI Matches	0.084	B1789884	TX5N2	1,3

(*) SIGNIFIES UNIT REVISION.

(1) CORRECT PISTON IS SUPPLIED WITH THE OUTDOOR UNIT.

(2) CORRECT PISTON IS SUPPLIED IN THE HIGHEST SALES VOLUME TESTED COMBINATION INDOOR UNIT.

ALL OTHER INDOOR COMBINATIONS, PISTON MUST BE PURCHASED FROM DISTRIBUTOR.

(3) TXV MUST BE PURCHASED SEPARATELY.

PISTON KIT CHART

PKCG-4001V
September 2018



WARNING

IT IS ESSENTIAL THAT INDOOR AND OUTDOOR UNITS BE PROPERLY MATCHED. FAILURE TO FOLLOW THESE INSTRUCTIONS OR TO PROPERLY MATCH EVAPORATORS AND CONDENSERS CAN RESULT IN UNIT DAMAGE, PROPERTY DAMAGE AND/OR PERSONAL INJURY. NO WARRANTY CLAIM WILL BE HONORED FOR MIX-MATCHED SYSTEMS THAT FAIL TO ADHERE TO THE SPECIFIED PISTON SIZE.

Outdoor Unit				Indoor Unit	Indoor Piston Size	Piston P/N	TXV Kit P/N (if used)	Note
GSH130484A*				All AHRI Matches	0.084	B1789884	TX5N2	1,3
GSH130601A*				All AHRI Matches	0.093	B1789893	TX5N2	1,3
GSH130603A*				All AHRI Matches	0.093	B1789893	TX5N2	1,3
GSH130604A*				All AHRI Matches	0.093	B1789893	TX5N2	1,3
GSZ140181A*		ASZ140181A*		AWUF31	0.051	B1789851	TX2N4/TX2N4A	2,3
				ARUF30B14	0.052	B1789852	TX2N4/TX2N4A	2,3
				All AHRI Matches	N/A	TXV only	TX2N4/TX2N4A	3
		ANZ140181A*		All AHRI Matches	0.051	B1789851	TX2N4A	1,3
GSZ140191A*				AWUF19**16A*	0.047	B1789847	TX2N4A	2
				ACNF31**16A*	0.049	B1789849	TX2N4A	2
				AR*F31B14A*	0.051	B1789851	TX2N4A	1
				AWUF31B14A*	0.051	B1789851	TX2N4A	1
				All Other AHRI Matches	TX2N4A	TX2N4A	TX2N4A	3
GSZ140241A*		ASZ140241A*		AWUF31 & 32	0.057	B1789857	TX2N4A	2,3
				All AHRI Matches	N/A	TXV only	TX2N4A	3
		ANZ140241A*		All AHRI Matches	0.057	B1789857	TX2N4A	1,3
GSZ140251A*				AWUF25**16A*	0.055	B1789855	TX2N4A	2
				AWUF31**16A*	0.057	B1789857	TX2N4A	1
				AWUF32**16A*	0.057	B1789857	TX2N4A	1
				ACNF31**16A*	0.057	B1789857	TX2N4A	1
				All Other AHRI Matches	TX2N4A	TX2N4A	TX2N4A	3
GSZ140301A*		ASZ140301A*		AWUF31 & 32	0.065	B1789865	TX3N4	2,3
				ARUF30B14	0.065	B1789865	TX3N4	2,3
				All AHRI Matches	N/A	TXV only	TX3N4	3
		ANZ140301A*		All AHRI Matches	0.065	B1789865	TX3N4	1,3
GSZ140311A*				AWUF31**16A*	0.065	B1789865	TX3N4	1
				AWUF32**16A*	0.065	B1789865	TX3N4	1
				All Other AHRI Matches	TXV only	TX3N4	TX3N4	3
GSZ140361A*				All AHRI Matches	N/A	TXV only	TX3N4	3
		ANZ140361A*		All AHRI Matches	0.072	B1789872	TX3N4	1,3
		ASZ140361(A,B)*		All AHRI Matches	N/A	TXV only	TX3N4	3
		ASZ140381A*		All AHRI Matches	0.072	B1789872	TX3N4	1,3
GSZ140371A*				All AHRI Matches	TXV only	TX3N4	TX3N4	3

(*) SIGNIFIES UNIT REVISION.

(1) CORRECT PISTON IS SUPPLIED WITH THE OUTDOOR UNIT.

(2) CORRECT PISTON IS SUPPLIED IN THE HIGHEST SALES VOLUME TESTED COMBINATION INDOOR UNIT.

ALL OTHER INDOOR COMBINATIONS, PISTON MUST BE PURCHASED FROM DISTRIBUTOR.

(3) TXV MUST BE PURCHASED SEPARATELY.

PISTON KIT CHART

PKCG-4001V
September 2018



WARNING

IT IS ESSENTIAL THAT INDOOR AND OUTDOOR UNITS BE PROPERLY MATCHED. FAILURE TO FOLLOW THESE INSTRUCTIONS OR TO PROPERLY MATCH EVAPORATORS AND CONDENSERS CAN RESULT IN UNIT DAMAGE, PROPERTY DAMAGE AND/OR PERSONAL INJURY. NO WARRANTY CLAIM WILL BE HONORED FOR MIX-MATCHED SYSTEMS THAT FAIL TO ADHERE TO THE SPECIFIED PISTON SIZE.

Outdoor Unit			Indoor Unit	Indoor Piston Size	Piston P/N	TXV Kit P/N (if used)	Note	
GSZ140421A*			All AHRI Matches	N/A	TVX only	TX5N4	3	
		ASZ140421A*	All AHRI Matches	N/A	TVX only	TX5N4	3	
		ANZ140421A*	All AHRI Matches	0.078	B1789878	TX5N4	1,3	
GSZ140481A*			All AHRI Matches	0.080	B1789880	TX5N4	1,3	
		ASZ140481A*	All AHRI Matches	N/A	TVX only	TX5N4	3	
		ANZ140481A*	All AHRI Matches	0.080	B1789880	TX5N4	1,3	
		ANZ140491A*	All AHRI Matches	0.080	B1789880	TX5N4	1,3	
GSZ140601A*			All AHRI Matches	N/A	TVX only	TX5N4	3	
		ASZ140601A*	ASUF59	0.088	B1789888	TX5N4	2,3	
			All AHRI Matches	N/A	TVX only	TX5N4	3	
		ANZ140601A*	All AHRI Matches	0.088	B1789888	TX5N4	1,3	
GSZ140181K*	VSZ140181A*	ASZ140181K*	All AHRI Matches	0.051	B1789851	TX2N4A	1,3	
GSZ140181L*	VSZ140181B*	ANZ140181L*	All AHRI Matches	0.051	B1789851	TX2N4A	1,3	
GSZ140241K*	VSZ140241A*	ASZ140241K*	All AHRI Matches	0.057	B1789857	TX2N4A	1,3	
GSZ140301K*	VSZ140301A*	ASZ140301K*	All AHRI Matches	0.065	B1789865	TX3N4	1,3	
GSZ140361K*	VSZ140361A*	ASZ140361K*	All AHRI Matches	0.072	B1789872	TX3N4	1,3	
GSZ140421K*	VSZ140421A*	ASZ140421K*	All AHRI Matches	0.078	B1789878	TX5N4	1,3	
GSZ140481K*	VSZ140481A*	ASZ140481K*	All AHRI Matches	0.080	B1789880	TX5N4	1,3	
GSZ140491K*	VSZ140491A*	ASZ140491K*	All AHRI Matches	0.080	B1789880	TX5N4	1,3	
GSZ140601K*	VSZ140601A*	ASZ140601K*	All AHRI Matches	0.088	B1789888	TX5N4	1,3	
			SSZ140181(A,B)*	AWUF31	0.051	B1789851	TX2N4/TX2N4A	2,3
				All AHRI Matches	N/A	TVX only	TX2N4/TX2N4A	3
			SSZ140241(A,B)*	AWUF 31 & 32	0.057	B1789857	TX2N4A	2,3
				All Other AHRI Matches	N/A	TVX only	TX2N4A	3
			SSZ140301(A,B)*	AWUF 31 & 32	0.065	B1789865	TX3N4	2,3
				All Other AHRI Matches	N/A	TVX only	TX3N4	3
			SSZ140361(A,B)*	All AHRI Matches	N/A	TVX only	TX3N4	3
			SSZ140381A*	All AHRI Matches	N/A	TVX only	TX3N4	3
			SSZ140421A*	All AHRI Matches	N/A	TVX only	TX5N4	3
			SSZ140481A*	All AHRI Matches	N/A	TVX only	TX5N4	3
			SSZ140601A*	All AHRI Matches	N/A	TVX only	TX5N4	3
GSZ160181B*		ASZ160181L*	ACNF31	0.051	B1789851	TX2N4A	2,3	
			All AHRI Matches	N/A	TVX only	TX2N4A	3	
GSZ160241B*		ASZ160241L*	ACNF31	0.061	B1789861	TX2N4A	2,3	
			All AHRI Matches	N/A	TVX only	TX2N4A	3	

(*) SIGNIFIES UNIT REVISION.

(1) CORRECT PISTON IS SUPPLIED WITH THE OUTDOOR UNIT.

(2) CORRECT PISTON IS SUPPLIED IN THE HIGHEST SALES VOLUME TESTED COMBINATION INDOOR UNIT.

ALL OTHER INDOOR COMBINATIONS, PISTON MUST BE PURCHASED FROM DISTRIBUTOR.

(3) TXV MUST BE PURCHASED SEPARATELY.

PISTON KIT CHART

PKCG-4001V
September 2018



WARNING

IT IS ESSENTIAL THAT INDOOR AND OUTDOOR UNITS BE PROPERLY MATCHED. FAILURE TO FOLLOW THESE INSTRUCTIONS OR TO PROPERLY MATCH EVAPORATORS AND CONDENSERS CAN RESULT IN UNIT DAMAGE, PROPERTY DAMAGE AND/OR PERSONAL INJURY. NO WARRANTY CLAIM WILL BE HONORED FOR MIX-MATCHED SYSTEMS THAT FAIL TO ADHERE TO THE SPECIFIED PISTON SIZE.

Outdoor Unit				Indoor Unit	Indoor Piston Size	Piston P/N	TXV Kit P/N (if used)	Note
GSZ160301B*		ASZ160301L*		All AHRI Matches	N/A	TXV only	TX3N4	3
GSZ160361B*		ASZ160361L*		All AHRI Matches	N/A	TXV only	TX3N4	3
GSZ160421B*		ASZ160421L*		All AHRI Matches	N/A	TXV only	TX5N4	3
GSZ160481B*		ASZ160481L*		All AHRI Matches	N/A	TXV only	TX5N4	3
GSZ160601B*		ASZ160601L*		All AHRI Matches	N/A	TXV only	TX5N4	3
		ASZ160241(A,K)*	SSZ160241A*	All AHRI Matches	N/A	TXV only	TX2N4A	3
		ASZ160361(A,K)*	SSZ160361A*	All AHRI Matches	N/A	TXV only	TX3N4	3
		ASZ160481(A,K)*	SSZ160481A*	All AHRI Matches	N/A	TXV only	TX5N4	3
		ASZ160601(A,K)*	SSZ160601(A,B)*	All AHRI Matches	N/A	TXV only	TX5N4	3
		ASZC160241A*	DSZC160241A*	All AHRI Matches	N/A	TXV only	TX2N4A	3
		ASZC160361A*	DSZC160361A*	All AHRI Matches	N/A	TXV only	TX3N4	3
		ASZC160481A*	DSZC160481A*	All AHRI Matches	N/A	TXV only	TX5N4	3
		ASZC160601(A,B)*	DSZC160601(A,B)*	All AHRI Matches	N/A	TXV only	TX5N4	3
		ASZC180361A*	DSZC180361A*	All AHRI Matches	N/A	TXV only	TX3N4	3
		ASZC180481A*	DSZC180481A*	All AHRI Matches	N/A	TXV only	TX5N4	3
		ASZC180601(A,B)*	DSZC180601(A,B)*	All AHRI Matches	N/A	TXV only	TX5N4	3
GSZC160241C*		ASZC160241C*		All AHRI Matches	N/A	TXV only	TX2N4A	3
GSZC160361C*		ASZC160361C*		All AHRI Matches	N/A	TXV only	TX3N4	3
GSZC160481C*		ASZC160481C*		All AHRI Matches	N/A	TXV only	TX5N4	3
GSZC160601C*		ASZC160601C*		All AHRI Matches	N/A	TXV only	TX5N4	3
GSZC180241C*		ASZC180241C*		All AHRI Matches	N/A	TXV only	TX2N4A	3
GSZC180361C*		ASZC180361C*		All AHRI Matches	N/A	TXV only	TX3N4	3
GSZC180481C*		ASZC180481C*		All AHRI Matches	N/A	TXV only	TX5N4	3
GSZC180601C*		ASZC180601C*		All AHRI Matches	N/A	TXV only	TX5N4	3
CKL36-1P*				All AHRI Matches	0.071	B1789871	N/A	1
CKL49-1P*				All AHRI Matches	0.080	B1789880	N/A	1
CKL60-1P*				All AHRI Matches	0.093	B1789893	N/A	1
CK60-3P*				All AHRI Matches	0.093	B1789893	N/A	1
CKF36-2P*				All AHRI Matches	0.068	B1789868	N/A	1
CKF36-5P*				All AHRI Matches	0.068	B1789868	N/A	1
CKF48-5P*				All AHRI Matches	0.080	B1789880	N/A	1
CKF60-5P*				All AHRI Matches	0.093	B1789893	N/A	1
CPKF36-2P*				All AHRI Matches	0.073	B1789873	N/A	1
CPKF36-5P*				All AHRI Matches	0.073	B1789873	N/A	1
CPKF48-5P*				All AHRI Matches	0.084	B1789884	N/A	1

(*) SIGNIFIES UNIT REVISION.

(1) CORRECT PISTON IS SUPPLIED WITH THE OUTDOOR UNIT.

(2) CORRECT PISTON IS SUPPLIED IN THE HIGHEST SALES VOLUME TESTED COMBINATION INDOOR UNIT.

ALL OTHER INDOOR COMBINATIONS, PISTON MUST BE PURCHASED FROM DISTRIBUTOR.

(3) TXV MUST BE PURCHASED SEPARATELY.

PISTON KIT CHART

PKCG-4001V
September 2018



WARNING

IT IS ESSENTIAL THAT INDOOR AND OUTDOOR UNITS BE PROPERLY MATCHED. FAILURE TO FOLLOW THESE INSTRUCTIONS OR TO PROPERLY MATCH EVAPORATORS AND CONDENSERS CAN RESULT IN UNIT DAMAGE, PROPERTY DAMAGE AND/OR PERSONAL INJURY. NO WARRANTY CLAIM WILL BE HONORED FOR MIX-MATCHED SYSTEMS THAT FAIL TO ADHERE TO THE SPECIFIED PISTON SIZE.

Outdoor Unit				Indoor Unit	Indoor Piston Size	Piston P/N	TXV Kit P/N (if used)	Note
CPKF60-5N*				All AHRI Matches	0.093	B1789893	N/A	1
CPKF60-5P*				All AHRI Matches	0.093	B1789893	N/A	1
CPKF61-5N*				All AHRI Matches	0.093	B1789893	N/A	1
CPKF61-5P*				All AHRI Matches	0.093	B1789893	N/A	1

(*) SIGNIFIES UNIT REVISION.

(1) CORRECT PISTON IS SUPPLIED WITH THE OUTDOOR UNIT.

(2) CORRECT PISTON IS SUPPLIED IN THE HIGHEST SALES VOLUME TESTED COMBINATION INDOOR UNIT.

ALL OTHER INDOOR COMBINATIONS, PISTON MUST BE PURCHASED FROM DISTRIBUTOR.

(3) TXV MUST BE PURCHASED SEPARATELY.

PISTON KIT CHART

PKCG-4001V
September 2018



WARNING

IT IS ESSENTIAL THAT INDOOR AND OUTDOOR UNITS BE PROPERLY MATCHED. FAILURE TO FOLLOW THESE INSTRUCTIONS OR TO PROPERLY MATCH EVAPORATORS AND CONDENSERS CAN RESULT IN UNIT DAMAGE, PROPERTY DAMAGE AND/OR PERSONAL INJURY. NO WARRANTY CLAIM WILL BE HONORED FOR MIX-MATCHED SYSTEMS THAT FAIL TO ADHERE TO THE SPECIFIED PISTON SIZE.

Outdoor Unit	Indoor Unit	Indoor Piston Size	Piston P/N	TXV Kit P/N (if used)	Note
--------------	-------------	--------------------	------------	-----------------------	------

THIS PAGE LEFT INTENTIONALLY BLANK

(*) SIGNIFIES UNIT REVISION.

(1) CORRECT PISTON IS SUPPLIED WITH THE OUTDOOR UNIT.

(2) CORRECT PISTON IS SUPPLIED IN THE HIGHEST SALES VOLUME TESTED COMBINATION INDOOR UNIT.

ALL OTHER INDOOR COMBINATIONS, PISTON MUST BE PURCHASED FROM DISTRIBUTOR.

(3) TXV MUST BE PURCHASED SEPARATELY.