



AIRCRAFT TECHNICAL LOGS

Section 2. RECORD OF INSTALLATIONS & MODIFICATIONS TO AIRCRAFT

**Aeronautical Standards and
Legislation Branch**

AIRFRAME LOG

1. Nationality and Registration C G D Y S
2. Manufacturer's Designation CESSNA 441
S/N 414 - 0004
3. Record of
 - (a) Engine Installations
 - (b) Propeller Installations
 - (c) Airworthiness Directives (A/D)
 - (d) Service Bulletins (S/B)
 - (e) Special Inspections (S/I)
 - (f) Modifications (MODS)

RECORD OF ENGINE &

DATE	ENGINE OR PROPELLER MAKE & MODEL	SERIAL NO.	POSITION	DATE INSTALLED	DATE REMOVED
04 APR 94	TECH TSIO-520-NB	508541	RIGHT	11 APR 94	15 OCT 97
04 JAN 95	HARTZELL	748129	RIGHT	01 JAN 95	15 OCT 97
10 JUL 95	TECH TSIO-520-NB	521470	LEFT	10 JUL 95	
10 JUL 95	HARTZELL SAF 32C 93 N	748136	LEFT	10 JUL 95	
1 NOV 97	CONTINENTAL/PM TSIO-520-NB	509541	RIGHT	7 NOV 97	

PROPELLER INSTALLATION

REMARKS . REASON FOR CHANGE	SIGNATURE	LICENCE NUMBER
INSTALLED NEWLY IN ENG. FROM R.A.M. BY R.A.M. CRANKCASE DAMAGED REMOVED SENT TO R.A.M.	C. J. J. J. J. C. J. J. J. J.	11111222 11111222
INSTALLED "H.B.V." HOOK RECD PROPELLER REMOVED FOR ENGINE REMOVAL	C. J. J. J. J. C. J. J. J. J.	11111222 11111222
ENGINE INSTALLED BY R.A.M. "H.B.V." R.A.M.	C. J. J. J. J.	11111222
INSTALLED AFTER ENGINE ENGINE INSTALLATION.	C. J. J. J. J.	11111222
CRANKCASE REPLACED BY R.A.M. - WIKO TEXAS	C. J. J. J. J.	1333465.

AIRWORTHINESS DIRECTIVES (A/D), SERVICE BULLETINS (SA)

DATE	A/D, S/B, S/I, MODS	DETAILS OF
15 OCT 97	DUGEN BOTTLE	"O" RING STATIC TEST DUE - 15 OCT 98.
15 OCT 97	EMERGENCY EXIT	DUE - 15 OCT 98.
15 OCT 97	WIRE PHOTOGRAPHIC TENSION	DUE - 15 OCT 98.
15 OCT 97	ALL ELEVATOR CABLE TRAVEL	DUE - 15 OCT 98.
15 OCT 97	ALL ELEVATOR TRIM TRAVEL	CABLE TENSION DUE - 15 OCT 98.
15 OCT 97	SLIDER CONTROL SYSTEM ENTRY TIME	DUE - 15 OCT 98.
15 OCT 97	ELEVATOR TRIM CONTROL SYSTEM	DUE - 15 OCT 98.
15 OCT 97	ELEVATOR ELECTRIC TRIM CONTROL SYSTEM	DUE - 15 OCT 98.
15 OCT 97	ELECTRIC TRIM SYSTEM TRAVEL TIME	DUE - 15 OCT 98.
15 OCT 97	LANDING GEAR LANDING OPERATIONAL TIME	DUE - 15 OCT 98.
15 OCT 97	LANDING GEAR RETRACTOR GEAR BOX	DUE - 15 OCT 98.
15 OCT 97	LANDING GEAR RETRACTING TORQUE TABS	DUE - 15 OCT 98.
15 OCT 97	EMERGENCY MANUAL EXTEND	DUE - 15 OCT 98.
15 OCT 97	EMERGENCY EXTENDING SCREW DATA	DUE - 15 OCT 98.
15 OCT 97	TRIM ACTUATOR SYSTEM SCREW DATA	DUE - 15 OCT 98.
15 OCT 97	NOSE GEAR DRAG BRACE	DUE EVERY - 200 HRS.
16 OCT 97	AD 82-07-03	CONTROL FUEL HEATER DEACT TEST IN THE
15 OCT 97	MEB 91-9	FLAP ACTUATOR LIMIT SWITCH WSP 4
7 NOV 97		
15 DEC 97	MEB 92-1271	MIA 34 OH.
15 DEC 97	MEB 93-4 R1	ENGINE FUEL PUMP DRIVE COUPLING IN
15 DEC 97	MEB 91-13	CRANKSHAFT ULTRASONIC, 1/2 SP.
16 DEC 97	AD 82-07-03	CONTROL FUEL HEATER DEACT TEST DUE
26 NOV 98	AD 98-01-08	EXHAUST ROLLER ROCKER ARMS 2nd REG
01 APR 98	AND SERA II NO 10	TRANSponder's ATIS UNARCA 3/11/2000 2nd REG
06 APR 98	AND SERA II NO 15	BOTH ALTIMETER REPAIRED RECORDED BY 2nd REG
99-19-01	99-19-01	Not applicable as engine

AIRFRAME AIRWORTHINESS DIRECTIVES (A/D), SERVICE BULLETIN DETAILS

DATE

A/D, S/B, S/I, MODS

AIRWORTHINESS DIRECTIVES APPLICABLE TO C-FDYS

- 18 Dec 1998
- 73-22-01 CARRIED IN AUGUST 1975 ...ONE OFF
 - 74-20-01 HAVED BEEN REPLACED ..ON/OFF
 - 75-23-08R5 EVERY 100 HRS (engine exaust inspection)
 - 76-04-03 modified in sept 1976
 - 76-08-02r2 MDIFIED IN APRIL 1976
 - 76-16-07 NOT APPLICABLE AS NOT MODIFIED WITH ALLISON 100 HRS
 - 78-11-05 NOT APPLICABLE (400a INSTALLED)
 - 78-13-05 NOT APPLICABLE BY SERIAL #
 - 88-03-07 EVERY 100 HRS FUEL LINE INSPECTION
 - 98-04-28 HAVE BEEN INCLUDED IN FLIGHT MANUAL 100 HRS
 - 72-03-07 NOT APPLICABLE BY SERIAL #
 - 76-13-07 NEW STYLE BOLTS INSTALLED IN JUNE 1988
 - 87-21-02R1 MODIFIED IN SEPT 1991
 - 90-02-13 REPLACED IN SEPT 1991
 - 96-12-22 INSPECTED
 - 97-01-13 NOT APPLICABLE BY TYPE INSTALLED100 HRS

Engines

- 77-13-22 MODIFIED IN JULY 1979
- 78-06-01 MODIFIED IN MAY 1980
- 79-05-09 MODIFIED IN MAY 1980
- 82-09-01 NOT APPLICABLE BY SERIAL #
- 86-13-04R3 NOT APPLICABLE BY TYPE INSTALLED
- 89-24-01R1 MODIFIED IN DEC 1990
- 80-01-04 MODIFIED IN MAY 1980
- 81-24-06 NOT APPLICABLE BY SERIAL #
- 87-23-08 WILL BE APPLICABLE AT ENGINE OVERHAULED
- 88-03-06 NOT APPLICABLE BY TYPE INSTALLED
- 91-19-03 NOT APPLICABLE BT TYPE INSTALLED
- 93-08-17 TYPE NOT INSTALLED
- 93-10-02 TYPE NOT INSTALLED
- 93-16-15 TYPE NOT INSTALED
- 94-06-09 TYPE NOT INSTALLED
- 96-12-22 TYPE NOT INSTALLED
- 97-26-17 WILL BE APPLICABLE AT ENGINE OVERHAULED
- 98-01-08 NOT INSTALLED

propellers

- 77-13-17 MODIFIED IN 1994
- 95-24-05R1 NOT APPLICABLE BY LETTER "R" STAMPED

18 Dec 1998

18 Dec 1998

82-02-03

Central heater not done

SPECIAL INSPECTIONS (S/I) AND MODIFICATIONS (MODS)

WORK OR INSPECTION PERFORMED

SIGNATURE

LICENCE
NUMBER

[Signature]

14/57104

Applicable at 1201 hrs heater Hub

[Signature]

14/57104


14/57104

RECORD OF AIRFRAME **AIRWORTHINESS DIRECTIVES (A/D), SERVICE BULLETINS (S/B),**

DATE	A/D, S/B, S/I, MODE	DETAILS OF
6 July 2000	2000-23-21	Crankshaft inspection will be due
	99-19-01	Crankshaft NDT will be due at
	2000-01-16	Exhaust inspection carried out
	96-12-22	carried out
	88-03-07	Fuel lines inspected
	75-23-08	Exhaust inspection carried out
19 March 01	75-23-08	Exhaust inspection
	88-03-07	Fuel lines inspection
	96-12-22	Engine oil filter inspection
	2000-01-16	Exhaust inspection LETTER "D"
19 March 01	2000-23-21	not applicable as Crankshaft
6 MAY 2001	2000-23-21	N/A by DATE OVERHAULED
6 MAY 2001	2000-01-16	EXHAUST INSPECTED AS PER
6 MAY 2001	99-19-01	N/A by DATE OVERHAULED
6 MAY 2001	82-07-03	DE-CAY TEST CARRIED OUT
6 MAY 2001	75-23-08RS	REPLACED BY 2000-01-16
6 MAY 2001	88-03-07	FUEL LINES INSPECTION C/O
6 MAY 2001	96-12-22	ENGINE OIL FILTER ADAPTER

Airworthiness Directives that has been complied on this 15 Dec 2001

CF2001-19 exhaust inspection clarification.....carried out
 2001-23-17 garmin GNS430 not installed
 2001-17-13 janetrol fuel heater regulator inspected and found serviceable
 2000-01-16 engine exhaust inspection carried out up to letter E
 96-12-22 engine oil filter adapter chek found serviceable


 G. Belanger 157104

SPECIAL INSPECTIONS (S/I) AND MODIFICATIONS (MODS)

WORK OR INSPECTION PERFORMED

SIGNATURE

LICENCE
NUMBER

AT engine overhaul NOT Applicable
 engine overhaul
 visual inspection & pressure test

not applicable at this time (carried out)
 not manufacture before 1998 & 2000 (NOTE)

SECTION "E" FOUND AIRWORTHY

C/O

M/S 7104