

# 2013 Dassault Falcon 2000LXS

SERIAL #:265 N885A



TAO THE  
AVIATION  
OFFICE

# 2013 Dassault Falcon 2000LXS

SERIAL #:265 N885A

Specifications and/or descriptions are provided as introductory information only and do not constitute representations or warranties.

Verification of specifications remain the sole responsibility of purchaser.



## HIGHLIGHTS

- HUD
- SVS
- EASy II Cert 4
- Dual Charts
- RAAS
- Ka-Band Internet

## AIRFRAME SPECIFICS

Total Time Since New	4,257.6 Hours
Total Landings Since New	2,735 Landings
Certificate of Airworthiness Date	17 December 2013
Home Base	Memphis, TN
Maintenance Tracking	FlightDocs
Certification	Part 91
Current Registration	N885A

## ENGINE SPECIFICS

Description: Pratt & Whitney 308C | Program Coverage: ESP Gold

	ENGINE 1	ENGINE 2
Serial Numbers	PCE-CFO595	PCE-CFO594
Total Hours Since New	3,803.9 Hours	3,852.3 Hours
Total Cycles Since New	2,467 Cycles	2,492 Cycles

## APU

Description	Honeywell 35-150
Serial Number	P-640
APU Total Time Since New	2,059 Hours
APU Total Cycles Since New	4,836 Landings
Program Coverage	MSP Gold

## MAJOR INSPECTION STATUS

1C - Last Performed:	Mar. 2, 2020	Next Due: Mar. 2, 2026
2C - Last Performed:		Next Due: Dec. 17, 2025
3C - Last Performed:		Next Due: Dec. 17, 2031

# 2013 Dassault Falcon 2000LXS

SERIAL #:265 N885A

Specifications and/or descriptions are provided as introductory information only and do not constitute representations or warranties.

Verification of specifications remain the sole responsibility of purchaser.

## AVIONICS

Honeywell Primus Epic (EASy II Cert 4)


TYPE OF UNIT	QUANTITY
Air Data Computer (ADC)	2
Attitude Heading Computer	3
Radio Altimeter (RA)	2
Weather Radar	1
XM Satellite Weather Receiver	1
TCAS w/ 7.1	1
GPS Receiver	1
VOR/LOC/ILS	2
Transponder	2
DME	2
Flight Management Computer	3
Flight Guidance Computer	2
VHF Comm Transceiver	3
HF Transceiver	2
Cockpit Voice Recorder	1
ELT	1

2013  
Dassault  
Falcon  
2000LXS

SERIAL #:265 N885A

Specifications and/or descriptions are provided as introductory information only and do not constitute representations or warranties.

Verification of specifications remain the sole responsibility of purchaser.



INTERIOR

Number of Passengers	Eight (8)
Galley Location	Forward Cabin
Number of Lavatories	One (1)
Forward Cabin Configuration	Four (4) Place Club
Aft Cabin Configuration	Four (4) Place Club
Last Refurbished Date	Soft Goods Refurbishment Accomplished in March 2020 at Duncan-Lincoln

EXTERIOR

Base Paint Color(s)	Matterhorn White
Stripe Paint Color(s)	Colonial Blue and Medium Gray
Last Painted	March 2020 at Duncan-Lincoln

CONNECTIVITY

High Speed Internet	Ka-Band
---------------------	---------

ADDITIONAL PERTINENT DATA

CPDLC	FANS 1/A
EASy II Cert 4	RAAS
HUD	Dual Charts
SVS	





TAO THE AVIATION OFFICE













TAO THE AVIATION OFFICE









TAO THE AVIATION OFFICE






TAO THE AVIATION OFFICE










**Daniel J. Kilkeary**

Managing Member

M: 646.954.0564 | O: 732.291.1635

[dan@theaviationoffice.com](mailto:dan@theaviationoffice.com)

[theaviationoffice.com](http://theaviationoffice.com)



The Aviation Office. All Rights Reserved. Commercial in Confidence.