

CHATILLON HALL CONDOMINIUM, INC

April 5, 2021

Town of Bay Harbor Islands
Building Department

TO WHOM IT MAY CONCERN:


The Chatillon Hall Condominium Association has established the attached requirements for unit owners who request to replace their windows or doors after the date of this letter.

Chatillon Hall Condominium, Inc.



Luis Lopez, President

RECEIVED
APR 09 2021
BY:



1020 94th STREET
BAY HARBOR ISLANDS
FLORIDA 33154
Chatillonhall1020@gmail.com

CHATILLON HALL CONDOMINIUM, INC

IMPACT WINDOW/DOOR REQUIREMENTS EFFECTIVE APRIL 5, 2021

WINDOWS

Impact Resistant, Horizontal Roller

Note: The windows in the front (north) of the building must have a fixed window from the bottom of the window sill, to a height of 34 inches above the floor. Then the horizontal roller windows will be placed above the fixed window.

Window Opening Closure Devices as required by building code

White frame

Light Grey tint

Bathroom windows are to be frosted (white)

DOORS

Doors may be solid or frame with a single, glass insert (may be clear or frosted)


Door color: White

Doors must be in-swinging and approved for high velocity hurricane zones



1020 94th STREET
BAY HARBOR ISLANDS
FLORIDA 33154
Chatillonhall1020@gmail.com


IMPACT WINDOWS - HORIZONTAL ROLLER
WHITE FRAME
LIGHT GREY TINT



VECTRA L.L.C. 11/19/19
Section 4

Published by the
Architectural Record
12/1/19

10



34"

Floor

