


EMP 48-12n Speed Pulse Converter



EMP48-12n has an M12 x 1.5 thread

Red is the 12 volt supply required by the sender.

With Smiths Motorcycle, Proled or Classic Speedometers connect to the green wire on the speedometer harness.

Black is - ground.

Should be connected directly to the earth wire from the speedo then to ground.

Yellow or White is the signal output from the sensor

It should be connected to the white/black wire on the Motorcycle, Classic, Proled or Mini Speedometer harness.