


## Pump System

The pump system is severely damaged, apparently corrective maintenance was never performed







## Pump System

There are missing motors, it will be necessary to change the pumps since they are not in good condition and do not have the water impeller.

The gaskets are old and it would be more expensive to buy the parts separately than to buy the complete pump.

