



corner of Miller Lane and Miller Lane West for a report of a telephone pole on fire. Arriving units were unable to safely attack the fire until PSEG could shut off the power to that system, which they eventually did and the fire was extinguished and the surrounding ground soaked down with a hose line. Photo credit: Michael Heller