ULTIM8®DECKING THE PREMIUM DECKING SOLUTION

Storage and Handling Guide

MCX Group Pty Ltd. Ph: +613 9982 4456 Email: info@mcxmaterials.com

Australia: 18/3 Westside Avenue, Port Melbourne, Victoria, Australia, 3207





MCX Group Pty Ltd. Ph: +613 9982 4456

Email: info@mcxmaterials.com

Storage and Handling Guide

LOADING AND UNLOADING CONTAINERS

Loading and unloading containers must be done in accordance with the ULTIM8 Decking Container Loading instructions.

OPENING PACKS

Care must be taken when cutting straps to open ULTIM8DECK packs. Packs must be flat and level on the ground before any straps are cut. Packs must not be moved if any straps have been removed or are broken. Missing straps must be replaced prior to moving packs.

Ensure carton cutter blades or Stanley knife blades do not contact the ULTIM8 Decking, which may cause damage to the boards.

STORAGE

ULTIM8 Decking boards:

- MUST be supported at least every 600mm on a level plane, including supports at both ends
- MUST be laid flat for storage, and never at an angle
- MUST be stored in dry conditions, at least 100mm off the ground
- MUST remain covered until it is time to use them for installation
- MUST NOT be stacked more that 4 pallets high, and then only where safe to do so
- MUST only be stored on racks with appropriate load ratings

TRANSPORT

ULTIM8 Decking boards:

- MUST be laid flat during transport, and never at an angle
- MUST always be appropriately strapped and secured during transportation
- MUST never dropped or 'dumped' when unloading
- MUST not be dragged along the ground when loading, unloading, or carrying, as it may result in damage
- MUST remain covered until it is time to use them for installation

HANDLING

Store & fix this side up: Carry this side up:





Always exercise caution and care when lifting, and always check the weight on the label before attempting to lift an ULTIM8 Decking board. Individual ULTIM8 Decking boards should always be carried by at least 2 people, wherever safe to do so. All relevant OH&S policies and practices should be observed.