

Created using **RPAS Wilco**®

Reference No: Title: Pilot Name: Pilot Certificate: Flight Start: Flight End: Flight Area (Latitude): Flight Area (Longitude): Altitude - Radius: Classification: FIR - Contact:

FBB7B7 Mission 2025-06-02 Massimo Cardelli PC2306019695 June 2, 2025 7:20 PM June 2, 2025 9:20 PM 42° 10' 11.08" N (42.17) 83° 2' 49.68" W (-83.047)

Alt: 400 ft - **Rad:** 100 m (0.05 nm)

UNCONTROLLED CZYZ - 905-676-4509

Please ensure you received all required authorizations prior to flight.

Disclaimer

This Site Survey was created using RPAS Wilco by AIM Robotics. The flight plan contained is intended only for RPAS flights on the date/time and location specified. The user accepts all responsibility for the accuracy and completeness of the information contained.

For the complete Terms & Conditions, see

https://rpaswilco.com/#/tnc

Included

Site Survey

Obstacles (if available)

Nearby Aerodromes

Canadian Aviation Regulations

Aerodrome Supplements

-METAR & TAF (if available)

-NOTAMs

-CFS

LIMITED TIME

DJI MAVIC 4 PRO



- ✓ Large CMOS Dual Tele Cameras
- CMOS Hasselblad Camera With HDR Video
- ✓ Infinity Gimbal With 360° Rotation
- ✓ DJI HDR Video Transmission
- 51-Min Flight Time
- ✓ Nightscape Omnidirectional Sensing
- Collapsible Remote Controller

SHOP NOW

Get a FREE 1-Year RPAS WILCO PRO Subscription!



www.aimrobotics.io



RPAS Specification


- Manufacturer: Chaos600
- Model: Hughes 500 MD defender
- Registration Number: C-2306810384
- Eligible for advanced operations:
- Manufacturer RPAS safety assurance:
 - Controlled Airspace: N/A
 - Near People: N/A
 - Over People: N/A

Mission Location Details

		Latitude	Longitude
×	MODEL	42° 10' 11.08" N (42.17)	83° 2' 49.68" W (-83.047)
•	Pilot Massimo Cardelli	42° 10' 14.68" N (42.1707)	83° 2' 53.28" W (-83.0481)



Airspace Classification



Overlying Airspaces


Class	Name	Floor	Ceiling
E	Southern Ontario Low Level Control Area CAE	2500MSL	6500MSL
C	Detroit, ON TCA	3000MSL	4000MSL
C	Detroit, ON TCA	4000MSL	6000MSL
С	Detroit, ON TCA	6000MSL	10000MSL
E	Windsor, ON TA	700AGL	12500MSL
В	Windsor, ON TA	12500MSL	18000MSL
E	Southern Ontario Low Level Control Area CAE	6500MSL	12500MSL
В	Southern Ontario Low Level Control Area CAE	12500MSL	18000MSL

Nearest Aerodromes & Distance from Operation

WINDSOR (CYQG - AERODROME - Cert)	Lat: 42.276	Long: -82.955	14.041KM	7.58NM	NE
ESSEX (CNE9 - AERODROME - Reg)	Lat: 42.096	Long: -82.879	16.108KM	8.7NM	SE
HARROW (CGL2 - AERODROME - Reg)	Lat: 42.059	Long: -82.841	20.994KM	11.34NM	SE
BILLING AIRSTRIP (CEB8 - AERODROME - Reg)	Lat: 42.187	Long: -82.782	21.932KM	11.84NM	E
COTTAM (CRB2 - AERODROME - Reg)	Lat: 42.14	Long: -82.653	32.657KM	17.63NM	E

REF

WINDSOR ON CYQG



	T2 CAP
OPR	Your Quick Gateway (Windsor) Inc. 519-969-2430 10-02Z‡ Cert
PF	A-2,3,6,7,8 C-4,5
CUST	AOE/325 (450 with staged off loading) 888-226-7277 13-05Z‡
FLT PLN FIC	Pilots to open/ close VFR flt plan with London rdo 123.375 or by phone. For alth method to file, close & rcv IFR Flt Pln/clnc see PRO London 866-WXBRIEF (Toll free within Canada) or 866-541-4104 (Toll free within Canada & USA)
WX	METAR AUTO H24 (See COMM). TAF H24, issue times: 00, 06, 12, 18Z, WxCam.
SERVICES FUEL OIL S	Call out chg may be levied for one or more svcs. 100LL, JA-1 FSII (avbl), HPR All
ARFF	1,2,3,4,5,6 PARTICIPATING CAT 5 1030-0315Z‡, O/T call out chgs may be levied.
SUP FL JASU	D-ice NC-10A/A1/B/C; DC:2000 AMP, 45kW, 28V; AC:90 KVA, 115/200V, 3 phase, 400 Hz.
PVT ADV	Great Lakes Flight Centre 122.95 519-969-7052 and 866-817-5266 Fax 519-969-3205 Air-Way Aviation 129.55 519-972-7244 Fax 519-972-7744 Gateway Aviation (World Aviation Services) 123.5 226-782-3581
MIL CON	Gateway Aviation Windsor 226-782-3581

N42 16 34 W82 57 19 Adj SE 7°W (2011) UTC-5(4) Elev 622' A5000 LO6 HI5

WINDSOR O	N (Cont'd)		
RWY DATA RWY CERT	Rwy 07(070°)/25(250°) 9000x200 ASPH Thld 07 displ 902′. Thld 25 displ 1143′ Rwy 12(123°)/30(303°) 5150x150 ASPH Thld 12 displ 570′. Thld 30 displ 321′ Rwy 07 RVR 1200(1/4sm)/Rwy 25 RVR 1200(1/4sm) AGN IV Rwy 12/30 AGN IIIB		
TWY CERT	Twy: E AGN III Twy: I AGN IIIA		
TWY RCR	Twy E uncontrolled. Twy I width 50'. 519-791-1663 10-05Z‡ CRFI Hrs extended as conds or usage warrant. PCN		
LIGHTING	07-AD AS(TE HI) P2, 25-AN(TE HI) P2, 12-AD(TE ME) P2, 30-(TE ME) P2 ARCAL-124.7 type K when TWR clsd		
COMM RCO ATIS GND TWR MF ARR/DEP VFR ADV AWOS	London rdo 123.375 (FISE) 126.7(bcst) 134.5 12-03Z‡ 121.7 12-03Z‡ (emerg only 519-969-3751) tfc 124.7 (E) 12-03Z‡ (6NM shape irregular to below 3000 ASL (CAR 602.98) Detroit 118.95 132.35 134.3 284.0 (E) Windsor Area-Detroit Apch Ctl 134.3 134.5 03-12Z‡		
NAV DME ILS	IQG 110.3 Ch 40 N42 16 52 W82 56 49 (633') IQG 110.3 (Rwy 25)		
PRO	When oprg VFR over Canadian Territory within the Detroit TCA (see VTPC) ctc Detroit apch ctl 134.3. Avoid Riverside descent area unless authorized by ATC. (Acft departing the Windsor area northbound or enroute to Detroit should remain W of Belle Isle or E of the Windsor class E airspace.) IFR tfc inbound Detroit City Airport Rwy 33 descending within the Riverside Descent Area from 3000 ASL. To file, close & rcv IFR Flt Pln/clnc when oprg in the Detroit TCA, ctc London FIC on 123.375 or by phone 1-866-541-4104. Pilots are requested to avoid flight below 2000 ASL when flying over the Jack Miner Bird Sancturary (Kingsville ON, N42 04 00 W82 45 00) & over Point Pelee National Park.		
CAUTION	Blasting areas may be active Mon-Fri 13-22Z‡ 1NM radius of N42 09 19 W83 00 21 and N42 05 21 W83 05 06 to 500 AGL. Migratory birds in vic of aprt Mar - May & Oct - Nov.		

ESSEX ON		CNE9
REF	N42 05 45 W82 52 46 4SW 7°W UTC-5(4) Elev 620′ A5000	ELEV 620 °
OPR	P. & A. Harrington 519-776-7441 Reg	i ii iii iii ii ii ii ii ii ii ii ii ii
PF	C-1,2,3,5 D-4,6	
FLT PLN FIC	London 866-WXBRIEF (Toll free within Canada) or 866-541-4104 (Toll free within Canada & USA)	1935' t
SERVICES S	2,3,5	
RWY DATA TWY RCR	Rwy 09/27 1935x70 GRASS Twy at hg entrance only. No win maint. A/D clsd in hvy rain periods. Call ahead to confirm rwy has dried up enough to land on.	£ £ £
COMM	tfc 122.8 5NM 3600 ASL	
PRO	Pilots are requested to avoid flight below 2000 ASL when flying over the Jack Miner Bird Sanctuary (Kingsville, Ont N42 04 00 W82 45 00) & over Point Pelee National Park.	
CAUTION Ditches at Thlds 09 & 27 and along rwy s Trees on apch to Rwy 27. Bldg at edge of		ides. Wind shear fr hg with N/NE/NW winds. of Rwy 09/27.

HARROW O	N	CGL2
REF	N42 03 34 W82 50 27 3.8ENE 7°W UTC-5(4) Elev 610′ A5000	Q Q ELEV 610 Q Q
OPR	Louis & Thérèse Levesque 519-733-2935 Reg PN	- 0-61 - Q
PF	C-1,2 E-3,4,5,6	Q DIUS 514 Q
FLT PLN FIC	London 866-WXBRIEF (Toll free within Canada) or 866-541-4104 (Toll free within Canada & USA)	2400 000 100
RWY DATA RCR	Rwy 01/19 3000x100 GRASS Thids 01 & 19 displ 400'. Rwy soft when wet. Opr Ltd win maint	
COMM	tfc 122.9 5NM 3600 ASL	
PRO	Pilots are requested to avoid fit below 2000 ASL when flying over the Jack Miner Bird Sanctuary (Kingsville, Ontario N42 04 W82 45) & over Point Pelee National Park.	
CAUTION	Trees 500' fr Thld Rwy 01, 60 AGL. Mar hydro line). Essex A/D 3NM NW.	ked hydro poles 400' fr Thld Rwy 19 (buried

ESSEX / BILLING AIRSTRIP ON

CEB8

REF	N42 11 12 W82 46 56 1.9E 7°W UTC-5(4) Elev 630' A5000	ELEV 630
OPR	Pam/Erik Billing 519-723-4479 Reg PN	
PF	B-1,2 C-3 D-4,6	
FLT PLN FIC	London 866-WXBRIEF (Toll free within Canada) or 866-541-4104 (Toll free within Canada & USA)	2025' 88 H
SERVICES FUEL OIL S	100LL (D) Emerg only 100 Emerg only 5	Sewage 2400
RWY DATA RCR	Rwy 10(099°)/28(279°) 2025x100 GRASS Opr Ltd win maint. Rwy may be soft when wet.	
CAUTION	Water lagoons 1500' SW of ThId 10, possible bird hazard. Ditch at ThId 28. Hydro wires along road near ThId 10. Wind turbine 0.5NM SW of ThId 10 1017 ASL (394 AGL). Numerous wind turbines in vic.	

COTTAM ON	l	CRB2	
REF	N42 08 24 W82 39 10 4E 7°W UTC-5(4) Elev 635´ A5000	ELEV 635 -	
OPR	R. I. Bell 519-839-4369 Reg PPR	ARDIUS 51/4	
PF	C-1,2 D-3,4,5,6		
FLT PLN FIC	London 866-WXBRIEF (Toll free within Canada) or 866-541-4104 (Toll free within Canada & USA)	Q t	
RWY DATA RCR	Rwy 01/19 2000x60 GRASS Thld 01 displ 400'. Opr Ltd win maint		
COMM ATF	tfc 122.9 5NM 3600 ASL	t	
PRO	Pilots are requested to avoid flt below 2000 ASL when flying over the Jack Miner Bird Sanctuary (Kingsville, Ont N42 04 W82 45) & over Point Pelee National Park.		
CAUTION	Bldgs & unmarked poles aprx 400' fr Thld 01. Ditch adj E Thld 01 & 19. Trees on apch to Rwy 01. Cultivated fields at both edges of Rwy 01/19.		

Canadian Aviation Regulations

Division III — General Operating and Flight Rules

For full listing please visit: https://laws-lois.justice.gc.ca/eng/regulations/SOR-96-433/FullText.html#s-901.27

Visual Line-of-sight

- 901.11 (1) Subject to subsection (2), no pilot shall operate a remotely piloted aircraft system unless the pilot or a visual observer has the aircraft in visual line-of-sight at all times during flight.
- (2) A pilot may operate a remotely piloted aircraft system without the pilot or a visual observer having the aircraft in visual line-of-sight if the operation is conducted in accordance with a special flight operations certificate RPAS issued under section 903.03.

Procedures

- 901.23 (1) No pilot shall operate a remotely piloted aircraft system unless the following procedures are established:
 - O (a) normal operating procedures, including pre-flight, take-off, launch, approach, landing and recovery procedures; and
 - O (b) emergency procedures, including with respect to
 - (i) a control station failure,
 - (ii) an equipment failure.
 - (iii) a failure of the remotely piloted aircraft,
 - (iv) a loss of the command and control link,
 - (v) a fly-away, and
 - (vi) flight termination.
- (2) If the manufacturer of the remotely piloted aircraft system provides instructions with respect to the topics referred to in paragraphs (1)(a) and (b), the procedures established under subsection (1) shall reflect those instructions.
- (3) No pilot shall conduct the take-off or launch of a remotely piloted aircraft unless the procedures referred to in subsection (1) are reviewed before the flight by, and are immediately available to, each crew member.
- (4) No pilot shall operate a remotely piloted aircraft system unless the operation is conducted in accordance with the procedures referred to in subsection (1).

Site Survey

901.27 No pilot shall operate a remotely piloted aircraft system unless, before commencing operations, they determine that the site for take-off, launch, landing or recovery is suitable for the proposed operation by conducting a site survey that takes into account the following factors:

- (a) the boundaries of the area of operation;
- (b) the type of airspace and the applicable regulatory requirements;
- (c) the altitudes and routes to be used on the approach to and departure from the area of operation;
- (d) the proximity of manned aircraft operations;
- (e) the proximity of aerodromes, airports and heliports;
- (f) the location and height of obstacles, including wires, masts, buildings, cell phone towers and wind turbines;
- (g) the predominant weather and environmental conditions for the area of operation; and
- (h) the horizontal distances from persons not involved in the operation.

Operations at or in the Vicinity of an Aerodrome, Airport or Heliport


- 901.47 (1) No pilot shall operate a remotely piloted aircraft at or near an aerodrome that is listed in the Canada Flight Supplement or the Water Aerodrome Supplement in a manner that could interfere with an aircraft operating in the established traffic pattern.
- Subject to section 901.73, no pilot shall operate a remotely piloted aircraft at a distance of less than
 - O (a) three nautical miles from the centre of an airport; and
 - O (b) one nautical mile from the centre of a heliport.
- (3) No pilot shall operate a remotely piloted aircraft at a distance of less than three nautical miles from the centre of an aerodrome operated under the authority of the Minister of National Defence unless the operation is conducted in accordance with a special flight operations certificate RPAS issued under section 903.03.

Records


- 901.48 (1) Every owner of a remotely piloted aircraft system shall keep the following records:
 - O (a) a record containing the names of the pilots and other crew members who are involved in each flight and, in respect of the system, the time of each flight or series of flights; and
 - O (b) a record containing the particulars of any mandatory action and any other maintenance action, modification or repair performed on the system, including
 - (i) the names of the persons who performed them.
 - (ii) the dates they were undertaken,
 - (iii) in the case of a modification, the manufacturer, model and a description of the part or equipment installed to modify the system, and
 - (iv) if applicable, any instructions provided to complete the work.
- (2) Every owner of a remotely piloted aircraft system shall ensure that the records referred to in subsection (1) are made available to the Minister on request and are retained for a period of
 - (a) in the case of the records referred to in paragraph (1)(a), 12 months after the day on which they are created; and
 - O (b) in the case of the records referred to in paragraph (1)(b), 24 months after the day on which they are created.
- (3) Every owner of a remotely piloted aircraft system who transfers ownership of the system to another person shall, at the time of transfer, also deliver to that person all of the records referred to in paragraph (1)(b).



GFA Issue time + 00 hr - CLOUDS AND WEATHER




GFA Issue time + 00 hr - TURBULENCE, ICING AND FREEZING LEVEL






GFA Issue time + 06 hr - CLOUDS AND WEATHER




GFA Issue time + 06 hr - TURBULENCE, ICING AND FREEZING LEVEL






GFA Issue time + 12 hr - CLOUDS AND WEATHER



GFA Issue time + 12 hr - TURBULENCE, ICING AND FREEZING LEVEL





WINDSOR - CYQG - Cert

METAR

METAR CYQG 022200Z AUTO 20013G19KT 9SM CLR 25/03 A2997 RMK SLP151 DENSITY ALT 1900FT=

TAF

TAF CYOG 021740Z 0218/0318 22010G20KT P6SM SKC FM030300 18007KT P6SM SKC FM031100 21010KT P6SM SKC BECMG 0313/0315 20015G25KT FEW040 RMK FCST BASED ON AUTO OBS. NXT FCST BY 030000Z=

NOTAM

(D1626/25 NOTAMN Q) CZYZ/QICAS/I/NBO/A/000/999/4217N08257W005 A) CYQG B) 2506041430 C) 2506041730 E) ILS RWY 25 U/S)

(S5342/25 NOTAMR S5328/25

Q) CZYZ/QFAXX/IV/NBO/A/000/999/4217N08257W005

A) CYQG B) 2506021645 C) 2506030045 E) RSC 07 6/6/6 DRY, DRY, DRY, VALID JUN 02 1644 - JUN 03 0044.

RSC 25 6/6/6 DRY, DRY, DRY, VALID JUN 02 1644 - JUN 03 0044.

RSC 12/30 DRY. VALID JUN 02 1644 - JUN 03 0044.

ADDN NON-GRF/TALPA INFO:

RMK: TWY TWY ALPHA, CHARLIE, DELTA, ECHO, FOXTROT, GOLF, HOTEL, INDIA, 202506021644, DRY.

RMK: APN APN APRON I, APRON III, 202506021644, DRY.)

(D1354/25 NOTAMR D0402/25

Q) CZYZ/QLAAS/IV/NBO/A/000/999/4217N08257W005

A) CYQG B) 2505141429 C) 2508131500EST

E) LOW INTST APCH LGT RWY 07 AND 12 U/S)

(G1039/25 NOTAMR G0197/25

Q) CZXX/QOEXX/IV/NBO/E/000/999/5245N09040W999

A) CZWG CZYZ B) 2504281317 C) 2507281400EST

E) AIRSPACE SECURITY WARNING ISSUED BY THE DEPARTMENT OF TRANSPORT IN RESPONSE TO THE SECURITY SITUATION IN THE DEMOCRATIC REPUBLIC OF CONGO. CANADIAN AIR OPR AND OWNERS OF ACFT

REGISTERED IN CANADA ARE RECOMMENDED NOT TO ENTER FIR KINSHASA (FZZA) BELOW FL260 DUE TO RISK FROM ANTI-ACFT WEAPONRY.)

(D1105/25 NOTAMR D0725/25

Q) CZYZ/QOBCE/IV/M/AE/000/008/4218N08254W005

A) CYQG B) 2504231109 C) 2507231600EST E) MULTIPLE MOBILE CRANES WITHIN 1641FT RADIUS CENTRED ON 421736N 0825410W APRX 11660FT BFR DTHR 25 AND 1950FT SOUTH EXTENDED RCL. 145FT AGL 746FT AMSL, LGTD, NOT PAINTED.)

(U0427/25 NOTAMN

Q) CZYZ/QOLAS/IV/M/AE/000/009/4219N08303W005

A) CYQG B) 2503120133 C) 2506062100EST

E) OBST LGT U/S TOWER 421859N 0830258W (APRX 4.8NM NW AD) 273FT AGL, 858FT AMSL.)

(G3517/24 NOTAMN

Q) CZYZ/QARXX/IV/NBO/E/000/999/4729N08055W999

A) CZYZ B) 2412260901 C) PERM

E) AMEND PUBLICATIONS:

AMEND MANDATORY IFR ROUTES: DELETE: CYKF H AND L ARR FR E A160 AND ABV RNAV TUKIR Q806 ILUSI ERBAL MAPEM DELETE: CYTZ H AND L ARR FR N RNAV DUTUD KENLU KIVUN UKROX DELETE: CYTZ H AND L ARR FR NW RNAV WALPP IKLUX KIVUN UKROX)



ESSEX - CNE9 - Reg

NOTAM

(G1039/25 NOTAMR G0197/25

Q) CZXX/QOEXX/IV/NBO/E/000/999/5245N09040W999 A) CZWG CZYZ B) 2504281317 C) 2507281400EST

E) AIRSPACE SECURITY WARNING ISSUED BY THE DEPARTMENT OF TRANSPORT IN RESPONSE TO THE SECURITY SITUATION IN THE DEMOCRATIC REPUBLIC OF CONGO. CANADIAN AIR OPR AND OWNERS OF ACFT DESCRIPTION OF AND ADDRESS OF ACFT OF THE FIRE VINSHASA

REGISTERED IN CANADA ARE RECOMMENDED NOT TO ENTER FIR KINSHASA (FZZA) BELOW FL260 DUE TO RISK FROM ANTI-ACFT WEAPONRY.)

(G3517/24 NOTAMN

Q) CZYZ/QARXX/IV/NBO/E/000/999/4729N08055W999

A) CZYZ B) 2412260901 C) PERM

E) AMEND PUBLICATIONS: AMEND MANDATORY IFR ROUTES: DELETE: CYKF H AND L ARR FR E A160 AND ABV RNAV TUKIR Q806 ILUSI ERBAL MAPEM DELETE: CYTZ H AND L ARR FR N RNAV DUTUD KENLU KIVUN UKROX DELETE: CYTZ H AND L ARR

FR NW RNAV WALPP IKLUX KIVUN UKROX)



HARROW - CGL2 - Reg

NOTAM

(G1039/25 NOTAMR G0197/25

Q) CZXX/QOEXX/IV/NBO/E/000/999/5245N09040W999 A) CZWG CZYZ B) 2504281317 C) 2507281400EST

E) AIRSPACE SECURITY WARNING ISSUED BY THE DEPARTMENT OF TRANSPORT IN RESPONSE TO THE SECURITY SITUATION IN THE DEMOCRATIC REPUBLIC OF CONGO. CANADIAN AIR OPR AND OWNERS OF ACFT

REGISTERED IN CANADA ARE RECOMMENDED NOT TO ENTER FIR KINSHASA (FZZA) BELOW FL260 DUE TO RISK FROM ANTI-ACFT WEAPONRY.)

(G3517/24 NOTAMN

O) CZYZ/OARXX/IV/NBO/E/000/999/4729N08055W999

A) CZYZ B) 2412260901 C) PERM

E) AMEND PUBLICATIONS: AMEND MANDATORY IFR ROUTES: DELETE: CYKF H AND L ARR FR E A160 AND ABV RNAV TUKIR Q806 ILUSI ERBAL MAPEM DELETE: CYTZ H AND L ARR FR N RNAV DUTUD KENLU KIVUN UKROX DELETE: CYTZ H AND L ARR FR NW RNAV WALPP IKLUX KIVUN UKROX)



BILLING AIRSTRIP - CEB8 - Reg

NOTAM

(G1039/25 NOTAMR G0197/25

Q) CZXX/QOEXX/IV/NBO/E/000/999/5245N09040W999 A) CZWG CZYZ B) 2504281317 C) 2507281400EST

E) AIRSPACE SECURITY WARNING ISSUED BY THE DEPARTMENT OF TRANSPORT IN RESPONSE TO THE SECURITY SITUATION IN THE DEMOCRATIC REPUBLIC OF CONGO. CANADIAN AIR OPR AND OWNERS OF ACFT

REGISTERED IN CANADA ARE RECOMMENDED NOT TO ENTER FIR KINSHASA (FZZA) BELOW FL260 DUE TO RISK FROM ANTI-ACFT WEAPONRY.)

(G3517/24 NOTAMN

O) CZYZ/OARXX/IV/NBO/E/000/999/4729N08055W999

A) CZYZ B) 2412260901 C) PERM

E) AMEND PUBLICATIONS: AMEND MANDATORY IFR ROUTES: DELETE: CYKF H AND L ARR FR E A160 AND ABV RNAV TUKIR Q806 ILUSI ERBAL MAPEM DELETE: CYTZ H AND L ARR FR N RNAV DUTUD KENLU KIVUN UKROX DELETE: CYTZ H AND L ARR FR NW RNAV WALPP IKLUX KIVUN UKROX)



COTTAM - CRB2 - Reg

NOTAM

(U0767/25 NOTAMN

Q) CZYZ/QOLAS/IV/M/AE/000/011/4204N08240W005 A) CXXX B) 2505030304 C) 2508022000EST

E) CRB2 COTTAM

OBST LGT U/S TOWER 420410N 0823958W (APRX 4.3NM SSW AD) 302FT

AGL, 1026FT AMSL.)

(G1039/25 NOTAMR G0197/25

Q) CZXX/QOEXX/IV/NBO/E/000/999/5245N09040W999

A) CZWG CZYZ B) 2504281317 C) 2507281400EST
E) AIRSPACE SECURITY WARNING ISSUED BY THE DEPARTMENT OF TRANSPORT IN RESPONSE TO THE SECURITY SITUATION IN THE DEMOCRATIC REPUBLIC

OF CONGO. CANADIAN AIR OPR AND OWNERS OF ACFT REGISTERED IN CANADA ARE RECOMMENDED NOT TO ENTER FIR KINSHASA

(FZZA) BELOW FL260 DUE TO RISK FROM ANTI-ACFT WEAPONRY.)

Q) CZYZ/QARXX/IV/NBO/E/000/999/4729N08055W999 A) CZYZ B) 2412260901 C) PERM

E) AMEND PUBLICATIONS:

AMEND MANDATORY IFR ROUTES: DELETE: CYKF H AND L ARR FR E A160 AND ABV RNAV TUKIR Q806 ILUSI ERBAL MAPEM DELETE: CYTZ H AND L ARR FR N RNAV DUTUD KENLU KIVUN UKROX DELETE: CYTZ H AND L ARR FR NW RNAV WALPP IKLUX KIVUN UKROX)