



# METER BRACKET INSTRUCTIONS


For Beta 2020+

1. Remove head light mask or number plate.


2. Unplug all wire harness connections from meter bracket, ***use caution.***

3. Remove bolt holding main harness on bracket and cut any wire ties attached to bracket.

4. Remove the two bolts that secure the stock meter mount bracket



5. Carefully remove meter screws and hardware.
6. Remove wire harness sockets from back of stock meter mount bracket by pinching tabs.



- 7. Remove pinch nut from stock bracket.
- 8. Remove meter rubber gromets from stock bracket, these will be used on new bracket.



---


9. Install pinch nut into new meter bracket as shown.

10. Carefully install stock rubber gromets into new bracket.




11. Install meter on to new bracket, be sure not to over tighten.

12. Reinstall wire harness sockets from back side, be sure that they snap in completely.



13. Mount new bracket using the included hardware and apply a small amount of blue Loctite, torque to 6NM.



14. Reinstall bolt for wire harness strap, take some time to zip tie wire harness well to avoid any rubbing or chaffing.

15. Plug in remaining wire harness connections, now is a good time to inspect your connectors and put a light coating of dielectric grease on them.







Reinstall head light  
mask/racing plate

- *Thank you for your business!*