




776 Jernee Mill Road Suite 128 , Sayreville, NJ 08872
1-888-308-3879



Neutral conductors can never be doubled-up under one terminal; the code has specifically prohibited this practice since 2002. For other terminations, the electrical code has a very basic rule; terminals for more than one conductor must be identified.