




776 Jernee Mill Road Suite 128, Sayreville, NJ 08872
1-888-308-3879



Not enough receptacles in the foyer

The purpose of this code is to reduce the use of extension cords. From any point along a wall line, a receptacle outlet needs to be within reach of a 6-ft. appliance cord, and that 6 ft. cannot be measured across a passageway. The bottom line is that extension cords start fires and create tripping hazards—the fewer of them, the better.