



776 Jernee Mill Road Suite 128, Sayreville, NJ 08872
1-888-308-3879



Strip Off the Sheathing

It's easier to strip the sheathing from the cables out in the open before they get shoved into the box. Remember to leave at least 1/4 in. of sheathing visible inside the box. If there's only one cable entering a box, install it through the knockout farthest from the stud.