


PRESSURE PART ENGINEERING LIMITED SITE WORKS SPECIAL CONDITIONS



This Schedule applies to all site installation and site welding works.

1. ACCESS AND FACILITIES

Buyer must provide safe, clear access, welfare, power, lifting facilities and permits to work.

2. WAITING TIME AND ABORTED VISITS

Waiting time, aborted visits and delays caused by others are chargeable at standard rates.

3. OUT OF SEQUENCE WORKING

Any requirement to work out of planned sequence is chargeable.

4. OTHER CONTRACTORS

The Company is not responsible for delays, damage or rework caused by other contractors.

5. STORAGE

If installation is delayed, storage charges apply.

6. SAFETY AND STRUCTURE

Responsibility for the integrity of existing structures rests with the Buyer.

7. VARIATIONS

Any change to scope, drawings, programme or sequence constitutes a variation.