## Mil Potrero Mutual Water Company Non-Lead Statement

Mil Potrero Mutal Water Company has completed the initial lead service line inventory required by U.S. EPA's Lead and Copper Rule Revisions. The deadline for the initial inventories was October 16, 2024.

Through completing a historical records review and field investigations, Mil Potrero Mutal Water Company has determined it has no lead or galvanized requiring replacement service lines in its distribution system. This includes any privately-owned or customer-owned service lines.

Mil Potrero Mutal Water Company reviewed all applicable sources of information, including

- All construction and plumbing codes, permits, and existing records or other documentation which indicates the service line materials;
- All water system records, including distribution system maps and drawings, historical records on each service connection, meter installation records, historical capital improvement or master plans, and standard operating procedures;
- All inspections and records of the distribution system that indicate service line material, including inspections conducted during the course of normal operations (e.g., checking service line materials when reading water meters or performing maintenance activities); and
- All previous service line or meter replacements were conducted.

In addition to reviewing the above sources of information, Mil Potrero Mutal Water Company used an alternative method to develop the inventory that was approved by the State Water Resources Control Board Division of Drinking Water on a case-by-case basis.

Mil Potrero Mutal Water Company used the interpolation method. The interpolation method is used when the water utility can divide their service area into uniform groups, such as neighborhoods or tracts. Each uniform group shares multiple common characteristics, such as time period built, location, or contractor. The service line materials for each group are assumed to be similar. Water utilities physically verified a percentage of the homes in that group to interpolate or determine the service line material for the remaining homes.

Mil Potrero Mutal Water Company created interpolation groups based on homes built before 1996 and verified 20 percent of that group. All service lines inspected by staff were verified as non-lead (plastic, copper or galvanized). No lead or galvanized requiring replacement service lines were identified.

Mil Potrero Mutal Water Company continues to document service line material information obtained from normal operations, such as service line maintenance or water meter readings, after October 2024 and will update the initial inventory accordingly.