Outbreak of Sporadic Diffuse Lamellar Keratitis (DLK) Related to a Steam Humidifier

Mark E Johnston MD FRCSC

johnston@nebraskaeye.com

www.nebraskaeye.com

Omaha NE

AAO New Orleans 2007

Financial Disclosures

The author has no financial interest in any product

Sporadic DLK

Sixteen patients

- Which eye
 - one right
 - eleven left
 - four bilateral;
- Duration of the ablation
 - nine hyperopia
 - seven myopia
- Type of Surgery
 - fourteen primary
 - two enhancements.

Risk factors-

- Left >>>right (10/1)
 - Unlikely to be related to instruments, autoclave or drops
 - Suggested an environmental etiology
- Hyperopia >>> myopia (10/1)
 - Surgery longer with more pulses
 - Suggests that excimer laser irradiation increases the risk

The third case of DLK occurred when the humidistat was turned up.



That day condensation was noted on a window with a crack in the thermal glass

When the humidifier chamber was checked, organic debris was noted in the chamber; the unit was turned off.




- The steam chamber in the humidifier is comparable to the chamber in an autoclave
- The unit had stayed full of fluid during the summer because of a slow leak in the water supply valve
 - Note organic brown debris in the bottom (and sides)
 - Note calcium deposit in the base

Mild cases occurred when:

- HEPA filters were upgraded
- new unit was installed


DLK events

- Turned off humidifier
- 2. Modified HEPA Filters
- 3. New Humidifier turned on



•DLK: Grade (0-4)

- All cases mild
- Treated with Pred forte hourly
- No adverse outcomes



New humidifier after one month of use



- Chamber is manually drained and refilled daily
- Calcium buildup is noted
- There is no evidence of organic debris or discoloration
- Chamber can be replaced yearly

Related risk factors

Laser Fragmentation of Debris

1. Excimer irradiation of chimney exhaust increases particle number two orders of magnitude

Christopher B. Stipe, Post-Doctoral Research Fellow Mechanical Engineering Department, University of Minnesota

2. Patient treatment with excimer laser increases the operating room particle number sixfold

Anonymous, A Mysterious Tale: The Search for the cause of 100+ cases of DLK, JRS 18,Sept 2002,Page 551-554

Air filtration

- 1. The highest number of cases occurred the week after the humidifier was turned off
 - Consistent with dispersal of material into the OR from areas not protected by HEPA filtration
- 2. Possible that contaminates were released when work was done on the air filtration system
 - Several mild cases were noted when the HEPA filters were changed or modified
 - Several mild cases were noted when a new humidifier was installed

Nozzle position:

Determines the difference between right and left eye

Air is pulled across the left eye and alone the nose

Compared to the left side, less air is pulled across the right eye





Conclusion

Events were consistent with

- airborne contaminants from the humidifier as the cause,
- the excimer laser creating multiple smaller particles
- the aspirator location increasing the incidence in left eyes