

DAVENPORT MOTOR SPORTS

25462 CR 43

Greeley, CO. 80631

Phone: 970-371-0022 Fax: - -

ESTIMATE #

021524

Estimate for Services

Estimate Date : 11/8/2020

DAVENPORT, ROB

25462 CR 43

Greeley, CO 80631

CELL: 970-371-0022

1968 Plymouth - Satellite - 440

Lic # : - CO

Odom. In: 0

VIN # :

Part Description / Number	Qty	Sale	Ext	Labor Description	Extended
440 SOURCE 512 FORGED ROTATING ASSEM 7567	1.00	2,142.00	2,142.00	MACHINE SHOP-BORE , HONE, DECK, THERMAL CLEAN, BALANCE ROTATING ASSEM BUILD 512	995.00 1,500.00
HUGHES 3500 STALL TRANSBRAKE CONVERTER 5644	1.00	1,178.10	1,178.10	MINI TUB AND SHEET METAL WORK FOR CELL	1,500.00
20 GALLON FUEL CELL ALUMINUM W8567	1.00	267.75	267.75	INSTALL WIRING HARNESS, MAKE CUSTOM DASH,	1,800.00
WEATHERSTRIP KIT- WINDSHIELD GASKET, DOOR SEALS, DOOR WINDOW FELTS, TRUNK SEAL 897434	1.00	428.40	428.40	BUILD 727- BILLET SERVOS, ALTO CLUTCHES, TRANSBRAKE	900.00
NEW OUTER DOOR HANDLES-PR 4747	1.00	85.68	85.68	INSTALL 8 PT ROLL CAGE INCLUDING MATERIALS	1,100.00
NEW FRONT BUMPER AND BOLTS 768964	1.00	315.95	315.95	RELOCATE REAR LEAF SPRINGS AND INSTALL CALTRAC SYSTEM	1,000.00
NEW DOOR SILL PLATES PR 69FG	1.00	96.39	96.39	MODIFY FRONT SHOCK TOWERS AND INSTALL AJE FRONT SUSPENSION AND STEERING	750.00
NEW HEADLINER FH76	1.00	198.14	198.14	FAB MOUNTS FOR FRONT ENGINE PLATE AND WIDEN RADIATOR SUPPORT FOR BIGGER RADIATOR	375.00
CALVERT RACING MONO SPRINGS, TRACTION KIT AND ADJUSTABLE REAR SHOCKS CAL98889	1.00	1,445.85	1,445.85	INSTALL SUBFRAME CONNECTORS AND DRIVESHAFT SAFETY LOOP	375.00
TCI RATTLER DAMPNER TCI745	1.00	423.05	423.05	3 REUPHOLSTER FRONT SEATS, DASH PAD, DOOR AND REAR PANELS, DECK PANEL, VISORS	1,320.00
TCI SFI FLEXPLATE TCI454	1.00	133.88	133.88	3.5 INCH EXHAUST WITH LOBAC MUFFLERS	750.00
MELLING STANDARD OIL PUMP MEL73	1.00	91.04	91.04	car purchase	3,500.00
Water Pump Mounting Gasket 11731	4.00	1.57	6.28	bodywork and paint- 2010 camaro synergy green, ditzler base, clear	10,000.00
Water Pump Mounting Gasket 11730	1.00	1.78	1.78		
Front Crankshaft Seal 3103	1.00	12.26	12.26		
RESISTOR SPARK PLUG 5553	8.00	3.20	25.60		
Automatic Transmission Front Pump Seal 331227H	1.00	18.84	18.84		
Automatic Transmission Front Pump Seal 331227H	2.00	10.22	20.44		
Wiper Blade 33-150	2.00	8.44	16.88		

DAVENPORT MOTOR SPORTS

25462 CR 43

Greeley, CO. 80631

Phone: 970-371-0022 Fax: - -

ESTIMATE #

021524**Estimate for Services**

Estimate Date : 11/8/2020

DAVENPORT, ROB

25462 CR 43

Greeley, CO 80631

CELL: 970-371-0022

1968 Plymouth - Satellite - 440

Lic # : - CO

Odom. In: 0

VIN # :

Part Description / Number	Qty	Sale	Ext	Labor Description	Extended
Ignition Switch <i>US50</i>	1.00	15.41	15.41		
Ignition Lock Cylinder <i>LC14400</i>	1.00	11.25	11.25		
Door Lock Cylinder Set <i>DL15020</i>	1.00	14.31	14.31		
Remanufactured Alternator <i>R111651A</i>	1.00	83.86	83.86		
Engine Mount Front Left <i>B2142</i>	1.00	5.37	5.37		
Engine Mount Front Left <i>A2283</i>	1.00	9.20	9.20		
Wheel Lug Nut <i>611-027</i>	10.00	2.24	22.40		
qa1 front coil springs <i>12HT130</i>	2.00	58.91	117.82		
QA1 Aluma Matic Coilover Shocks ALN5855P <i>ALN5855P</i>	2.00	160.65	321.30		
Trick Flow® Transmission Pans TFS-1009 <i>TFS-1009</i>	1.00	163.86	163.86		
Vibrant Performance High-Flow PTFE Hose End Fittings 28606 6AN 60 DEGREE <i>28606</i>	2.00	22.44	44.88		
Vibrant Performance High-Flow PTFE Hose End Fittings 28406 AN6 45 DEGREE <i>28406</i>	2.00	20.30	40.60		
Vibrant Performance High-Flow PTFE Hose End Fittings 28006 <i>28006</i>	4.00	12.80	51.20		
Vibrant Performance Braided Flexible Race Hoses 18976 AN6 PTFE FUEL HOSE <i>18976</i>	2.00	117.76	235.52		
Hyperfuel Inline Fuel Filters 80113 <i>80113</i>	1.00	29.99	29.99		
Procomp Electronics Air Cleaners PCE104-1047 <i>PCE104-1047</i>	1.00	63.19	63.19		
QA1 Eccentric Camber Bolt Adjusters KIT52361 <i>52361</i>	1.00	56.76	56.76		
Lokar Hi-Tech Throttle Cables TC-1000U <i>TC-1000U</i>	1.00	55.69	55.69		
CVR Thermostat Housings TSH8BK	1.00	89.96	89.96		

DAVENPORT MOTOR SPORTS

25462 CR 43

Greeley, CO. 80631

Phone: 970-371-0022 Fax: - -

ESTIMATE #

021524**Estimate for Services**

Estimate Date : 11/8/2020

DAVENPORT, ROB

25462 CR 43

Greeley, CO 80631

CELL: 970-371-0022

1968 Plymouth - Satellite - 440

Lic # : - CO

Odom. In: 0

VIN # :

Part Description / Number	Qty	Sale	Ext	Labor Description	Extended
<i>TSH8BK</i>					
AutoMeter Ultra-Lite Series GPS Enabled Speedometers 4480	1.00	358.79	358.79		
<i>4480</i>					
AutoMeter Ultra-Lite Analog Gauges 4472	1.00	278.46	278.46		
<i>4472</i>					
Summit Racing® Universal Fit Triple-Pass Radiators SUM-380431-3	1.00	243.12	243.12		
<i>380431-3</i>					
AutoMeter Ultra-Lite Analog Gauges 4421	1.00	86.75	86.75		
<i>4421</i>					
Taylor ThunderVolt 50 10.4mm Spark Plug Wire Sets 98051	1.00	148.87	148.87		
<i>98051</i>					
Fragola Performance Systems Flare Caps 492908-BL	2.00	6.42	12.84		
<i>492908-BL</i>					
Optima RedTop Starting 12-Volt Batteries 9004-003	1.00	240.98	240.98		
<i>9004-003</i>					
Taylor 4-Post Battery Disconnect Switches 1033	1.00	35.34	35.34		
<i>1033</i>					
Summit Racing® Remote Battery Jumper Terminals SUM-G1430	1.00	21.42	21.42		
<i>SUM-G1430</i>					
Allstar Performance OIL Gauge Line Kits ALL46110-60	1.00	28.92	28.92		
<i>ALL46110-60</i>					
Hughes Performance Locking Trans Dipsticks HP1235A	1.00	68.54	68.54		
<i>HP1235A</i>					
Taylor ThunderVolt 50 10.4mm Spark Plug Wire Sets 98051	1.00	149.94	149.94		
<i>98051</i>					
Cardone Industries 85-350 wiper motor	1.00	101.75	101.75		
<i>85-350</i>					
Allstar Performance Junction Blocks ALL76146	1.00	8.57	8.57		
<i>ALL76146</i>					
Summit Racing® Universal Fit Triple-Pass Radiators SUM-380431-3	1.00	243.12	243.12		
<i>SUM-380431-3</i>					
Allstar Performance Aluminum Line Clamps ALL18302-10	10.00	3.21	32.10		
<i>ALL18302-10</i>					
OER Rear Trim Panels MN2176 TRUNK MOLDING	1.00	491.59	491.59		
<i>MN2176</i>					
MSD Pro-Billet Distributors 85465	1.00	375.92	375.92		

DAVENPORT MOTOR SPORTS

25462 CR 43

Greeley, CO. 80631

Phone: 970-371-0022 Fax: - -

ESTIMATE #

021524**Estimate for Services**

Estimate Date : 11/8/2020

DAVENPORT, ROB

25462 CR 43

Greeley, CO 80631

CELL: 970-371-0022

1968 Plymouth - Satellite - 440

Lic # : - CO

Odom. In: 0

VIN # :

Part Description / Number	Qty	Sale	Ext	Labor Description	Extended
85465					
MSD Blaster HVC-2 Ignition Coils 8253	1.00	259.18	259.18		
8253					
Vibrant Performance Braided Flexible Race Hoses 18976	2.00	117.81	235.62		
18976					
Procomp Electronics Air Cleaners PCE104-1047	1.00	63.15	63.15		
PCE104-1047					
QA1 Eccentric Camber Bolt Adjusters 52361	1.00	56.76	56.76		
52361					
QA1 High Travel Coilover Springs 10HT300	2.00	58.91	117.82		
10HT300					
Summit Racing® Air Filter Bases SUM-G3000B	1.00	13.91	13.91		
SUM-G3000B					
Summit Racing® Powerlid Air Filter Assembly Tops SUM-239500	1.00	66.40	66.40		
SUM-239500					
RCI Camlock Harnesses 9211CD	2.00	137.09	274.18		
9211CD					
Mopar Performance Hood Pin and Cable Kits P4529405	1.00	53.55	53.55		
P4529405					
B&M Stealth Pro Ratchet Shifters 81119	1.00	455.18	455.18		
81119					
Summit Racing® Heater Hose SUM-294023	1.00	61.05	61.05		
SUM-294023					
Summit Racing® Weld-In Bungs SUM-220018	2.00	6.43	12.86		
-220018					
Meziere Barb to Male AN Fittings WP12058S	2.00	21.42	42.84		
WP12058S					
Earl's Performance Breather Tanks CT101ERL	2.00	85.68	171.36		
CT101ERL					
Allstar Performance Universal Seat Mount Kits ALL98100	2.00	39.63	79.26		
ALL98100					
Allstar Performance Crankcase Evacuation Systems ALL34145	1.00	41.77	41.77		
ALL34145					
B&M Magnum Grip Shifter Side Plates 81164	1.00	100.67	100.67		
81164					
Mastercraft Stratus AS Tires 90000034525	2.00	89.96	179.92		
90000034525					

DAVENPORT MOTOR SPORTS

25462 CR 43

Greeley, CO. 80631

Phone: 970-371-0022 Fax: - -

ESTIMATE #

021524

Estimate for Services

Estimate Date : 11/8/2020

DAVENPORT, ROB

25462 CR 43

Greeley, CO 80631

CELL: 970-371-0022

1968 Plymouth - Satellite - 440

Lic # : - CO

Odom. In: 0

VIN # :

Part Description / Number	Qty	Sale	Ext	Labor Description	Extended
Harland Sharp Heavy-Duty Roller Rockers S70016KE S70016KE	1.00	1,033.52	1,033.52		
DJM Suspension Universal Lowering Blocks SB2LK SB2LK	1.00	81.40	81.40		
FiTech Go EFI 8 Power Adder Plus 1200 HP Fuel Injection Systems with Hyperfuel In-Tank Modules 37012 37012	1.00	1,970.64	1,970.64		
Hedman Husler Race Headers 75340-6 75340-6	1.00	1,204.88	1,204.88		
Lunati Voodoo Camshafts 40230734 Mechanical roller tappet 0.600 int./0.600 ex Duration at 050 inch Lift:255 int./263 exh. 40230734	1.00	409.12	409.12		
Lunati 95525 billet 3 bolt timing set 95525	1.00	111.38	111.38		
Mickey Thompson ET Drag Slicks 3055 28 x 10.50-15 3055	2.00	235.62	471.24		
Race Star 92 Drag Star Gloss Black Wheels 92-510152B 15x10 92-510152B	2.00	221.70	443.40		
Race Star 92 Drag Star Gloss Black Wheels 92-537140B 15x3.75 92-537140B	2.00	192.78	385.56		
Dorman Electric Fans 620-039 620-039	1.00	338.44	338.44		
Summit Racing® Custom-Fit Molded Carpet Kits SUM-461042 SUM-461042	1.00	214.20	214.20		
Turbo Action Cheetah XtremeAction Valve Bodies 17899XA 17899XA	1.00	853.59	853.59		
Trick Flow® Track Heat® Intake Manifolds for Big Block Mopar TFS-61600113 TFS-61600113	1.00	374.85	374.85		
Trick Flow® Rocker Arm Shaft Studs TFS-61600613 TFS-61600613	1.00	64.26	64.26		
Trick Flow® Cast Aluminum Valve Covers TFS-61611802 TFS-61611802	1.00	160.65	160.65		
Trick Flow® PowerPort® 270 Cylinder Heads for Big Block Mopar TFS-6161T784-C01 TFS-6161T784-C01	2.00	1,429.79	2,859.58		
Trick Flow® by Comet MLS Head Gaskets TFS-61694380-051	2.00	107.10	214.20		

DAVENPORT MOTOR SPORTS

25462 CR 43

Greeley, CO. 80631

Phone: 970-371-0022 Fax: - -

ESTIMATE #

021524

Estimate for Services

Estimate Date : 11/8/2020

DAVENPORT, ROB

25462 CR 43

Greeley, CO 80631

CELL: 970-371-0022

1968 Plymouth - Satellite - 440

Lic # : - CO

Odom. In: 0

VIN # :

Part Description / Number	Qty	Sale	Ext	Labor Description	Extended
<i>FS-61694380-051</i>					
moser 8 3/4 complete 1968-70) - 35 Spline - Sealed Ball Bearing - 1/2"-20 x 3" MOPAR (.685" Knurl) - Wilwood Forged Dynalite (Black P/C 4-Piston Caliper, 12.19" Rotor) - Back Brace ,steel Spool 35 spline - 1350 Series Yoke - Forged <i>875m</i>	1.00	4,069.80	4,069.80		
AJE MOPAR 62-72 B & E BODY RACE KIT-FRONT SUSPENSION, K MEMBER AND BRAKE KIT WITH QA1 DOUBLE ADJUST COIL OVERS <i>mpbrk</i>	1.00	5,140.80	5,140.80		
Vibrant Performance High-Flow PTFE Hose End Fittings 28906 6AN 90 DEGREE <i>28906</i>	3.00	22.44	67.32		
Rear Main Bearing Seal Set <i>BS40240</i>	1.00	13.75	13.75		
chrome steering column tilt <i>657567</i>	1.00	374.85	374.85		
steering coupler and u joint kit with shaft <i>89i9u</i>	1.00	321.30	321.30		
Rear Axle Pinion Bearing <i>HM89443</i>	1.00	28.63	28.63		
Rear Axle Pinion Bearing <i>M88048</i>	1.00	14.31	14.31		
Pinion Race <i>M88010</i>	1.00	8.66	8.66		
Pinion Seal <i>5126</i>	1.00	13.29	13.29		
Selector Shaft Seal <i>759037</i>	1.00	1.44	1.44		
Rear Axle Pinion Bearing <i>HM803149</i>	1.00	30.67	30.67		
Differential Carrier Gasket <i>RDS6583</i>	1.00	5.28	5.28		
inner race <i>hm89410</i>	1.00	0.00	0.00		
PINION BRG <i>HM89410</i>	1.00	9.20	9.20		
BEARING <i>7216N</i>	1.00	0.00	0.00		
PINION BRG <i>HM803110</i>	1.00	20.45	20.45		

Phone: 970-371-0022 Fax: - -

ESTIMATE #

021524

Estimate for Services

Estimate Date : 11/8/2020

DAVENPORT, ROB

25462 CR 43

Greeley, CO 80631

CELL: 970-371-0022

1968 Plymouth - Satellite - 440

Lic # : - CO

Odom. In: 0

VIN # :

Part Description / Number	Qty	Sale	Ext	Labor Description	Extended
Automatic Transmission Filter	1.00	8.46	8.46		
58707					
Shop Supplies			45.00		

Parts/Supplies: 34,917.50

Labor: 9,300.00

Sublet: 16.565.00

Total : \$ 60,782.50

I hereby authorize the above repair work to be done along with the necessary material and hereby grant you and/or your employees permission to operate the vehicle described for testing and/or inspection. Express mechanic's lien is hereby acknowledged on above vehicle to secure the amount of repairs thereto.

I understand that my vehicle will be reassembled within 5 days of the date shown above if I choose not to authorize the service recommended. All Parts removed will be discarded unless instructed otherwise. Any vehicle left unpaid after 5 days may incur storage charges at the rate of \$25 per day. Not responsible for lost or stolen items left in vehicles. Not responsible for damage related to fire, theft or any other causes including vandalism. No warranty EXPRESSED OR IMPLIED on discounted work, work not paid in full or performance work. Manufacturers warranties and their terms are not the responsibility of DAVENPORT MOTOR SPORTS. No warranty on used parts, performance or commercially used engines or parts or . No warranty if customer supplies their own parts. Engines and transmissions carry builders warranty which is separate from shop warranty and Davenport motor sports

Signature _____ Date _____ Time _____