

Green Tea Clear Deodorant

23442



Phase	%	Tradename	INCI	Supplier	Function
A	60.0	ZEMEA	Propanediol	CovationBIO	Biostatic humectant
A	24.5		Water		Solvent
B	7.0	Sodium Stearate OP-100V	Sodium Stearate	Hallstar	Gelling agent
C	8.0	Geomulse 15	Polyglyceryl-10 Caprylate/caprate	Arxada	Solubilizer
D	0.5		Fragrance		Fragrance

Ingredients: Propanediol, Water, Sodium Stearate, Polyglyceryl-10 Caprylate/Caprate, Fragrance

Procedure

1. Heat and maintain A to 85C-95C
2. Add B to A with slow mixing until clear
3. Add C while making up lost water
4. Reduce A/B/C temperature to 80C
5. Add D with slow mixing then package while hot

Distinctives

- ✚ Clear, natural deodorant stick
- ✚ Use green tea fragrance or whatever desired
- ✚ Excellent base for ingredients with deodorancy properties
- ✚ High ZEMEA level ensures a layer of microbe discouraging water activity reducing film is applied to the skin,