- 1) Monthly maintenance was conducted on the gate to verify both the YELP system and security cameras.
- 2) New exit camera is functioning well since being replaced last quarter.
- 3) Two vendor codes were removed due to 1+ Year of no activity. Committee following up with several members to confirm if other codes can be removed due to sales or completed work.
- 4) Gate Activity:

May 2020 thru May 2021:

Clickers 4,861

Entry Code 2,626

Directory 159

Total 7,646Gate