


Hong Kong - Typhoon (Hurricane) Mangkhut Damage - Wan Chai - Sept 2018



DSC00114 Central Plaza



DSC00116 Central Plaza Walkway



DSC00117 Central Plaza Walkway Glass Sheets




DSC00119 Immigration Tower (Govt)



DSC00120 Immigration Tower (Govt)



DSC00121 Immigration Tower (Govt)



DSC00124 Immigration Tower (Govt)




DSC00126 Immigration Tower

Hong Kong - Typhoon (Hurricane) Mangkhut Damage - Wan Chai - Sept 2018



DSC00130 Gloucester Road Garden



DSC00132 Revenue Tower (Govt)



DSC00137 Revenue Tower (Govt)



DSC00138 Revenue Tower (Govt)




DSC00139 Immigration Tower (Govt)



DSC00140 Gloucester Road




DSC00142 Gloucester Road



DSC00145 Dah Sing Bank

Hong Kong - Typhoon (Hurricane) Mangkhut Damage - Wan Chai - Sept 2018



DSC00146 Dah Sing Bank



DSC00148 Central Plaza




DSC00149 Central Plaza




DSC00150 Gloucester Road




DSC00155 Gloucester Road



DSC00156 Central Plaza Building




DSC00159 Central Plaza Glass Everywhere



DSC00160 Central Plaza Glass Everywhere

Hong Kong - Typhoon (Hurricane) Mangkhut Damage - Wan Chai - Sept 2018



DSC00164 Gloucester Road



DSC00167 Central Plaza Glass Everywhere



DSC00168 Central Plaza




DSC00169 Central Plaza



DSC00172 Central Plaza



DSC00175 Central Plaza



DSC00177 Central Plaza




DSC00178 Central Plaza

Hong Kong - Typhoon (Hurricane) Mangkhut Damage - Wan Chai - Sept 2018



DSC00180 Central Plaza



DSC00181 Central Plaza



DSC00184 Harbour Road



DSC00185 Harbour Road



DSC00186 Convention Plaza



DSC00187 Convention Plaza



DSC00191 Lifted By By Water



DSC00196 McDonalds Taped