

# RECALL LIST – WINTER 2024

## [Moonsea Pack and Play Mattresses](#)

Hazard: The recalled mattresses violate multiple provisions of the federal safety regulation for crib mattresses, including the thickness test and missing warnings and labels. The product poses a suffocation hazard to infants.

## [Bugaboo Dragonfly Seat Strollers](#)

Hazard: In “parent-facing” mode, the backrest of the seat can move downward, placing the infant in a negative recline. In this situation, an unrestrained infant could tumble from the seat, posing an injury hazard.

## [Vibe Bear Playyard Mattresses](#)

Hazard: The recalled mattresses violate multiple provisions of the federal safety regulation for crib mattresses, including the firmness and thickness tests, and are missing warnings and labels. The product poses a suffocation hazard to infants.

## [Wooden Music Shaker and DTR M&M Maracas Baby Rattles](#)

Hazard: The bottom portion of the recalled baby rattles can detach, posing choking and/or ingestion hazards.

## [Colorful Metal Neodymium Magic Magnetic Balls - 8 color, 5mm](#)

Hazard: CPSC testing determined the magnetic ball sets do not comply with the requirements of the mandatory federal toy regulation because they contain one or more magnets that fit within CPSC’s small parts cylinder, and the magnets are stronger than permitted. When high-powered magnets are swallowed, the ingested magnets can attract each other, or another metal object, and become lodged in the digestive system. This can result in perforations, twisting and/or blockage of the intestines, infection, blood poisoning and death.

## [Bubba Bull Plush Toys](#)

Hazard: The eyes of the plush toys can break off, posing a choking hazard to young children.

## [Klickpick Home Children’s Cup Sets](#)

Hazard: The bottom exterior of the stainless-steel cups contains an accessible solder bead with levels of lead that exceed the federal lead content ban. Lead is toxic if ingested by young children and can cause adverse health effects. In addition, the lid can crack and break during use producing sharp edges and small parts, posing laceration, and choking hazards to children.

## [Tiblue 8 oz and 12 oz children’s cups](#)

Hazard: The bottom exterior of the stainless-steel cups contains an accessible solder bead with levels of lead that exceed the federal lead content ban. Lead is toxic if ingested by young

children and can cause adverse health effects. In addition, the lid can crack and break during use producing sharp edges and small parts, posing laceration, and choking hazards to children.

#### **DODO Baby House Pack and Play Mattresses**

Hazard: The recalled mattresses violate multiple provisions of the federal safety regulation for crib mattresses, including the thickness test and missing warnings and labels. The product poses a suffocation hazard to infants.

#### **PandaEar Stainless Steel Toddler Cups, 8 oz.**

Hazard: The bottom exterior of the recalled stainless-steel cups contains an accessible solder bead with levels of lead that exceed the federal lead content ban. Lead is toxic if ingested by young children and can cause adverse health effects. In addition, the lid can crack and break during use producing sharp edges and small parts, posing choking and laceration hazards to children.

#### **13-Piece Toy Mushroom Peg Sorters**

Hazard: The stems of the toy mushrooms can detach, posing a choking hazard to young children.

#### **LAOION Children's Cups**

Hazard: The bottom exterior of the stainless-steel cups contains an accessible solder bead with levels of lead that exceed the federal lead content ban. Lead is toxic if ingested by young children and can cause adverse health effects. In addition, the lid can crack and break during use producing sharp edges and small parts, posing choking and laceration hazards to children.

#### **Creativity Street Assorted Craft Buttons**

Hazard: The recalled children's craft buttons contain levels of lead that exceed the federal lead content ban. Lead is toxic if ingested by young children and can cause adverse health effects.

#### **Yoocaa Baby Loungers**

Hazard: The recalled loungers fail to meet the safety requirements of CPSC's Infant Sleep Products Rule, creating an unsafe sleeping environment for infants and posing a suffocation risk and fall and entrapment hazards to infants. The failures include not having a stand and not meeting the requirements for side height and fabric-sided openings. The product's sides are shorter than the minimum side height limit; the sleeping pad's thickness exceeds the maximum limit; and an infant could fall out of an enclosed opening at the foot of the lounger or become entrapped.

#### **Cosco Jump, Spin & Play Activity Centers**

Hazard: The activity centers' straps can detach or break while a child is in the activity center, posing fall and injury hazards to the child.

### **Thomas & Friends Wooden Railway Troublesome Truck & Crates and Thomas & Friends Wooden Railway Troublesome Truck & Paint**

Hazard: The small plastic piece containing a high-powered magnet that connects one train to another can detach or become loose, posing choking and magnet ingestion hazards.

### **YourHealthToolkit 5-Pound Children's Weighted Blankets**

Hazard: A young child can become entrapped by unzipping and entering the blanket, posing a risk of death by asphyxiation.

### **Sleepyhead Loveys and Bandana Bibs**

Hazard: The care instruction label on the Sleepyhead Loyal and Bandana Bib can detach, posing a choking hazard to young children.

### **The FORT Children's Play Tents**

Hazard: The magnets used to connect the various pieces of The FORT can become dislodged from their pouches, posing choking and laceration hazards to young children.

### **Rainbow Road Series Board Books**

Hazard: The plastic binding rings can detach from the books, posing a choking hazard to young children.

### **HONEY JOY Infant Swings**

Hazard: The swing violates the Safe Sleep for Babies Act because the product was marketed for infant sleep and has an incline angle greater than 10 degrees. Infant fatalities have occurred in inclined sleepers, after the infants rolled from their back to their stomach or side while unrestrained, or under other circumstances. The swing also violates the Safety Standard for Infant Swings.

### **Chuckle & Roar Ultimate Water Beads Activity Kits**

Hazard: If a water bead is ingested, it expands and can pose ingestion, choking and intestinal obstruction hazards inside a child's body, resulting in severe discomfort, vomiting, dehydration, and a risk of death to a child.

### **Boon Flair & Flair Elite highchairs**

Hazard: The bolts used to secure the seat of the recalled highchair to the pedestal base can become loose and allow the seat to detach, posing a fall hazard.

### **Ecnup Kids bike helmets**

Hazard: The recalled helmets do not comply with the coverage, positional stability, and labeling requirements of the CPSC federal safety standard for bicycle helmets. The helmets can fail to protect in the event of a crash, posing a risk of head injury.

### **Simplex3 Toddler Towers**

Hazard: The towers can tip over while in use posing fall and injury hazards to young children.

### **Zipadee Kids Convertible House Bed Frames and Montessori Floor Beds**

Hazard: The spindles used on the recalled beds are spaced at a distance that creates a serious entrapment hazard that can lead to strangulation and/or death to children. The design of the bed allows a child's torso to slip through the rail opening but will not allow their head to pass, posing entrapment and strangulation hazards that could result in death.

### **Room & Board Natural Organic Latex and Latex and Spring Crib Mattresses**

Hazard: The recalled crib mattresses fail to comply with multiple provisions of the Federal Safety Standard for Crib Mattresses, including the firmness test and missing warnings and labels. The product poses a suffocation hazard to infants.

### **Philips Avent Digital Video Baby Monitors**

Hazard: The rechargeable lithium-ion batteries in the Parent Unit monitors can overheat during charging, posing a risk of burns and property damage.