

## 2007 DASSAULT FALCON 900EX EASy serial number 178

Total Time: 6397 Cycles: 3540

Eng #1 ser. No. 112701 TSN: 6204 CSN: 3385 TSCZI/MPI: 376 Eng #2 ser. No. 112690 TSN: 6113 CSN: 3330 TSCZI/MPI: 554 Eng #3 ser. No. 112687 TSN: 6134 CSN: 3364 TSCZI/MPI: 113

Engines: Honeywell TFE731-60-1C - 7000 Hour TBO - Enrolled on MSP Gold

<u>APU</u>: Honeywell GTCP36-150(F) – Loaner installed

Avionics Suite: Standard Honeywell EASy II Cert 4 with the following options:

- Head-Up Guidance (HGS); Enhanced Vision System (EFVS)
- Synthetic Vision System (SVS)
- WAAS/LPV
- RAAS
- XM Graphical Weather
- Automatic Descent Mode (ADM)
- CPDLC FANS 1/A+ & ATN B1
- Thrane & Thrane Aviator 700D
- Triple IRS; Triple FMS
- Push-to-Load Functionality (to be installed at C inspection)

Maintenance: Operated Part 91. Enrolled on Veryon Maintenance Tracking (formerly FlightDocs)

- 3C Inspection and Landing Gear dimension/corrosion check and additional service bulletins to begin May 12, 2025 at Standard Aero – Springfield IL
- Currently enrolled on the Dassault OCIP Program for A & B inspections

Interior: Standard Twelve passenger configuration plus forward side-facing crew jumpseat

- Forward four-place club; mid-cabin four place dining/conference group opposite storage credenza; aft cabin single chair opposite berthable three-place divan with full-length closet. Aft cabin divider with electric pocket privacy curtain. Forward crew and aft lavatories
- Hi Gloss Qtr Fig Sycamore veneer. Satin nickel plating
- New carpet to be installed at C inspection
- Forward galley with marble countertop. Warming oven, microwave, coffee maker.
- New Collins Aerospace Venue Cabin Management System to be installed at C inspection
- Jetwave communications
- Dual USB Cabin and Cockpit Charging Systems to be installed at C inspection

Exterior: Overall Matterhorn White. New July 2025 at Standard Aero Springfield, IL

All Information current as of 05/02/2025