

1959-60 Lark 2 Door Sedan

Rubber Kit

KIT # GRK-997R

Windshield gasket	1942X2	\$ 79.00	"U" channel clips (2)	271475	\$ 2.00 ea.
Door sill seals	800401X4	\$ 15.00 pr.	Back glass gasket	2035X1	\$ 79.00
Door upper corner seals	1337344-5	\$ 22.00 pr.	Trunk seal	800252	\$ 40.00
Around door seal	800400	\$ 34.00 pr.	Gas lid bumpers (2)	261419	\$ 2.00 ea.
Cowl seal	298965	\$ 15.00	Hood bumpers (6)	1339574X1	\$ 1.25 ea.
Vent division seal	310738	\$ 44.00 pr.	Hood bumpers (2)	1332093X2	\$ 2.50 ea.
Lower vent "u" channels	800851	\$ 26.00 ea.	Weatherstrip adhesive	30540	\$ 12.00
Around vent window seal	310736-7	\$130.00 pr.			
Door window "u" channels	800504	\$ 26.00 ea.			
Quarter window "U" chnl. (79")	800504X8	\$ 36.00 ea.			
Window run (fuzzystrip) (8 pc.)	800507X6	\$ 76.00 set			
Fuzzystrip ret. clip (26)	1624X1	\$.50 ea.			

Rubber Kit, \$645.

Value if purchased separately: 755.50

GLASS

		Clear	Green	Green w/ shade
Windshield, curved:	CH574	\$315	\$325*	\$335
Vent glass	CH2024T	\$ 28 ea.	\$ 30 ea.	
Door glass	CH4032T	\$ 84 ea.	\$ 99 ea.	
Quarter glass	CH4222S	\$ 69 ea.	\$ 81 ea.	
Back Glass	Call for availability			

Additional Parts (not in kits)

	Part #	Price
Boot, accelerator, at floor	513536X1	\$ 6.00
Door glass setting strip	1835X30	\$ 10.00 ea.
Headliner kit (specify color), "Acme" brand	Call for price and options	
Firewall grommets		
Main wiring	532909	\$ 8.00
Speedometer cable to firewall	1548474	\$ 8.00
Body Parts Manual, reprint (1959-64)	800437	\$ 35.00
Chassis Parts Manual, reprint (1959-64)	800432	\$ 46.00
Shop Manual, reprint (1959-60)	800426	\$ 55.00
All Manuals on CD (Body, Chassis, Shop & supp.)	801203	\$ 24.95

STUDEBAKER GLASS & RUBBER

4150 S. Streeter Ave., Idaho Falls, ID 83406 studebakerglass.com Phone: 208-390-6306

Revision: 4/16/2018