

Glass and Rubber Combo

1959-60 Lark 2 Door Hard-top

Kit number RK1001

Windshield gasket	1942X2	\$ 80.00	Catswhiskers ret. clips (40)	1882X1	\$.50 ea
Door sill seals	800401X4	\$ 15.00 pr.	Back glass gasket	2035X4	\$ 80.00
Door upper corner seals	1337344-5	\$ 22.00 pr.	Trunk seal	800252	\$ 40.00
Door seal, front	800400X5	\$ 16.00 pr.	Gas lid bumpers (2)	261419	\$ 2.00 ea.
Rear of door seal	1331996-7	\$ 86.00 pr.	Hood bumpers (6)	1339574X1	\$ 1.25 ea.
Cowl seal	298965	\$ 15.00	Hood bumpers (2)	1332093X2	\$ 2.50 ea.
Vent division seal	1320725	\$ 22.00 ea.	Weatherstrip adhesive	30540	\$ 12.00
Vent window lower channel	800852	\$ 28.00 ea.			
Verticle seal, door glass to qtr.	1331620-1	\$ 20.00 pr.			
Window stop (2 reqd.)	1328454	\$ 15.00 ea.			
Around vent window seal	1332310-1	\$130.00 pr.			
Above door seal	1331926-7	\$150.00 pr.			
Catswhiskers set (8 pc.)	800507X10	\$ 75.00 set			

Complete Rubber Kit,
value if purchased separately: \$892.50
KIT PRICE \$748.00

Glass & Glass Kit

		Clear	Green	Grey (44%)
Windshield	CH574	\$325.	\$325	*
Vent glass	CH2247T	\$ 28. ea.	\$ 30.	\$ 30.
Door glass,	CH4223T	\$ 78. ea.	\$ 93.	\$ 93.
Quarter glass, 1959-60	CH4224S	\$ 78. ea.	\$ 93.	\$ 93.
Back window glass	Call for availability			

*Grey windshield not available, use green or green w/ shade (CH574 GBN, \$335).

Side glass kit, 6 pc. 1959-60	RK6001E	\$324.	\$380.	\$380.
-------------------------------	---------	--------	--------	--------

Studebaker Glass & Rubber

Tom & Carla Senecal, 300 Lawndale Dr. Spring Creek NV 89815 775-385-8170

