

1962-64 GT Hawk

Rubber Parts & Rubber Kit (RK008)

Windshield gasket	1942X1	\$ 99.00	Qtr. Glass to frame setting strip	1770X2	\$ 12.00 ea
Windshield post seal	1347012-3	\$ 24.00 pr.	Vertical seal, dr. wind. to qtr.	1343342	\$ 20.00 pr.
Vent lower ext. seal	307546-7	\$ 22.00 pr.	Cats-whisker set (6 pc)	800507X12	\$ 45.00
Door sill seals	800401X4	\$ 15.00 pr.	Cats-whisker ret. Clip (28)	1624X1	\$.50 ea.
Upper W/S post to door seal	770153	\$ 10.00 pr.	Outer qtr. Window seal kit	801100	\$ 30.00
Upper door corner seal	1347014-5	\$ 30.00 pr.	Cowl to hood seal	298965	\$ 15.00
Above Door Seal	1347010-1	\$125.00 pr.	Trunk seal, vulcanized corners	1347074	\$ 65.00
Around vent frame seal	1347006-7	\$130.00 pr.	Back glass gasket	1343726	\$ 99.00
Vent window stop seal (2)	801697	\$ 4.00 ea.	Gas lid bumpers (2)	261419	\$ 2.00 ea.
Vent division seal	1347005	\$ 44.00 pr.	Rear valance bumpers (5)	287427	\$ 2.50 ea.
Front of door seal	303928-9	\$ 36.00 pr.	Hood bumpers (8)	274974	\$ 2.50 ea.
Rear of door seal	1347016-7	\$ 90.00 pr.	Front hood bumpers (2)	1351407	\$ 3.50 ea.
Door window to v-channel liner	304181	\$ 45.00 ea.	Air Vent lid seal (2)	284991	\$ 6.00 ea.
Door glass to glass chnl. tape	1992X1	\$ 10.50 ea.	Loctite weatherstrip adhesive	30540	\$ 12.00 ea.
Door glass to frame setting strip	1770X1	\$ 12.00 ea.			

Kit Price: \$1005.00 Price sold seperately \$1048.00

Glass & Glass Kits

		Clear Glass	Green Glass	Grey (Limo*) Glass
Windshield,	CH306	\$279.00	\$279.00	\$345.00 **
Vent Glass, tempered	CH2981	\$ 28.00	\$ 30.00	\$ 34.00*
Door Glass, tempered	CH4370	\$ 53.00	\$ 55.00	\$ 61.00*
Quarter Glass, tempered	CH2413	\$ 35.00	\$ 36.00	\$ 40.00*
Back Glass	CHB3133	\$345.00	\$355.00	\$375.00*
Complete (8 pc.) Glass Kit	GK8008	\$803.	\$818.	\$886.
Side Glass Kit (6 Pc.)	GK6008	\$215.	\$218.	\$243.

Note: all side glass is tempered!!

* Grey (Limo) Glass is DOT legal in all 50 states.

** Also available in gray with darker gray sunband, \$365. and green with dark blue sunband, \$335.

Additional Parts (not in kits)

	Part #	Price
Accelerator pedal, type A, steel linkage connection	532800	\$26.00
Accelerator pedal, type B, rubber socket	535117	\$25.00
Boot, accelerator pedal	513536X1	\$ 6.00
Firewall insulator	298747	\$99.00
Headliner kit, vinyl (specify color)	by description	\$225.00
Headliner kit, cloth (specify color)	by description	\$245.00
Firewall grommets		
Main wiring, 1953-55	532909	\$ 8.00
Main wiring, 1956-58	1540836	\$ 8.00
Speedometer cable, 1953-58	1548474	\$ 8.00
O/D control cable, 1953-54	533855	\$ 3.00
Heater hose, where needed	1556859	\$ 3.50
Front fender to body shim	298340	\$12.00 each
Rear fender to body shim (at door pillar)	299850	\$ 6.50
Body Parts Manual, 1953-58 (reprint, 540 pgs.)	800436	\$40.00
Chassis Parts Manual, 1951-54 (reprint, 364 pgs.)	800430	\$35.00
Chassis Parts Manual, 1955-58 (reprint, 570 pgs.)	800431	\$45.00
Electronic Manuals on CD (Body, chassis)	801203	\$24.95

STUDEBAKER GLASS & RUBBER

Tom & Carla Senecal 300 Lawndale Dr. Spring Creek NV 89815