

MCW Finishes - Acrylic Lacquer

Painting Instructions.

MCW paints are airbrush ready. No need to add additional thinner.

Spray at 15-25 psi depending on your airbrush.

A good lacquer primer should be applied before painting. MCW can supply this if needed.

Spray close to your work. 2-3 inches. This paint dries very fast. You want to spray "wet" coats. The paint is thin, but it is hard to make it run.

You can go over the model in multiple passes without waiting for each coat to dry.

You can wet sand between coats for an extra deep gloss. This paint will not hide details even with 4-6 coats.

All of our paints, even military colors and gloss. For military models, this will help with decals and weathering. MCW makes 20%, 40%, and 60% flat clear coats for military kits.

Clean your airbrush with any lacquer thinner. "big box" thinner is not as high quality as the thinner we use to thin the paint with. It is ok to clean your brush with but is not recommended to thin MCW paints.

Please call us at 330-830-7755 with any questions.